



**SERVICE BULLETIN
AND
SERVICE LETTER**

INDEX

PIPER AIRCRAFT, INC.

Published by

Piper Aircraft, Inc.
Attn: Technical Publications
2926 Piper Drive
Vero Beach, Florida 32960
U.S.A.

© 2003–2024 Piper Aircraft, Inc.



Member
General Aviation
Manufacturers Association

SERVICE PUBLICATION AVAILABILITY

Piper terminated production of all Aerofiche (i.e., microfiche) products in 2008.

Service Publications (i.e., service bulletins, letters, etc.) are available as described in the Customer Service Information File on the Piper website.

The latest revision of this publication is also available as free downloads from the Piper Aircraft, Inc. website at:

<http://www.piper.com/technical-publications-documents/>

GENERAL

The Service Bulletin and Service Letter Index is split by publication type (i.e., SB or SL) and then arranged by aircraft model number (i.e., PA-28, etc) with similar model series grouped together (see Table of Contents). Within these series, applicable service bulletins/letters are listed in numerical order. To locate a specific bulletin or letter, select the appropriate service publication type (i.e., SB or SL) and then locate the affected aircraft series grouping. Bulletins/letters which apply are listed therein and are identified by Subject, Model(s) Affected, and the Issue Date of the Service Bulletin/Letter. Additionally, the index may list part or kit numbers and related A.D. numbers. The Air Transport Association Code (ATA Spec. 100 / iSpec 2200) is provided to assist in maintenance record keeping and researching publications.

NOTES

1. Airworthiness Directives referred to by number in the A.D. No. column and A.D. numbers listed in individual service bulletins / service letters are those which applied at the time of publication. Refer to the latest FAA Bi-weekly listing for current A.D. information. A searchable database of AD's is available on the FAA website. See the "Airworthiness Directives" link at "www.faa.gov".
2. When ** appears in the Part/Kit No. column, material requirements are too extensive to be listed in the index; refer to the appropriate service bulletin/letter for material identification.
3. When Part/Kit No. and/or A.D. No. column is left blank or indicates "N/A," no material and/or Airworthiness Directive is involved.
4. Airworthiness Directives may be issued without an associated service bulletin/letter; therefore, refer to Airworthiness Directive Listings issued by the FAA to determine all Airworthiness Directives applicable to an aircraft. See Note 1, above.
5. Type Certificates (TC's) for the following aircraft models are not held by Piper: AE-1, HE-1, J5A, J5A-80, J5B, J5C, L-14, PA-12, PA-12S, PA-14, PA-25, PA-60, and Stinson 108-3. See Supersession List for affected service bulletins / letters. The current TC holder(s) may be identified through the FAA (see the "Regulatory and Guidance Library" at <http://rgl.faa.gov/>).

SERVICE BULLETIN AND SERVICE LETTER
INDEX

TABLE OF CONTENTS

<u>SUBJECT</u>	<u>PAGE NO.</u>
Service Publication Availability	iii
General	iv
Notes	iv
Table Of Contents	v
Supersession List	vii

SERVICE BULLETINS

CLASSIC AIRCRAFT: (B-2 thru PA-22)	SB1
PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250	SB9
PA-24, PA-30/39	SB17
PA-28, PA-28R, PA-44/PA-44T	SB23
PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350	SB43
PA-31T/31T1, PA-31T2/31T3, PA-42	SB55
PA-32 Series	SB65
PA-34-200/200T/220T	SB79
PA-36	SB87
PA-38-112	SB91
PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46-701TP, PA-46R-350T	SB95

SERVICE LETTER

CLASSIC AIRCRAFT: (B-2 thru PA-22)	SL1
PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250	SL7
PA-24, PA-30/39, PA-28, PA-28R, PA-44/PA-44T	SL23
PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350	SL37
PA-31T/31T1, PA-31T2/31T3, PA-42	SL47
PA-32 Series	SL53
PA-34-200/200T/220T	SL61
PA-36	SL67
PA-38-112	SL69
PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46-701TP, PA-46R-350T	SL71

THIS PAGE INTENTIONALLY BLANK

SUPERSESSION LIST

The following service bulletins / letters have been superseded, become obsolete, were never issued, or are no longer maintained by Piper, as indicated (see Note 5).

NOTE: This list is not all inclusive. Additionally, it does not include supersessions by a normal (i.e. - A, B, C, etc.) revision within the same SB/SL number.

<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>
SB 0005	Obsolete	SB 0101	PA-12	SB 0670	SB 1235
SB 0006	Obsolete	SB 0102	PA-12	SB 0687	SB 1007
SB 0010	Obsolete	SB 0105	PA-12/14	SB 0698A	SB 0811A
SB 0011	Obsolete	SB 0106	PA-12/14	SB 0699 (PA-34 only)	SB 0899
SB 0012	Obsolete	SB 0107	PA-12	SB 0716	Not Used
SB 0013	Obsolete	SB 0109	PA-12/14	SB 0720	PA-60
SB 0014	Obsolete	SB 0114	STINSON 108-3	SB 0730	Not Used
SB 0015	Obsolete	SB 0115	STINSON 108-3	SB 0735	PA-25
SB 0016	Obsolete	SB 0137	SB 0140	SB 0743	PA-60
SB 0017	Obsolete	SB 0141	SB 0354B	SB 0746A	PA-60
SB 0019	Obsolete	SB 0147	Obsolete	SB 0750	PA-60
SB 0020	Obsolete	SB 0154	Obsolete	SB 0755	PA-60
SB 0022	Obsolete	SB 0170	Obsolete	SB 0756	PA-60
SB 0024	Obsolete	SB 0204	PA-25	SB 0757	PA-60
SB 0025	Obsolete	SB 0206	PA-25	SB 0761	PA-60
SB 0026	Obsolete	SB 0215	PA-25	SB 0770	PA-60
SB 0027	Obsolete	SB 0217	PA-25	SB 0793	SB 0809
SB 0029	Obsolete	SB 0221	PA-25	SB 0815	PA-60
SB 0030	Obsolete	SB 0227	SB 0230A	SB 0818	PA-60
SB 0031	J5A/B/C	SB 0241A	PA-25	SB 0830	PA-25
SB 0032	Obsolete	SB 0247	PA-25	SB 0832	PA-60
SB 0033	Obsolete	SB 0298 (portions)	SB 0312	SB 0833	Not Used
SB 0034	J5A/B/C	SB 0302	Obsolete	SB 0864	SB 1008
SB 0037	Obsolete	SB 0318A	SB 0343	SB 0886	SB 1372
SB 0038	Obsolete	SB 0328	PA-25	SB 0875	SB 0876A
SB 0039	Obsolete	SB 0341	PA-25	SB 0878	PA-25
SB 0041	Obsolete	SB 0366	SB 0456A	SB 0880A	PA-60
SB 0051	Obsolete	SB 0371	SB 0456A	SB 0894	SB 1087
SB 0052	Obsolete	SB 0372B	SB 0446A	SB 0898	PA-60
SB 0054	SB 0083	SB 0377	SB 0456A	SB 0902	PA-60
SB 0057	Obsolete	SB 0378	SB 0456A	SB 0903	PA-60
SB 0059	Obsolete	SB 0388	SB 0456A	SB 0908	PA-60
SB 0060	J5A/B/C	SB 0410	PA-25	SB 0909	SB 0913A
SB 0062	Obsolete	SB 0413	SB 1123	SB 0918	PA-60
SB 0064	Obsolete	SB 0414	PA-25	SB 0920	PA-60
SB 0067	Obsolete	SB 0416	SB 0446A	SB 0942	PA-60
SB 0069	Obsolete	SB 0426	PA-25	SB 0950	PA-60
SB 0070	Obsolete	SB 0430	SB 0492	SB 0978A	SB 1372
SB 0087	J5A/B/C	SB 0456A	SB 1266	SB 1011	SB 1216
SB 0090	PA-12	SB 0457	SB 0479B	SB 1038	VSP-145
SB 0092	PA-12	SB 0532	PA-25	SB 1096	Not Used
SB 0093	PA-12	SB 0534	SB 0644E	SB 1101	Not Used
SB 0094	PA-12	SB 0540A	Cancelled	SB 1112	Not Used
SB 0096	PA-12	SB 0551A	PA-25	SB 1115	Not Used
SB 0097	PA-12	SB 0581	Not Used	SB 1116	Not Used
SB 0098	PA-12	SB 0605	Obsolete	SB 1124	Not Used
SB 0100	PA-12	SB 636A	SB 1273C	SB 1129	Not Used

SUPERSESSION LIST

(continued)

<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>
SB 1133	Not Used	SL 0265	753-755	SL 0604	SB 0531
SB 1142	Not Used	SL 0282	SB 0145	SL 0632	PA-25
SB 1148	Not Used	SL 0308	SSL-141	SL 0640	PA-25
SB 1149	Not Used	SL 0331	PA-25	SL 0646	PA-25
SB 1155	Not Used	SL 0332A	PA-25	SL 0694	SB 0492
SB 1163	Not Used	SL 0335	PA-25	SL 0702	PA-25
SB 1165	Not Used	SL 0337	PA-25	SL 0703	Obsolete
SB 1189A	Not Used	SL 0342	PA-25	SL 0721A	PA-25
SB 1191A	Obsolete	SL 0343	PA-25	SL 0724	PA-25
SB 1195	SB 1395	SL 0344	PA-25	SL 0728	PA-25
SB 1203	SL 1117	SL 0351	SB 0354B	SL 0748	Obsolete
SB 1206	Not Used	SL 0357A	PA-25	SL 0760	SB 1131
SB 1215	SSL 436	SL 0361	PA-25	SL 0775A	Obsolete
SB 1218A	SB 1385	SL 0371	SB 0209	SL 0799	SB 0955
SB 1219	SL 1125	SL 0371A	SB 0209	SL 0811	SB 1248
SB 1221	Not Used	SL 0376	PA-25	SL 0812	PA-25
SB 1222	Not Used	SL 0377	PA-25	SL 0914	PA-60
SB 1224	Not Used	SL 0383	PA-25	SL 0918	PA-60
SB 1231	Not Used	SL 0385	PA-25	SL 0919	PA-60
SB 1239	Not Used	SL 0387	PA-25	SL 0953	SB 0896
SB 1249	SB 1252	SL 0392	SB 0924	SL 0955	SB 0868
SB 1263	Not Used	SL 0396 (portions)	SL 0527D	SL 0957	PA-60
SB 1265	Not Used	SL 0399	PA-25	SL 0980	SB 0908
SB 1268	SB 1270	SL 0403	PA-25	SL 1030	SSL 435
SB 1272	Not Used	SL 0428	SB 0222A	SL 1042	Not Used
SB 1277	Not Used	SL 0452	SL 0486A	SL 1044	Not Used
SB 1281	SB 1285	SL 0455	PA-25	SL 1050	Not Used
SB 1287A	Not Used	SL 0463A	PA-25	SL 1061	Not Used
SB 1292	Not Used	SL 0468A	PA-25	SL 1064	Not Used
SB 1294	Not Used	SL 0479	PA-25	SL 1068	Not Used
SB 1298	Not Used	SL 0488	Obsolete	SL 1070	Not Used
SB 1310	SB 1339	SL 0489	Obsolete	SL 1071	Not Used
SB 1320	SL 1229	SL 0493	Cancelled	SL 1073	Not Used
SB 1321	Not Used	SL 0496	Obsolete	SL 1080	Not Used
SB 1330	Not Used	SL 0510	Obsolete	SL 1083	Not Used
SB 1335	SA 46-28	SL 0515	PA-25	SL 1094	Not Used
SB 1345A	SB 1372	SL 0521	Obsolete	SL 1096	Not Used
SB 1347	Not Used	SL 0528	Obsolete	SL 1098	Not Used
SB 1348	SA 46-31	SL 0536	PA-25	SL 1099	Not Used
SB 1351	Not Used	SL 0540	Obsolete	SL 1101	Not Used
SB 1353	SA 28-05	SL 0551	Obsolete	SL 1103A	Not Used
SB 1356	SL 1297	SL 0554	Obsolete	SL 1109	SL 1142
SB 1373	Not Used	SL 0563	PA-25	SL 1109A	Not Used
SB 1374	Not Used	SL 0570	SB 0343	SL 1112	Not Used
SB 1376	Not Used	SL 0572	Obsolete	SL 1114A	Not Used
SB 1394	Not Used	SL 0583	Obsolete	SL 1115B	Not Used
SB 1398	Not Used	SL 0586	PA-25	SL 1119	Not Used
SB 1406	Not Used	SL 0588	SB 0840 - PT1	SL 1133	Not Used
SL 0108	PA-12	SL 0590	SB 0840 - PT2	SL 1136B	Not Used
SL 0110	PA-12	SL 0597	SB 0965	SL 1139A	SL 1147
SL 0113	PA-12/14	SL 0600	SB 1199	SL 1143	Not Used
SL 0160	SL 0221	SL 0601	SB 0356	SL 1144	Not Used
SL 0191	SL 0233	SL 0602	Obsolete	SL 1145	Not Used

SUPERSESSION LIST

(continued)

<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>
SL 1146	Not Used	SL 1341	Not Used		
SL 1150	Not Used	SL 1342	Not Used		
SL 1151	Not Used				
SL 1152	Not Used				
SL 1155A	Not Used				
SL 1163	Not Used				
SL 1166	Not Used				
SL 1167	Not Used				
SL 1169	Not Used				
SL 1171	Not Used				
SL 1173	Not Used				
SL 1174	Not Used				
SL 1176	Not Used				
SL 1180	Not Used				
SL 1181	Not Used				
SL 1182	Not Used				
SL 1186	Not Used				
SL 1187	Not Used				
SL 1190	Not Used				
SL 1191	Not Used				
SL 1192	Not Used				
SL 1202A	SL 1247				
SL 1206A	Not Used				
SL 1207	SL 1217				
SL 1209	SB 1300				
SL 1215A	SL 1254				
SL 1223	VSP 248				
SL 1225	SSL 482				
SL 1235	SB 1324				
SL 1237	Not Used				
SL 1241	SL 1216				
SL 1242	SL 1231A				
SL 1243	Not Used				
SL 1248	SSL 493				
SL 1258	SB 1349				
SL 1266B	Not Used				
SL 1271	Not Used				
SL 1272A	SB 1369				
SL 1287	Not Used				
SL 1288	Not Used				
SL 1289	SB 1364				
SL 1290	Not Used				
SL 1295	SB 1366				
SL 1298	SSL 507				
SL 1299	Not Used				
SL 1303	SL 1292A				
SL 1305	SB 1375				
SL 1306	SL 1309				
SL 1307	SL 1293A				
SL 1312	SB 1383				
SL 1315	SB 962				
SL 1319	SB 1379				
SL 1328	Not Used				

THIS SPACE INTENTIONALLY BLANK

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1	How to Rig Cub E2, J2, J3 Airplanes	E2, J2 & J3	2/15/46			2A1
2	Special Tubing in Fuselage	All Models Manufactured thru December 1945	2/15/46			2A2
3	Nose Heavy Condition	All Models Manufactured thru December 1945	2/15/46			2A3
4	Maintenance of Fuel System	All Models Manufactured thru December 1945	2/15/46			2A4
7	Reinforcement of Stabilizer Yoke	J2	2/18/46			2A5
8	Reinforcement of Stabilizer Yoke	E2 and F2	2/18/46			2A7
9	Tail Surface Bracing	E2, F2 & J2	2/18/46			2A9
18	Replacement Tail Brace Wire Nipples	J2 and J3	2/18/46			2A11
21	Engine Mounting Bolt Failures	J3C-65 Cubs with Continental A50 Engine Installation	2/18/46			2A14
23	Removal of Bug Screen	J4	2/18/46			2A15
28	Electrical Wiring	J4	2/18/46			2A16
35	Reinforcement of Windshield Attachment	J3	2/19/46			2A20
36	Inspection of Motor Mount	J3	11/4/41			2A22
40	Outlet Reinforcement on 12 Gallon Fuel Tanks	J3	2/19/46			2A23
42	Elevator Bungee Installation	J3S	2/19/46			2B1
43	Stabilizer Link Tubes and Rear Support Bearing Bracket	J3	2/19/46			2B3
44	Operation of Airplanes with Enclosure Door Open	J3	2/19/46			2B6
45	Control System Interference	J3	2/19/46			2B7
46	Strainer Attachment Fittings	J3F-50, J3L-50, J3L-55, J4, J4A, J4B, J4D	2/19/46			2B9
47	Preparation for Winter Operation	J3 Series, E2, J2, J3, 40 H.P. (not equipped with Adequate Carburetor Heater.)	2/19/46			2B11
48	Mufflers: 1. Failure of Inner-Baffle End Attachments 2. Inspection 3. Remedial Measures for Preventing Engine Failure	J4A and J4F	2/19/46			2B13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
49	Revised Washer for Fin Brace Rod Clevis	J3	2/19/46			2B16
50	Ribstitching	E2, J2, J3 J4	2/19/46			2B17
53	Fuel Shut-off Swivel Fitting	J3	2/20/46			2B19
55	Fuel Tank Vents	J4E	2/20/46			2B21
56	Wing Aileron Bellcrank Bracket Failures	J4	2/20/46			2B23
58	Steerable Tail Wheel Shock Cords	All Models Manufactured thru December 1945	2/20/46			2C2
61	Aging of Protective Finish on Wood Wing Spars	J3, J4, L4 and L4A	2/20/46			2C4
63	Stabilizer Aluminum Yoke Casting	J3, L-4, L-4A, L-4B.	2/20/46			2C5
65	Fuel Tank Repairs	J4E	2/20/46			2C7
66	Flexible Hose End Fittings (3/8" Synthetic)	J3, J4	2/20/46			2C10
68	Stabilizer Rear Bearing Bracket	J3	2/20/46			2C11
71	Exhaust Muffler Inspection and Repair	J3, J4 Airplanes Incorporating Exhaust Mufflers.	2/20/46			2C12
72	Rudder Pedal and Floorboard Attachment Lugs	J3	2/20/46			2C13
73	Cockpit Enclosure Modification	L4	2/20/46			2C16
74	Rigging Procedure	J4	2/20/46			2C18
75	Carburetor Heat Control	J3 Airplanes with Carburetor Heat Control	2/20/46			2C20
76	Windshield Replacement	J3 Airplanes with Formed Eyebrow Fairing Tubes.	2/20/46			2C24
77	Seats, Safety Belts and Control Cables	E2, F2, J2, J3	2/18/46			2D4
78	Wing Drag Wire Inspection	E2, F2, H2, J2	2/18/46			2D6
79	Reinforcing of Rib Nose Structure	J4	2/18/46			2D9
80	Fuel Valve Control	J3 and J4 (Except Those with Auxiliary Fuel Tanks Installed.)	2/18/46			2D14
81	Motor Mount Failure	All Models Manufactured thru December 1945	2/20/46			2D17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
82	Safety Wire for Control System Turnbuckles	E2, J2, J3, J4	2/20/46			2D18
83	Tailskid Spring Attachment Reinforcement	E2, J2, J3	2/20/46			2D20
84	Winterization of J3C-65	J3	5/9/46			2E1
85	Reworking of Bottom Cowl for Replacing Airscoop EQ5259 and EQ5370	J3	4/25/46			2E4
86	J3 Lift Struts and Lift Strut Clevis Bolts	J3	10/16/46			2E5
88	Relocation of J3 Scott Brake Cylinders	J3	10/11/46			2E10
89	Replacement of Kem Gasoline Filter Gasket	J3	7/11/46			2E15
91	Inspection of Fuel Strainer Installation	J3	8/6/46			2E17
95	Defective Glass Fuel Strainer Bowls	J3	9/11/46			2E23
99	Header Tank Installation on PA-11 Airplanes	PA-11	7/29/47			2F6
103	Shock Strut Stop Discs	J3, PA-11	10/20/47			2F20
104	Fuel Line Fitting	PA-11	1/30/48			2F21
108	Model PA-11 Front and Rear Seats	PA-11	10/20/48			2G6
110	Windshield Attachment	PA-15	11/29/48			2G11
111	Torque Tube Connector Tube Assembly	J3, PA-11	3/14/49			2G12
112B	Service Inspection Notes	J3, J4, PA-11 PA-15, PA-16, PA-17	11/19/59			2G13
113	Weight and Balance Form	PA-11	5/3/49			2G16
116	Battery Box Lid	PA-20, 22	3/9/51			2G17
117B	Chafing of Master Switches	PA-20, 22	4/14/52			2G19
118	Battery Box Lid Modification	PA-16-,20,22	9/21/51			2G20
119	Freezing of Nose Wheels	PA-22	11/7/51			2G21
120	Replacing of Front and Rear Lift Strut Forks and Barrels	J3, PA-11	3/28/52			2G24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
121	Oil Radiator Lines	PA-18, PA-18A, PA-20, PA-22-135 Models	8/25/52			2H3
122	Fuel Grade Specification Lycoming O-290-D2	PA-18, PA-18A, PA-18S PA-20, PA-22	11/21/52			2H4
123	Front Spar Interference	PA-20, 22	5/7/54			2H5
124	PA-22 Landing Gear	All PA-22's	8/30/54		55-07-02	2H6
135	Fuel Selector Valve Pointer	PA-20, 22	3/29/55			2I1
143	Magneto Ground Wire Terminal Attachment Fitting	J-Series, E-Series, PA-11, PA-15, PA-16, PA-17, PA-18, PA-19, PA-20, PA-22	10/7/55			2I12
148A	Fuel Tank Caps	PA-18, 18A 22, 23, L21 B	5/29/57			2I17
153A	Brake Master Cylinder Diaphragm	PA-22	11/21/60	750-384		3240 2J1
157D	Lift Strut Fork Inspection And/Or Replacement	J-2/J-3/NE-1/ L4/J4/PA-11/ PA-15/PA-16/PA-17/ PA-18/L-21A/L-21B/ L-18/PA-19/PA-20/ PA-22	4/22/86	**		5701 2J5
158	All PA-20 Name Plates	PA-20	9/20/57			2J8
161A	Fire Hazard	PA-16, 20, 22	9/23/59	**	57-22-01	2600 2J12
163A	Fusing of Cigar Lighter Circuit	PA-20, 22	7/7/58		58-16-01	3310 2J16
165	Aileron Hinge Reinforcing Bracket	J3, L4, L18B, PA-11, PA-15, PA-16, PA-17	5/22/58	**	58-12-02	5750 2J22
166	Chafing of Master Switch Wires	PA-22	8/5/58			2J24
174B	Fabric, Fuselage, Inspection and Maintenance of In Area of Windshield Top Attachment Channel	J4, PA-15/16/17 PA-20 PA-22	11/30/61			5300 2K15
181	Cables, Control. 1/8" - 7 x 19 Flexible Stainless Steel, Replacement of	PA-18/18A/18S PA-18AS-150 PA-22/22S PA-22S-150 PA-22	11/5/59	**	61-16-05	2700 2L4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
182	Foreign Registered Airplanes- Inspection of Control Cables And Replacement of 1/8" - 7 x 19 Flexible Stainless Steel Control Cables	J3/ PA-11/11S/15/16/ 16S/17/18/20/20S/ 20-115/20-135/22/ 22S-135/22-150/ 22S-160, L-4/L-18B/L-18C/ L-21A/L-21B/ L-21B Modified	11/5/59			2700 2L10
183	Tie Rods - Tail Brace Streamline	PA-20, PA-22, PA-22-135/150/160	11/9/59		60-01-07	5340 2L12
184	Safety Belt Attachment	PA-22-150/160	12/9/59	754-273	60-05-03	5340 2L13
198	Clevises, Tail Brace, Replacement of	PA-22-108	1/6/61	754-381		5510 3A13
203	Modification of Cabin Heat Box Plate	PA-22-108	4/21/61	**		2140 3B1
207A	Rudder Pedal Assembly, Inspection of Weld (P/N 40892-04 And 05)	PA-18, PA-18A	5/10/62		62-02-05	2720 3B7
218	Vacuum Pump Spined Coupling, Replacement	PA-18 PA-22-108	11/11/63	**		3710 3C9
250A	Installation of Right Fuel Tank Quantity Gauge Placard	PA-22	1/29/70	15306-00	67-24-02	2840 3F8
264	Aircraft Flight Manual Supplement, Revision To (Para 15.0)	PA-22S-135	12/22/67			3G10
305	Inspection of Carburetor Drain Plugs	PA-18-150	11/25/69			7310 3K12
324	Vacuum Pump Adapter Drive Assembly	PA-18-150	9/24/70			3710 4A9
351	Fuel Line Replacement	PA-20	5/3/72	**	72-21-03	2820 4D9
354B	Fuel Selector Valve Lubrication	PA-18/PA-20 PA-22	5/19/82	**	60-10-08	2820 4D15
445	Fuel Cap Inspection	PA-18	1/24/75	454-039		2810 5A20
485	Rerouting of Rudder Control Cables	PA-18-150	1/27/76	**		2720 5F2
522	Fuel Tank Cap Modification, Wing	PA-11, PA-16, PA-18/18-150 PA-20, PA-22	9/28/76		78-10-03	2810 5J4
528D	Wing Lift Strut Assembly Inspection/Replacement	J-2/J-3/NE-1/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-20/PA-22	10/19/90	**	99-26-19 2015-08-14	5701 5J21
573	Fuel Tank Cap Modification, Wing	PA-11, PA-16, PA-18/18-150, PA-20, PA-22	2/8/78		78-10-03	2810 6E14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-18-150	2/25/80			3450 6L14
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0 7H4
706B	Tail Brace Wire Support Installation	PA-18-150	10/9/91	**	81-06-08	5510 7L7
759	Exhaust Muffler Inspection and Modification, Piper Part Number 12433-00, 12433-14, 12232-00	PA-18	6/22/83	452-093		7820 8H12
771A	Parking Brake Application	PA-20, PA-22	9/6/2011	81090-002		1130
819	Fuselage Door Frame Tube Corrosion: Repair and Protection	J-4/PA-15/ PA-16/PA-17/PA-20/ PA-22	2/28/86	**		5300 9G13
836A	Aluminum Wire Inspection	E-2/J-2/J-3/NE-1/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22	8/26/86	**		2400 9J4
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800 10A7
868	Forward Fuel Header Tank Installation	PA-11, PA-18	8/19/87	60763-02		2810 10C3
910A	Wing Lift Strut Assembly Inspection	PA-18/18A/L-18/ PA-19/L-21A/L-21B	10/10/89	**	99-26-19 2015-08-14	5701 10L3
924	Shimmy Dampener Replacement	PA-22	9/13/89	21701-06		3250 10aB17
935	Relocation of Aircraft Serial Number Data Plate	PA-18-150	3/13/90	765-400		1125 10aE5
966	Tail Surfaces Replacement	PA-18-150	1/21/94	**		5500 10aK3
979	Installation of Fuel Cap Cover	PA-18-150	1/12/95	**		5500 10bB6
1020	Inspection of the Artex 110-4 ELT and ELT Attachment Bracket	PA-18-150	7/10/98	**		2563 10b111
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-18 PA-18-150 PA-22	11/5/98	753-910		3711 10bJ20
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-18/18A/18S PA-18-150 PA-20/20S PA-22/22S	9/25/2000	**		3714 10cB1
1044	Lift Strut Attachment Fitting Inspection Access Provision and Wing Component Corrosion Inspections.	E-2/F-2/TG-8 J-2/J-3/J-4/ PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22	7/27/2000	481-096		5701 10cB19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1048	Stainless Steel Control Cables	PA-18-150	1/3/2001	N/A		2702 10cC9
1172A	Lift Strut Attachment Bolt Inspection	PA-16/-16S PA-18/-18A/-18S PA-18 "105"/-18S "105" PA-18 "125"/-18S "125" PA-18 "135"/-18S "135" PA-18AS "135" PA-18 "150"/-18A "150" PA-18S "150"/-18AS "150" PA-18A (Restricted) PA-18A "135" (Restricted) PA-18A "150"(Restricted) PA-19/-19S/-20/-20S PA-20/-20S "115" PA-20 "135"/-20S "135"/ PA-22/-22-135/-22S-135 PA-22-150/160/-22S-150/160 PA-22-108 Colt	12/11/2006	NAS464-P6-11 402-830		5700 10eA5
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-22 PA-22-108 PA-22-135 PA-22-150/160	4/12/2019	N/A		7414
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1379B	Rudder Inspection	J3C-65/L-4/NE-1/NE-2 J4 PA-11/L-18B PA-15/-17 PA-16 PA-18/-19/L-18C/L-21A/L-21B PA-20 PA-22	5/14/2024	N/A		5540

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
125	Fuel System Model PA-23	PA-23	9/29/54			2H7
126	PA-23 Power Plant	PA-23	10/18/54			2H9
127	PA-23 Airplane Flight Manual	PA-23	10/15/54			2H11
128	PA-23 Landing Gears	PA-23	10/28/54			2H12
129	Carburetor Air Box	PA-23	12/28/54			2H13
130	Heater Fuel Line	PA-23	12/31/54			2H14
131	Addition of Rudder Extrusion Chafe Strip to Wing Root Fairing	PA-23	1/3/55			2H15
132	Fuel Valve Actuator Handle Locks	PA-23	1/5/55			2H17
133	Landing Gear Down Lock Latches	PA-23	1/18/55			2H19
134	Main Landing Gear Attachment Point	PA-23	3/31/55			2H22
136	Hydraulic System - Thermal Relief Valve	PA-23	4/26/55			2I3
138	Hydraulic Actuating Cylinders	PA-23	5/9/55			2I6
139	Flexible Fuel Valve Controls - right and left	PA-23	5/26/55			2I7
140	Landing Gear CO2 Extension System	PA-23	6/8/55			2I8
142	Wing Front Spar Attachment Fitting	PA-23	10/4/55			2I11
143	Magneto Ground Wire Terminal Attachment Fitting	PA-23	10/7/55			2I12
144	Hot Air Ducts	PA-23	4/11/56			2I13
145	New Anti-Retracton Device	PA-23	12/31/56			2I14
146B	Elevator Butt Rib And Torque Tube Attachment Casting Cracks	PA-23	10/25/62		63-12-02	5520 2I15
149	Reinforcement of Aileron Balance Weights	PA-23	12/10/56			2I19
150	Front Stabilizer Fittings - right and left	PA-23	12/21/56			2I21
151	Elevator Push Pull Tube Rollers	PA-23	2/11/57			2I22
152A	Oil Pressure Line	PA-23	8/29/58	17766-07	57-10-02	7930 2I24
155B	Empennage Casting Cracks	PA-23	10/28/63			5500 2J2
156	Thread Exposure on the Heim Rod End Bearing	PA-23	7/2/57			2J4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
159	Rudder Trim Tab Control Rod Attachment	PA-23	10/1/57			2J9
160	Stabilizer Attachment Fitting	PA-23	10/7/57	17093-00		5510 2J11
162	Rudder Trim Tab Adjustment Screw, Part No. 18453-00	PA-23	2/17/58	18453-02	58-04-03	2720 2J15
169	Placard, Operating Limitations	PA-23	2/4/59	754-224	59-08-03	1100 2K3
175	Circuit Protector, Starter Solenoid	PA-23	6/9/59	754-220	60-03-07	2400 2K17
176	Bellcrank Attachment, Elevator Control Tube	PA-23 PA-23-160	7/3/59	**		2730 2K18
185A	Ribs, Wing Stations 95 And 110 Located Below the Main Wing Fuel Cell	PA-23 PA-23-160	9/3/63	**		5710 2L14
186	Fuel Lines And Fuel Line Fittings, Replacement of	PA-23-250	4/12/60	492-222 492-223		2810 2L16
188	Baggage Compartment Doors, Positive Locking of	PA-23-250	5/12/60			5230 2L19
189	Stabilator Tab Horn Modification	PA-23-250	6/22/60	754-329		2740 2L21
194	Instrument Panel Face Plate, Replacement of	PA-23-160	8/23/60			2500 3A7
195A	Baffles, Right Engine, Modification of	PA-23-250	9/13/60	754-335		7230 3A8
196	Rudder Tab Horn Bolt Installation	PA-23-250	9/9/60	754-344		2720 3A10
199A	Stabilator Tab Horn Assembly, Inspection of	PA-23-250	4/3/61	754-393		2740 3A15
200	Oil Radiator Lines, Replacement of	PA-23-250	4/18/61	754-387		7920 3A19
213	Rudder Trim Tab Horn, Inspection of	PA-23/23-160	3/5/63			2720 3B23
214	Carburetor Airbox Throat Vanes, Removal of	PA-23-235/23-250	4/19/63			7160 3C1
218	Vacuum Pump Spined Coupling, Replacement of	PA-23-235/23-250	11/11/63	**		3710 3C9
219A	Heater, 940DB, Modification And Rewiring of	PA-23-250	9/23/64	**		2140 3C12
225	Vacuum Pump Mounting Gasket, Replacement of	PA-23-235/23-250/ E23-250	11/9/65	751-886		3710 3D12
226	Vacuum Pump Drive Couplings, Replacement of	PA-23-235/23-250/ E23-250	12/20/65	**		3710 3D13
230A	Alternate Air System Modification, Engine Induction	PA-23-250/ E23-250	5/6/66	757-021	66-18-03	7160 3D21
242	Fuel System, Modification of	PA-23-250/ E23-250	1/9/67	757-106		2800 3E17
243	Starter Vibrator, Replacement of	PA-23-250 E23-250	1/6/67	757-103		8010 3E18
269	Manifold Pressure Gauge Line Filter	PA-23-250	2/23/68	760-167		7710 3G19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
273	Tailpipe, Turbocharger, Clearance To Firewall, Inspection of	PA-23-250 PA-E23-250	5/8/68	**		8120 3H1
280	Artificial Horizon, R.C. Allen 3", Case Leakage of	PA-23-250	7/10/68			3420 3H20
290	Fuel Flow Gauge Assemblies, Replacement of	PA-23-250 "D"	5/23/69	760-293		7330 3J3
296	Fuselage Aft Section Assembly, Inspection of	PA-23-250 "D"	5/26/69	760-324		5310 3J16
300	Hydraulic Pump Hose Assembly Inspection	PA-23-250	6/3/69	17766-05		2910 3K3
303	Autocontrol III And Altimatic III Series Roll Servo Modification and Roll Bridle Cable Replacement	PA-23-250 PA-E23-250	11/10/69	760-364		2210 3K8
306	Alternator System Modification	PA-23-250 "D"	1/9/70	760-346	70-22-05	2430 3K14
319	Exhaust System Inspection And Modification	PA-23-250	4/19/71	33178-02 33178-03	72-14-05	7810 3L17
320A	Autopilot Servo And Bridle Cable Installations, III Series, Inspection of	PA-23-250	7/6/72			2210 3L23
324	Vacuum Pump Adapter Drive Assembly	PA-23-250	9/29/70			3710 4A9
331	Electric Trim Switch Inspection And Modifications	PA-23-250	2/5/71	760-505	71-12-05	2730 4B3
334	Alternate Air Hose Replacement	PA-23-250	3/17/71	48076-02	71-21-06	7160 4B14
335A	Engine Controls Support Bracket Assembly Inspection	PA-23 PA-23-160 PA-23-250	11/17/71	16975-00	71-12-01	7610 4B16
340	Fuel Cell Vent/Drain Lines	PA-23 PA-23-160/-235 PA-23-250	5/24/71		88-21-07	2810 4C2
345	Bungee Installation, Stabilator	PA-23-250	10/7/71	760-565	72-21-07	2740 4C21
349	Master Switch Modification, Electrical System	PA-23-250	4/26/72	760-602 760-606		2450 4D5
353	Fuel Filter Assembly Outlet Port, Inspection of	PA-23-250	6/1/72	**		7310 4D13
375	Firewall Sealing, Lower	PA-23-250	6/20/73	757-758		5310 4F15
380	Pitch Servo Bridle Cable Installation, Revised	PA-23-250	7/9/73			2210 4F23
385	Wing Leading Edge Modification	PA-23-250	5/4/73	**		5720 4G10
389	Bridle Cables and Bridle Cable Clamp Installation	PA-23-250	8/13/73			2210 4G17
401A	Heater Fuel Valve, Inspection of	PA-23 PA-23-160/-235 PA-23-250	5/16/2000	19460-00	74-22-05	2148 4H24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
404	Flux Sensor Caution Placard Installation	PA-23-250	11/12/73	33564-00		3420
408B	Flap Outboard Hinges, Replacement	PA-23-250	5/14/75	**	74-10-01	5750
441	Manifold Pressure Hose Clamping of	PA-23-250	1/2/75	760-602 760-606		7710
451	Throttle Control Shaft, Inspection of	PA-23-250	2/26/75			7610
452	Instrument Glare Shield Panel Replacement	PA-23-250	3/3/75	760-932	75-11-05	2510
455	Fuel Selector Valve Inspection	PA-23-250	4/30/75	492-222 492-223		2820
461	Encoding Altimeter Harness Rewiring	PA-23-250	4/17/75	760-971		3410
486	Wing Tip Navigation Light Wire Insulation	PA-23-250 "F"	10/11/76	761-099	77-01-05	3340
493	Magnetic Compass Deviation	PA-23-250	3/25/76	761-044	76-11-07	3440
498	Fuel Cell Vent Line Assemblies, Inboard, Inspection of	PA-23-250 "F"	4/5/76			2810
507	Fuel System Control Cables At Swivel Fittings, Inspection of	PA-23 PA-23-160/-235 PA-23-250	11/10/76	**	80-18-10	7320
511A	Oxygen System Outlet Refinement	PA-23-250	8/24/76	**		3510
514	Stabilator Tab Modification	PA-23-250 "F"	9/20/76	761-083		2740
515	Control Cable Ball Joint Retainer Installation	PA-23-250	1/17/77	**		7610
523	Cigar Lighter Element, 24 Volt, Replacement	PA-23-250 "F"	10/8/76	55674-02		3310
527	Electric Trim Switch Modification	PA-23-250	11/5/76	756-047	77-09-10	2740
530	Fuel Crossfeed Operation	PA-23-250 PA-E23-250	12/10/76	**	77-23-09	2820
540	Stabilator Tip Tube And Weight Assembly Inspection And Reinforcement	PA-23-250 "F"	1/4/1977	**	2021-25-11	2740
540B	Stabilator Tip Tube And Weight Assembly Inspection And Reinforcement	PA-23-250 "F"	2/9/21	**	2021-25-11	5510
546	Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection of	PA-23-250	5/18/77	**	75-05-04	3340
547	Stabilator Tip Rib, Inspection of	PA-23-250 "F"	3/1/77	**	2021-25-11	2740
550	Engine Control Cable Inspection	PA-23-250 "F"	3/29/77	**		7230
558	Altimatec V and V F/D Series; M-4D F/D Series: And Sperry SPZ-200 F/D	PA-23-250	6/10/77			2210

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
559	Rudder Tail Light Inspection	PA-23-250	8/31/77	472-956		3340 6C3
564	Inspection of Emergency Gear Extension Control	PA-23-250 PA-E-23-250	4/25/77			3200 6C16
566	Horizontal Situation Indicator, EDO Aire Mitchell NSD-360, Modification To	PA-23-250	10/11/77	**		3420 6D9
569	Stabilator Tab Horn Replacement	PA-23-250	8/24/77	761-143	2021-25-11	5510 6E2
590	Inspection of Stabilator Tab Horn/ Stabilator Trim Control Rod Attachment	PA-23-250	1/20/78			2740 6G11
604A	Forward Baggage Door Locking System Modification	PA-23-250	6/8/79	**		5230 6I4
606	Stabilator Assembly Lower Surface Rivet And Rib Attachment Inspection	PA-23-250	7/12/79	**	79-26-01	2730 6I10
629	Landing Gear Hose Assembly Inspection And Replacement	PA-23-250	11/15/78	17766-27		3230 6L10
630A	Collins VIR-350 and VIR-351 Navigation Receiver Modification	PA-23-250	2/25/80			3450 6L14
635	Landing Gear Selector Lever Inspection And Replacement	PA-23 PA-23-235 PA-23-250	1/3/79	761-213	79-11-06	3200 7A23
662	Exhaust System Inspection And Modification	PA-23-250	11/1/79	763-975		7810 7E15
663	Fuel Line/Electrical Harness Inspection	PA-23-250	9/24/79	**		2810 7E17
671	Flap Control System Inspection and Reinforcement	PA-23 PA-23-160/-235 PA-23-250	10/20/80	**	81-04-05	2750 7F14
672A	Step Attachment Area Inspection/ Reinforcement	PA-23 PA-23-160/-235 PA-23-250	4/16/81		80-26-04	5340 7F23
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0 7H4
683	Propeller Feathering, Minimum Engine RPM	PA-23 PA-23-160/-235 PA-23-250	5/16/80	Placard **		6120 7H18
721	Heater Fuel Regulator Valve Shroud/ Drain Modification	PA-23-250	4/5/82	764-141		2820 8B12
771A	Parking Brake Application	PA-23 PA-23-160/-235 PA-23-250	9/6/2011	81090-002	85-02-05	1130

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
797B	Fuel Port Restrictor Installation	PA-23-250 "F"	9/1/87	566-500		2812 9B14
798	"TURBO" Marking Removal	PA-23-250	12/11/84	N/A		1110 9B19
805A	TRW Hartzell Propeller Products Service Bulletin No. 142B (O-ring Deterioration)	PA-23-250	3/14/86	N/A		6110 9D15
822	Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-23 PA-23-160/-235 PA-23-250	4/2/86	17766-02	96-21-04	2912 9H3
827A	Part I - Fuel System Draining Procedure - Water Contamination	PA-23 PA-23-160	11/4/88	N/A	90-23-18	2824 9H20
827A	Part II - Apache Dual-Fuel Drain Installation	PA-23 PA-23-160	11/4/88	765-363	92-13-04	2824 9H22
836A	Aluminum Wire Inspection/Replacement	PA-23 PA-23-160/-235 PA-23-250	8/26/86	**		2400 9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800 10A7
884	Lock Wiring of V-Band Couplings	PA-23-250	4/8/88	**		7800 10G20 2100
932A	Improved Fuel System Drainage and Inspection	PA-23 PA-23-160/-235 PA-23-250	8/30/90	**	90-23-18	2815 10aD16 2824
980	Shoulder Harness Installation	PA-23 PA-23-235 PA-23-250	1/18/95	**		5500 10bB10
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-23-250	1/29/96	**		2437 10bD16
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-23-235 PA-23-250	9/22/98	460-632	99-05-09	7167 10bI20
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-23-250	11/5/98	766-656		5741 10bJ20
1035A	Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Service Bulletin No. 101SB020, Rev. 3"	PA-23-250 PA-E23-250	3/22/2007	**	2003-14-03	7311 10bL16
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-23 Series PA-23-250 Series	9/25/2000	**		3714 10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1051B	Flap Torque Tube Replacement	PA-23 PA-23-160/-235 PA-23-250 PA-E23-250	11/5/2002	104622-002	81-04-05R1	2755
1079	Untested Fuel Pump	PA-23-250 Series	7/20/2001	62220-005		2825
1147	Turbocharger Clamp, Incorrect Substitution	PA-23-250	5/14/2004	555-511		7200
1160A	Stabilator Torque Tube Assembly Inspection	PA-23-235 PA-23-250 PA-E23-250	11/28/2022	16067-000 652-579		5519
1194B	Nose Baggage Door Components, Periodic Replacement of	PA-23-250 PA-E23-250	4/12/2012	**	2009-13-06	5230
1266	Fuel Warning Placard and POH Inspection	PA-23-250 "B" PA-23-250 "C" PA-23-250 "D" PA-23-250 "E" PA-E23-250	12/16/2014	**	2015-24-05	1130
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-23-150/160	4/12/2019	N/A		7414
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-23-250 PA-E23-250	10/30/2015	N/A		7310
1295	Nose Baggage Door Lock Inspection	PA-23-250 PA-E23-250	3/24/2017	88409-002	2009-13-06	5230
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1299A	Periodic Replacement of Main Landing Gear Drag Link Bolt	PA-23-150 PA-23-160 PA-23-235 PA-23-250	12/18/2019	402-356 402-427 691-367		3210

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB16

SERVICE BULLETIN INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
164	ADF Indicator Excess Wire, Battery Cable Insulation, Muffler Replacement, Nose Gear Door Retraction Rod, Control Wheel Replacement and Reinforcement Nose Wheel Steering Arm Mounting Bracket	PA-24	5/16/58			2J17
167	Oil Cooler Line Clearance	PA-24	1/6/59	451-855	59-07-05	7920 2K1
168	Nose Gear Retraction Assist Cord	PA-24	1/16/59	754-205	58-25-05	3230 2K2
171	Weight And Balance	PA-24 PA-24-250	3/18/59			800 2K4
172	Control Wheel Sprocket Mounting Hole, Inspection of	PA-24/PA-24-250 (w/Autocontrol)	4/27/59	**	59-12-09	2700 2K5
173	Aileron Balance Weight Attachment, Bulkhead	PA-24 PA-24-250	6/23/59	754-233	59-13-02	2710 2K13
177	Fuel Cell Filling Instructions	PA-24/PA-24-250	8/5/59	21994-00		2810 2K20
178	Control Tube Guide Blocks Safety Wiring of	PA-24 PA-24-250	9/24/59			2700 2K22
179	Door Window, Refitting of	PA-24/PA-24-250	11/6/59			5630 2K24
180	Fuel Cell Vent Tubes, Modification of	PA-24 PA-24-250	11/6/59		59-26-02	2810 2L2
187	Safety Switches. PA-24 and 24-250 Landing Gear-Service Letter 314A, Dated June 8, 1954	PA-24	4/15/60	754-221		3230 2L18
190A	Insulation-Cabin Heat Induction System	PA-24	3/14/60	754-308		2140 2L23
191	Hinge Bracket, Aileron—Part No. 20211-00	PA-24 PA-24-250	6/16/60	20211-00		5150 3A1
192	Throttle Limit Switch Bracket	PA-24	6/17/60	754-334		7610 3A3
193	Fuel Cell Vent Tube, Modification of	PA-24	6/17/60		60-24-03	2810 3A5
197	Master Cylinder, Brake, Replacement of	PA-24	12/2/60	455-929		3240 3A12
201	Vacuum Pumps, Dry, Replacement of	PA-24	4/13/61	481-681		3710 3A21
202	Exhaust System, Comanche. Inspection of	PA-24	5/22/61	754-396	61-20-02	7810 3A22
205	Circuit Protector Wiring, Inspection of	PA-24	8/15/61			2400 3B3
208	Gascolator Bowl Drain Valve	PA-24	12/19/61			7310 3B9
210	Muffler Shrouds, Replacement of	PA-24/24-250	10/3/62	754-484	62-26-05	7810 3B12
211	Main Fuel Cell Cavity Modification	PA-24-250	11/2/62	754-492		2810 3B17
212	Engine-Driven Fuel Pump, Installation of Vent Lines (PA-24-250 W/Fuel Injection)	PA-24-250	12/5/62	756-700		2820 3B20
216	Fuel Cell Drain Modification	PA-24/24-250	8/5/63	756-756	68-13-03	2810 3C4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
218	Vacuum Pump Spined Coupling, Replacement of	PA-24/24-250 PA-30	11/11/63	753-865		3710 3C9
219A	Heater, 940DB, Modification And Rewiring	PA-30	9/23/64	756-815		2140 3C12
220	Alternate Air Doors, Replacement of	PA-30	3/3/64	756-794	64-09-05	7160 3C14
222A	Airspeed Limits, Restriction To, Removal of (Replacement of Stabilator Torque Tube)	PA-30	8/10/64	756-827	64-28-03	3410 3C17
224	Pitch Servo—Modification of— Mitchell Bulletin No. A55	PA-24-250 PA-24-260 PA-24-400 PA-30	4/7/65	756-923	65-11-04	2210 3D3
228	Fuel Purge Valve Hose Assembly, Replacement of	PA-24-400	1/7/66	756-994	66-30-07	2810 3D15
229A	Airspeed Limits, Restriction, Removal of	PA-30	6/17/66	**	66-28-06	3410 3D16
231A	Fuel Tank Caps	PA-24/24-250	10/10/66	25983-00	68-13-03	2810 3D23
232	Brake Disc Assembly, Inspection of	PA-30	6/8/66	757-039		3240 3D24
235	Airspeed Limit, Never-To-Exceed Standardization of	PA-30	9/16/66	**	66-28-06	3410 3E6
236	Oxygen Cylinder	PA-30	12/29/66	757-094	67-19-05	3510 3E8
238	Fuel Purge Valve Hose Replacement	PA-24-400	12/7/66	757-099		3420 3E10
246	Oxygen Cylinder Rear Retaining Strap Modification of	PA-30	3/21/67	758-109	67-19-05	3510 3E22
263	Flight Manual Revision	PA-30	1/15/68	760-168		General 3G9
280	Artificial Horizon, R.C. Allen 3", Case Leakage of	PA-24-260 PA-30	7/10/68			3420 3H20
299	Flight Manual Revision	PA-30 "C"	5/29/69	**		General 3K2
301A	Airplane Flight Manual And New Placards	PA-30	11/25/69	760-354 760-355	69-24-04	1100 3K5
306	Alternator System Modification	PA-30 "C"	1/9/70	760-347	70-22-05	2430 3K14
310	Modifications, Twin Comanche (Airspeed Marking, Stall Warning Horn Installation)	PA-30	5/6/70	760-408 760-373		3410 3K24 2700
314A	Selector Valve, Fuel Modification	PA-30/39	9/28/70	760-444		2820 3L8
315	Limit VNE Airspeed	PA-30	7/8/70	**		1100 3L10
320A	Autopilot Servo and Bridle Cable Installation, III Series, Inspection of	PA-24-260 PA-30/39	7/6/72			2210 3L23
324	Vacuum Pump Adapter Drive Assembly	PA-24 PA-30/39	9/29/70			3710 4A9
331	Electric Trim Switch Inspection and Modification	PA-24-260 PA-30/39	2/5/71	760-505	71-12-05	2730 4B3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
336	Seat Frame Tube Replacement, Vertically Adjustable	PA-24-260 PA- 30/39	3/11/71			2510 4B18
343	Hartzell Service Bulletin No. 96, Amended 8/18/71 And Supplement No. 1 Amended 8/18/71	PA-30	9/9/71	**		6110 4C13
349	Switch Modification, Master, Electrical System	PA-30/39	4/26/72	**		2450 4D5
354B	Fuel Selector Valve Lubrication	PA-24-180/24-250	5/19/82	**	60-10-08	2820 4D15
362	VNE Speed Limit	PA-24-250/24-260	8/14/72	**		3410 4E19
362A	Rudder Balance Weight Installation (Does not cancel Service Bulletin No 362)	PA-24-180/24-250/ 24-260	10/6/72	760-705		2720 4E22
381	Manual Revision, Pilot's Operating/Airplane Flight	PA-39	8/29/73	**		General 4G1
394	Rudder Pedal, Warning, Improper Use of	PA-24-180/24-250/ 24-260/24-400 PA-30/39	9/28/73	757-436		2720 4H7
411A	Stabilator Torque Tube Bearing Block Attachment Fitting Rivet Replacement	PA-24-180/24-250/ 24-260/24-400 PA-30/39	4/10/74	760-835	94-13-10	2740 4J9
464A	Stabilator Torque Tube Bearing Block Attachment Fitting Rivets, Inspection of	All PA-24 Series PA-30/39	3/22/76	760-835	75-27-08	5530 5C16
496	Stabilator Balance Weight Tube Replacement	PA-24-250/260	6/4/76	28035-00	76-19-07	2740 5G13
511A	Oxygen System Outlet Refinement	PA-24-260/ PA-24-400 PA-30/39	9/24/76	761-032 752-583		3510 5I3
515	Control Cable Ball Joint Retainer Installation	PA-24-250 PA-24-260/400 PA-30/39	1/17/77	55447-02		7610 5I10
527	Electric Trim Switch Modification	PA-24-260 PA-30/39	11/15/76	756-047	77-09-10	2740 5J18
597	Fuel Selector Valve Replacement	PA-30/39	4/19/78	492-137	78-12-07	2840 6H10
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 7H4 15.0
751	Spar Cap Chafing Inspection	PA-24-400 PA-24-180/250/260 PA-30/39	5/24/83	**	83-19-03	5740 8G13
771A	Parking Brake Application	PA-24 PA-24-250/260 PA-24-400 PA-30/39	9/6/2011	81090-002	85-02-05	1130
798	"TURBO" Marking Removal	PA-24 Series PA-30/39	12/11/84	N/A		1110 9B19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-24-260 PA-30/-39	3/14/86	N/A		6110
836A	Aluminum Wire Inspection/Replacement	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	8/26/86	**		2400
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800
861	Heated Alternate Air Induction System Installation	PA-24-260	5/4/87	760-516	91-21-09	7314
884	Lock Wiring of V-Band Couplings	PA-24-260 PA-30/-39	4/8/88	**		7800 2100
980	Should Harness Installation	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	1/18/95	**		5500
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-24 PA-24-250/-260	9/22/98	460-632	99-05-09	7167
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	11/5/98	753-910		3711
1035A	Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3"	PA-24-260 PA-24-400	3/22/2007	**	2003-14-03	7311
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	9/25/2000	**		3714
1160A	Stabilator Torque Tube Assembly Inspection	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	11/28/2022	652-580 652-581 652-582 652-583		5519
1189	Stabilator Horn Assembly Inspection	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	4/29/2010	**	2012-17-06	5510
1266	Fuel Warning Placard and POH Inspection	PA-24-250/260/400 PA-30/39	12/16/2014	**	2015-24-05	1130
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-24	4/12/2019	N/A		7414
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-24-250/-260 PA-30/39	10/30/2015	N/A		7310

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB21

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
209	Propeller Bolts, Replacement of	PA-28-150/160	4/17/62	754-462V	62-19-03	6110	3B11
223	Sender Unit, Stewart-Warner Fuel Quantity Gauge, Modification of	PA-28-140/150/160/180/235	2/12/65	756-906V	65-06-06	2840	3D1
234	Spinner Modification	PA-28-150/160/180	8/2/66	757-046V 757-047V	66-20-05	6110	3E4
237	Rudder Trim Installation Modification	PA-28-140/150/160/180/235	11/1/66	757-085V		2720	3E9
240	Inspection of Aileron Balance Weight, Assembly, Rudder Horn Assembly And Stabilator Balance Weight Assembly For Corrosion	PA-28-140/150/160/180/235	12/13/66		67-12-06	2710	3E12
245	Family Seats Center Safety Attachment, Inspection of	PA-28-140	3/8/67			5340	3E20
248	Torque Links, Main Landing Gear	PA-28-140/150/160/180/235	5/12/67	65691-00V 757-123V	70-18-05 67-20-04	3210	3F2
249A	Fuel System Improvement Kit	PA-28-235	3/1/68	757-139V	67-26-02	2800	3F6
251D	Fuel Tank Inspection	PA-28-140/150/160/180 PA-28-201T PA-28-235 PA-28R-180/200 PA-28R-201/201T PA-28RT-201T	2/24/2009	757-572V	67-26-03	2810	3F10
253	Fuel Line Modification, Tip Tank	PA-28-235	7/7/67	757-151V 757-152V	67-26-02	2810	3F14
261	Aft Spar Wing Attachment Bolts, Inspection of	PA-28-140/150/160/180/235	11/10/67	760-162V		5710	3G5
274	Retraction Fitting Replacement, Main Gear	PA-28R-180	6/3/68	760-208V	68-12-04	3230	3H5
279	Bridle Cable, Servo, Inspection	PA-28-140/150/160/180/235 PA-28R-180	6/24/68	**		3210 2210	3H16
281	Artificial Horizon, R.C. Allen 3", Case Leakage of	PA-28-140/180/235 PA-28R-180	7/10/68			3420	3H24
285	Fuel Selector Control Stop Assembly	PA-28-235	11/22/68	760-251V		2820	3I11
287	Tail pipe Replacement	PA-28-140/150/160/180	1/15/69	63666-02V		7810	3I15
288	Engine Breather Line Modification	PA-28R-180	1/16/69			7160	3I17
292	Landing Gear Modification, Cherokee Arrow	PA-28R-180	3/6/69	760-292V 67150-00V		7110 3230 3200 2910	3J6
293	Brace, Baggage Floor	PA-28-140"B"	3/5/69	760-314V		5230	3J10
295	Retaining Pin, Control Wheel	PA-28-180/235 PA-28R-180/200	4/30/69		69-15-01	2700	3J14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
297	Hose Replacement, Air Induction Inlet	PA-28R-180/200	5/22/69	700-328V	69-12-01	7160 3J18
298	Carburetor Heat Control Assembly (see also SB 312)	PA-28-140"B"/ 180"D"/235"C"	6/2/69	760-320V		7310 3J23
305	Drain Plugs, Carburetor, Inspection of	PA-28-140/150/ 160/180/235	11/25/69			7310 3K12
309	Spinner/Bulkhead Inspection And Replacement	PA-28R-180/200	5/8/70	760-410V	70-09-02	6110 3K20
311A	Selector Valve, Fuel Modification	PA-28-235	9/28/70	760-438V		2820 3L3
312	Carburetor Heat Cable Replacement	PA-28-140"B"	6/9/70	760-387V		7310 3L5
313	Terminals, Magneto Filter	PA-28-140/150/160/180/ 235	7/1/70	23969-02	71-14-06	7430 3L6
316	Flight Manual Weight And Balance Data Revision	PA-28R-180/200	10/20/70	**		800 3L12
317	Rib, Vertical Fin, Inspection	PA-28 PA-28R-180/200	11/18/70	760-451V		5530 3L14
322	Vacuum Pump Adapter Drive Assembly	PA-28-140/180/235 PA-28R-180/200	9/29/70	760-477V		3710 4A3
326	Selector Handle (2Tank) Fuel Valve, Inspection of The	PA-28-140/150/160/180 PA-28R-180/200	11/9/70			2820 4A14
327	Stabilator Balance Weight Tube Assembly Inspection	PA-28-140/150/160/180/ 235 PA-28R-180/200	12/9/70	**	70-26-04	2740 4A16
332	Switch, Electric Trim, Inspection And Modification	PA-28-180/235 PA-28R-180/200	4/16/71	760-517V	72-17-05	2730 4B7
337	Seat Frame Tube Replacement Vertically Adjustable	PA-28-140/180/235 PA-28R-180/200	3/11/71	**		2510 4B20
339	Owner's Handbook Revision	PA-28R-180/200	6/16/71	**		2720 4B24
342	Fuel System Instructions And Modification	PA-28-235	9/7/71	760-560V	77-12-01	2800 4C6
348	Air Conditioning System. Improvement	PA-28-140	1/25/72	760-581V		2150 4D4
350	Stabilator Hinge Attaching Bolts, Inspection of	PA-28-140/180/235, PA-28R-200	3/30/72	**		5550 4D7
355	Valve, Fuel Selector, Lubrication	PA-28-140/150/160/180	6/5/72	**		2820 4E1
356	Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement	PA-28-140/150/160/180/ 235 PA-28R-180/200	9/1/72	**		7160 4E7
357A	Terminal Replacement, Alternator Output Wire	PA-28-140/150/160/180/ 235 PA-28R-180/200	11/14/72	588-398V		2420 4E9
360	Hose System, Modification, Air Induction	PA-28-140/150/160/180/ 235 PA-28R-180/200	11/9/72	**		7160 4E14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
368	Antenna Protector, Transponder, Installation	PA-28-140/180/235 PA-28R-200	11/22/72	760-697V		3450 4F7
376	Fuel Selector Control System Modification	PA-28-235	4/19/73	**	77-12-01	2820 4F18
387	Alternator Installation Modification	PA-28-140/150/160/180/ 235 PA-28R-180/200	2/4/74	760-741V 760-742V		2430 4G15
393	Seat Belt, Rear, Attachment Modification	PA-28-140/180/235 PA-28R-200	12/18/73	760-794	74-09-04	5340 4H4
395	Rudder Pedal, Warning, Improper Use of	PA-28-140/150/160/180/ 235 PA-28R-180/200	11/9/73	757-436		2720 4H9
424	Wing Reinforcement Modification	PA-28-151	6/21/74	760-878V	74-14-04	5710 4K16
427	Air Conditioning System Modification	PA-28-140/180 PA-28R-200	8/9/74	760-822V		2150 4K23
434	Seaplane Propeller Modification	PA-28S-180	11/22/74	79528-00		6110
435	Aileron Centering—(I) Cable Inspection—(II) Modification	PA-28-151	11/4/74	**	74-24-12	2710 4L15
436	Placard Inspection, Operating Limitations	PA-28-180	12/10/74	76206-00V 76298-00V	74-26-07	1110 4L18
444	Fuel Valve Replacement	PA-28-235	1/15/75	760-895V		2820 5A19
448	Cable Operation Inspection, Throttle and Mixture Control	PA-28-140/151/180/235 PA-28R-180/200	2/19/75	**		7320 5B4
449A	Alternator (Chrysler) Modification And Wire End Terminal Replacement	PA-28-140/151/180/235 PA-28R-200	5/7/75	558-398V		2430 5B8
450	Quick Drain Valve Inspection Fuel Gascolator	PA-28-140/151/180 PA-28R-200	2/10/75		75-08-03	2820 5B12
454	Induction Air Shroud Modification	PA-28-151	3/10/75	760-922V		7160 5B19
474	Carburetor Air Box Modification	PA-28-151	6/27/75	760-985V	75-16-04	7160 5D21
475	Instrument Panel Dimmer Control Assembly Modification	PA-28-140 PA-28-151 PA-28-180 PA-28-235 PA-28R-200	7/10/75			3310 5E1
510B	Landing Gear, Nose, Trunnion Modification	PA-28R-200	8/31/76	761-074V	76-15-08	3220 5I1
519A	Fuel Selector Valve Inspection And Replacement	PA-28-235	9/2/76	492-259 492-262	76-18-04	2820 5I21
531	Engine Oil Hose Replacement	PA-28-140	1/10/77	63901-72V	76-25-06	7920 5L5
533	Fuel Gauge Calibration Inspection	PA-28-140/180/ 151/181/235 PA-28R-200	1/6/77	**	77-01-01	2840 5L8
536	Carburetor Air Filter Box, Inspection of	PA-28-151	1/13/77		77-01-03	7310 5L15
538	Engine Control Cable Inspection	PA-28-151	1/14/77	67639-06V		7610 5L20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
541	Throttle Attachment Inspection	PA-28-140/151/ 181/235 PA-28R-200	2/15/77	**		7610 6A5
543	Starter/Magneto Switch Inspection And Replacement	PA-28-151/181/ 235,PA-28R-200	2/9/77	757-597V		7410 6A9
548	Engine Control Rod End Bearing Inspection	PA-28-140/151/ 161/180/181/235 PA-28R-200/201 PA-28R-201T	3/7/77	**	77-23-03	7230 6A23
556	Electric Trim Switch Modification	PA-28-180/235 PA-28R-180/200	7/25/77			2730 6B20
561	Battery Power Lead Relocation	PA-28R-201/201T	4/6/77			2430 6C7
563	Landing Gear, Nose, Actuator Rod End Bearing Change	PA-28R-201/201T	5/13/77	452-357V		3230 6C14
565	Horizontal Situation Indicator Modification To Edo Aire Mitchell, Edo Aire Mitchell Service Bulletin No. MB-13	PA-28R-200/ 201/201T	6/2/77	**	77-12-01	3420 6C20
571A	Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection	PA-28-235	10/20/77	**	77-12-01	2810 6E5
576	TCM-TS10360 Series Engines, To Disseminate Information	PA-28R-201T	11/30/77			7200 6E23
577	Single Mask Oxygen System Turbo Arrow III	PA-28R-201T	5/1/78	763-808V		3500 6F1
578B	Nose Landing Gear Down Lock Replacement	PA-28R-201/ 201T	9/27/78	67150-04V		3230 6F3
580	Engine Cowling Air Scoop Drain Hole	PA-28-181/235	10/19/77		76-25-06	7100 6F13
582	Pitot and Static Sump Drain Inspection	PA-28-161/181	12/6/77	**		3410 6F15
611	Hose Assembly Inspection and Replacement	PA-28R-200 PA-28R-201T PA-44-180	11/14/78	**		2820 6J5
612	Fuel Gascolator Assembly Inspection	PA-28-161 PA-28R-201T PA-28R-201	10/25/78		79-02-05	7310 6J10
623	Diode Assembly Inspection	PA-28-140/151/ 161/180/181/235 PA-28R-200 PA-28R-201 PA-28R-201T	11/1/78			2450 6K16
625A	Fuel And Vapor Return Lines Support	PA-28R-201T PA-28RT-201T	8/15/80	63882-73V		2810 6K22
627	Fuel Line Inspection And Modification	PA-44-180	10/24/78	63976-34	79-02-02	2810 6L5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-28-161/181 PA-28-236 PA-28R-201 PA-28R-201T PA-44-180	2/25/80			3450	6L14
631B	Battery Protection and Correct Rear Seat Installation	PA-28-151/161	10/29/81	**	81-23-05	2430 2510	7A1
632	Wing Tip Strobe Light Modification	PA-44-180	12/7/78	481-193 761-237V		3340	7A8
634	Engine Primer Modification	PA-44-180	12/28/78	763-908V	79-12-11	7310	7A21
638	Inspection of Fuel Line Union Fitting	PA-28-161/181 PA-28-236 PA-28-201T PA-28R-201/201T PA-28RT-201/201T	4/23/79	**	79-13-03	2810	7B13
639	Throttle Cable Installation Modification	PA-44-180	1/10/79	**	79-05-11	7610	7B17
642	Air Filter Seal Inspection	PA-28-140	2/1/79			7160	7C2
646A	Fuel Tank Vent Modification And Vent Hose Replacement	PA-28-161/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-201/201T PA-28RT-201/201T	3/5/80	763-934V	79-22-02	2810	7C17
650	"P" Lead - Bendix Magneto	PA-28-236 PA-44-180	7/20/79	470-864V		7410	7D3
666	Carburetor Air Box Rivet Replacement	PA-44-180	10/31/79	420-859		7310	7F2
667	Part I - Carburetor Air Box Modification	PA-28-236	10/3/79	763-926V		7310	7F4
667	Part 11 - Engine Induction Air Scoop	PA-28-236	10/3/79	763-953V		7160	7F5
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 1 5.0	7H4
678	Nose Landing Gear Down Lock Bushing Replacement	PA-44-180	3/24/80	764-010V	80-12-03	3230	7H5
679	Throttle Linkage Modification	PA-28-181	3/24/80	764-009V	80-14-02	7610	7H6
681	Boom Microphone Isolation Relay	PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201/201T PA-44-180	4/24/80	456-703 180-500	80-14-03	2350	7H11
689A	Aileron Push Rod Functional Check	PA-44-180	10/24/80	**	80-21-11	2710	7J7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
691A	Muffler Assembly Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201	10/8/80	**	80-19-01	7820	7J11
694	Throttle Rod End Assembly	PA-28R-200 PA-28R-201 PA-28RT-201	9/9/80	MS-24665-132		7610	7J22
695	Nose Cone Spar Check / Reinforcement	PA-44-180	9/10/80	764-080V	81-10-01	5350	7K1
696	Master and Alternator	PA-44-180 PA-44-180T	3/16/81	99377-60V		2450	7K4
699	Rudder Torque Tube Attachment Fitting and Hardware Inspection	PA-28RT-201 PA-28RT-201T	4/1/81	**		2720	7K11
702	Aileron Reinforcement	PA-44-180	12/4/80	764-088V	81-10-04	5710	7K19
714	Oil Cooler Hose Installation Inspection	PA-44-180T	6/10/81	35801-09V		7920	8A12
717	Fuel Selector Line Inspection	PA-28-140/150/160/180 PA-28-151/161 PA-28-181 PA-28-236 PA-28R-180/200 PA-28R-201 PA-28RT-201	7/8/81			2820	8A22
719	Engine Mount Reinforcement	PA-44-180	10/15/81	**		7120	8B3
724A	Nose Landing Gear Inspection, Rigging, and Modification	PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	4/20/82	**	82-06-11	3220	8C1
725B	Aileron Balance Weight Attachment Inspection and Rework	PA-44-180 PA-44-180T	11/3/97	764-148V	81-16-10	2715	8C9
738	Nose Landing Gear Actuator Rod End Inspection / Replacement	PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	4/20/82	452-729V		3230	8D15
738	Addendum 1 - Nose Landing Gear Actuator Rod End Inspection / Replacement	PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	11/23/87	452-729		3230	8D15
749	Stabilator Assist Springs Inspection	PA-44-180 PA-44-180T	11/8/82	**		2370	8G8
753	Expanded Spin Recovery Procedures	PA-28-140	12/15/82	87369-44		2700	8G18
769	Landing Gear Back-Up Actuator Override Mechanism	PA-28R-180 PA-28R-200	10/19/83	**		2920	8I18
771A	Parking Brake Application	PA-44-180/180T	9/6/2011	81090-002	85-02-05	1130	
774	Baggage Door Latch Replacement	PA-28-150/160/180 PA-28R-180	2/22/84	**		5230	8J9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
775	Electrical Bus Modification	PA-44-180/180T	6/20/84	764-937V		2430	8J11
787C	Main Landing Gear Trunnion Housing Inspection	PA-44-180/180T	11/7/2000	2599-002	94-13-11	3211	8L8
789B	Aft Inboard Wing Access Panel & Aft Wing Spar Modification	PA-28-140 PA-28-150/160 PA-28-180 PA-28-235 PA-28R-180/200	12/3/2018	764-998V 765-106V N/A	SAIB CE-11-12	5711	
798	"TURBO" Marking Removal	PA-28-201T PA-28R-201T PA-28RT-201T	12/11/84	N/A		1110	9B19
801	King Auto Pilot Servo Bridle Clamp Installation	PA-28-161/181 PA-28-236 PA-28RT-201T	12/11/84	**		2200	9C6
804	Battery Strap Installation	PA-28-180/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-200 PA-28R-201/201T PA-28RT-201T	4/26/85	765-157		2430	9D12
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	3/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-28-150/160 PA-28-180 PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	5/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180/181 PA-28-235/236 PA-28-201T PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	8/26/86	**		2400	9J4
839	Muffler/Stack Modification	PA-28-181	6/19/86	765-191		7822	9J14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
840A	Fuel Selector Valve Cover Replacement	PA-28-140 PA-28-150/160 PA-28-180 PA-28R-180 PA-28R-200	11/7/2013	**	71-21-08	2822
847	Ammeter Replacement	PA-44-180T	8/28/86	765-302	86-20-11	2430 9K23
848	Niagara Oil Cooler Inspection/Replacement	PA-28-236	10/3/86	16599-00		7921 9L1
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800 10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180 PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180 PA-28R-200 PA-28R-201/201T	2/17/87	**		5550 10A9
866A	Back Up Landing Gear Extender Removal or Alternate Means of Compliance	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	3/4/88	765-303		3236 10B22
884	Lock Wiring of V-Band Couplings	PA-28-201T PA-28R-201T PA-28RT-201T PA-44-180T	4/8/88	**		7800 10G20 2100
886	Wing Spar Inspection	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T	6/8/88	**		5711 10H3
896	Shoulder Harness Installation & Usage	PA-28-140 PA-28-150/160/180 PA-28-151/161/181 PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	11/28/88	**		5340 10I13
901	Maneuvering Airspeed Placard Replacement	PA-28-161 Cadet	3/14/89	35669-143		2501 10J14
905	Auxiliary Primer Switch Replacement	PA-28-201T PA-28R-201T PA-28RT-201T	4/6/89	**		7315 10K7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
906	Oildyne Hydraulic Pump Replacement	PA-28R-201 PA-28RT-201T	4/10/89	**		2911 10K12
916B	Addition of Wing Stall Strips	PA-28-161 Cadet PA-28-161 Warrior II PA-28-181 II	11/22/89	**		1130 10aA8
933A	Trunnion Replacement	PA-28R-201 PA-28R-201T	2/20/90	67054-03		3222 10aD21
937	Engine Mount Inspection and Modification	PA-44-180 PA-44-180T	4/2/90	86212-024		7120 10aE11
938	Wire Protection	PA-28R-201 PA-28R-201T	6/12/90	181-531 488-698		3262 10aE15
940A	Throttle Microswitch	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	11/28/90	67210-08 487-925		7613 10aE21
965	Inspection of Flap Lever and Bolt	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-161 Cadet PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	9/1/93	**		2750 10aJ22
975	Aging Landing Light Seal Replacement and Landing Light Support Modification	PA-28-140 PA-28-150/160/180	11/2/94	**		7160 10bA5
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	12/12/94	**	SAIB CE-11-12	5740 10bA12
978A	Wing Spar Inspection	PA-28-161 Cadet PA-28-161 Warrior III PA-28-181 Archer III PA-28R-201 PA-28R-201T	8/6/99	**		5711 10bB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
990	Pacific Scientific Seat Belt Replacement	PA-28-161 PA-28-181 PA-28R-201 PA-44-180	1/3/96	**		5346 10bD12
991A	Replacement of Modification of the Alternator Out Light Fuse	PA-28-161 Cadet PA-28R-201 PA-28R-201T	1/29/96	**		2437 10bD16
992	Replacement of Spinner and Additional of New Forward Spinner Bulkhead	PA-28-181	3/14/96	**		6110 10bD22
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	9/12/96	**		5311 10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-28-181	8/11/97			7162 10bG1
1006A	Corrosion Inspection of Main Spar Behind Fuel Tanks	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-181 Pilot 100i PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T	9/25/24	**	SAIB CE-11-12	530 10bG4
1016B	Aileron Replacement	PA-44-180 PA-44-180T	5/26/2016	86562-24/-28 86562-25/-29		2715
1019	Inspection of the Engine Oil Cooler	PA-28-181 III	6/3/98	85472-10		7925 10bI6
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-28-161 Cadet PA-28-161 III PA-28-181 III PA-28-236 PA-28R-201 PA-44-180	7/10/98	**		2563 10bI11
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-28-140 PA-28-150/160/180 PA-28-181 II & III PA-28-235 PA-28-201T PA-28R-201T PA-28RT-201T	9/22/98	460-632	99-05-09	7167 10bI20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1023	Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	10/8/98	**		2902 10bJ6
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings."	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 CADET PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T PA-44-180 PA-44-180T	11/5/98	753-910		3711 10bJ20
1028	Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips	PA-44-180 PA-44-180T	12/2/98	**		5755 10bk12
1033A	Engine Mount Inspection and Modification	PA-44-180	6/12/2006	767-518 89361-016		7121 10bL10
1036	Garmin Service Bulletin No. 9905 "GNS430 Mod 1"	PA-28-181 III	10/1/99	**		3426 10cA1
1037	Inspection for Gascolator Bowl Drain Security	PA-28-161 III PA-28-181 III PA-28R-201	10/28/99	**		2824 10cA5
1040	Flight Control Wheel Collar Retainer Modification	PA-28-161 III PA-28-161 Cadet PA-28-181 III PA-28R-201 PA-44-180	3/20/2000			2701 10cA19
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-28-140 PA-28-150/-160/-180 PA-28S-160/-180 PA-28-151/-161 PA-28-161 Cadet PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	9/25/2000	**		3714 10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1048	Stainless Steel Control Cables	PA-28-161 II/III PA-28-161 CADET PA-28-181 II/III PA-28-236 PA-28R-201 PA-28R-201T PA-44-180	1/3/2001	N/A		2702 10cC9
1050	Engine Baffle Assemblies, Installation of Longer Screws	PA-28-161 III PA-28-181 III	3/7/2001	418-421 408-051 690-611		7236 10cC15
1057	Low Noise Muffler Replacement	PA-28-181 III	7/12/2001	766-681		7821 10cD24
1079	Untested Fuel Pump	PA-28-161 III PA-28-181 III	7/20/2001	62220-004		2825 10cI4
1083C	S-TEC System 55X Autopilot	PA-28-181 III PA-28R-201 PA-44-180	5/30/2002	767-316 767-317 767-320		2218 10cI19
1104	Air Box Interference	PA-28-181 III	3/22/2002	104606-002		7160 10dA18
1109	Gear Warning Indication	PA-44-180	4/12/2002	472-054 473-028		3264 10dB14
1110	Air Box Inspection	PA-44-180	5/16/2002	86245-034		7160 10dB18
1117	Rudder Trim System Bolt Inspection	PA-44-180	6/3/2002	402-285 691-306		2721 10dC16
1118	Alternate Air Inlet Adapter Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201	4/19/2002	99047-000		7164 10dC20
1119	Toe Brake Installation Inspection	PA-28R-201	8/16/2002	424-184 762-587		3241 10dD1
1122	Wing Rib Inspections	PA-28-151 PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-236 PA-28-201T PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T	3/7/2003	35617-001 104721-002		5712 10dD14
1127B	Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110B)	PA-44-180 PA-44-180T	4/18/2005	767-367 **	3-11-14	2800 10dE16
1131A	Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004)	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 II/III PA-28-161 Cadet PA-28-235	1/18/2016	65489-002 65490-000		3210

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-28R-180 PA-28R-200 PA-28R-201 III PA-28R-201 PA-28RT-201	6/10/2003	**		2800
1135	GMA-340 Audio Panel Wiring	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	7/16/2003	N/A		2370
1136	Auxiliary Fuel Pump Switch	PA-28-201T PA-28R-201T PA-28RT-201T	9/2/2003	588-006 (99377-029)		2800
1137	Stabilator Balance Weight Tube Assembly	PA-28-161 III PA-28-181 III PA-28R-201	11/6/2003	N/A		2749
1138	GNS-430 / GI-106 Wiring	PA-28-161 III	10/30/2003	N/A		3457
1139A	Control Wheel Attachment Inspection	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	4/9/2004	**	4-14-12	2701
1141	Clip Nut Replacement	PA-28-161 III PA-28-181 III PA-28R-201	12/9/2003	477-640		5351
1143	Nose Cone Spar Assy Inspection	PA-44-180 PA-44-180T	7/13/2004	**	81-10-01	3220
1151E	4130N Steel Hardness Discrepancy	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	6/9/2004	N/A		5741
1153	Overhead Switch Panel Assembly Modification	PA-28-181 III	2/8/2005	767-382		3340
1156A	Nose Gear Drag Link Bolt Periodic Inspection & Replacement	PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	11/9/21	402-940		3220
1161D	Rib Assembly Inspection and Modification - Aft Wing, WS 49.25	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	2/19/2024	767-397 767-398		5712
1162B	European Requirements for Avidyne Entegra Equipped PA-28 and PA-32 Model Aircraft	PA-28-161 III PA-28-181 III PA-28R-201	9/7/2006	652-589 767-419 767-422		3400
1164	Propeller RPM Limitation and Tachometer Re-Marking	PA-28R-200	5/5/2006	767-510 62177-019		7714

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1167	Nose Gear Centering Springs	PA-28-161 II/III PA-28-161 Cadet PA-28-181 II/III	5/31/2006	767-514 767-519		3220 10dL16
1178	Nose Gear Forging Inspection / Replacement	PA-28R-201 PA-44-180	9/24/2007	67050-007 67050-002		3222 10eB10
1179	Main Landing Gear Cylinder Assembly Inspection	PA-28-161 III PA-28-181 III	2/1/2008	65490-000		3213 10eB14
1186	Aileron Handling Placard	PA-44-180 PA-44-180T	9/7/2007	88428-002 (Kit)		2710 10eD1
1187	Voltage Suppressor Replacement	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	2/8/2008	88432-002 (Kit)		3400 10eD4
1188	Emergency Gear Extension Cable Routing Modification	PA-44-180 PA-44-180T	4/14/2008	88433-002 (Kit)		3200 10eD12
1197E	Control Wheel Shaft Inspection	PA-28-140 PA-28-150/(S)-160/(S)-180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	11/2/2017	**	2010-15-10	2710
1198A	Fuel Selector O-Ring	PA-28-235	4/20/2009	485-330 485-332		2823
1199	Main Landing Gear Torque Link Inspection	PA-28-140 PA-28-150/160/180 PA-28-235	2/16/2009	78033-000 63312-002	72-08-06	3213
1207	Periodic Replacement of Nose Gear Downlock Pivot Bolt	PA-44-180/180T	2/15/2010	**		3220
1209	Nose Gear Actuator Modification	PA-44-180	1/5/2010	N/A		3220
1213A	Emergency Gear Extension Cable Routing Inspection	PA-44-180	10/23/2015	**		3230
1220C	Throttle Cable Seizing	PA-44-180	4/27/2017	88501		7600
1223	Wire Screen Replacement	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	11/10/10	**		2126

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1226	Radio Support Plate Inspection	PA-28-161 III	10/28/10	79009-000		3450
1227	Rudder Trim Tab Inspection	PA-44-180	11/2/10	N/A		5540
1240	Fuel Pump Coupling Inspection	PA-44-180	1/26/2012	556-406		2820
1242A	Rudder Pedal Assembly Inspection	PA-28-140 PA-28-150/(S)-160/(S)-180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	5/12/2020	99938-000 99938-001		2710
1244C	Aft Wing Attach Fitting Inspection Requirements	PA-28 Series PA-28S Series PA-28R Series PA-28RT Series PA-44 Series	12/3/2018	764-998		5740
1245A	Stabilator Control System Inspection	PA-28 Series PA-28S Series PA-28R Series PA-28RT Series PA-44 Series	11/28/2012	N/A	2013-02-13	2730
1251	Stabilator Trim Barrel Inspection	PA-28-140/150/160/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T/235/236 PA-28R-180/200 PA-28R-201/201T PA-28S-160/180	4/10/2013	63530-000		5755
1253	Firewall Inspection	PA-28-181 III	1/7/2013	N/A		7130
1259A	Engine Control Cable Mounting Bracket Replacement	PA-44-180	5/5/2017	106895-002		7610
1261	Alternator INOP Wiring Modification	PA-44-180	9/11/2013	88545-002		3150
1274	Control Wheel Bushing Inspection	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	2/9/2015	68273-002		2701
1276A	Left Wing Root Rib Inspection	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	4/29/2016	88569 95639-002 95640-000		5710

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1278B	Left Wing Sta. 131.60 Rib Inspection	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	5/2/2019	35118-030		5712
1279A	Wing Rib Inspection at Right Side WS 140.09	PA-28-161 III PA-28-181 III PA-28R-201	3/3/2016	N/A	2015-20-13	5712
1280A	H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1	PA-28-161 Cadet PA-28-161 II-III PA-28-181 III PA-28R-201 PA-28-236 PA-44-180/-180T	4/29/2016	459-887		2620
1282B	Oil Pressure Pickup Port Relocation	PA-44-180	1/12/2016	88573-001 88573-002		7930
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-28-140 PA-28-150/-160/-180/-235 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28R-180/-200 PA-28R-201 PA-28RT-201 PA-44-180/-180T	4/12/2019	N/A		7414
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201 PA-44-180	10/30/2015	N/A		7310
1287	Lower Wing Skin Inspection	PA-44-180/-180T	6/1/2017	88611-701		5730
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1300	Air Box Gasket Replacement	PA-44-180	3/22/2017	44P710003-001		7160
1302B	Rear Seat Inspection	PA-28-161 II-III PA-28-161 Cadet PA-28-181 III	5/5/2017	110145-001		2520
1303A	Diode Module Installation	PA-44-180	10/15/2018	681-020		3410
1304B	Main Wing Spar Inspection	PA-28-140 PA-28-150/-160 PA-28-180 PA-28-235	12/2/2021	765-106 88692		5740
1307	Plane-Power Alternator Mounting Hardware Replacement	PA-28-181 III PA-44-180	6/28/2017	88617-001 88616-001		2410

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1309A	Fuel Tank Selector Placards Inspection	PA-28-140 PA-28-150/-160 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T	3/6/2018	581-685 581-686 581-687 581-890 581-891 582-693 582-694	2018-02-05	2822
1311	Baggage Compartment Closeout Inspection	PA-28-151/-161 PA-28-161 Cadet PA-28-181 III	12/11/2017	65667-000		2550
1312	Emergency Exit Inspection	PA-44-180	6/20/2017	N/A		5220
1313A	Stabilator Trim Pulley Bracket Inspection	PA-28-140 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-201T PA-28-235 PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T	1/17/2018	65636-801		2700
1316	Plane-Power Alternator Idler Pulley Bracket Improvement	PA-28-181 III	11/3/2017	88619-001		2410
1323	Fuel Injection Servo Vapor Return Fitting Replacement (Lycoming S.I. 1572, Plug Replacement of Vapor Return Fitting on Piper Installation of IO-360-B4A)	PA-28-181 III	9/27/2018	**		7322
1324	Winterization Kit Replacement (Fuel Injected Engines)	PA-28-181 III	3/22/2018	85470-005		7900
1325	K400 Relay Wiring Inspection and Mod	PA-44-180	6/19/2018	N/A		3297
1331A	Stabilator Idler Arm Assembly Inspection	PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T	9/27/2018	N/A		5520
1340C	Plane-Power Alternator Support Replacement	PA-28-181 III	7/15/2022	106972-004		2430
1342A	Stabilator Fitting Inspection	PA-28-140 PA-28-150/-160 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-201T PA-28-235 PA-28-236 PA-28R-180/-200 PA-28R-201/-201T	11/2/2021	62645-004		5510

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1345A	Main Wing Spar Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T	9/17/2021	**	2020-26-16	5711
1354	Fuselage Station 247 Bulkhead Inspection	PA-44-180 PA-44-180T	10/18/2023	88686-701		5310
1355B	Tee Bar Assembly Inspection	PA-28-140 PA-28-150/-160/-180/-235 PA-28S-150/-160 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	8/18/2022	28F40A003		2701
1357	Wing Rib Inspections at WS 106.19 and WS 123.15.	PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-236 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T	10/27/2020	N/A		5712
1362	Aft Wing Rib Inspection at Wing Stations 36.92 and 49.25	PA-28-181 III	11/2/2020	N/A		5712
1363	Rivet Dimple Inspection For Tool Marks	PA-28-181 III PA-44-180	11/13/2020	N/A		5700/5300
1365A	Pilot and Copilot Seat Upholstery Inspection	PA-28-181 III PA-28-181 Piper Pilot 100i PA-44-180	7/22/2021	484-829		2510
1366	Main Wing Spar Hardware Inspection	PA-28-140 PA-28-150/-160/-180/-235 PA-28S-150/-160 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	5/14/21	96352		5711

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1368	Heater Fuel Pump Leak Inspection and Replacement (Hartzell ASB 85)	PA-44-180	7/14/21	**		2140
1372	Main Wing Spar Inspection	PA-28-151 PA-28-161 II-III / Cadet PA-28-181 II-III / Pilot 100i PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/-201T PA-28RT-201/-201T	4/4/24	88731-701 / -702	Pending	5711
1375D	Periodic Replacement of Main Landing Gear Attachment Hardware	PA-28-140 PA-28-150/-160/-180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-235 PA-28-236	1/29/2023	**		3210
1377B	Main Wing Spar Inspection at the Landing Gear Truss Bracket	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	9/24/2024			5740
1378	Fuselage Skin Rivet Inspection	PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-236	8/30/2022	**		5330
1381	Lower Fuselage Skin Rivet Insp.	PA-44-180/180T	6/9/2022	MS20470AD4		5300
1383	Microphone And Headphone Jack Improvement	PA-28-181 III PA-28-181 Pilot 100i	9/8/2022	**		2340
1386	Archer Diesel Cowling Inspection	PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC.	8/22/2022	STC SA03303AT		7110
1387	Archer Diesel Instructions For Continued Airworthiness (ICA)	PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC.	10/17/2022	STC SA03303AT		0400
1388A	Archer Diesel Fuel System Inspection	PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC.	5/10/2024	STC SA03303AT		2820
1389A	Fuselage Skin and Wing Rib Inspection	PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	2/19/2024	86486-006 67681-806		5300 / 5710

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1391C	GFC 500 Autopilot Pitch Trim	PA-28-181 Pilot 100i	1/8/2024	88730-701		2216
1393	Engine Control Cables Inspection	PA-28-181 III PA-28-181 Pilot 100i PA-44-180	12/22/2022	455-350 653-946		7600
1396	Propeller Spinner Modification	PA-28-181 III PA-28-181 Pilot 100i	4/1/2024			6113
1397	Lower Cockpit Channel Inspection	PA-44-180	4/27/2023	189-625		5300
1399	Wing Rib Modification	PA-28-151/-161 PA-28-181 PA-28-201T PA-28R-201/-201T PA-28-236 PA-28RT-201/-201T	3/16/2023	35615-001 35615-003		5700
1405A	Fuselage Skin Rivet Inspection, FS 156	PA-28-236 PA-28-151 PA-28-161 PA-28-161 II PA-28-161 III PA-28-181 II PA-28-181 III PA-28-181 Pilot 100i PA-28-201T PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	10/25/2023			5330
1411A	Autopilot Rigging Inspection	PA-28-181 III PA-28-181 Pilot 100i PA-44-180	7/2/2024			2700
1412	Main Wing Spar Inspection	PA-28-140 PA-28-150/-160/-180 PA-28S-160/-180 PA-28-236 PA-28-201T	5/9/2024			5711
1413	Aft Wing Spar Attach Fitting Inspection	PA-28-181 III PA-PA-181 Pilot PA-28R-201 PA-44-180	4/18/2024	66762-000 62448-002/-003 68621-002/-003 88365-002 / 87584-000		5741
1415	Rivet Inspection Near FS 104.70	PA-28-181 Pilot 100i	5/14/2024			5300
1416A	Fuel Flow Transducer Inspection	PA-28-181 Archer III PA-28-181 Pilot 100i PA-44-180 Seminole	7/2/2024			2840

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
254	Oil Cooler Hoses, Engine Replacement & Rerouting of	PA-31	8/17/67	757-167	67-25-06	7920 3F16
255	Emergency Exit Window Mechanism, Modification of	PA-31	8/9/67	757-159		5220 3F17
256	Pneumatic Pump Hose, Replacement	PA-31	8/25/67	757-175		3710 3F18
257	Modifications, Piper Navajo (Five Sections)	PA-31	10/10/67	**		7720 3F19 3210 6110 7920 2810 2910 3200
258	Alternate Air Box Assembly	PA-31	11/1/67	757-189		7160 3F24
262	Terminals, Solenoid, Insulation of	PA-31	12/19/67	757-185		3310 3G8
265	Louvered Access Plates, Wing Fillet	PA-31	2/5/68	**		5710 3G11
266	Fasteners, Engine Cowling	PA-31	2/23/68	760-190 757-179		7110 3G13
267A	Flight Manual Revision	PA-31	5/28/68	**		General 3G15
268	Valve Assembly, Manifold And Check	PA-31	2/28/68	760-174		7710 3G18
270	Deicer Boot Installation, Elevator Tip	PA-31	2/23/68	757-200		3010 3G20
271	Filter, Inline, Pneumatic System	PA-31	3/1/68	460-866		3710 3G21
272A	Terminal Screws, Electrical, Security of - Voltage Regulator Selector Switch And Master Switch	PA-31	5/6/68	**		2430 3G22
276	Channel Clearance, Aileron Cable/Floorboard Support	PA-31	5/23/68	**		2710 3H11
277	Level, Fuel Selector, Cable Attachment Assembly	PA-31-300	7/10/68	760-214	77-26-02	2820 3H13
278	Control Panel (Fuel) Area, Rerouting And Securing of Wire In The, And Clearance of The Cross Feed Line	PA-31-300	5/27/68	760-216	68-13-01	2800 3H15
280	Artificial Horizon, R.C. Allen 3", Case Leakage of	PA-31-300	7/10/68			3420 3H2
283	Warning System, Landing Gear, Modification To The	PA-31-300	10/4/68	760-250		3260 3I5
284	Torque Tube Assembly, Elevator, Inspection of - Section I; Replacement of The Steel Elevator Torque Tube Assembly, Part Numbers 40070-00 or 40070-04 With Aluminum Elevator Torque Tube Assembly, Part Number 40070-05 - Section II	PA-31/300	9/27/68	40070-05		2740 3I6
286	Hinge Attaching Rivets, Door, Main Landing Gear (In Board)	PA-31/300	10/29/68	420-236		3210 3I13
289	Friction, Elevator Control System	PA-31/300	2/17/69		69-06-04	2730 3I19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
294	Stall Strips	PA-31/300	5/16/69	760-321 760-322	69 11 05	5720	3J12
304	Stall Strip Inspection	PA-31/300	11/17/69	**		5720	3K9
306	Alternator System Modification	PA-31/300	1/9/70	760-349 760-358	70-22-05	2430	3K14
307	Electrical System Modification, Wing Flap	PA-31/300	3/23/70	760-381		2750	3K16
308A	Seats, Aft Facing	PA-31/300	5/4/70	**		2570	3K17
320A	Autopilot Servo And Bridle Cable Installations, III Series, Inspection of	PA-31/300 PA-31P	7/6/72			2210	3L23
323	Spar Assemblies, Rudder And Elevator, Modification of The	PA-31/300	9/21/70	**	70-26-06	5520	4A6
325	Battery Drain Relocation	PA-31/300	11/23/70	760-436	71-01-04	2430	4A12
330	Selector Mechanism Modification Landing Gear 11A	PA-31	1/20/71	760-510		3200	4B1
331	Switch, Electric, Trim Inspection And Modification	PA-31/300 PA-31P	2/5/71	760-505	71-12-05	2730	4B3
333	Safety Strap, Cabin Entrance Door, Inspection And Replacement	PA-31	2/18/71	**		5210	4B10
338	Rivet Installation, Longitudinal Bulkhead	PA-31P	4/21/71	**		5300	4B22
344	Emergency Gear Extension Operation Information, Revised	PA-31 PA-31P	10/12/71	760-570		3200	4C19
346	Flight Manual, Airplane, Mandatory Revision	PA-31	3/23/72	**		2430	4C22
347	Weldon Service Bulletin WPSB-2 (Electric Fuel Pumps)	PA-31	11/17/71	760-573 760-574		2820	4C24
361	Elevator Hinge Bracket Reinforcement, Inspection	PA-31	8/17/72	43757-17 43757-18		5550	4E16
363	Cowl Shield Installation	PA-31/300/310 PA-31-350	2/19/73	760-689		7110	4E24
365	Torquemeter Oil Pump, Replacement of (Reference Avco Lycoming Service Bulletin No. 350 Dated July 21, 1972)	PA-31P	8/29/72	LW12637		7920	4F3
379A	Rudder Control Cable Routing, Inspection of	PA-31-350	10/25/74	41953-03 41953-04	75-06-04	2720	4F20
383	Fuel Selector Valve Control Handle, Modification of	PA-31-350 PA-31P	4/25/73	760-755		2820	4G4
384	Propeller Blade Shank, Inspection of (Hartzell Service Bulletin No. 94A Dated March 1, 1973)	PA-31/300/310	4/25/73	**		6110	4G5
386	Moisture Shield Installation, Circuit Probe	PA-31-310 PA-31-350	9/11/73	760-772		2450	4G13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
389	Bridle Cable And Bridle Cable Clamp Installation	PA-31-310 PA-31-350 PA-31P	8/13/73			2210 4G17
391	Loading Instructions, Cargo	PA-31-310	6/6/74	**		5230 4G23
392	Automatic Flight Control System (V Series) Precautionary Operating Placard And System Modification	PA-31-310 PA-31-350 PA-31P	7/11/73	760-793		2210 4H2
394	Rudder Pedal, Warning, Improper Use of	PA-31/300/310 PA-31-350 PA-31P	9/28/73	757-436		2720 4H7
398	Copilot Gyro Operation - Altimatic V Series Automatic Flight Control System	PA-31-310 PA-31-350 PA-31P	9/13/73	**		2210 4H15
399	High Altitude Operation. Ignition System For (Avco Lycoming Service Instruction No. 1291, Dated November 2. 1973)	PA-31-350	10/29/73	**		7420 4H16
400	Alternator Pulley And Belt Replacement	PA-31-310 PA-31-350	2/6/74	760-805		2430 4H21
405	Fuel Crossfeed Control Mod	PA-31-350	10/31/73	760-814		2820 4I13
407	Ball Joint Assemblies Control Attachment, Inspection of	PA-31/300 PA-31-350 PA-31-P	11/14/73	469-142		5340 4I22
409	Elevator Control Tube, Inspection of	PA-31P	6/7/74	40847-04	75-09-10	2730 4J4
415	MAA Plate Replacement And Tailpipe Gasket Installation	PA-31-310	1/21/74	462-062		7810 4J19
417	Heater (Manual) Fuel Shut-off Valve, Removal of	PA-31-300	8/26/74		74-26-04	2140 4J22
419	Elevator Control Tube Attachment, Inspection of	PA-31-310 PA-31-350 PA-31P	2/20/74			2730 4K2
420	Windshield, Heated, Inspection of	PA-31P	8/7/74	760-882		3040 4K4
421	Fuel Selector Valve Replacement	PA-31P	3/18/74	492-239		2820 4K9
422	Fuel Selector Valve Control Handle, Inspection of	PA-31-350	3/11/74			2820 4K11
423	Deicer (Propeller Electric) Solenoid Replacement	PA-31P	3/13/74	487-167		6110 4K13
431	Placard, Electric Razor Outlet	PA-31-350	8/5/74	SK-23601 SK-2361		3320 4L8
432	Fuselage Bulkhead, Modification To The	PA-31-310 PA-31-350	9/6/74	760-295		5310 4L9
433	Elevator Control Tube Inspection of	PA-31/300/310 PA-31-350	12/17/74	**	75-09-10	2730 4L11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
442	Circuit Breaker Rewiring, Emergency Fuel Pump	PA-31/300/310 PA-31-350	1/22/75	760-905		2820 5A15
443	Fuel Cell Fitting (Main) Inspection of	PA-31/300	4/4/75	760-929 40518-00/01		2810 5A16
446A	Cable Replacement, Rudder/Nose Gear Steering	PA-31P	7/8/75	760-923	75-16-02	2720 3250 5A23
458	Propeller Air Charge Loss, Aircraft Operating Advisory	PA-31P	4/11/75	**	75-22-14	6100 5C3
460A	Battery Drain And Vent Relocation	PA-31-350	1/23/76	761-029 760-941	76-04-10	2430 5C8
461	Encoding Altimeter Harness Rewiring	PA-31-310 PA-31-350 PA-31P	4/17/75	**		3410 5C10
462A	Tailpipe Support Bracket Installation	PA-31P	11/3/75	760-974	76-06-09	7810 5C12
470	Propeller Feather Assist Spring Assembly Installation	PA-31P	10/27/75			6110 5D6
473	Alternator Switch Bus Bar Link Installation	PA-31P	3/24/76	49167-03	76-11-06	2450 5D19
478A	Airspeed Limitation Placard, Installation of	PA-31P	8/20/76	761-075	76-11-01	3410 5E7
479B	Alternate Air Door Magnetic Catch Assembly Modification/Replacement; Engine Induction Air System	PA-31-325 PA-31-350	3/23/76	761-037 761-038	80-13-06	7160 5E9
480	Emergency Fuel Pump Circuit Breaker Placards, Inspection of	PA-31-310/325 PA-31-350	10/10/75	**		2820 5E11
487	Control Shaft Collar Attachment Modification	PA-31-300/310 PA-31-325 PA-31-350 PA-31P	11/7/75	401-264 407-584	76-04-11	2710 5F7
488	Landing Gear Selector Cable Forward Attachment Pin, Modification of	PA-31-310/325 PA-31-350 PA-31P	10/24/75	**	96-24-13	3200 5F10
492A	Exhaust System Modification TIG0-541 -E1A	PA-31P	5/29/2012	**	76-06-09	7800
494B	Flap Control System, Inspection of	PA-31-300/325 PA-31-350 PA-31P	7/17/79	**	82-27-13	2750 5G6
497	Throttle And Propeller Pitch Control Attachment Modification	PA-31P	3/29/76	761-031		7610 6120 5G16
500	Elevator Balance Weight Modification	PA-31-325 PA-31-350	4/23/76	761-040 761-041	76-15-07	2730 5G23
507	Fuel System Control Cables At Swivel Fittings, Inspection of	PA-31/300/325 PA-31P	11/10/76	**	80-18-10	7320 5H15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
509	Engine Mount Assembly Attachment Nuts, Replacement of	PA-31-310/325 PA-31-350	6/25/76	404-890		7120 5H22
511A	Oxygen System Outlet Refinement	PA-31/300/325 PA-31-350 PA-31P	9/24/76	761-032 752-583		3510 5I3
512	Seat Track Modification	PA-31/325	10/21/76	761-086		5340 5I5
515	Control Cable Ball Joint Retainer Installation	PA-31/300/325 PA-31/350	1/17/77	55447-02		7610 5I10
521	Stabilizer Stringer Attachment, Inspection of	PA-31/325 PA-31/350	9/20/76	522-881	77-01-06	5530 5J1
523	Cigar Lighter Element Replacement, 24 Volt	PA-31/325 PA-31-350 PA-31P	10/8/76	55674-02		3310 5J7
525	Seat Latch Mechanism Modification, Pilot/Copilot	PA-31/300 PA-31-350 PA-31P	11/15/76	55842-02		5340 5J12
526A	Microphone And Phone Jack Relay Modification, Pilot/Copilot	PA-31/300/325 PA-31-350 PA-31P	7/25/77	48757-02	77-08-02	2350 5J15
527	Electric Trim Switch Modification	PA-31/300 PA-31-350 PA-31P	11/5/76	756-047	77-09-10	2740 5J18
529	Aircraft Data (MAA) Plate Inspection And Replacement	PA-31	11/5/76	53750-02	77-03-03	5330 5K3
535	Radio Power Relay Cover Spacer Bushings, Replacement of	PA-31/325 PA-31-350	12/15/76		77-07-03	2450 5L13
544	Airspeed Placard Installation	PA-31-325	3/8/77	761-125	77-10-09	3410 6A11
546	Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection of	PA-31/325 PA-31-350 PA-31P	5/18/77	**		3340 6A16
549	Elevator Bungee Link Modification	PA-31/325 PA-31-350	2/16/77		78-01-02	2730 6B2
550	Engine Control Cable Inspection	PA-31/325 PA-31-350	3/29/77	**		7230 6B4
554	Spar Reinforcement, Front, Right Wing	PA-31/325 PA-31-350	3/7/77		77-14-14	5710 6B15
558	Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D	PA-31/325 PA-31-350 PA-31P	6/10/77			2210 6C1
560	Flap Condition. Asymmetric, Recommended Operating Procedure	PA-31/300/325 PA-31-350 PA-31P	4/4/77	**		2750 6C5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
566	Horizontal Situation Indicator, Modification To Edo-Aire Mitchell NSD-360	PA-31/325 PA-31-350	10/11/77	**		3420 6D9
567	Flap Solenoid Repositioning	PA-31/300/325 PA-31-350	6/7/77		77-19-06	2750 6D20
574	Fuel Crossfeed Control Shaft Security	PA-31-350	7/13/77	**		2820 6E17
575	Inspection of Horizontal, Stabilizer And Vertical Fin Stringer Attachment Rivets	PA-31/325 PA-31-350	8/3/77	522-881	77-24-01	5510 6E19
591	Inspection of Goodyear BTC-39 Fuel Cells	PA-31/300 PA-31-350 PA-31P	3/22/78	**		2810 6G13
592	Inspection of Fuel Selector Lever Assembly Installation	PA-31/325	2/16/78		78-08-10	2820 6G24
595	Elevator Outboard Hinge Bracket Rivets Replacement	PA-31/325 PA-31-350	6/5/78	762-575		5550 6H4
604A	Forward Baggage Door Locking System Modification	PA-31/300/325 PA-31-350 PA-31P	6/8/79	**		5230 6I4
621	Elevator Cable Inspection And Cable Guard Installation	PA-31-350	10/13/78	71045-02 189-545	78-26-11	2730 6K10
626C	Elevator Down Spring Inspection/Replacement	PA-31/300 PA-31-325 PA-31-350	2/28/97	**	98-08-18 79-01-04	2730 6L1
629	Landing Gear Hose Assembly Inspection And Replacement	PA-31-325 PA-31-350	11/15/78	17766-27		3230 6L10
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-31 PA-31-325 PA-31-350 PA-31P	2/25/80			3450 6L14
636A	Superseded by SB 1273 and Atlanta ACO AMOC letter dated Jun 10, 2015				96-12-12	
641	Heater Fuel Drain Hose Modification	PA-31/300/325 PA-31-350	4/5/79	**		2140 7B22
643A	Oil And Manifold Pressure Tubes Inspection	PA-31 PA-31-325 PA-31-350	12/8/80	41907-00 41913-00		7930 7C4 7710
644E	Turbo-Charger Exhaust Coupling Inspection/Replacement	PA-31/31-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	5/9/2012	**	2014-23-03 2013-10-04	8123
645A	Crossfeed Valve Inspection	PA-31/31-325 PA-31-350	7/2/79	**		2820 7C14
647A	Outboard Flap Track Inspection Inspection And Reinforcement	PA-31 PA-31-325 PA-31-350 PA-31P	11/24/80	763-986	80-14-06 81-23-06	2750 7C19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
648A	Part I - Scott Fuel Selector Valve Inspection	PA-31 PA-31-300 PA-31-350 PA-31P	4/27/87	760-504	80-18-10	7324	7C21
648A	Part II - Fuel Selector Valve Control Cable Inspection	PA-31 PA-31-300/325 PA-31P	4/27/87	**		7324	7C23
648A	Part III - Fuel Selector Valve Control Cable Replacement	PA-31 PA-31-300/325 PA-31P	4/27/87	**		7324	7C24
649	Elevator Control Stop Inspection	PA-31/31-300 PA-31-325 PA-31-350	3/29/79		79-12-02	2730	7D1
651	Control Shaft Roll Pin Inspection	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	5/11/79	480-732	79-14-02	2710	7D6
653	Modification of Weight and Balance Plotters	PA-31 PA-31-325 PA-31-350	12/3/79	Placard**		800	7D11
654	Cigar Lighter Installation Modification	PA-31 PA-31-325 PA-31-350	6/23/80	**		3310	7D13
658	Elevator Inspection And Reinforcement	PA-31P	7/31/79	763-943	80-02-15	2730	7E5
659	Rudder And Aileron Trim Tab Attachment Inspection	PA-31P	7/19/79	406-829		2710 2720	7E7
664	Elevator Torque Tube Attachment Inspection	PA-31 PA-325 PA-31-350	12/14/79	**		2730	7E20
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA	7H4
682	Main Landing Gear Inboard Door Hinge Inspection/Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	7/24/80	**	80-26-05	3210	7H15
684	PA-31-350 Chieftain/Takeoff Flaps	PA-31-350	4/14/80	**	80-08-05	2750	7I16
685	Elevator Bellcrank Assembly Inspection	PA-31 PA-31-325 PA-31-350	9/23/80	**		2730	7I18
688	Placards Installation Check	PA-31 PA-31-325 PA-31-350	7/1/80	Placard**	80-17-06	1130	7I24
690	Elevator Balance Weight Inspection	PA-31 PA-31-325 PA-31-350	7/7/80	**	80-17-02	2730	7J9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
693	Engine Baffle Seats Inspection/Modification	PA-31/31-300 PA-31-350	7/28/80	**	80-20-04	7230	7J16
697	PA-31, PA-31-325 Takeoff Flaps	PA-31 PA-31-325	8/11/80	**	80-21-07	2750	7K7
700A	Nose Wheel Inspection/Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	10/12/81	551-791	97-07-03	3240	7K14
704	Cabin Fan Fuse Installation	PA-31 PA-31-325 PA-31-350	6/7/82	**		N/A 2120	7L1
705	Main Landing Gear Door Actuator Fitting	PA-31P	6/30/81			3250	7L5
707	PA-31-350 Chieftain Takeoff Flaps	PA-31-350	2/4/81	764-101		2750	7L11
708	PA-31 and PA-31-325 Takeoff Flaps (Refer to SB 697)	PA-31 PA-31-325	4/7/81	764-101		2750	7L16
737	Elevator Outboard Hinge Installation Inspection	PA-31P	4/23/82	764-381		5550	8B12
739	Restriction of Flap Travel and Inspection of Wing Flap Flexible Drive Shaft	PA-31 PA-31-325 PA-31-350 PA-31P	3/1/82	**	82-27-13	2750	8D19
752	Cigar Lighter Circuit Modification	PA-31P	10/18/82	454-656		3310	8G16
771A	Parking Brake Application	PA-31P	9/6/2011	81090-002	85-02-05	1130	
779B	Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	10/12/87	**	85-08-05	3200	8K1
797B	Fuel Port Restrictor Installation	PA-31, 31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	9/1/87	**	87-21-01	2812	9B14
798	"TURBO" Marking Removal	PA-31, 31-310 PA-31-325 PA-31-350 PA-31P	12/11/84	N/A		1110	9B19
802	Aft Bulkhead (Fuselage Station 332 0) Inspection	PA-31P	12/12/84	764-983	85-05-01	5310	9C10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
805A	TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration)	PA-31 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	3/14/86	N/A		6110 9D15
822	Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	4/2/86	17766-02	96-21-04	2912 9H3
825	Crossover Fuel Line Inspection	PA-31-300 PA-31-310	4/8/86			2823 9H14
826A	Elevator Hinge Inspection/Replacement	PA-31P	9/22/86	45253 03		5550 9H17
829	Oil Separator Assembly Replacement	PA-31P-350	4/18/86	2564-02		7250 9I9
836A	Aluminum Wire Inspection/Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 PA-31P	8/26/86	**		2400 9J4
845A	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-31/PA-310/325 PA-31-350 T1020 PA-31P PA-31P-350	10/9/87		88-05-05	3218 9K16
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800 10A7
859	Nose Gear Shuttle Valve Bracket Installation	T-1020	3/30/87	765-315		3225 10A18
860	Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P	4/14/87	**		3210 10A20
884	Lock Wiring of V-Band Couplings	PA-31 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350	4/8/88	**		7800 10G20 2100
897B	Elevator Butt Rib Refinement	PA-31P	7/15/97	**		5520 10I21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
907	Windshield Heat Fuse Installation	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020	4/11/89	**		3047 10K15
923	Main Landing Gear Actuator Reinforcement Bracket Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350	8/16/89	73786-02	96-21-11	5740 10aB13
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-31 PA-31-325 PA-31-350 PA-31P-350	3/7/94	**	94-17-13	6113 10aC1
927	Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs	PA-31-300	12/4/89	**	2001-23-08	6113 10aC18
967	Aileron Hinge Inspection and Replacement	PA-31P	1/24/94	**	96-21-03	5750 10aK15
974	Aileron Hinge Inspection and Replacement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31P-350	10/19/94	**	96-21-03	5750 10bA1
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P	1/29/96	**		2437 10bD16
998A	Elevator Spar Inspection	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P-350	8/4/97	**	99-12-05	2730 10bDF1
1002	Elevator Down Spring Inspection /Replacement	PA-31P	6/5/97	**	98-08-18	2739 10bF17
1003	Wing Spar Splice Plate Replacement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020	6/16/97	**	98-09-25	5711 10bF20
1004	Inspection of the E303 Electrical Connector and Heater Blower Power Wire	PA-31-350 PA-31-350 T 1020	6/6/97	**		2451 10bF22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1007	Horizontal Stabilizer Spar and Outboard Hinge Inspection and Modification	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350	9/30/97	766-646	99-06-01	5511 10bG13
1008	Elevator Butt Rib Refinement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350	9/30/97	766-642		5521 10bG15
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020	11/5/98	753-910		3711 10bJ20
1035A	Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3"	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	3/22/2007	**	2003-14-03	7311 10bL16
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	9/25/2000	**		3714 10cB1
1045	Forward Wing Spar Attach Bracket Inspection	PA-31 PA-31-300	9/18/2000	**		5741 10cB23
1105A	Rudder Torque Tube Assembly Inspection	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	9/22/2003	767-349		2725 10dA22
1125	Elevator Trim Wheel Replacement	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	4/15/2003	43751-000		2733 10dE11
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	6/10/2003	**		2800 10dG5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1174	Lock Assembly Inspection / Modification (Cabin Door, Baggage Doors, Nacelle Locker Door)	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	2/15/2007	473-146 88406-002		5200 10eA13
1194B	Nose Baggage Door Components, Periodic Replacement of	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	4/12/2012	**	2009-13-06	5230
1233C	Periodic Replacement of Main Landing Gear Rod Ends	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	6/15/2023	762-554 758-440		3210
1246	Emergency Exit Window Inspection	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020	10/29/2012	41307-000 41307-003 53181-000 453-694		5220
1257A	Fuel Hose Inspection	PA-31-350 PA-31-350 T-1020	8/4/2015	39995-034 LW-18302		7310
1260A	Front Spar Attachment Bulkhead Inspection	PA-31-350 PA-31-350 T-1020	5/12/2020	88614-701 44758-000 44758-001		5312
1266	Fuel Warning Placard and POH Inspection	PA-31 PA-31-300 PA-31P	12/16/2014	**	2015-24-05	1130
1273C	Bulkhead Modification at FS 317.75	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020	11/9/2022	764-028	2016-05-01	5300
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-31-300	10/30/2015	N/A		7310
1289A	Bulkhead Inspection, Fuselage Station 332.00	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020	10/26/2016	88578-001		5312
1295	Nose Baggage Door Lock Inspection	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	3/24/2017	88409-002	2009-13-06	5230
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1301	Wiring Inspection	PA-31P-350	1/6/2017	N/A		2497

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
440	Refinement Modifications, Cheyenne	PA-31T	12/17/74	**		2750 6110 3420 2150 6140	5A9
446A	Cable Replacement, Rudder/Nose Gear Steering	PA-31T	7/8/75	760-923	75-16-02	2720 3250	5A23
453A	Scoop Modification, Engine Air Inlet	PA-31T	4/7/75	760-942		7160	5B18
456A	Warning Placard Replacement	PA-31T	5/28/75	**		2840	5B24
459	Servo Cable Clamp Replacement, Aileron And Rudder, M-4D Automatic Flight Control System	PA-31T	4/22/75	33078-03		2210	5C6
465	Fuel Vent Line, Inspection of	PA-31T	5/21/75			2810	5C20
466	Air Conditioning System Modification	PA-31T	6/2/75	760-979		2150	5C22
468	Elevator Trim Tab Attachment Hinges And Screw Assembly, Inspection of	PA-31T	5/9/75	**		5550	5D2
476	Elevator Trim Control Cable Turnbuckles, Inspection of	PA-31T	10/9/75	454-867		2730	5E4
477A	Elevator Control Tube And Trim Tab System Modification	PA-31T	11/3/75	760-989	76-03-01	2730	5E6
481A	Elevator Assembly Inspection And Elevator Butt Rib Replacement	PA-31T	11/3/75	**	76-03-01	5520	5E14
484	Starter Generator System Modification	PA-31T	12/5/75	761-019		8010	5E24
487	Control Shaft Collar Attachment Modification	PA-31T	11/7/75	401-264 407-584	76-04-11	2710	5F7
488	Landing Gear Selector Cable Forward Attachment Pin, Modification of	PA-31T	10/24/75	**	96-24-13	3200	5F10
494B	Flap Control System, Inspection of	PA-31T	7/17/79	**	82-27-13	2750	5G6
504	Elevator Hinge System Modification	PA-31T	6/1/76	761-056	76-18-06	5550	5H8
511A	Oxygen System Outlet Refinement	PA-31T	9/24/76	761-032 752-583		3510	5I3
515	Control Cable Ball Joint Retainer Installation	PA-31T	1/17/77	55447-02		7610	5I10
517	Engine Oil Temperature Gauge Placard Installation	PA-31T	10/5/76	757-487		7930	5I17
523	Cigar Lighter Element Replacement, 24 Volt	PA-31T	10/8/76	55674-02		3310	5J7
525	Seat Latch Mechanism Modification, Pilot/Copilot	PA-31T	11/15/76	55842-02		5340	5J12
526A	Microphone And Phone Jack Relay Modification, Pilot/Copilot	PA-31T	11/30/76	48757-02	77-08-02	2350	5J15
546	Whelen Wing Tip Lights, Reference FAA Airworthiness Directive, Inspection of	PA-31T	5/18/77	**		3340	6A16

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
558	Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D	PA-31T	6/10/77			2210 6C1
560	Flap Condition, Asymmetric, Recommended Operating Procedure	PA-31T	4/4/77	**		2750 6C5
562	Annunciator Panel Oil Temperature Indicator System Modification	PA-31T	10/4/77	**		3310 6C10
568	Nose Wheel Replacement (High Flotation Tire Option)	PA-31T	4/26/77	45520-07		3240 6E1
570A	Inspection of Main Landing Gear Actuating Cylinder Rod End Bearing Assy.	PA-31T	8/30/78	762-554	78-02-01	3230 6E3
572	Pilot's Operating Manual/Pilot's Operating Handbook Revision	PA-31T	6/9/77	**		800 6E12
585	Air Control Cable Stand-off Installation	PA-31T	3/9/78	763-821		2130 6F22
588	Pilot's Operating Manual (POM) / Pilot's Operating Handbook (POH) Revision, Flap Selector Operation	PA-31T	11/24/78	**		2750 6G7
589B	Inspection of Turn And Bank Suction System Check Value/ Vacuum System Modification	PA-31T	9/25/79	**		3420 6G8
591	Inspection of Goodyear BTC-39 Fuel Cells	PA-31T	3/22/78	**		2810 6G13
594A	Modification of Left And Right Circuit Protector Mounting Board Installation	PA-31T/31T1	7/7/78	763-873		3910 6H2
598A	Inspection of Main Landing Gear Brake Discs (Cleveland)	PA-31T	6/13/78	754-618 754-626		3240 6H12
599A	Replacement of Cleveland High Flotation Nose Wheel Assembly	PA-31T PA-31T1	10/4/78	551-782		3240 6H14
604A	Forward Baggage Door Locking System Modification	PA-31T	6/8/79	**		5230 6I4
629	Landing Gear Hose Assembly Inspection And Replacement	PA-31T PA-31T1	11/15/78	17766-27		3230 6L10
630A	Collins VIR-305 And VIR-351 Navigation Receiver Modification	PA-31T PA-31T1	2/25/80			3410 6L14
640	Electroluminescent Panel Inverter Replacement And/Or Relocation	PA-31T PA-31T1	6/22/79	763-929 763-944	79-19-09	3910 7B20
647A	Outboard Flap Track Inspection and Modification	PA-31T PA-31T1	11/24/80	763-986	81-23-06	2750 7C19
651	Control Shaft Roll Pin Inspection	PA-31T PA-31T1	5/11/79	480-732	79-14-02	2710 7D6
658	Elevator Inspection And Reinforcement	PA-31T PA-31T1	7/31/79	763-943	80-02-15	2730 7E5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
659	Rudder And Aileron Trim Tab Attachment Inspection	PA-31T PA-31T1	7/19/79	406-829		2710 2720 7E7
660	Gyro Inverter Power Selector Switch Guard Installation	PA-31T1	9/26/79	29321-02		3940 7E9
665A	Throttle Control Ball Joint Connector and Rod End	PA-31T PA-31T1	5/30/80	**		7320 7E23
674	Rudder Trim Mechanism Modification And Trim Tab Rigging	PA-31T PA-31T1	1/23/80	**		2720 7G13
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0 7H4
680	Ground Clearance Switch Fuse Installation	PA-31T PA-31T1	4/23/80	**		3450 7H7
682	Main Landing Gear Inboard Door Hinge Inspection/Replacement	PA-31T PA-31T1	7/24/80	**	-25-01 80-26-05	3210 7H15
692	Oxygen Mask Replacement	PA-31T	8/6/80	474-108		3510 7J14
704	Cabin Fan Fuse Installation	PA-31T2 PA-42	6/7/82	**		2120 7L1
705	Main Landing Gear Door Actuator Fitting	PA-31T PA-31T1	6/30/81			3250 7L5
715A	Elevator Control Tube Inspection	PA-31T PA-31T1 PA-31T2	4/25/83	**		2730 8A15
722	Avionics Cooling Fan Inspection/Replacement	PA-31T PA-31T1	4/16/82	764-375		2300 8B14
726	Razor Inverter Wiring Inspection	PA-42	7/21/81			3320 8C11
727	Powerplant Firewall Inspection	PA-42	7/21/81	411-583 404-559		5410 8C13
728	Hydraulic Pump Replacement	PA-42	9/17/82	**		2910 8C15
731	Heater Air Distribution Box Thermal Switch Installation	PA-31T PA-31T1	3/17/82	764-227 764-228		2140 8C21
733	Emergency Exit Window Installation	PA-31T PA-31T1 PA-31T2	1/25/82	189-743	82-11-04	5630 8D3
734	Fuel Scavenge Pump Check Valves Relocation	PA-31T PA-31T1 PA-31T2	12/11/81			2820 8D6
736	Nacelle Fuel Tank Check Valve Installation	PA-42	12/17/82	492-233 57761-06		2820 8D10
740	Ice Vane and Control Circuit Breaker Replacement	PA-42	4/15/83	454-722		3020 8E18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
741	Part I - Wing Flap Travel Restriction and Inspection of Wing Flap Flexible Drive Shaft	PA-31T	3/1/82	**		2750
741	Part II - Wing Flap Operating Procedures	PA-31T PA-31T1	3/1/82	**		2750
742	Engine Oil Hose and Fitting Replacement	PA-42	10/12/82	764-407		7920
754	Air Conditioning Condenser Fan Impeller Replacement	PA-31T PA-31T1	2/14/83	460-102 506-501		2100
764	Pilot's Side Window Inspection	PA-42	7/27/83	**		5610
765	Rivet Installation/Replacement, Tail Fin Fuselage	PA-42	7/11/83	**		5530
766A	Main Landing Gear Slotted Up Lock Hook Brackets Replacement	PA-31T2 PA-31T3	8/15/2017	40616		3210
767	Cleveland 40-106 Main Landing Gear Wheels Replacement	PA-31T PA-31T1	10/25/83	551-775		3240
768A	Main Landing Gear Pivot Shaft Assy Bolts Inspection/Replacement	PA-42 PA-42-720 PA-42-1000	5/24/85	**		3210
773A	Bulkhead (Fuselage Station 332.0) Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	5/3/84	**	96-10-13	5310
776A	Part I - Fuel Quantity Placards Replacement	PA-31T/T1 PA-31T2	2/16/88	**		1100
776A	Part II-Weight And Balance Plotter Replacement	PA-31T/T1 PA-31T2	2/16/88	**		1100
777	Fuel Quantity Placards	PA-42	3/19/84	**		1100
778	Aileron Trim Tab Control Tube & Rudder Cable Retainer Hardware Inspection	PA-42	4/24/84	**		2700
779B	Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection	PA-31T/T1 PA-31T2/T3 PA-42	10/12/87	**	85-08-05 N/A	3200
779B	Part II - Landing Gear Upper Bearing And Strut Assembly Inspection	PA-42	10/12/87	**		3200
785	Inline Fuel Filter Mod - Janitrol	PA-42 PA-42-720	7/19/84	**		7312
788	Avionics (Copilot) Bus Lead Hardware Replacement	PA-42 PA-42-720	7/19/84	**		2457
795A	Electrical Connector Improvement	PA-31T/T1 PA-31T2	4/29/85	**		2430

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
806	Revision of Airspeed Markings Due To Position Error Change	PA-42-720	7/1/85	765-181		3412 9E1
807	Flow Strip Position Inspection	PA-42 PA-42-720	6/19/85	N/A		5721 9E4
812	Rudder Stop Inspection And Replacement	PA-42-1000	11/4/85	75695-05		2720 9F11
814	Generator Control Unit Sleeve Installation	PA-42-1000	3/14/86	765-190		2430 9F18
816C	Ignition Select Mode During Approach and Landing	PA-42-1000	3/28/89	765-306	86-21-10	7428 9G1
817D	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-42-1000	1/15/2015	**		3218
821A	Special Inspection of Fuel Quantity Probes	PA-31T/PA-31T1 PA-31T2/PA-31T3	5/14/86	**		2842 9G23
822	Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-31T/T1/T2 PA-31T3 PA-42 PA-42-720	4/2/86	17766-02	96-21-04	2912 9H3
823	Engine Control Cables Modification	PA-42-1000	3/19/86	765-195		7324 9H6
826A	Elevator Hinge Inspection/Replacement	PA-31T/31T1 PA-31T2/31T3	9/22/86	45253-03		5550 9H17
831	Ice Deflector Vane Modification	PA-31T1 PA-31T3	4/18/86	765-156		7250 9I16
835	Wing - Nose Rib, Station 0.50, Modification And Wire Harness Inspection	PA-42-1000	5/15/86	765-305		5712 9J1
836A	Aluminum Wire Inspection/Replacement	PA-31T/T1	8/26/86	**		2400 9J4
838	Fuel Vent System Installation-Wing Panel Modification	PA-42-1000	6/23/86	765-192		2814 9J11
841A	Main Landing Gear, Forward Side Brace Inspection/Replacement	PA-31T3 PA-42 PA-42-720/720R	10/8/87	**		3218 9J19
842	Rudder Trailing Edge Rework	PA-42-1000	6/23/86	765-200		5523 9K1
843	Part I - Garrett Service Bulletin No TPE331-72-7029	PA-42-1000	3/27/87	**		7201 9K4
843	Part II - Starter/Generator Bracket Retrofit Installation	PA-42-1000	3/27/87	**		7201 9K4
844	Stick Pusher Relay Box Modification	PA-42-1000	7/28/86	765-307		2201 9K12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
845A	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-31T/31T1 PA-31T2	10/9/87	**	96-10-14	3218	9K16
846A	Wing Tip Tank Vent Line Assembly Inspection (Piper Part Number 75389-02)	PA-42-1000	9/19/86	**	86-18-10	2813	9K21
849	Improved Brake Piston/Insulator And Pressurized Brake Reservoir Installation	PA-42-1000	10/8/86	**		3243	9L5
850	Part I - Garrett Service Bulletin No. TPE331-75-7001	PA-42-1000	10/8/86	**		7120	9L7
850	Part II - Left Engine Mount Inspection	PA-42-1000	10/8/86	**		7120	9L7
857	Tailcone Drain Holes, Fuselage Station 332.00	PA-42 PA-42-720 PA-42-720R PA-42-1000	3/10/87	N/A		5305	10A12
859	Nose Gear Shuttle Valve Bracket Installation	PA-42 PA-42-720 PA-42-720R PA-42-1000	3/30/87	765-315		3225	10A18
860	Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement	PA-31T/31T1/31T2 PA-31T3 PA-42	4/14/87	**		3210	10A20
867	Fuel Quantity Sensor Replacement	PA-42-1000	6/24/87	765-335		2840	10C1
869	Fire Extinguisher Annunciator Circuit Modification	PA-42 PA-42-720 PA-42-1000	9/9/87	**		2600	10C5
870	Lear Siegler Power Equipment Corporation (LSPEC) Service Information Letter No. 23090-004-01	PA-42-1000	9/25/87	**		2400	10C7
873	Part I - Engine Mount Inspection And Barrel Nut Replacement	PA-42-1000	12/22/87	**		7100	10D13
873	Part II - Engine Inlet Inspection And Modification	PA-42-1000	12/22/87	**		7100	10D14
874	Nacelle Rework	PA-42-1000	2/8/88	765-320 765-334		5410	10E4
877	Control Column Chain Inspection	PA-42-720 PA-42-720R PA-42-1000	1/6/88	472-684		2702	10F19
881B	TPE 331-14 Engine Idler Gear Bearing Replacement	PA-42-1000	2/19/88	**		7261	10G10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
882	Outboard Flap Transmission Clearance Inspection/Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	3/8/88	89140-02 89141-02		2758 10G14
884	Lock Wiring of V-Band Couplings	PA-31T/31T1 PA-31T2/31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	4/8/88	**		7800 10G20 2100
885	Main Landing Gear Actuator Attach Bolt	PA-42-1000	5/4/88	**		3213 10H1
887	Elevator Skin/Stringer Inspection/Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	6/29/88	**		2730 10H10
888	Rudder Pedal Torque Tube Attach Bracket Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	7/12/88	**		2721 10H13
889	Main Landing Gear Uplock Hook Bracket Inspection and Roller Modification	PA-31T1	7/1/88	41413-79		3230 10H17
897B	Elevator Butt Rib Refinement	PA-31T/31T1 PA-31T2	7/15/97	**		5520 10I21
911	Tip Tank Tailcone Attachment Improvement	PA-42-1000	5/30/89	765-379		5722 10L9
912	Rework of Plug - Main Landing Gear Oleo Tube	PA-42-1000	6/9/89	**		3212 10L11
914	Bleed Air Hose Replacement	PA-42 PA-42-720 PA-42-720R	7/12/89	**		2181 10aA1
922	Main Landing Gear Actuator Attach Bracket Replacement	PA-42 PA-42-720 PA-42-720R	8/16/89	765-372		5740 10aB11
923	Main Landing Gear Actuator Reinforcement Bracket Replacement	PA-31T PA-31T1/31T2 PA-31T3	8/16/89	73786-02	96-21-11	5740 10aB13
925	Addition of Check Valve To Motive Flow Supply Line	PA-42 PA-42-720 PA-42-720R	11/13/89	**		2823 10aB20
929A	Main Landing Gear Upper Strut Housing Inspection	PA-42-1000	8/9/94	75215-04		3211 10aD3
931	Elevator Trim Wheel Shaft Roll Pin Safety Wire Installation	PA-42-720 PA-42-720R PA-42-1000	1/9/90	**		2733 10aD13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
945	Cheyenne Rudder Torque Tube Assembly	PA-42 PA-42-720 PA-42-720R PA-42-1000	10/19/90	**		5541 10aG8
954	Instrument Static Line Installation	PA-31T/31T1 PA-31T2//31T3	3/3/92	**		3410 10aH20
957	Engine Fuel Pump Overboard Drain Line Installation	PA-42 PA-42-720 PA-42-720R	2/24/92	766-257		2820 10aI9
967	Aileron Hinge Inspection and Replacement	PA-31T PA-31T1 PA-31T2 PA-42 PA-42-720 PA-42-720R PA-42-1000	1/24/94	**	96-21-03	5750 10aK15
969A	Upper Main Gear Housing Inspection and Replacement	PA-42 PA-42-720 PA-42-720R	5/19/2022	57680-09		3211
972	Emergency Exit Window Inspection and Replacement	PA-42-1000	9/21/94	**		5620 10aL10
974	Aileron Hinge Inspection and Replacement	PA-31T3	10/19/94	**	96-21-03	5750 10bA1
984	Inspection and Replacement of Outer Side Windows	PA-42 PA-42-720 PA-42-720R	7/14/95	**		5750 10bC10
1032	Elevator Spar Refinement	PA-31T PA-31T1 PA-31T2	7/15/99	766-655		2730 10bL6
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	9/25/2000	**		3714 10cB1
1047	Elevator Spar Refinement	PA-31T3 (T1040)	12/4/2000	766-655		2730 10cC6
1048	Stainless Steel Control Cables	PA-42 PA-42-720 PA-42-1000	1/3/2001	N/A		2702 10cC9
1105A	Rudder Torque Tube Assembly Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	9/22/2003	767-349		2725 10dA22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1125	Elevator Trim Wheel Replacement	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	4/15/2003	43751-000		2733 10dE11
1128	Engine Fuel Valve Inspection (Honeywell OIL OI331-19)	PA-42-1000	2/21/2003	N/A		2800 10dE24
1174	Lock Assembly Inspection / Modification (Cabin Door, Baggage Doors, Nacelle Locker Door)	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	2/15/2007	473-146 88406-002		5200 10eA13
1194B	Nose Baggage Door Components, Periodic Replacement of	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000	4/12/2012	**	2009-13-06	5230
1233C	Periodic Replacement of Main Landing Gear Rod Ends	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000	6/15/2023	762-554 758-440		3210
1235	Data Plate Inspection	PA-31T PA-31T1	11/3/2011	N/A		1120
1248	Engine Oil Cooler Inlet Hose Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	9/5/2012	565-484 565-936		7900
1295	Nose Baggage Door Lock Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000	3/24/2017	88409-002	2009-13-06	5230
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1301	Wiring Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	1/6/2017	N/A		2497
1380	Structural Rework and Inspection	PA-42-1000	1/3/2024	See SB		5100

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1
PA-31T2/31T3
PA-42

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB64

SERVICE BULLETIN INDEX

PA-32 SERIES

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
233	Brake Disc Assembly, Inspection of	PA-32-260	6/8/66	757-039V		3240	3E2
237	Rudder Trim Installation Modification	PA-32-260	11/1/66	757-085V		2720	3E9
239	Windshield Collars, Inner And Outer, Replacement of	PA-32-260	12/12/66	757-095		5610	3E11
240	Balance Weight Assembly Aileron And Stabilator, Inspection of, For Corrosion	PA-32-260	12/13/66		67-12-06	2710	3E12
244	Heater Duct Tunnel Modification Cabin	PA-32-260/300	2/2/67	757-110V		2140	3E19
248	Torque Links, Main Landing Gear	PA-32-260/300	5/12/67	**	67-20-04 70-18-05	3210	3F2
249A	Fuel System Improvement Kit	PA-32-260/300	3/1/68	757-139V	67-26-02	2800	3F6
251D	Fuel Tank Inspection	PA-32-260/300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T	2/24/2009	757-572V	67-26-03	2810	3F10
252	Mixture Control Cable, Inspection of	PA-32-300	5/15/67	65451-05V		7320	3F12
253	Fuel Line Modification, Tip Tank	PA-32-260/300	7/7/67	757-151V 757-152V	67-26-02	2810	3F14
259	Storm Window Placard, PA-32-260 Cherokee	PA-32-260	11/7/67	757-314V		5610	3G2
260	Duct, Engine Air Inlet, Replacement of The	PA-32-300	11/8/67	760-159V	67-30-06	7160	3G4
261	Aft Spar Wing Attachment Bolts, Inspection of	PA-32-260/300	11/10/67	760-162V		5710	3G5
275	Electrical System, Modification of The	PA-32-260/300	6/19/68	**		2400	3H8
279	Bridle Cable, Servo. Inspection of And Modification To	PA-32	6/24/68	**		2210	3H16
281	Artificial Horizon, R.C. Allen 3", Case Leakage of	PA-32-260/300	7/10/68	**		3420	3H24
282	Mixture Control Cable, Replacement	PA-32-300	8/12/68	760-235V		7320	3I4
285	Stop Assembly, Fuel Selector Control	PA-32-260	11/22/68	760-251V		2820	3I11
291	Flight Manual Revision	PA-32S-300 PA-32-260/300	3/28/69	760-313V		3250	3J5
295	Pin, Retaining, Control Wheel	PA-32-260 "B" PA-32-300 "B"	4/30/69	**	69-15-01	2700	3J14
305	Carburetor Drain Plugs Inspection	PA-32-260	11/25/69			7310	3K12
311A	Selector Valve, Fuel, Modification	PA-32-260/300 PA-32S-300	4/28/70	760-438V		2820	3L3
317	Rib Inspection, Vertical Fin	PA-32-260/300	11/18/70	760-451V		5530	3L14
321A	Throttle Knob Roll Pin Retaining Ring	PA-32-260/300	11/2/70	756-044V		7610	4A1
322	Vacuum Pump Adapter Drive Assembly	PA-32-260/300	9/29/70	760-477V		3710	4A3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
327	Stabilator Balance Weight Tube Assembly Inspection	PA-32-260/300 PA-32S-300	12/9/70	**	70-26-04	2740 4A16
329A	Belt Attachment Modification, Seat	PA-32-260/300 PA-32S-300	3/25/71	760-515V	71-09-05	5340 4A23
332	Switch, Electric Trim, Inspection And Modification	PA-32-260/300	4/16/71	760-517V	72-17-15	2730 4B7
337	Seat Frame Tube Replacement, Vertically Adjustable	PA-32-260/300	3/11/71	**		2510 4B20
342	Fuel System Instructions And Modification	PA-32-260/300 PA-32S-300	9/7/71	760-560V	77-12-01	2800 4C6
350	Stabilator Hinge Attaching Bolts, Inspection of	PA-32-260/300	3/30/72	**		5550 4D7
356	Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement	PA-32-260/300 PA-32S-300	9/1/72	**		7160 4E7
357A	Terminal Replacement, Alternator Output Wire	PA-32-260/300	11/14/72	588-398V		2420 4E9
360	Hose System Modification, Air Induction	PA-32-260/300 PA-32S-300	11/9/72	**		7160 4E14
368	Antenna Protector, Transponder, Installation	PA-32-260/300	11/22/72	760-697V		3450 4F7
376	Fuel Selector Control System Modification	PA-32-260/300 PA-32S-300	4/19/73	**	77-12-01	2820 4F18
387	Alternator Installation Modification	PA-32-260/300	2/4/74	760-742V		2430 4G15
395	Rudder Pedal, Warning Improper Use of	PA-32-260/300	11/9/73	757-436V		2720 4H9
403	Stall Warning Light Relocation	PA-32-260/300	1/29/74	760-808V	74-09-02	2780 4I9
412	Glove Compartment Modification	PA-32-260/300	4/9/74	581-025		2510 4J12
427	Air Conditioning System Modification	PA-32-300	8/9/74	760-822V		2150 4K23
428	Steering System Modification	PA-32-260/300	7/30/74	760-885V	74-18-13	3250 4L1
444	Fuel Valve Replacement	PA-32-260/300	1/15/75	760-895V		2820 5A19
448	Cable Operation Inspection, Throttle And Mixture Control	PA-32-260/300	2/19/75	**		7320 5B4
449A	Alternator (Chrysler) Modification And Wire End Terminal Replacement	PA-32-260/300	5/7/75	558-398V		2430 5B8
463	Door Forward Baggage, Inspection And Modification	PA-32-260/300	4/17/75	760-972V	75-10-03	5230 5C14
469A	Oil Cooler Assembly Inspection	PA-32-300	9/5/75	**		7920 5D4
475	Instrument Panel Dimmer Control Assembly Modifications	PA-32-260/300	7/10/75			3310 5E1
503A	Fuel Tank Line Assembly, Inboard, Inspection of	PA-32R-300	10/11/77	**	76-11-09	2810 5H5
510B	Landing Gear, Nose, Trunnion Modification	PA-32R-300	8/31/76	761-074V	76-15-08	3220 5I1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
519A	Fuel Selector Valve Inspection And Replacement	PA-32-260/300 PA-32R-300	9/2/76	**	76-18-04	2820	5I21
520	Muffler Shroud Inspection	PA-32-300 PA-32R-300	10/18/76	**		7810	5I23
524	Induction Air Box Bolt Replacement	PA-32-300 PA-32R-300	2/2/77	**		7160	5J9
533	Fuel Gauge Calibration Inspection	PA-32-260/300	1/6/77	**	77-01-01	2840	5L8
537	Throttle Linkage Bolt Replacement	PA-32-300 PA-32R-300	1/12/77	**	80-14-02	7610	5L17
538	Engine Control Cable Inspection	PA-32-260/300 PA-32R-300	1/14/77	**		7610	5L20
541	Throttle Attachment Inspection	PA-32-260	2/15/77	**		7610	6A5
543	Starter/Magneto Switch Inspection And Replacement	PA-32-260/300 PA-32R-300	2/9/77	757-597V		7410	6A9
548	Engine Control Rod End Bearing Inspection	PA-32-260/300 PA-32R-300	3/7/77	**	77-23-03	7230	6A23
556	Electric Trim Switch Modification	PA-32-260/300	7/25/77	756-047		2730	6B20
557	Fuel Line Modification	PA-32-260	5/19/77	63882-17V		2810	6B23
563	Landing Gear, Nose, Actuator Rod End Bearing Change	PA-32R-300	5/13/77	452-357V		3230	6C14
565	Horizontal Situation Indicator, Modification To Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13	PA-32-260/300 PA-32R-300	6/2/77	**		3420	6C20
571A	Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection	PA-32-260 PA-32-300 PA-32S-300	10/20/77	**	77-12-01	2810	6E5
580	Engine Cowling Scoop Drain Hole	PA-32-260	10/19/77			7100	6F13
586B	Engine Oil Coolers (Left and Right), Inspection	PA-32R-300 PA-32RT-300	7/24/78	763-859V	78-01-03 78-16-08	7920	
593	Nose Landing Gear Lock Hook Replacement	PA-32R-300	6/9/78			3230	6H1
616	Hydraulic Pressure Switch Inspection And Nose Gear Actuator Rod End Bearing Replacement	PA-32RT-300 PA-32RT-300T	5/1/79			2930 3230	6J19
619	Control Column Stop Modification	PA-32RT-300 PA-32RT-300T	9/22/78	763-895V	78-22-07	2710	6K4
622	Pitch Trim Re-Wiring On Aircraft Equipped With Altimatic IIIC	PA-32-260/300 PA-32R-300	9/28/78	35669-60 35669-61		2210	6K14
624	Loading Limitation Placard And Manual Change	PA-32-260/300 PA-32S-300	5/24/79	763-911V		800	6K19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T	2/25/80			3450 6L14
646A	Fuel Tank Vent Modification And Vent Hose Replacement	PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T	3/5/80	**	80-14-01	2810 7C17
652	Fuel Flow Indicator Line- Replacement	PA-32RT-300T	6/15/79	67700-348	79-13-04	7330 7D9
655	Firewall Reinforcement	PA-32RT-300T	8/27/79	763-935V		5410 7D15
656	Window Curtain Rod Support Area Inspection	PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T	9/13/79	**		5520 7D17
657A	Turbo-Charger Exhaust Coupling And Tailpipe Flange Inspection	PA-32RT-300T	8/14/79	556-108		7810 7E1
669	Altimatec IIC Autopilot Trim Servo Cable Alignment Modification	PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T	1/14/80	**		2210 7F10
675	Throttle Operation Pre-And Post-Flight Check	PA-32RT-300T PA-32R-301T	2/19/80	67639-013V		7610 7G21
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0 7H4
681	Boom Microphone Isolation Relay	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	4/24/80	456-703	80-14-03	2350 7H11
701	Rudder/Aileron Interconnect Bracket Interference	PA-32-301 PA-32-301T	12/4/80	68525-08V 419-948		2720 2710 7K16
703	Aileron Balance Weight Attachment Inspection and Rework	PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T	3/4/81	764-091V		2710 7K20
738	Nose Landing Gear Actuator Rod End Replacement	PA-32R-300 PA-32R-301 SP PA-32R-301T SP PA-32RT-300 PA-32RT-300T	4/20/82 4/20/82	452-729V 452-729V		3230 3230 8D14 8D15
738	Addendum 1 - Nose Landing Gear Actuator Rod End Inspection / Replacement	PA-32R-300 PA-32R-301 SP PA-32R-301T SP PA-32RT-300 PA-32RT-300T	11/23/87	452-729		3230 8D15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
747	Nose Landing Gear Actuator Attach Bolt Replacement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	9/17/82	86700-46V 402-869V		3230	8G3
772	Fuel Selector Inspection/Replacement	PA-32R-300 PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T	4/6/84	69735-05V		2820	8J3
789B	Aft Inboard Wing Access Panel & Aft Wing Spar Modification	PA-32-260 PA-32-300	12/3/2018	764-998V 765-106V	SAIB CE-11-12	5711	
798	"TURBO" Marking Removal	PA-32RT-300T	12/11/84	N/A		1110	9B19
801	King Auto Pilot Servo Bridle Clamp Installation	PA-32-301/301T PA-32R-301/301T	12/11/84	**		2200	9C6
804	Battery Strap Installation	PA-32-301T	4/26/85	765-157		2430	9D12
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	3/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-32-260 PA-32-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T	5/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-32-301T	8/26/86	**		2400	9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800	10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32R-301/301T	2/17/87	**		5550	10A9
866A	Part I - Back Up Landing Gear Extender Removal	PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	3/4/88	765-199		3236	10B22
866A	Part II - Alternate means of Compliance	PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	3/4/88	N/A		3236	10B22
884	Lock Wiring of V-Band Couplings	PA-32-301T PA-32R-301T PA-32RT-300T	4/8/88	**		7800 2100	10G20
886	Wing Spar Inspection	PA-32-260/300	6/8/88	**		5711	10H3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
896	Shoulder Harness Installation & Usage	PA-32-260/300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	11/28/88	**		5340 10I13
904	Textron Lycoming Service Bulletin No. 484	PA-32-301T PA-32RT-300T PA-32R-301T	3/20/89	**		7821 10K1
906	Oildyne Hydraulic Pump Replacement	PA-32R-301 PA-32R-301T	4/10/89	**		2911 10K12
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-32-301T PA-32R-301T	3/7/94	**	94-17-13	6113 10aC1
927	Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs	PA-32-300 PA-32S-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T	12/4/89	**	2001-23-08	6113 10aC18
933A	Trunnion Replacement	PA-32R-301	2/20/90	67054-03		3222 10aD21
938	Wire Protection	PA-32R-301 PA-32R-301T	6/12/90	189-531 488-698		3262 10aE15
946	Forward Left Fuselage Frame Inspection and Replacement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	3/4/91	766-244		5311 10aG11
952	Textron Lycoming Service Bulletin No. 499 "Installation of One-Piece Exhaust Pipe"	PA-32RT-300T PA-32-301T PA-32R-301T	5/9/91	**		7821 10aH11
955	Engine Mount and Nose Landing Gear Attachment	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	3/3/92	766-252 766-253	93-05-10	7120 10aH23
965	Inspection of Flap Lever and Bolt	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	9/1/93	**		2750 10aJ22
968	Exhaust System Hardware and Gasket Replacement	PA-32R-301	3/11/94	**		7810 10aK21
970	Defrost System Modification	PA-32R-301	4/18/94	**		7810 10aL2
971	Exhaust System Inspection and Replacement	PA-32R-301	9/2/94	**		7810 10aL5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
973	Engine Lower Cowling Modification	PA-32R-301	9/30/94	**		7810 10aL19
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	12/12/94	**	SAIB CE-11-12	5740 10bA12
986	Inspection for Proper Orientation of Battery Vent Tube Assembly	PA-32R-301 II HP	9/6/95			2430 10bC22
990	Pacific Scientific Seat Belt Replacement	PA-32R-301 II HP	1/3/96	**		5346 10bD12
993	KLN-90B GPS Wiring Modification	PA-32R-301	3/18/96	**		3441 10bE4
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-32R-301 II HP	9/17/96	**		5311 10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-32R-301 II HP	8/11/97			7162 10BG4
1006A	Corrosion Inspection of Main Spar Behind Fuel Tanks	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T PA-32R-301T II TC	9/25/24	**	SAIB CE-11-12	530 10bG4
1009	Replacement of the Engine Induction Air Inlet Elbow at the Fuel Injector Servo	PA-32R-301 II HP	10/6/97	**		7161 10bG18
1015A	Replacement of the Ammeter Shunt Wire Fuse Assemblies	PA-32R-301 II HP	6/11/98	101166-10 101166-11		2434 10bH14
1018A	Product Improvement, Winterization Plate Kit(Revised)	PA-32R-301T II TC	6/7/99	766-653		7921 10bI2
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-32R-301 II HP PA-32R-301T II TC	7/10/98	758-696		2563 10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32R-301 SP PA-32R-301 II HP	9/22/98	460-632	99-05-09	7167 10bI20
1023	Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	10/8/98	**		2902 10bJ6
1024	Replacement of Control System Spacers and Inspection of Aileron Cables	PA-32R-301 II HP PA-32R-301 II TC	10/1/98	**		2712 10bJ12
1025	Replacement of the Alternate Air Door	PA-32R-301T II TC	10/21/98	**		7164 10bJ16
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	11/5/98	753-910		3711 10bJ20
1028	Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips	PA-32R-301 II HP PA-32R-301T II TC	12/2/98	**		5755 10bK12
1030A	Distribution of Textron Lycoming Service Bulletin 538A, "Air Inlet tube Replacement" and Drain Improvement	PA-32R-301T II TC	9/10/99	**		7168 10bK21
1031	Horizon Engine Instruments Repair or Replacement	PA-32R-301 II HP PA-32R-301T II TC	7/14/99	**		7710/7720 10bL3
1035A	Distribution of Textron Lycoming Service Bulletin 529B, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3"	PA-32-301T PA-32R-301T SP PA-32R-301T II TC PA-32RT-300T	3/22/2007	**	2003-14-03	7311 10bL16
1036	Garmin Service Bulletin No. 9905 'GNS430 Mod. 1"	PA-32R-301 II HP PA-32R-301T II TC	10/1/99			3426 10cA1
1039	Manifold Pressure Gauge (MAP) Wiring Modification	PA-32R-301 II HP PA-32R-301T II TC	2/14/2000			7715 10cA15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-32-260 PA-32-300/-32S-300 PA-32-301 PA-32-301T PA-32RT-300 PA-32RT-300T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	9/25/2000	**		3714 10cB1
1048	Stainless Steel Control Cables	PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC	1/3/2001	N/A		2702 10cC9
1049	Engine Baffle Brace Installation	PA-32R-301 II HP PA-32R-301T II TC	4/9/2001	766-684		7236 10cC13
1081A	Horizon Aerospace Analog Instrument Pointer Calibration	PA-32R-301 II HP PA-32R-301T II TC	12/9/2002	N/A		7700 10cl12
1083C	S-TEC System 55X Autopilot	PA-32R-301 II HP PA-32R-301T II TC	5/30/2002	767-318		2218 10cl19
1092B	Engine Mount Inspection	PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC	4/28/2003	38729-021 38729-022 104642-002		7121 10cK22
1131A	Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004)	PA-32-260	1/18/2016	65489-002 65490-000		3210
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	6/10/2003	**		2800 10dG5
1135	GMA-340 Audio Panel Wiring	PA-32R-301 II HP PA-32R-301T II TC	7/16/2003	N/A		2370 10dG13
1137	Stabilator Balance Weight Tube Assembly	PA-32R-301 II HP PA-32R-301T II TC	11/6/2003	N/A		2749 10dG20
1139A	Control Wheel Attachment Inspection	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	4/9/2004	**	4-14-12	2701 10dH4
1141	Clip Nut Replacement	PA-32R-301 II HP PA-32R-301T II TC	12/9/2003	477-640		5351 10dH15
1145A	Autopilot Installation and Testing	PA-32-301FT PA-32-301XTC	2/17/2004	600-520 692-411		2210 10dl4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1151E	4130N Steel Hardness Discrepancy	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	6/9/2004	**		5741 10dJ4
1161D	Rib Assembly Inspection and Modification - Aft Wing, WS 49.25	PA-32R-300 PA-32RT-300/300T PA-32R-301 SP PA-32R-301T Turbo SP PA-32R-301 II HP PA-32R-301T II TC	2/19/2024	767-397 767-398		5712 10dK19
1162B	European Requirements for Avidyne Entegra Equipped PA-28 and PA-32 Model Aircraft	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	9/7/2006	652-591 767-418 767-422		3400 10dL1
1169A	Tailcone Pressure Duct Support Strap	PA-32-301FT PA-32-301XTC	1/17/2007	767-547		2100 10dL22
1171	Stormscope Erroneous Strike Indication	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	9/20/2006	767-548		3400 10eA3
1178	Nose Gear Forging Inspection / Replacement	PA-32R-301 II HP PA-32R-301T II TC	9/24/2007	67050-002		3222 10eB10
1179	Main Landing Gear Cylinder Assembly Inspection	PA-32-301FT PA-32-301XTC	2/1/2008	65490-000		3213 10eB14
1180A	V-Band Exhaust Coupling Inspection	PA-32R-301T II TC	3/14/2007	**		7200 10eB18
1187	Voltage Suppressor Replacement	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	2/8/2008	88432-002 (Kit)		3400 10eD4
1197E	Control Wheel Shaft Inspection	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32S-300	11/2/2017	**	2010-15-10	2710

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1198A	Fuel Selector O-Ring	PA-32-260 PA-32-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	4/20/2009	485-330 485-332		2823
1199	Main Landing Gear Torque Link Inspection	PA-32-260 PA-32-300	2/16/2009	78033-000 63312-002	72-08-06	3213
1216B	Aileron Rib Inspection	PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	9/5/2012	38650-007 38650-008		5755
1242A	Rudder Pedal Assembly Inspection	PA-32-260 PA-32(S)-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	5/12/2020	99938-000 99938-001		2710
1244C	Aft Wing Attach Fitting Inspection Requirements	PA-32 Series PA-32R Series PA-32RT Series PA-32S Series	12/3/2018	764-998		5740
1245A	Stabilator Control System Inspection	PA-32 Series PA-32R Series PA-32RT Series PA-32S Series	11/28/2012	N/A	2013-02-03	2730
1247B	Garmin SafeTaxi® Limitation	PA-32-301FT PA-32R-301T II TC	3/13/2019	N/A		3420

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1251	Stabilator Trim Barrel Inspection	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32S-300	4/10/2013	63530-000		5755
1280A	H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	4/29/2016	459-887		2620
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-32-300 PA-32-301 PA-32-301FT PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32RT-300	10/30/2015	N/A		7310
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1304B	Main Wing Spar Inspection	PA-32-260 PA-32-300	12/2/2021	765-106 88692		5740
1342A	Stabilator Fitting Inspection	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	11/2/2021	62645-004		5510
1355B	Tee Bar Assembly Inspection	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T	8/18/2022	28F40A003		2701

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1366	Main Wing Spar Hardware Inspection	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T PA-32S-300	5/14/21	96352		5711
1372	Main Wing Spar Inspection	PA-32-260/300 PA-32S-300	4/4/24	88731-701 / -702	Pending	5711
1375D	Periodic Replacement of Main Landing Gear Attachment Hardware	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC	1/29/2023	**		3210
1377B	Main Wing Spar Inspection at the Landing Gear Truss Bracket	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	9/24/2024			5740
1412	Main Wing Spar Inspection	PA-32-300 PA-32-301FT PA-32-301XTC PA-32-301/-301T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T	5/9/2024			5711

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
251D	Fuel Tank Inspection	PA-34-200	2/24/2009	757-572V		2810 3F10
350	Stabilator Hinge Attaching Bolts Inspection of	PA-34-200	3/30/72	**		5550 4D7
352	Pitot Static System Lines Replacement	PA-34-200	6/13/72	760-614V 760-615V		3030 4D12
357A	Terminal Replacement, Alternator Output Wire	PA-34-200	11/14/72	588-398V		2420 4E9
358	Induction Air Box Valve Inspection	PA-34-200	7/31/72	96776-00V	72-17-01	7160 4E11
359	Pitot Static System Instrument Lines Modification	PA-34-200	10/10/72	760-679V		3410 4E13
364A	Circuit Breaker Replacement, Fuel Pump, Electric	PA-34-200	11/16/72	454-707		2820 4F1
367	Stabilator Tip Balance Weight Inspection	PA-34-200	8/25/72	**	72-18-06	2740 4F5
368	Antenna Protector, Transponder Installation	PA-34-200	11/22/72	760-697V		3450 4F7
369	Wing Assembly, Aft, Inspection and Modification of	PA-34-200	9/8/72	760-696V	73-11-02	5110 4F8
370	Fuel Injector Servo Mounting Nut Inspection	PA-34-200	9/12/72			7310 4F10
373A	Exhaust System Inspection	PA-34-200	6/12/73	**	73-14-02	7810 4F12
374	Induction Air Box Replacement	PA-34-200	2/2/73	760-722V	72-17-01	7160 4F14
382	Fuel Tank Vent Systems, Inspection	PA-34-200	8/22/73			2810 4G2
390A	Trim Tab, Rudder Servo, Inspection	PA-34-200	5/30/73	**	73-13-01	2210 4G20
395	Rudder Pedal, Warning, Improper Use of	PA-34-200	11/9/73	757-436		2720 4H9
406	Oleo Struts, Main Landing Gear, Inspection and Maintenance of	PA-34-200	11/16/73	**	73-11-02	3210 4I15
412	Glove Compartment Modification	PA-34-200	4/9/74	581-025		2510 4J12
429	Fuel Line Chafing—Engine Nacelles, Prevention of	PA-34-200	8/12/74	760-877V 760-886V	74-17-08	2810 4L3
437A	Spar Straps, Inspection of Seneca	PA-34-200	10/16/75			5710 5A1
438	Fuel Quantity, Revised Usable	PA-34-200/200T	8/6/75	**	75-20-03	2840 5A6
447	Baggage Door Inspection and Modification to the Forward	PA-34-200/200T	2/7/75			5230 5B1
475	Instrument Panel Dimmer Control Assembly Modification	PA-34-200/200T	7/10/75			3310 5E1
483	Turbocharger Oil Hose Modification, Seneca II	PA-34-200T	11/12/75	761-023V	75-25-03	8010 5E23
491	Pneumatic Deicer Tubing Inspection	PA-34-200T	2/19/76	761-018V		3700 5F16
502A	Heated Lift Detector Inspection	PA-34-200T	7/1/76	69669-156V 472-890V		3260

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
542	Induction Air Box Filter Locator Change	PA-34-200T	2/25/77	761-130V		7160 6A7
545	Fuselage Rivets, Inspection and Installation	PA-34-200/200T	2/23/77	522-898		5330 6A13
548	Engine Control Rod End Bearing Inspection	PA-34-200/200T	3/7/77	452-557	77-23-03	7230 6A23
553	Avionics Bus Bar Inspection and Modification	PA-34-200/200T	4/15/77	761-133V		2450 6B13
555	Rudder Cable Guard Inspection, Seneca II	PA-34-200T	3/9/77	62701-72V		2720 6B17
565	Horizontal Situation Indicator Modification to Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13	PA-34-200T	6/2/77	**		3420 6C20
576	TCM TS10360 Series Engines To Disseminate Information	PA-34-200T	11/30/77			7200 6E23
579	Inspection of Vertical Fin and Stabilator Attachment Fittings	PA-34-200/200T	11/14/77	**	80-09-04	5550 6F5
584	Engine Instruments and Fuel Flow Line Inspection and Modification	PA-34-200T	12/13/77	**		7330 6F20 7700
596A	Fuel Line Inspection and Modification	PA-34-200T	9/22/78	**	78-21-03	2810 6H6
601	Inspection of Battery Box Vent	PA-34-200T	8/11/78		78-21-03	2430 6H20
602	Inspection of the Main Wing Spar Attaching Nuts	PA-34-200T	7/3/78	404-532V		5750 6I1
611	Hose Assembly Inspection and Replacement	PA-34-200T	11/14/78	**		2820 6J5
630A	Collins VIR-350 and VIR-351 Navigation Receiver Modification	PA-34-200T	2/25/80			3450 6L14
633B	Forward Baggage Door Inspection and Modification	PA-34-200 PA-34-200T	10/3/80	36521-02V	88-04-05	5230 7A10
656	Window Curtain Rod Support Area Inspection	PA-34-200T	9/13/79	**		5520 7D17
668	Avionics Master Relay Wiring Inspection	PA-34-200T	11/12/79			2450 7F6
669	Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification	PA-34-200T	1/14/80	**		2210 7F10
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15 0 7H4
681	Boom Microphone Isolation Relay	PA-34-200T	4/24/80	456-703 180-500	80-14-03	2350 7H11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
711	Missing Rivets, Left Hand Fuselage Station 108	PA-34-220T	3/27/81	**		5330	8A3
712A	Fuel Selector Valve Inspection and Cable Clevis Replacement	PA-34-220T	4/20/81	491-960V 764-121V		2820	8A7
718A	Seneca III Surface Deicer System	PA-34-220T	10/29/81	764-222V		3000	8B1
732	Landing Gear Selector Switch Shield	PA-34-220T	11/11/81	87431-02V 488-702V	82-04-08	3200	8C23
758	Radio Master Relay Replacement	PA-34-220T	2/14/83			2450	8H10
762	Exhaust System Heat Exchanger Inspection	PA-34-200	5/26/83	78463-10V 78463-18V	83-14-05	7810	8H21
787C	Main Landing Gear Trunnion Housing	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T IV	11/7/2000	2599-002	94-13-11	3211	8L8
798	"TURBO" Marking Removal	PA-34-200T	12/11/84	N/A		1110	9B19
801	King A/P Servo Bridle Clamp Installation	PA-34-220T	12/11/84	**		2200	9C6
805A	TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration)	PA-34-200 PA-34-200T PA-34-220T	3/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-34-200T	5/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-34-200 PA-34-200T PA-34-220T	8/26/86	**		2400	9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800	10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-34-200 PA-34-200T PA-34-220T	2/17/87	**		5550	10A9
872	Forward Baggage Compartment Door Latch Spring Installation And Door Assembly Inspection	PA-34-200 PA-34-200T PA-34-220T	11/9/87	765-330	88-04-05	5230	10D5
884	Lock Wiring of V Band Couplings	PA-34-200T PA-34-220T	4/8/88	**		7800 2100	10G20
893	Nose Gear Centering Attach Belt	PA-34-200 PA-34-200T	10/11/88	400-910	92-13-05	3220	10I3
896	Shoulder Harness Installation & Usage	PA-34-200 PA-34-200T PA-34-220T	11/28/88	**		5340	10I13
899	Rudder Torque Tube Fitting Replacement	PA-34-200 PA-34-200T PA-34-220T	2/10/89	**	92-08-04	2720	10J8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
905	Auxiliary Primer Switch Replacement	PA-34-200T PA-34-220T	4/6/89	**		7315 10K7
906	Oildyne Hydraulic Pump Replacement	PA-34-200T PA-34-220T	4/10/89	**		2911 10K12
938	Wire Protection	PA-34-220T	6/12/90	189-531 488-698		3262 10aE1
956	Main Landing Gear Trunnion Attach Fittings	PA-34-200 PA-34-200T PA-34-220T	3/3/92	**		3211 10aH10
965	Inspection of Flap Lever and Bolt	PA-34-200 PA-34-200T PA-34-220T	9/1/93	**	96-10-03	2750 10aJ3
976	Inspection for and Replacement of Components with Suspect "O" Rings	PA-34-220T	12/9/94	**		2911 10bA10
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-34-200 PA-34-200T PA-34-220T	12/12/94	**	SAIB CE-11-12	5740 10bA12
983	Station 49.5 Frame Inspection	PA-34-220T	5/25/95	**		5310 10bC4
987	Prop Deice Timer Wiring Inspection	PA-34-220T III PA-34-220T IV	9/11/95	**		3000 10bD1
988	Pneumatic Deice Switch Relocation	PA-34-220T III PA-34-220T III (28V) PA-34-220T IV	11/9/95	558-790 179-771		3013 10bD4
989	Inspection for Stabilator Trim Screw Assembly Attachment Hardware	PA-34-220T IV	12/20/95	**		2791 10bD8
990	Pacific Scientific Seat Belt Replacement	PA-34-220T IV	1/3/96	**		5346 10bD12
993	KLN-90B GPS Wiring Modification	PA-34-220T IV	3/18/96	**		3441 10bE4
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-34-220T (IV)	9/12/96	**		5311 10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-34-220T (V)	8/11/97			7162 10bG1
1010	Replacement of Fuel Selector Levers	PA-34-220T V	11/3/97	766-645		2822 10bG21
1013	Replacement of Crankcase Breather System	PA-34-220T V	2/5/98	**		7925 10bH6
1014	Replacement of Battery Power Fuse	PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	3/2/98	461-681		2436 10bH11
1017	Alternator Regulator Wiring Diagram	PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	4/10/98	**		2436 10bH21
1020	Inspection of the Artex 110-4 ELT and ELT Attachment Bracket	PA-34-220T IV PA-34-220T V	7/10/98	**		2563 10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	9/22/98	460-632	99-05-09	7167 10bI20
1023	Inspection of Landing Gear Cylinder and Distribution of Parker Hannifin Service Bulletin SB7063	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	10/8/98	**		2902 10bJ6
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-34-200 PA-34-200T PA-34-220T III(28V) PA-34-220T IV	11/5/98	753-910		3711 10bJ20
1031	Horizon Engine Instruments Repair or Replacement	PA-34-220T V	7/14/99	**		7710 10bL3 7720
1039	Manifold Pressure Gauge (MAP) Wiring Modification	PA-34-220T V	2/14/2000			7715 10cA15
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	9/25/2000	**		3714 10cB1
1042	Heated Deice Panel Inspection	PA-34-220T V	6/9/2000	31637-003		3041 10cB10
1043	Deice Control Valve Replacement	PA-34-220T V	7/13/2000	**		3014 10cB15
1048	Stainless Steel Control Cables	PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	1/3/2001	N/A		2702 10cC9
1081A	Horizon Aerospace Analog Instrument Pointer Calibration	PA-34-220T V	12/9/2002	N/A		7700 10cI12
1083C	S-TEC System 55X Autopilot	PA-34-220T V	5/30/2002	767-319		2218 10cI19
1097A	Pneumatic Deicer Deflate Valve Assembly Replacement	PA-34-220T V	2/25/2002	592-676		3010 10cL16
1100A	Stabilator Trim Link Assembly	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	10/31/2001	96003-000		5511 10cL12
1113	Nose Gear Down Lock Pin Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	6/5/2002	95829-000 95830-000		3235 10dC3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1123D	Nose Gear Inspection and Product Improvements	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	1/26/2022	767-357 767-358 767-359 767-368 693-215 95394-005	2005-13-16 2022-09-13	3220
1127B	Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110b)	PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	4/18/2005	767-367 **	3-11-14	2800 10dE16
1130	Vertical Fin Contour / Rivet Check	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	11/11/2003	767-369		5300 10dF8
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-34-200	6/10/2003	**		2800 10dG5
1135	GMA-340 Audio Panel Wiring	PA-34-220T V	7/16/2003	N/A		2370 10dG13
1136	Auxiliary Fuel Pump Switch	PA-34-200T	9/2/2003	588-006 (99377-029)		2800 10dG17
1137	Stabilator Balance Weight Tube Assembly	PA-34-220T V	11/6/2003	N/A		2749 10dG20
1139A	Control Wheel Attachment Inspection	PA-34-220T V	4/9/2004	**	4-14-12	2701 10dH4
1141	Clip Nut Replacement	PA-34-220T V	12/9/2003	477-640		5351 10dH15
1146	Vertical Fin Aft Spar Reinforcing Angle Low Edge Distance Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	11/5/2004	**		5300 10dI10
1151E	4130N Steel Hardness Discrepancy	PA-34-220T V	6/9/2004	N/A		5741 10dJ4
1157A	Pressurized Magnetos & Tachometer Sensor Assemblies; Field Upgrade	PA-34-220T V	6/20/2005	**		7414 10dK1
1161D	Rib Assembly Inspection and Modification - Aft Wing, WS 49.25	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	2/19/2024	767-397 767-398		5712 10dK19
1184	Inspection of Engine Mount for Evidence of Contact with Oil Line Fitting	PA-34-220T V	6/15/2007	37105-000		7120 10eC12
1187	Voltage Suppressor Replacement	PA-34-220T V	2/8/2008	88432-002 (Kit)		3400 10eD4
1197E	Control Wheel Shaft Inspection	PA-34-200 PA-34-200T PA-34-220T III	11/2/2017	**	2010-15-10	2710

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
		PA-34-220T III (28V) PA-34-220T IV PA-34-220T V				
1223	Wire Screen Replacement	PA-34-220T V	11/10/2010	**		2126
1225	Inaudible Traffic Information System (TIS) or Traffic Advisory System (TAS) Aural Alerts	PA-34-220T V	7/26/2011	N/A		3440
1241	Wastegate Clearance Inspection	PA-34-220T V	5/10/2012	**		7120
1242A	Rudder Pedal Assembly Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	5/12/2020	99938-000 99938-001		2710
1244C	Aft Wing Attach Fitting Inspection Requirements	PA-34 Series	12/3/2018	764-998		5740
1245A	Stabilator Control System Inspection	PA-34 Series	11/28/2012	N/A	2013-02-03	2730
1247B	Garmin SafeTaxi® Limitation	PA-34-220T V	3/13/2019	N/A		3420
1252	Garmin G600 Systems Software Upgrade to Version 0942.40	PA-34-220T V	10/2/2013	N/A		3420
1254	Stabilator Drain Hole Inspection	PA-34-220T V	1/14/2013	N/A		5755
1270A	Re-enablement of GDL 69, GSR 56, and/or GTS 825 for EASA Importation	PA-34-220T V	6/4/2014	N/A		3420
1274	Control Wheel Bushing Inspection	PA-34-220T V	2/9/2015	68273-002		2701
1280A	H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1	PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	4/29/2016	459-887		2620
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-34-200	4/12/2019	N/A		7414
1285	Propeller Deice Timer Inspection	PA-34-220T IV PA-34-220T V	8/14/2015	N/A		3060
1286A	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-34-200	10/30/2015	N/A		7310
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1303A	Diode Module Installation	PA-34-220T V	10/15/2018	681-020		3410
1337	Emergency Power Supply Modification	PA-34-220T V	2/15/2019	107279-002	2020-24-09	2497
1355B	Tee Bar Assembly Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	8/18/2022	28F40A003		2701
1366	Main Wing Spar Hardware Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	5/14/2021	96352		5711
1368	Heater Fuel Pump Leak Inspection and Replacement (Hartzell ASB 85)	PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	7/14/2021	**		2140
1377B	Main Wing Spar Inspection at the Landing Gear Truss Bracket	PA-34-200 PA-34-200T II PA-34-220T III PA-34-220T IV PA-34-220T V	9/24/2024			5740
1402	Airworthiness Directive 2021-08-15	PA-34-220T V	7/2/2024		2021-08-15	3445
1411A	Autopilot Rigging Inspection	PA-34-220T V	12/4/2023			2700
1413	Aft Wing Spar Attach Fitting Inspection	PA-34-220T V	4/18/2024	66762-000 62448-002/-003 68621-002/-003 88365-002 / 87584-000		5741

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
396	Propeller Stop, Low Pitch	PA-36-285	1/29/74			6110 4H11
397	Fuel Quantity Placards, Revised	PA-36-285	5/2/74	**	74-13-07	2840 4H12
402	Starter Shaft Inspection Tiara (Continental Aircraft Engine Service Bulletin #M73-20)	PA-36-285	10/5/73	**		8010 4I4
418	Lift Detector Relocation And Modification	PA-36-285	8/13/74	760-843V	74-21-02	2700 4K1
425	Wing Spar Center Section Bolts, Replacement of	PA-36-285	6/14/74	760-871V	74-14-06	5750 4K18
439	Flap Control System, Modification of The	PA-36-285	12/27/74	760-903V	75-01-02	2750 5A8
467	Spray Pump Windmill Assembly Modification	PA-36-285	10/29/75	**		910 5C24
471A	Wing Attachment Fittings, Forward And Aft, Inspection And Modification	PA-36-285	7/16/76	**	77-02-06	5750 5D15
472	Main Spar Center Section Carry Through Assembly Modification of	PA-36-285	6/6/75	760-978		5310 5D18
482	Control Stick Torque Tube Inspection of	PA-36-285	10/22/75	**		7610 5E21
489	Muffler Clamp Installation	PA-36-285	3/12/76	761-017		7810 5F13
490	Safety Harness Installation Modification	PA-36-285	6/30/76	761-022 761-057		5340 5F14
495B	Rudder Control Horn Attachment Bolts, Inspection of	PA-36-285/300 PA-36-375	7/13/81	**	76-05-07	2720 5G11
499	Induction Air Filter Cover Assembly	PA-36-285	3/18/76			7160 5G20
501	Wing Main Spar Lower Bolt Replacement	PA-36-285	4/27/76	761-058	76-25-02	5750 5H1
505	Precautionary Operating Placard Installation	PA-36-285	4/29/76	98000-62		1130 5H10
506	Tail Structure Modification	PA-36-285	8/23/76	761-034 761-067	77-04-02	3270 5H12
508	Fuel Tank Vents, Inspection of	PA-36-285	6/15/76			2810 5H19
513	Engine Air Induction System Modification	PA-36-285	7/15/76	761-053		7160 5I6
516	Control Rod End Bearing	PA-36-285	1/20/77	761-095		7200 2140 2730 2710 5I13
518	Rudder Spar Hinge Inspection	PA-36-285	2/22/77	98125-04	77-21-03	5550 5I19
539	Fuel Quantity Gauge Inspection	PA-36-285	1/27/77	76784-02		2840 5L23
546	Whelen Wing Tip Strobe Lights Reference FAA Airworthiness Directive, Inspection of	PA-36-285/300	5/18/77	**		3340 6A16

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
552A	Wing Spar Carry Through Assembly Inspection	PA-36-285 PA-36-300	8/3/2018	**	2021-11-16	5700
583	Voltage Regulator/Over Voltage Relay Rewiring	PA-36-300	10/31/77	**		2430
587	Exhaust Stack Modification	PA-36-300	2/6/78	**		7810
608A	Inspection/Replacement of Elevator And Aileron System Control Rod End Bearings	PA-36-285/300 PA-36-375	9/29/78	**	78-26-05	2710
615	Inspection of Engine Mount And Modification If Required	PA-36-285	9/21/78	763-887	79-12-09	7120
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-36-300 PA-36-375	2/25/80			3450
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0
713	Fuel Cell Inspection	PA-36-285/300	5/11/81	97989-00		2810
	and Servicing	PA-36-375		97989-01		
729	Rudder Cable and Seat Belt Attachment Shackle Inspection	PA-36-285/300 PA-36-375	9/22/81	486-566		2720
744	Wing Spar and Wing Spar Carry-Through Assembly and Components Replacement	PA-36-285/300 PA-36-375	5/12/82	**		5710
771A	Parking Brake Application	PA-36-285/300/375	9/6/2011	81090-002	85-02-05	1130
797B	Fuel Port Restrictor Installation	PA-36-285/300 PA-36-375	9/1/87	566-502		2812
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-36-285/300 PA-36-375	3/14/86	N/A		6110
828	Fuselage Tubing Crack Inspection	PA-36-300 PA-36-375	4/7/86	**	92-15-15	5345
836A	Aluminum Wire Inspection/Replacement	PA-36-285/300 PA-36-375	8/26/86	**		2400
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-36-285 PA-36-300 PA-36-375	3/7/94	**		6113
1035A	Distribution of Textron Lycoming Service Bulletin 529A, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-36-375	3/22/2007	**		7311
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-36-285 PA-36-300 PA-36-375	9/25/2000	**		3714

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-36

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1286	Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement	PA-36-285/300	9/22/2015	N/A		7310
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB89

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB90

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
600A	Aft Fuselage/Tail Cone Area Rivet Replacement	PA-38-112	4/28/78			5350	6H16
603	Fuel Gauges And Instrument Cluster Grounding Harness Installation	PA-38-112	7/25/78	**	79-17-05	2840 3310	6I2
607A	Part I - Inspect And Attain Clearance Between The Rudder Leading Edge And The Vertical Fin Trailing Edge	PA-38-112	6/2/78				6I13
607A	Part II - Install Straps To Maintain Clearance Between Rudder Leading Edge And Vertical Fin Trailing Edge	PA-38-112	6/2/78			2730	6I14
607A	Part III - Inspect And Attain Clearance Between Elevator Leading Edge And Stabilizer Trailing Edge	PA-38-112	6/2/78	763-872		2720	6I15
609A	Pilot And Copilot Control Wheel Replacement Modification	PA-38-112	7/31/78	**		2700	6I23
610	Gascolator Fuel Line Installation Inspection	PA-38-112	7/18/78	462-049		7310	6J2
613A	Installation of Bearing Retention Plates On Bottom Rudder Hinge Bracket Assembly	PA-38-112	1/11/80	763-881	79-03-02	5550	6J12
614	Inspection of Throttle And Mixture Control Placards For Proper Placement	PA-38-112	8/11/78	**		7610 7320	6J14
617B	Engine Mount Inspection/ Replacement	PA-38-112	1/30/81	**	81-23-07	7120	6J22
618	Inspection of Left And Right Wing Rear Spar Attach Fittings	PA-38-112	9/5/78	**		5110	6K1
620	Tomahawk Magneto Replacement	PA-38-112	10/26/78	**		7410	6K6
628A	Inspection of Vertical Fin Forward Spar Attachment Plate	PA-38-112	11/8/78	77553-05		5530	6L7
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-38-112	2/25/80			3450	6L14
637	Part I - Inspection of Upper Forward Vertical Fin Spar Attach Fitting	PA-38-112	12/29/78	77615-07	79-08-02	5510	7B5
637	Part II - Inspection of Vertical Fin/Fuselage And Horizontal Tail/Vertical Fin Spar Attach Fitting Bolt	PA-38-112	12/29/78		79-08-02	5510	7B7
661	Control Column Installation Modification	PA-38-112	8/22/79		85-11-06	2700	7E12
673B	Replacement of Main Landing Gear Attachment Clamp, Bolts, And Barrel Nuts	PA-38-112	10/2/86	765-171 765-172	90-19-03	3210	7G11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
676	Nose Gear Strut Modification	PA-38-112	6/5/80	764-007		3220	7H1
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0	7H4
686	Upper Rudder Hinge Bracket Replacement	PA-38-112	5/23/80	**	98-03-16 80-22-13	5550	7I20
709	Aileron Torque Tube Bearing Inspection	PA-38-112	7/13/81	**		2710	7L21
710	Vertical Fin Forward Spar Attachment Plate Replacement Life Limits	PA-38-112	10/10/82	**	82-27-08	5530	8A1
723	Aileron Balance Weight Rib Inspection/Reinforcement	PA-38-112	8/19/81	**	82-02-01	2710	8B18
745	Part I - Forward Fin Spar Inspection Piper Part No. 77601-03	PA-38-112	10/10/82	764-427	82-27-08	5510	8F19
745	Part II-Fuselage Bulkhead Assembly Inspection, Piper Part No. 77553-02	PA-38-112	10/10/82	77553-06	82-27-08	5310	8F20
745	Part III - Fin Spar Attachment Plate Replacement Piper Part No. 77553-05	PA-38-112	10/10/82	77553-05	82-27-08	5510	8F20
745	Part IV-Aft Vertical Fin Spar Inspection, Piper Part No. 77601-02	PA-38-112	10/10/82	**	82-27-08	5510	8F21
748	Radio Support Installation	PA-38-112	8/4/82	477-673		2320	8G6
760	Throttle Cable Inspection Replacement of Jam Nut	PA-38-112	4/16/84	2458-02		7610	8H15
763A	Upper Forward and Aft Vertical Fin Spar Inspection and Reinforcement	PA-38-112	7/25/83	764-965	83-19-01	5530	8I1
800	Elevator Control Travel Modification	PA-38-112	11/19/84	76193-02	85-11-06	2730	9C4
813	Throttle Cable Installation Inspection	PA-38-112	1/3/86	77907-002		7612	9F14
834	Rear Spar Frame Stiffener Installation (Fuselage Station 99.29)	PA-38-112	4/22/86	765-177		5310	9I23
836A	Aluminum Wire Inspection/Replacement	PA-38-112	8/26/86	**		2400	9J4
851	Carburetor Air Box Valve Assembly Inspection/Modification	PA-38-112	10/9/86	**		7163	9L16
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800	10A7
879	Rivet Inspection - Wing Skin To Spar, Top Inboard	PA-38-112	1/22/88	**		5730	10G3
890	Forward Tunnel Inspection and Flap Handle Cover Rework	PA-38-112	7/7/88	765-358		2752	10H20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
891	Wiring Modification Wing To Main Wire Harness Connectors	PA-38-112	7/15/88	764-530		2453
936	Replacement of a 90 Degree Fitting and Inspection of the Tee Fitting and Nipple at the Oil Pressure Transducer	PA-38-112	3/16/90	**		7257
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-38-112	1/29/96	**		2437
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings."	PA-38-112	10/5/98	753-910		3711
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-38-112	9/25/2000	**		3714
1200	Landing Gear Modification and Hardware Replacement	PA-38-112	5/29/2009	88455-002	90-19-03	3207
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies	PA-38-112	4/12/2019	N/A		7414
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P,
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0 7H4
780A	Part I - Flap Drive Mechanism Modification	PA-46-310P	10/10/85	765-118V		2910 8K7
780A	Part II - Flap Selector Valve Replacement	PA-46-310P	10/10/85	83729-04		2910 8K8
781	Aft Rudder Cable Inspection	PA-46-310P	6/25/84	**		2720 8K10
782A	Magneto Switch Guard Installation	PA-46-310P	4/24/85	N/A		7410 8K12
783	Interference of Elevator to Stabilizer	PA-46-310P	6/13/84	765-132V		5520 8K15
784	Pressure Outflow & Safety Valve Routing Inspection	PA-46-310P	8/7/84	557-114		2130 8K17
786	Toe Brake Cylinder Clevis Rework	PA-46-310P	8/20/84	N/A		3241 8L6
790A	Part I - Turbo Oil Scavenge Reservoir Inspection	PA-46-310P	2/14/85	**		7250 9A1
790A	Part II - Turbo Oil Scavenge Oil Line Support	PA-46-310P	2/14/85	**		7250 9A2
790A	Part III - Lower Cowl Modification	PA-46-310P	2/14/85	N/A		7250 9A3
791	Oxygen System Electrical Wiring Rerouting	PA-46-310P	8/20/84	N/A		3529 9A7
792	Fuel Supply Line Replacement & Wing Rib Modification	PA-46-310P	8/7/84	**		2814 9A13
794	Electric Fuel Pump Circuitry Modification	PA-46-310P	8/30/84	**		2820 9A20
796B	Part I - Lower Wing Rivet Replacement	PA-46-310P PA-46-350P	1/25/95	**		5733 9B8
796B	Part II - Wing to Fuselage Fairing Replacement	PA-46-310P	1/25/95	**		5733 9B9
796B	Part III - Upper Inboard Wing Rivet Replacement	PA-46-310P	1/25/95	**		5733 9B9
799	Landing Gear Control Lever Safety Tab Modification	PA-46-310P	10/26/84	**		3260 9C1
803A	Pneumatic Surface Deice Pressure Control Valve	PA-46-310P	3/21/86	765-159 84523-805		3014 9C18
805A	TRW Hartzell Propeller Service Bulletin No. 142 (O-ring Deterioration)	PA-46-310P	3/14/86	N/A		6110 9D15
808	Main And Nose Landing Gear Actuator Seal Replacement	PA-46-310P	7/10/85	**		2930 9E10
809	Nose Landing Gear Steering Rotator Inspection And Replacement	PA-46-310P	7/1/85	**		3251 9E21
810	Gear Safety Solenoid Installation Modification	PA-46-310P	7/9/85	422-166 406-385		3200 9F1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
820A	Aft Wing Attach Fitting Fastener Inspection/Replacement	PA-46-310P	4/20/2011	680-660 557-501		5741
824	Electric Flap Motor - Actuator Installation Rework	PA 46-310P	3/21/86	**		2753 9H11
837	Main Landing Gear Lower Torque Link Bolt Inspection	PA-46-310P	5/21/86	424-052		3213 9J8
852	Alternate Air Control Linkage Adjustment	PA-46-310P	11/14/86	N/A	87-04-01	7164 9L19
853	Fuel Drain Replacement	PA-46-310P	11/17/86	765-317		2823 10A1
854A	Deice Timer Protection - Electrical Circuit Change	PA-46-310P	10/28/87	**		3016 10A3
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800 10A7
858	Nose Landing Gear Steering Rotator Horn Attach Bolt Replacement	PA-46-310P	4/1/87	401-302 407-565		3251 10A15
862A	Electrically Operated Flap System, Actuator Tube Replacement	PA-46-310P	8/11/87	85070-02		2753 10B3
863A	Part I - Aileron Cable Routing - Wing	PA-46-310P	1/31/89	765-331		2712 10B6
863A	Part II - Phenolic Fairlead Installation	PA-46-310P	1/31/89	**		2712 10B7
865A	Part I - Freon Compressor Drive Pulley Nut Inspection And Belt Removal	PA-46-310P	7/14/87	**	87-12-12	2513 10B13
865A	Part II - TCM Mandatory Service Bulletin M87-13 "Broken Starter Adapter Shafts"	PA-46-310P	7/14/87	**		2513 10B14
871	Airframe And Powerplant Operational Limitations	PA-46-310P	10/13/87	**		7100 10C15
876B	Part I -Malibu Return To Service	PA-46-310P	4/14/88	**	87-14-02	7200 10E8
876B	Part II - Teledyne Continental Motor Service Bulletin M88-5 "Broken Starter Adapter Shafts"	PA-46-310P	4/8/88	**	88-17-03	7200 10E9
883	Additional Post Lighting - Flight and Engine Instrumentation	PA-46-310P	3/10/88	765-353		3311 10G18
884	Lock Wiring of V-Band Couplings	PA-46-310P	4/8/88	**		7800 2100 10G20
892A	Powerplant Cooling Improvement	PA-46-310P	5/17/89	765-365	88-25-08	7520 10I1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
895	Alternate Air Box Bearing Block Modification	PA-46-310P	11/17/88	420-219		7160 10I10
896	Shoulder Harness Installation & Usage	PA-46-310P	11/28/88	**		5340 10I13
900	Missing Upper Fuselage Rivets	PA-46-310P	2/13/89	522-601		5333 10J11
913A	Malibu Return to Service	PA-46-310P	6/29/89	N/A	89-14-01	7226 10L15
915	Lycoming Service Bulletin No. 487 (Included with Lycoming Kit)	PA-46-350P	7/8/89	**	89-15-10	7311 10aA5
917	Angle Support Forward Baggage Compartment	PA-46-310P	7/19/89	765-367		2551 10aA14
919	Carpet Runner Retainer Installation	PA-46-310P	8/3/89	765-369		2520 10aB2
921	Aileron Inspection	PA-46-310P PA-46-350P	8/15/89	**		2715 10aB9
928A	Textron Lycoming Service Bulletin No. 491A, Inspection of Exhaust Transition Bolts	PA-46-350P	3/22/90	**		7800 10aC12
930	Inspection of Emergency Exit Window Fit	PA-46-350P	12/14/89	N/A		5621 10aC20
934	Inspection and Rerouting of the Manifold Pressure Line	PA-46-350P	2/8/90	**		7716 10aD12
939	Weight and Balance Plotter	PA-46-350P	6/8/90	N/A		1110 10aE4
941	Improved Engine Baffle Support	PA-46-350P	7/17/90	**		7236 10aE9
943A	Landing Gear Locking Actuator End Gland Replacement	PA-46-310P	8/15/90	763-060		3235 10aF1
944	Empennage Rivet Replacement	PA-46-310P PA-46-350P	10/5/90	**		5510 5530 10aF12
947A	Low Vacuum Annunciator Light Operation	PA-46-310P PA-46-350P	10/29/91	**		3720 10aF23
948	Inboard Wing Rib Inspection, Modification, Replacement	PA-46-310P PA-46-350P	1/25/91	**		5710 10aG3
949	Wing Rib Reinforcement	PA-46-310P PA-46-350P	2/18/91	766-247 766-248 766-249		5712 10aG10
951	Mixture Control Cable Inspection and Routing	PA-46-350P	2/18/92			7320 10aG14
953	Elevator Trim Cable Guide Tube Splice	PA-46-310P PA-46-350P	10/29/91	766-272		2730 10aG23
958	Horizontal Stabilizer Drain Hole Installation	PA-46-310P PA-46-350P	9/22/92			5510 10aH17
959	Fuselage Rivet Installation	PA-46-310P PA-46-350P	3/31/93	**		5310 10aH20
960	Engine Mount Heat Shield	PA-46-310P PA-46-350P	3/31/93	766-267 766-268		7120 10aI3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
961	Alternate Air Door Replacement and Control Linkage Inspection	PA-46-310P PA-46-350P	10/21/92	**		7160 10a15
962	Corrosion Inspection and Protection	PA-46-310P PA-46-350P	9/29/93	**		5510 10aJ4
963	Electric Flap Cam Assembly Modification	PA-46-310P PA-46-350P	6/11/93	766-245		2750 10a17
964B	Hydraulic Power Pak Pressure Switch Replacement	PA-46-310P PA-46-350P	5/24/96	766-278 766-277		2911 10aJ14
976	Inspection for and Replacement of Components with Suspect "O" Rings	PA-46-350P	12/9/94	**		2911 10bA10
981	Hydraulic Power Pak Lower Manifold Inspection	PA-46-310P PA-46-350P	1/17/95	**		2911 10bB15
982	Installation of Limitations Placard	PA-46-350P	4/3/95	**		1100 10bC1
985	Hydraulic System Power Pak Pressure Switch Replacement	PA-46-310P PA-46-350P	6/16/95	765-457		2911 10bC17
990	Pacific Scientific Seat Belt Replacement	PA-46-350P	1/3/96	**		5346 10bD12
993	KLN-90B GPS Wiring Modification	PA-46-350P	3/18/96	**		3441 10bE4
994	Intermittent Main Landing Gear Indication (Parker Hannifin SB7049) (Attached)	PA-46-310P PA-46-350P	3/8/96	**		2911 10bE6
995C	Turbine Inlet Temperature (T.I.T.) System Calibration and Probe Replacement	PA-46-310P PA-46-350P PA-46R-350T	11/17/2009	**	2011-06-10	7726 (10bE11)
997	Inspection of Jack Pad attachment Area at Wing Cutout for Radar	PA-46-310P PA-46-350P	2/7/97	766-628		5740 10bE20
999	Modification of Inertia Reel Shoulder Harness Mounting Brackets	PA-46-310P PA-46-350P	3/5/97	766-638		5346 10bF9
1000	Inspection of Engine Electrical Harness and Installation of Chafing Protection	PA-46-350P	4/25/97	49990-36 488-702		2436 10bF11
1001	Inspection for Missing Washers at Nose Gear Steering Arm Rod End	PA-46-350P	6/16/97	**		3251 10bF14
1012	Distribution of Textron Lycoming Service Bulletin 531, Inspection of turbochargers and Tailpipes	PA-46-350P	2/4/98	**		7800 10bH3
1014	Replacement of Battery Power Fuse	PA-46-350P	3/2/98	461-681		2436 10bH11
1017	Alternator Regulator Wiring Mod	PA-46-350P	4/10/98	**		2436 10bH21
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-46-350P	7/10/98	**		2563 10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
1021	Modification of Control Wheel Quadrant Stop and Inspection of Forward Pressure Bulkhead	PA-46-310P PA-46-350P	8/4/98	766-654		5346	10b111
1027	Modification of Forward and Aft Wing Attach Fittings	PA-46-350P	11/19/98	766-656 766-657	99-16-06	5741	10bK4
1029	Distribution of Textron Lycoming Service Bulletin 534, Turbocharger Oil Drain Tank Inspection/Replacement	PA-46-350P	4/30/99			7164	10b17
1034	Battery Master Contactor Wiring Modification	PA-46-350P	8/17/99	84350-11 84350-12		2454	10bL13
1035A	Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3"	PA-46-350P	3/22/2007	**	2003-14-03	7311	10bL16
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-46-310P PA-46-350P	9/25/2000	**		3714	10cB1
1046	POH Supplement Installation	PA-46-350P	11/28/2000	**		2212	10cC4
1048	Stainless Steel Control Cables	PA-46-350P	1/3/2001	N/A		2702	10cC9
1052	Nose Gear Steering Bungee Assy Modification	PA-46-500TP	2/26/2001	766-690		3255	10cC23
1053	Outside Air Temperature Probe Relocation	PA-46-500TP	4/3/2001	766-688		3416	10cD2
1054	Pilot and Co-Pilot Seat Inspection and Modification	PA-46-310P PA-46-350P PA-46-500TP	4/12/2001	**		2514	10cD6
1055	Engine Control Quadrant Inspection and Modification	PA-46-500TP	5/29/2001	82995-003		7601	10cD9
1056	Fuel Drain Valve Inspection and Replacement	PA-46-500TP	4/4/2001	766-691		7319	10cD21
1058	Overhead Switch Panel Replacement	PA-46-500TP	5/31/2001	680-839 688-497		3110	10cE3
1059	Low Pressure Engine Driven Pump Leakage Inspection	PA-46-500TP	6/11/2001	461-752		7311	10cE6
1060	Brake Pedal Binding	PA-46-310P PA-46-350P PA-46-500TP	5/15/2001	**		3241	10cE9
1061	Nose Landing Gear Strut Tube Snap Ring Inspection	PA-46-500TP	6/19/2001	N/A		3223	10cE13
1062	Inboard Flap Drive Bellcrank Inspection and Replacement	PA-46-310P PA-46-350P PA-46-500TP	5/11/2001	82905-002 82905-003	1-12-01	2755	10cE16
1063	Circuit Breaker Panel Modifications	PA-46-500TP	6/11/2001	581-657		2451	10cE22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SB99

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1064	Mass Flow Control Valve Support Clip Installation	PA-46-500TP	6/14/2001	102501-002		2125 10cF4
1065	Primary Elevator Control Cable Replacement	PA-46-500TP	7/25/2001	**		2735 10cF10
1066	Cabin Door Latch Mechanism	PA-46-350P PA-46-500TP	7/10/2001	767-305		5213 10cF14
1067A	Entertainment Console (Small Cabinet) Voltage Dropping Resistor Shroud Installation	PA-46-350P PA-46-500TP	8/8/2001	767-301 767-302		2507 10cF17
1068	Fuel System Line Fitting Leakage	PA-46-500TP	7/19/2001	**		2823 10cF20
1069	Fuel System Trim Fitting and Solenoid Valve Modification	PA-46-500TP	7/19/2001	766-682		2825 10cG2
1070	Lightning Protection Rivets Installation	PA-46-500TP	7/16/2001	767-303		2816 10cG5
1071	Main Landing Gear Squat Switch Safelying	PA-46-500TP	7/2/2001	N/A		3237 10cG8
1072	Mass Air Control Valve Recall	PA-46-500TP	8/13/2001	592-640		2138 10cG12
1073	Magnetic Flux Detector Connector	PA-46-500TP	8/13/2001	599-693		3427 10cG15
1074	Cabin Bleed Air Restriction	PA-46-500TP	7/23/2001	N/A		2182 10cG20
1075A	Steering Horn Modification	PA-46-310P PA-46-350P	5/5/2003	85154-002 85154-012		3251 10cH1
1076	GI-106 NAV/GS Indicator Wiring Harness Inspection / Modification	PA-46-500TP	7/19/2001	N/A		3316 10cH6
1077	P&WC PT6A-42A Engine Oil-to-Fuel Heater Inspection	PA-46-500TP	7/13/2001	762-156		7200 10cH11
1078	Stall Warning Microswitch Bracket	PA-46-500TP	8/13/2001	767-306		2226 10cI1
1080	Lear Romec Fuel Pump	PA-46-500TP	7/26/2001	461-757		2820 10cI7
1082	Aft Stowage Compartment Drain	PA-46-500TP	8/13/2001	766-693		2550 10cI16
1084	Flight Into Known Icing (FIKI) Certification	PA-46-500TP	9/20/2001	**		3010 10cJ1
1085	Nose Landing Gear Steering Arm Chafing	PA-46-500TP	10/26/2001	767-304		3220 10cJ6
1086	Generator Ammeter Relay Kit	PA-46-500TP	10/3/2001	767-308		2434 10cJ10
1087B	Nose Gear Emergency Downspring Mechanism Replacement	PA-46-310P PA-46-350P PA-46-500TP	5/27/2003	766-211 104723-002 104723-003		3235 10cJ13
1088	Aft Spar Splice Cap Inspection	PA-46-500TP	12/10/2001	767-321		2751 10cJ18
1089	Nose Gear Squat Switch Adjustment	PA-46-500TP	11/12/2001	N/A		3265 10cJ22
1090	Fuel Restrictor Assy / Fuel Return Solenoid Removal	PA-46-500TP	8/23/2001	767-324		2825 10cK1
1091	Pratt & Whitney PT6A-42A Engines - Turboprop Engine Oil-to-Fuel Heater Thermal Element Replacement	PA-46-500TP	9/20/2001	N/A		7200 10cK4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1093	Alternator Isolation Diode Installation	PA-46-500TP	12/5/2001	767-307		2430
1094	Fuel System Check Valve Replacement	PA-46-500TP	10/19/2001	592-670		2813
1095	Gear Warning Horn Mute Switch	PA-46-500TP	1/18/2002	766-697		3260
1098	Pneumatic Deice System Line Inspection and Replacement	PA-46-500TP	2/1/2002	102437-086		3015
1099	Feather Solenoid Suppression Diode Kit	PA-46-500TP	1/18/2002	767-328		6123
1102	Master Electrical Panel Mounting Plate Inspection and Fuse Block Protective Cover Installation	PA-46-500TP	3/8/2002	767-327		2400
1103F	Engine Mount Inspection	PA-46-310P PA-46-350P PA-46R-350T	9/1/2015	84010-002 89137-041 89137-042 89137-043		7120
1106	Nose Gear Steering System Improvement	PA-46-500TP	1/28/2002	767-336 767-338		3220
1107	Maneuvering Speed Placard Replacement	PA-46-500TP	3/7/2002	692-721		1100
1108	Flux Detector Relocation	PA-46-350P PA-46-500TP	3/11/2002	767-335 767-334		3429
1111	Float Switch Wiring Inspection	PA-46-500TP	8/19/2002	602-501		2424
1114	No. 1 GNS 530 Lighting Rewiring	PA-46-500TP	4/24/2002	766-696		3457
1121	Installation of Missing Rivets on Lower Surface of Horizontal Stabilizer Spar	PA-46-500TP	10/3/2002	MS20470AD5		5510
1126A	Emergency Gear Extension Cable Bracket Modification	PA-46-350P PA-46-500TP	2/21/2005	767-364		3237
1132	Electronic Control Module Failures	PA-46-500TP	6/4/2003	102226-002 102227-002 102227-006 102228-002 102228-006	4-03-32	2400
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-46-350P	6/10/2003	**		2800
1135	GMA-340 Audio Panel Wiring	PA-46-350P PA-46-500TP	7/16/2003	N/A		2370
1139A	Control Wheel Attachment Inspection	PA-46-350P PA-46-500TP	4/9/2004	**	4-14-12	2701
1140	Oxygen Generator Protective Cap Removal	PA-46-310P PA-46-350P PA-46-500TP	9/16/2003	471-025		3500
1144	Nose Gear Door Hinge Modification	PA-46-500TP	3/10/2004	**		5280
1150	Standby Airspeed and Altimeter Indicator Pitot/Static Lines Replacement	PA-46-500TP	12/9/2004	767-377		3411

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SB101

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1151E	4130N Steel Hardness Discrepancy	PA-46-350P PA-46-500TP	6/9/2004	**		5741 10dJ4
1152	Fuel Restrictor Replacement	PA-46-500TP	1/5/2005	767-386		2821 10dJ8
1154C	Engine Mount Inspection	PA-46-500TP	1/3/2008	102460-036 102460-002 767-515 401-509 (AN7-15A)		7121 10dJ14
1158A	Accessory Drive Pulley Improvement	PA-46-500TP	1/30/2006	102406-006		7260 10dK7
1159	Fuel System Check Valve	PA-46-500TP	11/10/2005	592-670		2813 10dK10
1166	Electronic Control Module Replacement	PA-46-500TP	1/5/2007	102227-007	4-03-32	3418 10dL12
1168	Elevator Trim Tab Hinge Rivets	PA-46-350P	9/1/2006	767-544		2711 10dL20
1170	Louvered Cover Assembly	PA-46-500TP	10/6/2006	767-545		2100 10eA1
1173B	Engine Oil Hose Assemblies	PA-46-500TP	11/16/2011	88407-002		7920
1175B	Pilot's Side Window Inspection	PA-46-310P PA-46-350P PA-46-500TP	9/30/2010	**		5610
1176	Rudder Quadrant / Torque Tube Inspection - Tailcone	PA-46-350P PA-46-500TP	1/16/2007	**		2720 10eA22
1177	Nose Wheel Assembly (Cleveland SB 7083A)	PA-46-500TP	11/14/2006	40-77B 767-569		3246 10eB3
1178	Nose Gear Forging Inspection / Replacement	PA-46-350P PA-46-500TP	9/24/2007	67050-005 67050-006		3222 10eB10
1180A	V-Band Exhaust Coupling Inspection	PA-46-350P	3/14/2007	**		7200 10eB18
1181B	Flap Track/Splice Strap Inspection and Modification	PA-46-350P PA-46-500TP PA-46R-350T	9/10/2009	104469-002		2750
1182	Wing Inspection Light	PA-46-350P	8/22/2007	84579-002		3340 10eC1
1183	Emergency Exit Door Inspection	PA-46-500TP	5/15/2007	82650-004 102919-002		5220 10eC5
1185	Placard Replacement	PA-46-350P PA-46-500TP	8/30/2007	684-762 684-761		2440 10eC21
1187	Voltage Suppressor Replacement	PA-46-350P PA-46-500TP	2/8/2008	88432-002 (Kit)		3400 10eD4
1190B	Aileron Quadrant Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	1/22/2009	82858-002		2710
1192	Stall Warning Heat Control Modification	PA-46-350P PA-46-500TP PA-46R-350T	9/15/2008	88452-002 (Kit)	2008-26-11	3418

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1193	Nose Gear Down Spring Replacement	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	3/3/2009	687-931		3230
1195B	Comm 1 and Comm 2 Antenna and Skin Inspection	PA-46-350P PA-46-500TP	4/15/2010	**		2312
1196	Collector Tank Fuel Drain Inspection	PA-46-350P PA-46R-350T	10/23/2008	84029-018 84029-017		2830
1201	Tie Bus Circuit Breaker Inspection	PA-46R-350T	2/16/2009	N/A		2400
1202	Beta / Reverse Lockout Lever Inspection	PA-46-500TP	3/18//2009	**		7600
1204	Re-Calculation of Wing Structure Life Limit Due To Unique Usage	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	12/18/2009	N/A		5711
1205	Relocation of the PY Heater Ground Wire Termination	PA-46-500TP	3/24/2010	106798-002		3230
1208	Lightning Diverter Inspection	PA-46-350P PA-46-500TP PA-46R-350T	2/15/2010	**		5180
1210	TWX670 Antenna Inspection	PA-46R-350T	12/21/2009	**		3450
1211	Aft Bulkhead Sealing Modification	PA-46R-350T	3/2/2010	PR-1422-A2 PR-1422-B4		5110
1212	Inspection of Flap Position Indicator Placard	PA-46-350P PA-46-500TP PA-46R-350T	1/5/2010	**		1130
1214A	Compressor Turbine Blade Inspection	PA-46-500TP	3/4/2010	N/A		7231
1217A	Starter Contactor Replacement	PA-46-350P PA-46R-350T	1/14/2011	88465-002		2400
1218	Rudder Skin Inspection	PA-46-500TP	10/13/10	83403-003 88471-002 106884-002		5540
1223	Wire Screen Replacement	PA-46-350P PA-46R-350T	11/10/10	**		2126
1228	Autopilot Circuitry Modification	PA-46R-350T	1/21/2011	88485-002		2210
1229	Avox Systems Service Bulletin No. 36758-35-01 (O ₂ Cylinder Bracket Latch Inspection)	PA-46-500TP	4/21/2011	453-528		3510
1230	Nose Wheel Grommet Inspection	PA-46-500TP	6/6/2011	463-526		3240
1232	Cabin Door Handle Placard Inspection	PA-46-350P PA-46-500TP PA-46R-350T	5/16/2011	100700-014		1120
1234	Engine Oil Cooler Control Valve Replacement	PA-46-500TP	6/23/2011	592-712		7920

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1236	Landing Gear Servicing and Placard Replacement	PA-46-500TP	10/6/2011	100700-084 100700-085 100700-086		1210
1237	Static Discharger Replacement	PA-46-350P PA-46-500TP PA-46R-350T	8/10/2011	456-904		2360
1238	Landing Gear Servicing and Placard Replacement - Meridian G1000 airplanes registered in Brazil	PA-46-500TP	7/23/2013	106787-072 106787-073		1210
1243C	Potential Landing Gear Malfunction	PA-46-350P PA-46-500TP PA-46R-350T	3/7/2012	102559-804RBL		3200
1247B	Garmin SafeTaxi® Limitation	PA-46-350P PA-46-500TP PA-46R-350T	3/13/2019	N/A		3420
1250A	Pilot Operating Handbook Permanent Revision	PA-46-350P PA-46R-350T	12/16/2013	**		7320
1255	Boost Pump Wiring Rerouting	PA-46-500TP	3/4/2013	88541-001		2820
1256	Nose Landing Gear Torque Link Hardware Replacement	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	1/23/2013	603-816 (MS14144-4)		3220
1258	Fuel Vent Valve Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	6/5/2013	106927-001	2013-13-01	2810
1262B	Wing Inspection	PA-46-500TP	4/23/2015	**		5713
1269A	GWX 68 Ground Rewire	PA-46-350P PA-46R-350T	3/10/2014	N/A		3440
1267A	Empennage Rivets Inspection	PA-46-500TP	12/18/2015	484-911		5500
1271A	Wing Spar Inspection	PA-46-310P PA-46-350P PA-46-500TP	12/12/2019	**		5711
1275	Nose Landing Gear Service Placard Replacement	PA-46-500TP	6/26/2015	100700-125		1130
1280A	H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1	PA-46-350P PA-46-500TP PA-46R-350T	4/29/2016	459-887		2620
1283A	Cabin Altitude Encoder Installation Modification	PA-46-350P PA-46-500TP	10/19/2016	Sandia P/N 305216-02		2130
1284B	Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick assemblies	PA 46-350P PA 46-500TP PA-46-600TP	4/12/2019	N/A		7414
1288A	Aft Vertical Fin Spar Inspection	PA-46-350P PA-46-500TP PA-46R-350T	5/18/2017	404-532 MS21042-6		5500
1290B	Flap Bracket Inspection, Inboard Bellcrank	PA-46-350P PA-46-500TP	12/14/2017	N/A		2750

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
		PA-46R-350T				
1291	Executive Table Placards Replacement	PA-46-350P PA-46-500TP PA-46R-350T	8/11/2016	88581-701 or 88581-702		2520
1293C	Engine Mount Doubler Installation and Towing Placards Replacement	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	3/9/2017	88582-701 88582-702 88584-701 (if required)		1100 7120
1296	Fuel Control Unit Manual Override Inspection – Pratt & Whitney Canada Service Bulletin A3487	PA-46-500TP	3/31/2016	N/A		7600
1297	Altimeter Inspection and Replacement (United Instruments SB No. 13)	All	5/10/2016	N/A		3416
1303A	Diode Module Installation	PA-46-600TP	10/15/2018	681-020		3410
1305	Flight Into Known Icing (FIKI) Modification	PA-46-600TP	7/13/2017	88592		3000
1306	Wing Rib Modification	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	1/10/2018	88609-001 88609-002		5712
1308	Wet-Wing Fuel Access Cover Inspection	PA-46-600TP	5/10/2017	Loctite 222MS 279-051		2810
1310	K303 Relay Relocation	PA-46-600TP	5/18/2017	584-423		2430
1314	Cabin Door Frame Inspection	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	3/12/2018	N/A		5311
1315	Cabin Door Threshold Rivet Replacement	PA-46-600TP	12/21/2017	N/A		5310
1317C	Aft Wing Spar Inspection	PA-46-600TP	8/9/2017	N/A	2017-16-03	5711
1318B	Fuselage Station 144.25 Rivet Replacement	PA-46-600TP	6/7/2018	88623-701 88624-701	2018-14-01	5330
1322	Stall Warning Heat Ground Wire Inspection	PA-46-500TP M500	2/28/2018	**		3418
1326A	Propeller Heat Sensor Wiring Modification	PA-46-600TP	1/3/2019	465-258 461-654		3060
1327	Aileron Control Cable Protection Tube Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	6/26/2018	88630-701		2710
1328	Aileron Quadrant Cable Guard Replacement	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	6/26/2018	46F44A701-701		2710
1329	Canted Frame Rivets Replacement	PA-46-600TP	2/3/2020	46F53A004 46F53A005		5310
1332A	Bulkhead Rivet Replacement	PA-46-600TP	1/29/2019	N/A		5312

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1333A	Forward Wing Spar Attach Fitting Inspection	PA-46-600TP	4/18/2019			5741
1334A	EL Panel Inverter And Windshield Heat Relay Ground Wiring Relocation	PA-46-600TP	12/5/2018	N/A		3040 3310
1336	Aileron-Rudder Interconnect Inspection	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	1/18/2019	83287-006		2700
1338	Main Gear Actuator Attach Fitting Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	3/25/2020	467-496		3211
1339A	Generator Relay (K303) Replacement	PA-46-600TP	9/9/2019	88646-002		2430
1341A	Lift Transducer Replacement	PA-46-600TP	5/1/2023	585-720		3418
1343	Canted Frame Doubler Inspection	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	2/3/2020	82279-002		5300
1344	Generator Relay (K303) Replacement	PA-46-500TP	10/23/2019	88647-002		2430
1349	Fuel Return Valve Wiring Modification	PA-46-500TP M500	2/14/2020	N/A		3425
1350A	Nose Landing Gear Steering Horn and Arm Assemblies Inspection	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	2/10/2021	46N32A009-801 83626-004 (85154-012)		3200
1352	Garmin G3000NG Software Version 2975.15	PA-46-600TP	4/10/2020	88678-001 190-02446-00 190-02447-00		3420
1358	Fuel Probe Modification	PA-46-350P M350	3/24/21	88667-701		2840
1360A	Aileron Drive Sector Inspection	PA-46-600TP	1/13/2021	46W440005		2710
1361	Autothrottle Potentiometer Wiring Inspection	PA-46-600TP	3/12/2021	46F34A021-002		2230
1364A	Fuel Quantity Capacitance Probe Inspection	PA-46-350P M350 PA-46-600TP	4/14/2021	**		2840
1367	Aft Rib Assembly Rivets Replacement	PA-46-600TP	9/17/21	MS20426AD-4		5712
1369	Elevator Spar Inspection	PA-46-500TP PA-46-600TP	8/12/21	88694-701 88694-702		5521
1370A	Inertial Separator Duct Shredder Angle Modification or Replacement	PA-46-500TP M500 PA-46-600TP	3/28/2022	46P710003-003 46P710015-003 88700-701/-702		7160
1371	M600 Wing Assembly Serialization Marking	PA-46-600TP	1/4/2022	46W57A100-001		1100
1385	Rudder Skin Strap installation	PA-46-500TP	10/25/2022	83403		5540
1395	Garmin G1000 Software Update Version 720.18	PA-46-500TP	2/20/2023	88681-001		3420
1390	Nose Landing Gear Emergency Down Spring Inspection	PA-46-350P, PA-46-500TP PA-46-600TP, PA-46R-350T	7/20/2023	487-399		3230
1392	Frame Assembly Inspection and Repair, Fuselage Station 282.00	PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46R-350T	10/15/2024	84201-004 46F53A213-001		5322

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1401	Steering Arm Modification	PA-46-600TP M600	10/23/23			3250
1402	Airworthiness Directive 2021-08-15	PA-46-350P M350 PA-46-500TP M500 PA-46-600 M600	8/24/2023		2021-08-15	3445
1403	Airfram Doubler Inspection	PA-46-500TP M500 PA-46-600TP M600	5/23/2024			5320
1404	Flap Drive Bracket Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	4/2/2024			5754
1407A	Piper Halo Autoland Brake Mechanism Modification	PA-46-600TP M600	10/17/2024			3240
1408	Replacement of Main Landing Gear Door Support Structure	PA-46-600TP M600	9/4/2024	46W57A730-701 46W57A730-702		5280
1409A	Control Column Assembly Inspection	PA-46-350P M350 PA-46-500TP M500 PA-46-600 M600	11/22/2023	485-083 (MS16625-2075)		2701
1410A	Vertical Stabilizer Installation Improvement	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	3/20/2024			5340
1411A	Autopilot Rigging Inspection	PA-46-350P Mirage/M350 PA-46-500TP Meridian/M500 PA-46-600TP M600 PA-46R-350T Matrix	7/2/2024			2700
1414A	Main Landing Gear Attachment Fitting Inspection Near WS 61.00	PA-46-600TP M600	7/1/2024	575-124 557-737 861-180 99G000002-701		3211
1416A	Fuel Flow Transducer Inspection	PA-46-350P M350	7/2/2024			2840
1417	Flight Into Known Icing (FIKI) Modification - M700	PA-46-701TP M700 Fury	5/31/2024	N/A		3000
1419	Flap Bracket Gap Inspection	PA-46-600TP M600 PA-46-701TP M700 Fury	10/14/24			5754
2000A	Current Limiter Inspection	PA-46-350P / M350 PA-46R-350T	3/10/2022	572-599 461-681	2009-07-08	2400

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SB108

SERVICE LETTER INDEX

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
32	Aileron Cable Pulley Installation	J3	6/15/42			13A1
100	Tie Rod Nipples- J3, 8-36 Type A	J3	11/23/43			13A2
107	Plexiglass One Piece Windshield For J3 Series	J3	10/15/45			13A3
109	Winter Operation Recommendations	J3, PA-11	10/15/47			13A5
114	Top Cowl Rivets	PA-16	6/13/49			13A10
129	Inspection of Landing Gear Shock Strut End Fittings	PA-15/17	10/28/49			13A11
131	Muffler Tail Pipe Inspection	PA-11	12/30/49			13A12
136A	Chafing of Fuel Line and Fuel Valve Operation	PA-20/22	9/2/52			13A13
138	Rudder Pedal Tube Attachment	PA-20	3/9/50			13A15
140	Rudder Cable Rub Block	PA-20	3/24/50			13A16
143	Stabilizer Adjustment Cable Pulley Modification	PA-20	5/5/50			13A18
144	Fuselage Doors	PA-15/17	5/5/50			13A19
145	Auxiliary Fuel Line	PA-20	6/1/50			13A20
146	Front Seat Frame Revision	PA-20	6/1/50			13A21
150	Bungee Cable PA-18-105	PA-18	7/10/50			13A22
153	PA-20 Windshield Supports	PA-20	7/12/50			13A24
154	Addition of Felt Strips on Wing Tank Covers	PA-11/16 PA-18/20	7/12/50			13B1
155	Muffler Tail Pipe Shroud	PA-18	7/14/50			13B2
157	Loose Connections	PA-16/20	8/1/50			13B4
159	PA-20 Baffle Seal	PA-20	10/24/50			13B5
161	Duraclad Finish	PA-18/20/22	2/13/51			13B6
162	Control Sticks	PA-18	3/6/51			13B8
165	Oil Radiator Hoses	PA-18 PA-20 PA-22	3/23/51	465-132 465-133 465-134		7920

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
169	Manifold Pressure Gauge Installation	All 1951 Models	4/20/51			13B9
175	Nose Wheel Bumper Block Spacer Plate	PA-22	8/1/51			13B10
176	Stabilizer Adjustment Mechanism	PA-20/22	8/10/51			13B11
177	Firewalls	All Models	8/10/51			13B13
178	Optional Oil Radiator Installation	PA-18	8/24/51			13B14
180	Nose Wheel Mount Stiffener Brace	PA-22	9/20/51			13B15
183A	Tail Wire Fittings	PA-18	11/12/51			13B16
186	Clearance Between Engine Mount and Tail Pipe/Clearance In Nose Wheel Steering Mechanism	PA-22	4/21/52			13B17
187	Brake Lever	PA-22	3/13/52			13B19
188	Flap Cable Installation	PA-18A	4/11/52			13B20
189	Tail Wheel Springs	PA-18A	4/17/52			13B22
194	Sealing of Firewalls	PA-20/22	9/2/52			13B23
195	Battery Cable And Rudder Cable Interference	PA-18A	10/6/52			13B24
196	Chafing of Oil Pressure Line	PA-18	10/6/52			13C2
203	Weight & Balance Form	PA-12	5/7/53			13C3
207	Oil Quick Drain Valve Assembly, Part No. 12956-04	PA-18 PA-22	6/18/53			13C4
209	Navigation Light Switch	All Classic Models	8/18/53			13C5
210	PA-18A Agricultural Airplane	PA-18A	8/24/53			13C6
212	Nose Wheel Shimmy Dampener, Part No. 13086-00	PA-22	10/7/53			13C8
213	Primer Lines	PA-18, 20, 22	10/7/53			13C10
214	Navigation Light Switch	All Classic Models	11/17/53			13C12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
216A	Replacement of Aileron Hinge Bearing Blocks Part No. 10921	All Classic Models	12/14/1953			
220	.040 Brass Safety Wire	All Classic Models	3/29/1954			
221	Carburetor Air Filter	All Classic Models	5/13/1957			
223	Engine Support Bushing	PA-12, 16 PA-18, 18A PA-20, 22	5/17/1954			
228	Two Person Safety Belts	PA-12, 14, 15 PA-16, 17, 20, 22	9/29/1954			
233	Fuel Selector Valve	PA-18, 20, 22	10/22/1954			
241	Cigarette Lighters	PA-22	1/24/1955			
242A	Special Air Filter Kits	PA-18A	2/20/1959	**		7160
243	Engine Mount	PA-22	2/8/1955			
247	Tail Reinforcement Agricultural Airplane	PA-18A	4/15/1955			
248	Auxiliary Fuel Tank	PA-22	5/13/1955			
258	Fuel Tank Cap	PA-22	11/30/1955			
259	RPM Restriction Placard	PA-18, 18A	11/30/1955			
260	Brake System	PA-22 (1956 Models Only)	11/30/1955			
283A	Inspection Forms, 100, 500, 1000 Hour	PA-18, 18A PA-22	2/26/1958			General
295A	Aircraft Finishes	All Classic Models	1/3/1964			
298C	Obsolete Airplanes	B-2/E-2/F-2/J-2/J-3/J-4 L-4/L-18B/L-18C/ NE-1 PA-11/15/16/17/18/19/ PA-20/22/TG-8	6/7/2021			General
303A	Aircraft Finish	PA-15/16/17 PA-18/20 PA-22 ***	9/23/1959			5300
312	Tooling - Piper Auto Control	PA-22	11/24/1958	**		2210
318	Air Filter, Carburetor, System Modification	PA-18/18A	4/6/1959	754-223		7160
321	Piper Autocontrol	PA-18, 22 ***	7/8/1959			2210

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
324C	Maintenance And Inspection of Exhaust Systems And Heat Exchanges	PA-18, 22	1/22/69		62-26-05 68-05-01	7810	13I1
327	FAA Bureau of Flight Standards Release No. 434	All Models ***	12/28/59			General	13I11
328	Lycoming Service Letter #L126 Dated 1/24/60	PA-22	2/17/60			7200	13I19
329A	Oil Cooler Lines, Inspection of	PA-22	5/17/60	**		7920	13J3
348	Airspeed Indicators, Replacement of	PA-22-108	12/9/60	11339-16		3410	13K11
349	Bushings, Engine Support, Adjustment of	PA-18/18A PA-22	12/14/60	**	61-16-05	7100	13K12
353A	Propeller Decal	PA-22-108	2/20/61			6100	13K16
355	Stainless Steel Control Cables	PA-18/18A PA-20 PA-22	2/23/61	**	61-16-05	2700	13K19
358B	Mount Assemblies, Engine And Nose Wheel Inspection	PA-22	6/7/66			7120	13K23
362B	Windshield Top Attachment, Modification of	PA-15 PA-16/17 PA-20 PA-22	12/11/74	754-404 760-799 754-404 754-404	74-17-04	5610	13L7
369	Inspection of Brake Cable And Pulleys	PA-22 PA-22-108	3/7/62			3240	14A5
373	Dry Vacuum Pumps (Airborne Mechanisms), Models 113A1 And 113A5 Installation of Oil Shields	PA-22-108	3/29/62	756-143		3710	14A11
400	Tail Brace Rods	PA-20 PA-22	3/20/63	10555-02 10556-02	60-01-07	5510	14C11
405	Bearing, Nose Gear Upper Oleo, Inspection of	PA-22	10/1/63	452-419	64-05-04	3220	14C20
406	Revision To Owners Handbook	PA-20 PA-22	9/26/63			General	14C22
410	Inspection And Lubrication of Stabilizer	PA-22 Series	10/16/63			5500	14D6
423	Muffler And Tailpipe Support Kits	PA-22-108	5/5/64	756-803 756-804		7810	14E13
485	Scott Aviation Corporation Modification Instructions 1-298 For Constant Flow (Semi-Disposable) Mask, Scott PN 28302	All Aircraft With Subject Mask Assy.	2/8/67	756-332		3510	14J9
486A	Cylinder Head Temperature Probe Location	PA-18 PA-22	4/16/68			7720	14J13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
491	Aeromarine Instrument Company Service Bulletin No. 201	Aeromarine Airspeed Indicator Equipped Aircraft	8/8/67			3400 14J18
513	Service Memos And Service Aids	All Models	8/30/68			General 14L2
529A	Autopilot Gyro Instrument Overhaul Centers	Piper Autopilot Equipped Aircraft	1/14/70			3400 15A17
544	Revised Gyro Service Procedure	3" D.G. 1 Attitude Gyros	1/5/70			3420 15C7
573	B.F. Goodrich Service Bulletin No. E-68-36B (Sealer For B.F. Goodrich Deicer And Strap)	B. F. G. Deicer Systems	3/4/71			3020 15F17
608	Covering, Aircraft Ceconite	PA-18-150	1/31/72			5300 15J10
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
617B	Piper Automatic Locator Transmitter Replacement	PA-18	8/30/73		72-22-03	2560 15K18
633	Inspection And Repair of Flood Exposed Airplanes	PA-18 ***	10/9/72			5300 16A18
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-18, 22	10/24/72	**		2430 16B2
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-15 PA-16, 18, 20, 22	4/9/73	**		7610 16C14
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-22	4/19/74			7230 16F9
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974)	PA-22	5/3/74	**		2210 16G13
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-11	5/31/74	**		7410 16J18
740	Fuel Requirements	PA-16, 18, 20, 22	4/20/76			2800 17A3
820	Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-18-150	7/28/80	**	79-18-05	2560 17J2
828	Electrical System Refinement	PA-18-150	8/28/78			2400 17J16
944	Fuel Selector Valve Inspection And Lubrication	PA-18-150	4/20/82	**		2820 18K11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1016	Strut Cuff & Door Catch Attachment Improvement	PA-20,22	11/11/95	766-269 766-270		5701
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702
1093B	Electrical Contactor Replacement Kit	PA-18 Series PA-22 Series	11/28/2017	88371		2400
1116A	Contactor Maintenance	PA-18 Series PA-22 Series	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	J-2 Series J-3 Series J-4 Series NE-1 L-4 PA-11 PA-15/17 PA-16 PA-18 Series PA-20 Series PA-22 Series	4/27/2011	MS20995-C32		2800
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1302	Replacement Of Locking Gascolator Drain Valve	PA-11 PA-15 PA-16 PA-17 PA-18 Series PA-20 Series PA-22 Series	12/1/2022	492-022 492-312		2821

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
220	.040 Brass Safety Wire	PA-23	3/29/54			13C14
221	Carburetor Air Filter	PA-23	5/13/57			13C17
227	Service Publication To The Field	PA-23	9/24/54			13C19
229	Balancer For The Hartzell HC-82XG-2 Propeller	PA-23	10/7/54			13C21
231	Electrical System	PA-23	10/11/54			13D1
235	Flap Spar And Stabilizer Spar Reinforcement	PA-23	10/28/54			13D4
236	Cabin Heater Modification	PA-23	10/28/54			13D6
239	Cabin Draft	PA-23	1/3/55			13D7
240	Landing Gear Actuating Lever	PA-23	1/17/55			13D8
246	Engine Oil Thermostat Kit	PA-23	4/15/55			13D12
249	Heater Fuel Line	PA-23	5/24/55			13D15
250	Reference Service Bulletin #138 - Hydraulic Actuating Cylinders	PA-23	6/8/55			13D17
251	Carburetor Air Boxes	PA-23	9/16/55			13D19
252	Primer Pump	PA-23	9/16/55			13D20
255	Cabin Door Handle Bracket	PA-23	10/24/55			13D22
256	Heater Fuel Shutoff Valve	PA-23	11/21/55			13D24
266	Throttle, Prop And Mixture Control Levers	PA-23	2/19/56			13E6
270	Electrically Heated Airspeed Pitot Head	PA-23	3/9/56			13E7
271	Landing Gear Door Hinges And Hinge Brackets	PA-23	3/19/56			13E8
274	Ground Wire For Audio Speaker - Phone Selector Switch	PA-23	3/23/56			13E9
277	Brake Bleeding	PA-23	3/29/56			13E11
278A	Landing Gear Drag Link Assemblies	PA-23	2/28/57			13E18
280	Rerouting of Engine Breather And Oil Separator Discharge	PA-23	9/11/56			13E20
281	Engine Nacelle Air Baffle	PA-23	9/12/56			13E22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
283A	Inspection Forms, 100, 500, 1000 Hour	PA-23	2/26/58			500 13E24
286	Auxiliary Fuel Valve Control Modification	PA-23	10/8/56			13F1
288B	Accessories, Optional Equipment And Modification Kits	PA-23	1/6/58		General	13F2
289	Engine Breather And Oil Separator Discharge Line Stoppage	PA-23	1/18/57			13F5
290	Elevator Horn Bushing Wear	PA-23	1/21/57			13F6
291	Wheels And Brakes	PA-23	6/5/57			13F7
292	Drag Link Assemblies	PA-23	9/5/57			13F8
293A	Cabin Heaters	PA-23	12/13/57			13F11
295A	Aircraft Finishes	PA-23	1/3/64			13F12
300B	Propeller Feathering	PA-23	3/30/59			6120 13F17
303A	Aircraft Finishes	PA-23	9/23/59			13F23
306	Carburetor Heat Shroud Support Modification	PA-23	10/10/58	754-192		7310 13G19
307	Nacelle Fairing Installation	PA-23	10/10/58	754-175		5450 13G20
312	Tooling-Piper Autocontrol	PA-23	11/24/58	**		2210 13H4
313	Elevator Control Tube Nylon Sleeve Installation Kit	PA-23	1/6/59	754-215		2730 13H5
319	Draining of Apache Fuel Strainers	PA-23	4/13/59			7310 13H20
320	Nacelle Fairing Installation	PA-23	4/23/59			5450 13H21
321	Piper Autocontrol	PA-23	7/8/59			13H22
322A	Fuel System Control Valves	PA-23	10/12/59	**	60-03-08	7320 13H23
324C	Maintenance And Inspection of Exhaust Systems And Heat Exchanges	PA-23/23-250	1/22/69		62-26-05 68-05-01	7810 13I1
326	PA-23 Elevator Tabs	PA-23	12/28/59			5520 13I10
330	South Wind Bulletin Dated February 22, 1960	PA-23	5/5/60	751-776		2140 13J5
333C	Radio Shelf Capacities	PA-23-235/250 UO-1	1/28/63			3400 13J13
334	Fuel Cell Filler Neck Reinforcement	PA-23-250 UO-1	6/16/60	754-332		2810 13J14
336	Modification of Oil Pressure Lines	PA-23	6/17/60	19148-00		7930 13J17
338	Locking of Main Cabin Door	PA-23-250	7/12/60			5210 13J20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
340	Sealing of Fuel Cell Filler Neck Riveted Seam	PA-23-250	6/29/60			2810 13J24
345	Hartzell Service Bulletin #75- Inspection of Hartzell Governor For Presence of Vent Hole	PA-23-250	9/14/60			6120 13K5
350	Installation of Brush And Retainer Plate Assembly, (Electric Propeller) Deicer B.F. Goodrich	PA-23/23-250 UO-1	12/19/60			6110 13K13
354	Reinforcement of Aztec Stabilator Leading Edge	PA-23-250	5/25/61	30334-00		2730 13K17
359	Modification of Fuel Cell Vent Tubes	PA-23	8/16/61			2810 13L1
363	Inspection And Modification of Flaps	PA-23-250 UO-1	11/30/61	**		2750 13L10
367	"Thermos Bottle" Type Fuel Cell Caps	PA-23/23-250	2/1/62		68-13-03	2810 13L21
368	Lycoming Service Instruction No. 1049 Dated December 29, 1961	PA-23	2/7/62	**		7200 14A1
388	Removal of Carburetor Heat Shroud Screen	PA-23-235 PA-23-250	11/2/62			7160 14B12
398	Replacement of Fuel Control Valves "O" Rings	PA-23-235 PA-23-250	3/6/63	755-837		7320 14C7
404	Inspection of Pitch Servo Assembly Chain Adjustment Screw, Altimatic And Altimatic II	PA-23/23-235 PA-23-250	9/16/63	**		2210 14C17
407	Rudder Trim Tab Control Rod, Installation of Roll Pin In, And Inspection of	PA-23	10/4/63	480-728	63-24-03	2720 14C23
425	Lycoming Service Bulletin No. 298	PA-23-235 PA-23-250	5/13/64	**		7200 14E17
432	Inspection of Auxiliary Power Plug Solenoid	PA-23-250	8/25/64	487-153		2400 14F10
438	Priority Valve Actuating Cable, Clamping	PA-23-250	11/4/64	756-878		3250 14F21
441	Fuel System, Modification of, And Replacement of Electric Fuel Booster Pumps	PA-23-250	1/20/65	756-880		2820 14G6
449A	Fuel Cells	PA-23-235 PA-23-250	2/18/69		72-11-01	2810 14G16
454	Pitch Breakaway Ball Bracket (Altimatic II)	PA-23-250	7/1/65	756-954		2210 14G21
462	Inspection of Engine Mount Tubes	PA-23-250	12/9/65	31215-00 31215-01	68-07-04	7120 14H13
464A	Fuel Injection, Bendix RS	PA-23 PA-E23-250	11/12/65			7310 14I1
466A	Stewart-Warner Heater Modification Kit	PA-23 PA-E23-250	8/8/67	756-995		2140 14I4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
472	Conduct Installation Modification, B.F. Goodrich Service Bulletin No. E-65-30	PA-23 PA-E23-250	3/16/66	757-017		3020 14I12
474	Increase In Flap Extension Speeds	PA-23-235/250 PA-E23-250	4/21/66	757-000		2750 14I16
480	FAA Aircraft Specification No. 1A10 Item 1(1)	PA-23/E23-250	7/8/66		General	14J1
482	Altitude Limitation, 25,000 Ft. Removal of	PA-23 PA-E23-250	9/20/66	757-063		3410 14J2
483	Airesearch Service Information Letter No. S. I. L. P-08	PA-23 PA-E23-250	8/17/66			7200 14J5
486A	Cylinder Head Temperature Probe Location	PA-23/23-235 PA-23-250	4/16/68			7720 14J13
487	Test Unit, Hydraulic Part Number 753-080 And Stand	PA-23 PA-235/250	2/13/67	753-080		710 14J14
504	B.F. Goodrich Service Bulletin No. E-67-34	PA-23 PA-E23-250	4/8/68			3240 14K14
511	Auxiliary Power Receptacle Installation, Modification To The	PA-23-250	8/30/68	760-180		2400 14K23
519	Alternator Ground Wire, Replacement And Relocation of	PA-23-250	12/31/68	760-282		2430 14L17
520	Inspection of Turbocharger Plenum Exhaust Welds	PA-23-250	2/3/69	**		7230 14L19
522	Fuel Pump Restrictor Fitting	PA-23-250	1/14/69	760-275		2820 15A1
525	Addition of Lock Washers To Electrical Switch Installations	PA-23-250	2/28/69	407-103 407-133		2450 15A8
532	Voltage Regulation Component Grounding	PA-23-250	7/7/69	760-331		2430 15B2
533	Exhaust Stack Assembly	PA-23-250	11/10/69	32907-07		7810 15B5
545	Turbo (Lycoming) Aztec Owners Handbook And Power Setting Chart	PA-23-250	2/2/70	**		7220 15C10
547	Lycoming Turbocharger Aztec, Modification	PA-23-250	3/25/70	**		8120 15C15
550B	Density Control Adjustment, Turbocharger (Ref. Avco-Lycoming Dated 4/5/74)	PA-23-250	7/10/74			8120 15C21
559	Alternate Air System, Inspection of	PA-23-250	8/3/70	32343-00		7160 15E4
560	Scott Fuel Selector Valves	PA-23-250	8/7/70	757-520		2820 15E6
562	Scott Aviation Service Bulletin No. 35-32	PA-23-235/250 PA-E23-250	8/25/70	**		2820 15E10
564	Revised Hartzell Propellers	PA-23-250 PA-E23-250	9/28/70	**		6120 15E18
566	Spacer Bushing Installation, Autopilot Servo	PA-23 PA-E23-250	11/25/70	760-472		2210 15F3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-23-250 PA-E23-250	7/27/2011	N/A	2011-26-04	7310
579	Heavy Duty Brake Disc Replacement	PA-23-250 PA-E23-250	5/26/71	760-538		3240 15G16
580	Fuel Selector Valve Packing Lubrication	PA-23-235 PA-23-250 PA-E23-250	5/24/71			2820 15G18
582A	Exhaust System (Turbocharger) Inspection And Modification (Lycoming S.B. #339A)	PA-23-250	6/3/74	**	2008-14-07	8100 15G23
584	Circuit Breaker Switch Inspection, 90 Amp Alternator	PA-23-250	7/8/71			2430 15H4
585	Inspection of Hydraulic Lines	All Apache/Aztecs	7/9/71			2910 15H6
591	Inspection And Reinforcement Spar, Wing Front	PA-23-235 PA-23-250	8/31/71	760-521 760-524		5710 15H12
592	Mounts, Engine Shock (Lord)	PA-23-250	10/6/71	475-116 475-117		7120 15H14
593	Connector Plug, Harness, Strain Relief Hood Installation	PA-23-250 with Alt. V & VF/D	10/11/71	760-555		2400 15H15
606A	Fuel System, Inspection And Modification	PA-23-235 PA-23-250	8/23/72	**	72-11-01	2800 15J3
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
613	Brake Disc Inspection, Heavy Duty (Cleveland Aircraft Products S. B. #ESB-7002)	PA-23-250	5/11/72	760-538		3240 15K4
617B	Piper Automatic Locator Transmitter Replacement	PA-23-250	8/30/73		72-22-03	2560 15K18
619	Retainer Spring, Piper Part Number 83302-13, Inspection of	PA-23-235 PA-23-250	6/9/72			7330 15L5 7160
627	Propeller Installation	PA-23-250	9/1/72			6100 16A1
628	Control System Inspection, Stabilator Trim	PA-23-250	9/18/72	31970-03		2740 16A4
629	Fuselage Frame Tube Corrosion Inspection	All Apache/Aztecs	9/5/72	760-703		5320 16A8
630	Lubrication of Fuel Valve Selector Mechanism	PA-23-250	9/13/72	**		2820 16A11
633	Inspection And Repair of Flood Exposed Airplanes	PA-23	10/9/72			5300 16A18
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-23	10/24/72	**		2430 16B2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos)	PA-23	2/8/73			2210 16B7
641	Replacement Exhaust Stack Support Assembly	PA-23-250	2/26/73	760-702		7810 16B13
642	Alternator Inoperative Warning Light, Revised	PA-23-250	2/19/73	760-711 760-712		2730 16B15
645	Starter Vibrator Wiring Inspection	PA-23-250	4/12/73	492-431 492-644		8010 16B20
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-23 PA-23-235 PA-23-250	4/9/73	**		7610 16C14
655	Airesearch Service Bulletin No. 1172-1A; Reference Avco Lycoming Service Bulletin No. 361	PA-23-250 Turbocharged	4/10/73	**		7200 16C21
667A	Stabilator Attachment Bolts	PA-23-235 PA-23-250	3/4/74	**	74-13-03	2740 16E1
672	Wing Rear Spar Inspection	PA-23-150/160	9/18/73	**		5710 16E12
674	Overvoltage Relay Inspection	PA-23-250	1/3/74	760-787		2430 16E16
676	Weight And Balance/Equipment List Correction	PA-23-250	10/4/73			3200 16E20
682B	Reference Lycoming Service Bulletin 367D	PA-23-250	4/19/74	**		7230 16F9
683	Stabilator Control Cable Attachment Fittings Inspection	PA-23-250	10/3/73			2740 16F16
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974)	PA-23 PA-23-235 PA-23-250	5/3/74	**		2210 16G13
696	Control Surface Balancing Recommendation	PA-23-250	5/2/74			2700 16G20
705	Oil Tanks, Turbocharger Modification of, And Related Installation (Airesearch Service Bulletin No. 14.1.10 And 14.1.11 Dated February 6, 1974)	PA-23-250	4/16/74	**		8100 16H13
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-23 PA-23-235 PA-23-250	2/27/74	**		7710 16I11
710	Inspection of Stabilator Control Cable And Rudder Control Cable Attachments	PA-23-250	5/2/74			2740 16J1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
717	Brake Assembly Cylinder Retract, Improved (Cleveland Aircraft Products Service Letter No. 7000-5)	PA-23-250	9/18/74	751-507		3240 16J16
723	Glideslope Indicator Placard	PA-23-250	8/14/74	**		3430 16K11
726	Cigar Lighter Placard 24 Volt	All PA-23-235/ 23-250	8/8/74	80247-02		3310 16K16
740	Fuel Requirements	PA-23	4/20/76			2800 17A3
786A	Refined Engine Mount Assembly	PA-23-250	8/31/76	**		7120 17F15
807A	Stabilator Outboard Nose Rib Installation	PA-23-250	9/8/77	761-141	2021-25-11	5570 17H13
815	Radar Antenna Mounting Plate Inspection And Modification	PA-23-250	3/8/78	48881-02		3440 17I15
820	Replacement of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-23-250	7/28/80	**	79-18-05	2560 17J2
830	24 Volt Cigar Lighter Element Replacement	PA-23-250	11/22/77	**		3310 17J19
846	Stabilator Assembly Lower Surface Rivet Inspection	PA-23-250	5/3/78	**		2740 17K23
853	Inspection For Cracked Flap Spars At Hinge Area	PA-23 PA-23-235 PA-23-250	6/8/79	**	81-04-05	2750 17L20
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702 20C2
1086	Propeller Blade De-ice Boots Maintenance	PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250	7/16/2004	N/A		3112 20F3
1093B	Electrical Contactor Replacement Kit	PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250	11/28/2017	88371		2400
1116A	Contactor Maintenance	PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250	4/27/2011	MS20995-C32		2800

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1175	POH Report 1948 Equipment List	PA-23-250 Aztec "F"	12/2/2013	N/A		2500	
1188	Landing Gear Hydraulic System Filter Maintenance	PA-23-150/160 PA-23-235 PA-23-250	3/19/2015	N/A		2912	
1265	Flight Control System Checks	All	8/6/2019	N/A		2700	
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110	
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720	

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	All PA-24 Models	8/10/51				13B13
207	Oil Quick Drain Valve Assembly, Part No 12956-04	PA-24	6/18/53				13C4
283A	Inspection Forms 100/500/1000 Hour	PA-24	2/26/58			500	13E24
295A	Aircraft Finishes	PA-24 PA-30	1/3/64				13F12
299	Cabin Door Lower Hinge Reinforcement, Cabin Door Holder And Landing Gear Oil Level Instructions	PA-24-180 PA-24-250	6/10/58	**		5210	13F15
301	PA 24 Comanche Landing Gear	PA-24	8/12/58			3200	13F20
302	Fuel Gauge Ground Wire	PA-24-180/250	8/19/58			2840	13F21
303A	Aircraft Finish	PA-24	9/23/59			5300	13F23
305	Miscellaneous Modifications; Door Latch, Oil Separator Inlet Hose, Landing Gear Retraction Tube Arm	PA-24-180/250	10/1/58	**	58-25-05	5200 7920 3230	13G14
310	Locking of Landing Gear Motor Release Arm	PA-24-180/250	11/10/58			3230	13H1
311	PA-24 1959 Owners Handbook	PA-24	11/22/58			General	13H3
312	Tooling - Piper Autocontrol	PA-24	11/24/58	**		2210	13H4
314A	Landing Gear Warning System	PA-24-180/250	6/8/59	754-221 754-217		3260	13H6
315	PA-24 Comanche Landing Gear Transmission Assembly	PA-24	2/4/59			3200	13H7
316	Cabin Sealing	PA-24-180/250	4/7/59	**		5300	13H16
317	50 Ampere Generator Installation	PA-24-180/250	4/6/59	754-230		2400	13H18
321	Piper Autocontrol	PA-24	7/8/59			2210	13H22
323	Defroster Operation	PA-24-180/250	11/23/59			2140	13H24
324C	Maintenance And Inspection of Exhaust Systems And Heat Exchanger	PA-24	1/22/69		62-26-05 68-05-01	7810	13I1
325	Front Cabin Window Defroster Kit	PA-24-180/250	12/24/59	754-293		2140	13I9
333C	Radio Shelf Capacities	All PA-24	1/28/63			3400	13J13
339	Insulation of Wiring At Starter Solenoid Switch	PA-24-180/250	7/12/60	13586-94		8010	13J21
345	Hartzell Service Bulletin #75 - Inspection of Hartzell Governor For Presence of Vent Hole	PA-24-250	9/14/60			6110	13K5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
346	Relocation of Safety Belt Buckle - Right Front Seat Only	PA-24-180/250	9/29/60			5340 13K8
347	Installation of Dry Vacuum Pump, Exhaust Tube	PA-24-180/250	12/2/60	754-358		3710 13K9
352	Modification of Windshield Defroster System	PA-24-180/250	12/28/60	754-380		2140 13K14
356	Installation of Landing Gear Retraction System, 30 Amp Circuit Protector	PA-24-180/250	3/31/61	454-661	63-27-03	3230 13K21
360	Flap Retractor	PA-24-180/250	9/5/61	754-413		2750 13L3
364A	Rubatex Blocks In Detached Or Loose Wing Panels	PA-24-180/250	3/14/62			5700 13L15
365	Special Bolt For Nose Gear Drag Link	PA-24-180/250	1/3/62	22066-00		3200 13L17
366	Nose Gear Clevis	PA-24-180/250	1/3/62	20859-03	65-25-03	3220 13L19
367	Caps, Fuel Cell, "Thermos Bottle" Type	PA-24-180/250	2/1/62		68-13-03	2810 13L21
368	Lycoming Service Instruction #1049 Dated 12/29/61	PA-24-250	2/7/62	**		7200 14A1
370	Modification To Engine Breather Line	PA-24/24-250	2/23/62			7200 14A7
372	Landing Gear Switch	PA-24-250	3/8/62			3230 14A10
373	Dry Vacuum Pumps (Airborne Mechanisms) Models 113A1 And 113A5, Installation of Oil Shields On	PA-24-180/250	3/29/62	756-143		3710 14A11
379	Landing Gear Safety Switch Harness	PA-24-180/250	8/10/62	754-475	64-22-03	3200 14A20
380	Door Hinges, Main Landing Gear, And Nose Gear Door Hinge Bushings	PA-24-180/250	8/8/62	**		3210 14A22
382	Redesigned Landing Gear Selector Switch Knob	PA-24-250	9/27/62	**		3200 14B1
393	Replacement of Bendix Fuel Pump	PA-24-250	2/1/63	481-686		2820 14B22
395	Flap Retraction Springs	PA-24-250	2/11/63	83302-54		2750 14C1
397	Inspection of Alternate Air Door Hinge Pin	PA-24-250	2/21/63			7160 14C5
404	Inspection of Pitch Servo Assembly Chain Adjustment Screw Altimatec And Altimatec II	PA-24-180/250	9/16/63	**		2210 14C17
408	Installation of Fuel Valve Control Stop	PA-30	10/9/63	756-774		7320 14D1
409	Replacement of Nose Gear Retraction Tube	PA-30	10/9/63	21109-05	64-16-06	3230 14D4
411	Drain Holes In PA-30 Cowling	PA-30	10/17/63			7110 14D8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
412A	Muffler And Tailpipe Support	PA-24-250	5/6/64	756-775	68-05-01	7810 14D11
414	Modification of Right Side Exhaust Stack	PA-24-250	11/27/63	756-777 756-778		7810 14D15
415	Sealing of The Nose Wheel Well	PA-30	12/3/63			3240 14D18
416	Heater Valve Friction Spring Installation	PA-30	12/3/63	756-779		2140 14D20
417	Replacement of Fuel Injector Inlet Screens	PA-30	12/16/63	756-782		7310 14E1
418	Replacement of Fuel Flow Gauge	PA-30	12/16/63	24536-00		7330 14E3
419	Inspection of Heater Air Distribution Box Attachment Screws	PA-30	2/24/64	**		2140 14E4
420A	Removal of Vanes From Throat of Carburetor Air Box	PA-24-250	3/10/72		64-10-04	7200 14E6
422	Rework of Propeller Spinner Assembly	PA-30	3/10/64	756-796		6110 14E11
424	Installation of "Generators On" Placard	PA-30	4/20/64	**		2430 14E15
425	Lycoming Service Bulletin No. 298	PA-24-180/250	5/13/64	**		7200 14E17
426	Propeller Flange Inspection, Crankshaft (Per Lycoming Service Bulletin No. 300) And Propeller Blades, Inspection of (Per Hartzell Service Bulletin No. 86)	PA-30	6/26/64			6110 14E22
430	Inspection of Nose Gear Drag Link Assembly	PA-30	8/17/64			3220 14F6
431	Insulation of Motor Mounts	PA-24-250	9/2/64	756-831		7120 14F8
433	Installation of Placard, (Cowl Flaps Open)	PA-24-400 PA-30	9/9/64	755-881		7110 14F12
434	Lycoming Service Instruction #1110	PA-24-250	9/30/64	25006-00		7200 14F14
435	Relocation of Nose Wheel Steering Tube Boot	PA-24-250	9/30/64	21378-00		3250 14F15
437	Replacement of Fuel Gauge Assembly	PA-24-400	11/4/64	450-771		2820 14F19
439	Lycoming Service Bulletin No.300A	PA-30	11/13/64			6110 14G1
440	Engine Compartment Changes	PA-24-400	12/3/64	**		7200 14G4
444	Installation of Special Steel Fittings On Auxiliary Fuel Pumps	PA-24-250	2/24/65	751-268		2810 14G9
445	Installation of Nose Gear Drag Link Clevis Reinforcement Bracket	PA-24-180/250	4/21/65	756-911		3270 14G11
446	Fuel Leakage At the Fuel Cell Gauge	PA-24-400	3/1/65	756-902		2810 14G13
447	Inspection of Landing Gear Transmission Retract Spring	All PA-24 PA-30	3/26/65	**		3230 14G14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
449A	Fuel Cells	PA-24-180/250/400 PA-30	2/18/69			2810 14G16
451	Fuel System Purging Valve	PA-24-400	5/14/65	756-922	66-30-07	2810 14G18
453	Engine Mount Refinishing	PA-24-400	8/23/65	756-306		7110 14G19
459	Mixture Control Cable Shield	PA-24-400	10/6/65	25079-00		7320 14H8
460	Revision To PA-30 Service Manual And Owner's Handbook	PA-30	9/17/65			3260 14H10
461	Inspection of Propeller Blades	PA-30	9/28/65			6110 14H11
464A	Bendix RS Fuel Injection	PA-24-250/260 PA-30	11/12/65	**		7310 14I1
465	Airworthiness Directive No. 65-25-03	PA-24/24-250	12/20/65			1617 14I3
469	Replacement of Allowance Placard, Baggage/Passenger	PA-24-260	2/11/66	756-997		5430 14I7
470	Starter Vibrating	PA-24-400	4/1/66	492-671		8010 14I8
477	FAA Airworthiness Directive No. 66-12-2 (Temporary Revision To Airspeed Limits)	PA-30	5/18/66			3410 14I19
478	Inspection of Baggage Door Latch Enlargements	PA-24-260	6/13/66		66-18-04	5210 14I22
481	Muffler And Tailpipe Support	PA-24-250	9/15/66	757-058	68-05-01	7810 14J2
486A	Cylinder Head Temperature Probe Location	PA-24	4/16/68			7720 14J13
490	Rajay Corporation Service Letter No. 10 (Relocation of Turbocharger Low Oil Pressure Warning Light Wire)	PA-30	6/28/67	757-312		7930 14J16
511	Modification To The Auxiliary Power Receptacle Installation	PA-24-260 PA-39	8/30/68	760-181 760-711		2400 14K23
516	Modification Fuel Cell Vent System	PA-24-180/250	3/7/69	760-277 760-281	68-13-03	2810 14L11
518	Modification of Exhaust Mufflers	PA-24-260	1/22/69	760-289	68-05-01	7820 14L14
525	Addition of Lock Washers To Electrical Switch Installations	PA-30	2/28/69	**		2400 15A8
532	Voltage Regulator Component Grounding	PA-30	7/7/69	760-332		2430 15B2
539	Fuel Selector Valve Control Handle Replacement	PA-30	2/18/70	760-356 760-357		2820 15B20
541	Fuselage Nose Cone Drain Holes	PA-30	12/4/69			5350 15C1
542	Control Surface Travel And Cable Tension	PA-30	2/17/70			2700 15C3
543	Induction System Drain Tube Relocation	PA-24-260 "C"	11/17/69	760-351		7160 15C5
546A	Nose Gear Push-Pull Rod Assembly	PA-24-180/250 PA-24-400	3/10/70	757-352		3250 15C12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
549	New Owner's Handbook	PA-30	3/20/70	**		General 15C19
552	Counter Rotating Power Plant Conversion-Kit	PA-30	5/1/70	760-368		7100 15D3
556A	Turbocharger Waste Gate Return Spring	PA-30/39	9/21/70	**		8120 15D17
557	Rajay Oil Scavenge Pump	PA-30	6/16/70	**		7250 15D19
558	Air Flow Modification Kit	PA-30	7/1/70	760-409		2700 15E1
564	Revised Hartzell Propellers	PA-30/39	9/28/70	**		6120 15E18
565	Rear Cabin Dome Light Mounting Screw	PA-24-260 PA-30/39	10/13/70			3320 15F1
566	Autopilot Servo Spacer Bushing Installation	PA-24-260 PA-30/39	11/25/70	760-472		2210 15F3
569	Engine Compartment Modifications	PA-24-260	12/28/70	760-463		7200 15F14
574	Revision To Emergency Gear Checklist	PA-24-260 PA-30/39	3/22/71			3200 15F20
575	Landing Gear (Nose) System Inspection	PA-30/39	4/8/71			3220 15F23
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-24-250/260 PA-24-400 PA-30/39	7/27/2011	N/A	2011-26-04	7310
584	90 Amp Alternator Circuit Breaker Switch Inspection	PA-30/39	7/8/71			2430 15H4
589	Stainless Steel Fuel Selector Valve Housing	PA-30	8/18/71	757-187	83-10-01	2820 15H10
595	Wing Flap System Maintenance	PA-24-250/260 PA-24-400 PA-30/39	10/11/71			2750 15I1
596A	Nose Landing Gear System Product Advancement Information	All PA-24 PA-30/39	9/5/75	**		3220 15I3
598	Adjustable Duct Micro Switch Inspection	PA-39	11/16/71	487-940		2140 15I9
599	Exhaust Wing Panel Corrosion Protection	PA-30/39	11/23/71			5750 15I10
605	Reissue of Owner's Handbook	PA-24-260T	2/7/72	**		8100 15J1
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
610	Tail Control Surface Inspection, Maintenance And Repair Information PA-24 Comanche Service Manual Temporary Revision TR 720127	All PA-24	2/28/72	**		2700 15J23
617B	Piper Automatic Locator Transmitter Replacement	PA-24 PA-39	8/30/73		72-22-03	2560 15K18
623	Inspection of Rajay Alternate Air Valve Bracket	PA-30/39 T.C.	8/9/72	**		7160 15L14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
627	Propeller Installation	PA-24-260 PA-30/39	9/1/72			6100 16A1
633	Inspection And Repair of Flood Exposed Airplanes	PA-24 PA-39	10/9/72			5300 16A18
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-24 PA-30	10/24/72	**		2430 16B2
637	Rajay Service Letter No. 19, Dated September 5, 1972	PA-30/39 T.C.	10/31/72	**		7160 16B5
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication—Rack And Pinion Type Servos)	PA-24 PA-30	2/8/73			2210 16B7
642	Revised Alternator Inoperative Warning Light	PA-39	2/19/73	760-711		2430 16B15
648	Battery Ground Inspection And Modification	PA-24-260 "C"	3/8/73			2430 16C2
650	Inspection of Transmission Assemblies, Landing Gear Retraction And Flap Control	PA-24-180/250 PA-24-260/400 PA-30/39	9/27/73	**		3230 16C5 2750
651	Rudder Balance Weight Arm Attachment Angle Installation Kit	PA-24-180/250 PA-24-260	2/27/73	760-732		2720 16C10
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-24 PA-30	4/9/73	**		7610 16C14
657	Fuel Selector Valve Control Handle Modification	PA-30/39	9/13/73	760-788		2820 16D3
665A	Intake Valves; Rotator Type (Reference Avco Lycoming Service Instruction No. 1280 A. 9/28/73)	PA-24-400	10/24/73	**		7160 16D16
667A	Stabilator Attachment Bolts	PA-24-260/400 PA-30	30/4/74	**	74-13-03	2740 16E1
679	Fuselage Aft Bulkhead Inspection	PA-30/39	1/21/74	760-783	74-16-08	5310 16F2
682B	Reference Lycoming Service Bulletin 367D	PA-24-250 PA-24-400 PA-30	4/19/74	**		7230 16F9
686	Inspection of Fuel Pressure Hose Assembly	PA-24-250/260	1/3/74	17766-43		7330 16F20
687	Stabilator Modification	PA-24-250/260	6/19/74	760-747	72-22-05	2740 16F23
695	Roll Servo Inspection, Maintenance And Sheer Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38 Dated March 18, 1974)	PA-24 PA-30	5/3/74	**		2210 16G13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
696	Control Surface Balancing Recommendation	PA-24 PA-30/39	5/2/74			2700 16G20
707	Flyball Assembly To Improve RPM Control. Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-24 PA-30/39	2/27/74	**		7710 16I11
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-24	5/31/74	**		7410 16J18
751	Fin Front Spar Modification	PA-24-180-250 PA-24-260/400	7/7/75			5520 17A23
758	Bendix Ignition Switches, Inspection of; Ref: Bendix Service Bulletin No. 583	PA-24-180/250 PA-24-260/400	5/17/76	761-065V		7410 17C2
772	Stabilator Attachment Bolts	PA-39	2/16/76	**	74-13-03	2740 17E4
777	Fin Front Spar Modification	PA-30/39	6/16/76		76-18-05	2740 17E12
782B	Landing Gear Manual Extension System And Nose Gear Down Lock Spring Installation	PA-24 PA-24-250/260 PA-24-400 PA-30/39	12/1/77	**	77-13-21	3230 17E23
787	Aileron Spar Inspection And Reinforcement	PA-24/24-250/260 PA-24-400 PA-30/39	12/1/76	760-914	77-08-01	5750 17F17
850	Aileron Nose Rib Inspection/Reinforcement	PA-24 PA-24-250/260 PA-24-400 PA-30/39	4/18/79		79-20-10	5750 17L8
851	PART A - Fuel Valve Internal Leak Check	PA-24-400 PA-30/39	8/31/78	**	79-12-08	2810 17L11
851	PART B - Fuel System Draining Procedure-Water Contamination	PA-30/39	8/31/78	**	79-12-08	2810 17L12
851	PART C - Fuel System Draining Procedures-Water Contamination	PA-24-400	8/31/78		79-12-08	2810 17L14
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702 20C2
1093B	Electrical Contactor Replacement Kit	PA-24 PA-24-250/260 PA-24-400 PA-30	11/28/2017	88371		2400

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1116A	Contactora Maintenance	PA-24 PA-24-250/260 PA-24-400 PA-30/39	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	PA-24 PA-24-250/260 PA-24-400	4/27/2011	MS20995-C32		2800
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
177	Firewalls	All PA-28/28R Models	8/10/51			13B13
295A	Aircraft Finishes	All	1/3/64			13F12
324C	Maintenance And Inspection of Exhaust Systems And Heat Exchanges	PA-28-140/150/160/180/235	1/22/69		62-26-05 68-05-01	7810 1311
373	Installation of Oil Shields On Dry Vacuum Pumps (Airborne Mechanisms, Models 113A1 And 113A5)	PA-28-150/160	3/29/62			3710 14A11
374	Modification of Bulkhead To Prevent Control Cable Interference	PA-28-150/160	4/10/62	754-461V		5310 14A13
375	Control Shaft-Left Hand, Installation of Micarta Sleeve On	PA-28-150/160	4/12/62	62852-00V		2700 14A15
381	Replacement of Wing Panels Service	PA-28-150/160	7/9/62	**		5730 14A23
386	Miscellaneous Airframe Modifications	PA-28-150/160	9/4/62	**		5300 14B7 5320 5550
389	Inspection of Exhaust Stacks	PA-28-150/160	12/11/62	**	62-26-05	7810 14B13
390	Cherokee Gas Cap Placard	PA-28-150/160/180	1/3/63	62142-00V		2810 14B16
391	Cherokee Sun Visors	PA-28-150/160/180	1/11/63	63230-00V		2510 14B18
394	Radio And Auto Control Cooling Kits	PA-28-150/160/180	2/4/63	754-477V 754-494V		2300 14B23
396	Inspection of Shaft Assembly (On Control T-Bar And Control Wheels), Double Sprocket	PA-28-150/160	2/14/63	62818-00V	64-06-06	2710 14C2
402	Installation of Heat Shield Kit	PA-28-150/160/180	5/22/63	756-727		2140 14C13
413	Inspection of Nose Gear (Upper) Oleo Bearing	PA-28-150/160/180	11/25/63	452-419		3230 14D13
421	Inspection of Oil Coolers	PA-28-235	3/4/64	18622-00		7920 14E9
425	Lycoming Service Bulletin No. 298 (Ac Fuel Pump Vent Restriction)	PA-28-140/150/160 PA-28-180/235	5/13/64	**		2800 14E17
427	Fuel Cooling Modification	PA-28-150/160/180	6/29/64	**		2820 14F2
429	Replacement of Oil Coolers	PA-28-235	8/10/64	**		7920 14F3
436	Check of Alternator Through Bolts	PA-28-140/150/160 PA-28-180/235	10/9/64	753-210V		2430 14F17
442	Lycoming Service Instruction No. 1110 (Ac Fuel Pump Replacement)	PA-28-140/150/160 PA-28-180/235	12/14/64	**		2820 14G7
443	Oil Line Relocation Kit	PA-28-150/160/180	1/27/65	756-905V		7920 14G8
450	Stabilator Trim Installation	PA-28-140/150/160 PA-28-180/235	9/24/65	**		2740 14G17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
456	Cherokee 235 Constant Speed Propeller Control	PA-28-235	6/4/65	756-959V		6120 14H2
457	Plastic On The Cherokee C Spinners	PA-28-150/160/180	6/29/65	756-963V	66-20-05	6110 14H3
458	Throttle Clamp	PA-28-140/150/160 PA-28-180/235	10/8/65	554-860V		7610 14H5
471A	Inspection of Propeller Spinner And Spinner Attaching Bulkhead	PA-28-150/160/180	5/23/66	**	66-20-05	6110 14I9
473	Sensenich Service Bulletin No. R-11 (Inspection of Mid-Blade Area of 76 EMM And 76 EMMS Propellers)	PA-28-180	3/1/66			6110 14I14
484	Fuel System Operating Procedures	PA-28-235	12/20/66			2800 14J7
486A	Cylinder Head Temperature Probe Location	PA-28-140/150/160/180/ 235	4/16/68			7720 14J13
494	Inspection of Cherokee Landing Gears	PA-28-140/150/160 PA-28-180/235	11/7/67	**		3200 14J24
495	Inspection of Constant Speed Propeller Control Cable	PA-28-235	1/29/68	**		6120 14K2
501	Oil Sump Drain Valve	PA-28R-180	5/2/68	756-517		7160 14K10
503	Inspection of Oil Cooler Hose	PA-28-140	4/18/68			7920 14K13
526	Sensenich Service Bulletin No. R-13	PA-28-140/150/160/180/ 235	5/15/69	760-325V		6100 15A11
527D	Inspection of Control Wheels	PA-28-140/150/160 PA-28-180/235	6/21/78	**	69-22-02	2700 15A14
534A	Availability of Engine Oil Quick Drain Valve	PA-28R-200	1/7/70	492-172V		7920 15B7
535A	Rudder Trim Locking Pin	PA-28-140/180/235 PA-28R-180/200	9/26/69			2720 15B9
561	Inspection of Cherokee Muffler Assembly	PA-28-140/150/160/S160 PA-28-180/S180	8/12/70	99482-00V 99482-02V		7820 15E8
566	Autopilot Servo Spacer Bushing Installation	PA-28-140/180/235 PA-28R-180/200	11/25/70	**		2210 15F3
567	Flight Manual Supplement (Expanded Center of Gravity Range)	PA-28-180/235	1/25/71	**		3200 15F6
568	Inspection of Engine Mount Tubes	PA-28R-180/200	1/5/71	**		7120 15F8
571	Flap Handle Assembly Modification	PA-28-140/150/160/180/ 235 PA-28R-180/200	3/30/71	400-673		2750 15F15
576	Stabilator Balance Weight Tube Replacement	PA-28-140/150/160 PA-28-180/S180/235 PA-28R-180/200	4/20/71			5510 15G2
577	Replacement Bridle Cable Servo Clamp	PA-28-140/150/160 PA-28-180/235 PA-28R-180	6/1/71	757-863V		2210 15G8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-28R-180/200 PA-28R-201 PA-28RT-201	7/27/2011	N/A	2011-26-04	7310
581	Inspection of Aileron Hinge Doublers	PA-28-140/150/160/180/235 PA-28R-180/200	7/12/71	760-540V		5550 15G20
587	Engine Baffle Modification	PA-28R-200	9/16/71	760-558V		7230 15H9
607	Emergency Gear Lever Knob	PA-28R-180/200	2/18/72	66980-02V	72-04-03	3200 15J9
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
611	Repositioning of Oil Cooler Hose	PA-28-140	4/28/72	760-599V		7920 15J24
612A	Fuel Leakage - Fuel Sender Unit	PA-28-140/150/160/180/235 PA-28R-180/200	6/8/72	68101-00V		7330 15K1
614	Stabilator Attachment Fittings Bolt Torque	PA-28-140/150/160/180/235 PA-28R-180/200	6/15/72		72-14-07	2740 15K6
615	Stabilator Drain Holes	PA-28-140/150/160/180/235 PA-28R-180/200	7/6/72			2740 15K8
616	Main Landing Gear Trunnion Repair	PA-28R-180/200	8/3/72	**		3210 15K14
617B	Piper Automatic Locator Transmitter Replacement	PA-28-140/180/235 PA-28R	8/30/73		72-22-03	2560 15K18
620	Forward Cabin Door Reinforcement	PA-28-140/150/160 PA-28-180/235/28S-180 PA-28R-180/200	2/23/73	760-729V		5210 15L8
621	Main Landing Gear Torque Link Replacement	PA-28-140/150/160/180/235	11/9/72	78032-00V		3210 15L10
626	Landing Gear Bolt Lubrication	PA-28R-180/200	11/20/72			3200 15L23
634	Revision Pilot's Operating Manual	PA-28R-200	12/14/72	**		1200 16A23
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-28-180 PA-28R-200	10/24/72	**		2430 16B2
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos)	PA-28-150/160/180/235	2/8/73			2210 16B7
644	Precautionary Throttle Operating Placard	PA-28-140/150/160	2/8/73	76406-00V	72-24-02	7610 16B19
647	Seat Back Stop Modification	PA-28-140/180/235 PA-28R-200	3/31/73	760-740V		2510 16C1
649	Airplane Flight Manual/Weight And Balance Revision	PA-28-235	5/3/73	**		800 16C4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-28-140/150/160/180/235	4/9/73	**		7610 16C14
662	Engine Mount Bolt Torque	PA-28-140/150/160/180/235 PA-28R-180/200	7/6/73	AN960-616		7120 16D10
665A	Inspection of Intake Valves, Rotator Type Knob, Emergency Gear Lever	PA-28R-200	10/24/73	**		7160 16D16
670A	Throttle Control Modification	PA-28-140	6/24/74	760-780V 760-872V	74-13-04	7610 16E7
671	Rudder Bar Assembly Inspection And Modification	PA-28-140/150/160/180/235 PA-28R-180/200	10/5/73			2720 16E9
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No 367D)	PA-28 PA-28R	4/19/74			7230 16F9
684	Landing Gear Lubrication	PA-28R-200	1/9/74			3200 16F18
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No ML-38, Dated March 18, 1974)	PA-28-150/160/235	5/3/74	**		2210 16G13
700	Toe Brake System Modification	PA-28-140/151 PA-28-180/235 PA-28R-200	4/9/74	760-842V		3240 16H5
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No 75, Dated November 16, 1973)	PA-28-235 PA-28R-180/200	2/27/74	**		7710 16I11
715	Emergency Locator Transmitter Switch Cover Modification	PA-28-140/151 PA-28-180/235 PA-28R-200	9/27/74	760-876V		2560 16J12
718	Bendix Magneto Bulletin No 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-28R	5/31/74	**		7410 16J18
720	Fuel Quantity Placard Inspection, Section I, Landing Light WIRE Rerouting, Section II	PA-28-235	6/26/74	**	74-18-06	2840 16K2 3340
731	Cherokee Warrior Product Refinement Program	PA-28-151	10/15/74	760-854 760-855 760-856		2800 16L1 3340 6110 7110 7160 7230 7920

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-28-140/151/180/235 PA-28R-200	12/3/74	760-857V		3450 16L8
735	Muffler Shroud Modification	PA28-151/180	12/11/74			7820 16L11
738A	Modification of The Overhead Fresh Air Vent System	PA-28-140/180/235 PA-28-151 PA-28R-200	1/14/75	760-900V 760-901V 760-902V		2120 16L20
740	Fuel Requirements	PA-28-140/150/151/160/ 180/181/235	4/20/76			2800 17A3
744	Steering System Modification	PA-28-140/151 PA-28-180/235	4/29/75			3250 17A13
745	Inspection of Wing Main Spar Attach Bolts	PA-28-140/151/180/ 235 (Crated) PA-28R-200 (Crated)	4/24/75	404-890		5710 17A14
747	Inspection of Throttle And Mixture Control Attachments	PA-28-180/235 PA-28R-200	5/28/75	**		7610 17A18
749	Torque Link Greaser Bolt Replacement Kit	PA-28-140/150/151 PA-28-160/180/181/235	10/14/75	760-910V		3210 17A21
756	Glideslope Indicator Placard, Dual (King Radio Installations Only)	PA-28-151/180/235 PA-28R-200	1/6/76	69669-112V		3430 17B22
758	Bendix Ignition Switches. Inspection of; Re: Bendix Service Bulletin No 583	PA-28-140/151 PA-28-180/181/235 PA-28R-180/200	5/17/76	761-065V		7410 17C2
761	Magnetic Compass Relocation Kit	PA-28-140/150/151 PA-28-180/235 PA-28R-180/200	11/17/75	760-795V		3440 17C14
762	Modification of ELT Remote Switches	PA-28-140/151/180 PA-28-181/235 PA-28R-200	1/26/76	760-009V		2560 17C15
763A	Seat Retention Mechanism Inspection, Rear Leg Quick-Disconnect	PA-28-180/235 PA-28R-180/200	11/14/75	**	75-24-02	2510 17C16
785	Carburetor Induction Air Shroud Modification	PA-28-151	9/15/76	**		7160 17F13
788	Air Conditioning Installation	PA-28-140/180/181 PA-28R-200	9/3/76	79584-02V 79589-05V		2150 17F19
793	Flap Warning Placard	PA-28-140/150/151/160/ 180/181/235 PA-28R-180/200 PA-28R-201/201T	1/6/77	35664-02		2750 17G5
796	Lower Cowl Drain Inspection	PA-28-150/160 PA-28-180/181/235	3/30/77			7100 17G10
800	Refinement of Narco ADF-140 Installation Performance	PA-28-140/151 PA-28-180/181/235 PA-28R-200	2/25/77	**		3450 17G19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
808	Hydraulic Pump Terminal Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T	6/8/77	**		2910 17H14
810	Backup Diaphragm Replacement Landing Gear Extender	PA-28R-180/200 PA-28R-201/201T	4/15/77	761-138V		3230 17H18
813	Vertically Adjustable Seat Refinement	PA-28-140/151/161 PA-28-180/181 PA-28R-200/201/201T PA-28R-235	6/9/77	**		2510 17I8
814	Refinement Program Cherokee III And Turbo Arrow III	PA-28R-201 PA-28R-201T	9/26/77			5300 17I10
814	Part I - Engine Mount Painting	PA-28R-201T	9/26/77	763-415V		7100 17I10
814	Part II - Aileron Bellcrank Stop Assembly	PA-28R-201 PA-28R-201T	9/26/77	761-142V		2710 17I11
814	Part III - Winterization Plate	PA-28R-201T	9/26/77	37793-02V		7200 17I11
814	Part IV - Landing Light Wire Rework	PA-28R-201T	9/26/77			3340 17I12
814	Part V - Exhaust Heat Shield	PA-28R-201T	9/26/77	486-648V		7810 17I12
820	Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-28-140/151/161 PA-28-180/181 PA-28-235 PA-28-236 PA-28R-200/201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180	7/28/80	**	79-18-05	2560 17J2
826	Spinner Bulkhead Doubler	PA-28-151/161	8/25/77	35667-02V		6110 17J14
832	Wheel Well Reinforcement	PA-28R-180/200/201 PA-28R-201T	1/25/78			3240 17J21
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-28-140/180/235 PA-28-151/161 II/181 II PA-28R-200 PA-28R-201/201T	2/9/78	**		3450 17K4
842	Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement	PA-28-140/150/151 PA-28-160/161 PA-28-180/181 PA-28-235	9/26/78	760-910V		3210 17K17
845	Engine Breather Tube Winterization Kit	PA-28-140/150/160/180 PA-28-151/161 II/181 II PA-28R-180/200 PA-28R-201	7/7/78	763-828V		7250 17K22
848	Exhaust Heat Shield	PA-28R-201T	6/21/78	763-843V		7810 17L4
856	Fuel Drain Cover Replacement	PA-28-235	9/15/78	763-883V	78-23-01	2810 18A21
859	Landing Light Installation Modification	PA-28-151/161	11/8/78	760-854V		3340 18B2
860	Engine Exhaust System Modification	PA-44-180	12/4/79	**		7810 18B4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
861	Part I - Forward Facing Seat Back Modification	PA-28-140/151/161 PA-28-180/181/235/236 PA-28R-200/201 PA-28R-201T PA-44-180	11/13/78	763-890V		2520 18B7
862	Main Landing Gear And Strut Fairing Replacement	PA-28-161/181 PA-28-236	3/30/79	763-918V		3210 18B11
863	Master Relay Diode Assembly - Refinement	PA-28-181 PA-28R-201 PA-28R-201T	11/17/78			2450 18B13
864	Part I - Forward Cabin Door Stop (Striker Plate) Installation	PA-28-140/151/161 PA-28-181/235/236 PA-28R-200/201 PA-28R-201T	12/8/78	**		5210 18B16
864	Part II - Cabin Heat Control Refinement	PA-28-140/151 PA-28-161/180/181 PA-28-235/236 PA-28R-180/200/201 PA-28R-201T	12/8/78	763-870V 763-871V		2140 18B19
864	Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision	PA-28-140/150 PA-28-160/180 PA-28-235	12/8/78	763-874		3420 18B20
867	Part I - Engine Baffles Reinforcement	PA-44-180	10/10/79	**		7230 18C4
867	Part II - Replacement of Nose Landing Gear Micro Switch Bracket	PA-44-180	10/10/79	763-925V		3230 18C5
867	Part III - Cowl Fastener Relocation	PA-44-180	10/10/79	420-690		7110 18C5
867	Part IV - Cabin Heater Air Inlet Valve Modification	PA-44-180	10/10/79	**		2140 18C6
867	Part V - Battery Box Drain Clamp Replacement	PA-44-180	10/10/79	454-983		2430 18C7
867	Part VI - Tachometer And Manifold Pressure Gauges Available Light Increase	PA-44-180	10/10/79			7710 18C7
867	Part VII - Landing Light Grounding Strap Installation	PA-44-180	10/10/79	**		3340 18C8
891	Air Induction Filter Retainer Improvement	PA-28-151/161	3/4/81	87349-02V		7160 18F24
895A	Magneto Switch Modification	PA-28R-201 PA-28RT-201T	3/19/81	153-010 488-396		7430 18G8
899	Part I - Aft Spinner Bulkhead Refinement	PA-28-161	10/3/80	36757-003V		6110 18G16
899	Part II - Forward Spinner Bulkhead Refinement	PA-28-161	10/3/80	**		6110 18G17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
901	Cabin Air Intake Duct Modification	PA-28-161/181/236 PA-28RT-201/201T PA-44-180	9/2/80	764-013V		2120 18G22
903A	Alternator Belt Installation (Air Conditioned Models)	Any Textron-Lycoming Powered PA-28	3/11/96	62833-82		2431 18H2
905	Compass Deviation-Battery Ground Wire Replacement	PA-28RT-201	1/21/81	764-087V		2430 18H7
906	Lower Cowl Exhaust Fairing Replacement	PA-44-180	4/21/81	**		7110 18H8
907	Weight And Balance Plotter Modification	PA-44-180	1/22/81	764-040V		800 18H10
908	Instrument Panel Lighting - Century 21 And 41 Autopilot Installation	PA-28-161/181 PA-28-236 PA-28RT-201 PA-28RT-201T	12/20/80			3310 18H11
910	Engine Oil Quick Drain Valve	PA-28R-200/201 PA-28RT-201	12/29/80	87369-26V 492-172V	81-11-02	7920 18H17
915	Firewall Reinforcement	PA-44-180	4/14/81	764-103V		5410 18I7
920	Required Placard Adhesion Check	PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	6/29/81			2500 18I19
933	Engine Baffle Seal Security	PA-44-180 PA-44-180T	11/23/81	189-780		7230 18J20
951	Aft Fuselage Moisture Drain	PA-28-236 PA-28RT-201	10/6/82	764-386V		2120 18L2
988	Nose Landing Gear Modification	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180 PA-44-180T	7/29/86	**	94-14-14	3225 19D1
997	Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08 08	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	5/14/87	**	87-08-08	5711 19D24
1019A	Alternator Support Bracket Improvement	PA-28-181 III	1/22/98	101103-02 418-421		2412 19H1
1024	Induction Airbox Air Valve Bushing Improvement	PA-28-181	8/4/99	**		7164 19H20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1027	Manifold Pressure Line Filters Addition	PA-44-180	11/5/99	560-686 **		7164 19I7
1028A	Induction Airbox Inspection/Repair and Inlet Air Duct Replacement	PA-28-181 III	1/14/2000	766-666 85479-003 85489-011		7164 19I11
1029A	Recognition Light Circuit Breaker Inspection/Replacement	PA-28R-201	1/24/2005	454-708 87369-053		2454 19I15
1033	Air Conditioning Hose Replacement	PA-28-181 III	7/9/2001	566-419 454-868		2155 19J4
1034A	Compass Accuracy Improvement Modification	PA-44-180	11/7/2013	766-699		3447
1038A	Combustion Heater Fuel Pump Replacement	PA-44-180 PA-44-180T	2/16/2011	88476-002		2148
1040A	Alternator Drive Belt Conversion Kit (for Aircraft Equipped with Optional Factory Installed Air Conditioning)	PA-28-180 PA-28-181 II/III PA-28R-200 PA-28R-201 PA-28RT-201	10/7/2021	767-310 (88306-000)		2410
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1045	Electric Fuel Pump Upgrade	PA-28R-201	3/26/2002	461-758		2825 19K21
1047	Pilot Sidepost Handgrip Kit	PA-28-161 Cadet PA-28-161 PA-28R-201 PA-44-180 PA-44-180T	5/28/2002	767-343		2510 19L3
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1060	Engine Primer Hose Improvement	PA-44-180	2/11/2003	63901-200 63901-201		7300 20A23
1063	Stabilator Bellcrank Bracket Assembly Inspection	PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	4/21/2003	N/A		2792 20B7
1066	Ignition Harness Routing Inspection	PA-28-181 III	4/24/2003	189-549		7420 20B17
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-11-01 CE-02-05 (SAIB)	2702 20C2
1074	S-TEC Autopilot Component Seating Procedure	All	11/3/2003	N/A		2210 20C14
1081	Rib Inspection at W.S. 36.22 R.H.	PA-28-161 III PA-28-181 III	7/1/2005	767-363 62066-000		5712 20E7
1087	Wing Aft Spar-to-Fuselage Attachment Hardware	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	3/30/2005	**		5740 20F6

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1089	Aircraft Painting Requirement	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	10/21/2004	N/A		1100
1093B	Electrical Contactor Replacement Kit	PA-28-140/150/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	11/28/2017	88371		2400
1095C	Classification and Disposition of Hail Damage	PA-28-140/150/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	5/7/2024	N/A		5100
1103	Attitude Indicator Standby Battery Failure	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	4/20/2007	88410-002 88414-002		3420
1106A	Sky-Tec Starter Cranking Instructions	PA-28-161 II-III PA-28-181 III PA-28R-201 PA-44-180	10/28/2009	N/A		8011
1108	Manifold Pressure Transducer Failures	PA-28R-201 PA-44-180	3/4/2008	N/A		7713
1116A	Contactor Maintenance	PA-28-140/150/160/180 PA-28-151/161/181 PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	3/15/2019	N/A		2435
1123	Avidyne EXP5000 Software Upgrade (Mod 57)	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	9/27/2010	N/A		3420
1124	Air Conditioning Servicing	PA-28-181 III	12/6/2010	197-511		2150

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1125	Stall Horn Bracket Replacement	PA-28-160/180 PA-28S-160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-201/201T PA-28RT-201/201T	7/27/2010	88472-002		2730
1126A	Voltage Suppressor Advisory	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	3/23/2017	N/A		3400
1134	Wing Tip Inspection Requirements	PA-44-180/180T	10/7/2010	N/A		5720
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	PA-28-140/150/160/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-28S-160/180	4/27/2011	MS20995-C32		2800
1149	Nose Cone Fastener Inspection	PA-44-180/180T	2/8/2012	**		5330
1153	Auxiliary Vacuum Pump Elapsed Time Indicator (ETI) Replacement	PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28R-201	6/12/2012	88509-002		3710
1156	Propeller Feather Stop Product Improvement	PA-44-180/180T	4/2/2012	78713-003		6120
1161	Fuel Quantity Gauge Installation and Calibration Requirements	PA-28-161 III PA-28-181 III	1/10/2013	88536-001		2840
1165	Hydraulic Pump Identification and Servicing Requirements	PA-28R Series PA-44 Series	10/18/2012			2910
1193	Garmin G1000 Software Update, Versions 1648.04 and 1983.02	PA-44-180	7/16/2015			3420
1213	Garmin G1000 NXi Software Update Version 2698.04	PA-28-181 III	9/29/2017	190-02130-00 190-02131-00		3420
1214	Garmin G1000 NXi Software Update Version 2694.04	PA-44-180	6/25/2018	190-02198-01 190-02199-01		3420
1215	Garmin G1000 Software Update Version 1618.05	PA-28-181 III	1/15/2019	190-01459-00 190-01460-00		3420
1216A	Garmin Software Update With Oil Pressure Transducer	PA-44-180	1/10/2020	88610-002		3420

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1218A	Crew Seat Control Cable Modification	PA-28-161 II-III PA-28-161 Cadet PA-28-181 II-III PA-28-236 PA-28R-201/201T PA-44-180/180T	8/8/2017	76356-003 554-422 487-490		2510
1226	Auxiliary Power Harness Inspection	PA-44-180	8/3/2018	88629-002		2440
1229	Control Quadrant Inspection	PA-28 Series PA-28R Series PA-44 Series	1/3/2019	408-815		7603
1239	One-Piece Propeller Spinner Kit (Optional)	PA-44-180	2/11/2019	44P61A701-001		6113
1240	Garmin G1000 NXi Software Update Ver. 3080.04	PA-28-181 III	7/18/2018	N/A		3420
1252	Improved Front Exhaust Assemblies	PA-44-180	9/5/2019	44P78A000-001 44P78A000-002		7800
1254	Oil Pressure Transducer Kit Installation And Garmin G1000 Sw Ver. 1618.05 Update	PA-28-181 III	12/19/2019	88608-002		3420
1255	Propeller Unfeathering System Accumulator Maintenance	PA-44-180/180T	3/20/2019	N/A		6123
1256	Gascolator Bracket Assembly Inspection	PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-236 PA-28R-201/201T III PA-28RT-201/201T IV	7/9/2019	N/A		2821
1262	Garmin G1000 NXi Software Update Version 3080.05	PA-28-181 III	5/30/2019	88650-001		3420
1263	Main Landing Gear Piston Tube Inspection	PA-44-180/180T	12/23/2020	67037-006		3213
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1267	Garmin G1000 NXi Software Update Version 3080.09	PA-28-181 III	1/21/2020	88664-002		3420
1268	Hartzell 'K' Flange Propeller Hub Replacement	PA-28-235 PA-28R-180 PA-28R-200, II PA-28R-201 III PA-28RT-201 IV	10/9/2019	N/A		6114
1273A	Fuel Selector Valve Maintenance Requirements	PA-28-140/150/160/180 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201	10/6/2021	491-947 (6S122)		2823

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1277C	Garmin G1000 NXi Software Update - Seminole	PA-44-180	10/23/2023	88695-701		3420
1278C	Garmin G1000 Software Update - Archer	PA-28-181 III	1/23/2024	88675-001		3420
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1284A	Aspen Avionics EFD1000 Update To Software Version 2.10.2	PA-28-181 III PA-44-180	5/15/2023	N/A		3420
1291	ADAHRS Support Modification	PA-28-181 III	2/24/2021	88685-701		5320
1293B	Garmin G1000 NXi Software Update - Archer	PA-28-181 III	1/23/2024	88683-701		3420
1302	Replacement Of Locking Gascolator Drain Valve	PA-28-140/150/160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II PA-28-181 II PA-28-201T PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T	12/1/2022	492-022 492-312		2821
1309	Nose Landing Gear Steering Horn Inspection	PA-28-140/150/160/180 PA-28-181	2/13/2023	63300-004		3250
1311	Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits'	PA-28-151/161 PA-28-161 Cadet PA-28-180 PA-28-181 Archer II-III/Pilot PA-28-236 PA-28R-180-200 PA-28R-201 PA-28RT-201 PA-44-180/180T	6/7/2022	470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40		7120
1313	Interior Panel Attachment Mod	PA-28-181 Pilot	6/3/2022	289-765 28F250003-001		2510
1318A	Brake Line Modification	PA-28-161 Warrior II PA-28-181 Archer III PA-28-181 Pilot PA-28R-201 Arrow III / Arrow	3/24/2023	454-934		3240
1320	Wing And Fuselage Skin Repair Limitations	PA-28-140/150/160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	12/1/2022	N/A		5100

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1321	Garmin G5 EFI Standby Display Software Update Version 8.00	PA-28-181 Archer III PA-44-180	2/23/2023	88728-701		3420
1322A	Garmin G1000 Software Update Version 1983.04	PA-44-180	6/11/2024	88716-701		3420
1324A	Garmin G1000 NXi Software Update – Seminole	PA-44-180	1/8/2024	88717-707		3420
1325	Garmin G1000 Software Update Version 1648.06	PA-44-180	3/13/2023	88710-707		3420
1326A	Garmin G1000 NXi Software Update – Archer	PA-28-181	1/24/2023	88717-707		3420
1327G	Wing Walk Modification and Inspection	PA-28-140 PA-28-150 PA-28-160 PA-28-180 PA-28-235 PA-28-236 PA-28R-180 PA-28R-200 PA-28-151 PA-28-161 PA-28-181 PA-28-201/-201T PA-28R-201/-201T PA-28RT-201/-201T	9/25/2024	N/A		5720
1330B	Garmin G3X Software Update - Piper Pilot	PA-28-181 Pilot	4/1/2024	487-402		3420
1331A	Improved Spring Attachment Plate	PA-28R-180/200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	7/1/2024	67753-000		3210
1334	Improved Nose Landing Gear Down Spring	PA-44-180	3/4/2024			3230
1337	Flight Controls Maintenance Improvements	PA-28-181 Pilot PA-28-181 Archer III PA-44-180	1/29/2023			2700
1346	Spar Box Inspection	PA-28-140 PA-28-150 PA-28-160/PA-28S-160 PA-18-180/PA-28S-180 PA-28-161 PA-28-181 PA-28-201T PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	11/12/2024			5711

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
487	Test Unit, Hydraulic (And Fabricated Jack Stand)	PA-31 PA-31-300	2/13/67	753-080		710 14J14
492	Replacement of: (I) Landing Gear Selector Handle (And Associated Link Rod To Power Pak), General Instructions For Inspection And Operation of, And (II) Nose Gear Idler Link Assy.	PA-31	9/6/67	**		3200 14J20 3220
497	Manifold Pressure Gauge Filter Assembly	PA-31	1/30/68	760-171		7710 14K4
498	Nose Gear Idler Link Assembly (Identification Tag)	PA-31	3/1/68	760-170		3230 14K5
500	Altimatic III Series- (I) Radio Coupler (II) Amplifier Replacement	PA-31	3/22/68	760-191 760-192		3400 14K7
502	Navajo Cabin Heat Modification	PA-31	3/18/68	760-187 760-188		2140 14K12
504	B. F. Goodrich Service Bulletin No. E-67-34	PA-31	4/8/68			3240 14K14
505A	Fuselage Drain Holes	PA-31	5/2/68			5300 14K16
506	Main Landing Gear (Outboard) Door Actuator Bracket	PA-31	5/2/68	757-178		3210 14K18
507	ADF Installation Spacer	PA-31	5/22/68	760-211		3400 14K19
508	Propeller Counterweight Attachment Bolt Clearance	PA-31 PA-31-300	7/9/68	43556-00		6120 14K20
509	Pneumatic Pump Air Inlet Relocation	PA-31	6/24/68	760-200		3710 14K22
512	Attachment of Rudder Tab Hinge Brackets	PA-31 PA-31-300	10/8/68	760-243		2720 14L1
514	Flight Control Cable Systems	PA-31/31-300	9/19/68			2210 14L3
517	Beacon (Rotating) Attachment Screws-Shock Mounted Beacon	PA-31 PA-31-300	10/23/68			3340 14L13
523	Modification To The Fuselage Bulkhead	PA-31 PA-31-300	4/9/69	760-295		5310 15A3
524	Weldon Electric Fuel Pump Modification	PA-31 PA-31-300	5/20/69	760-316 760-317		2810 15A5
530	Hydraulic Fluid Level Gauge "O" Ring Replacement	PA-31 PA-31-300	5/23/69	484-815		2910 15A22
531	Cowl Flap Support Assembly	PA-31/31-300	8/22/69	760-330		7110 15A24
532	Voltage Regulation Component Grounding	PA-31 PA-31-300	7/7/69	760-333		2430 15B2
537	Landing Gear Door Hinge Bracket Reinforcement	PA-31 PA-31-300	10/16/69	760-348		3230 15B15
538	Inspection of Propeller Blade Shank (Hartzell Service Bulletin No. 94)	PA-31 (2 Blade Props)	10/23/69			6110 15B17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
548	Inspection of The Right Engine Control System Installation	PA-31 PA-31-300	3/16/70			7610 15C17
550B	Turbocharger Density Control Adjustment	PA-31 PA-31-350	7/10/74			8120 15C21
553	Equipment (Required) Pressurized Navajo Service Support	PA-31P	5/20/70	**		2130 15D12
555	Inspection of Nose Gear Idler Link Assembly	PA-31 PA-31-300	7/8/70			3220 15D15
562	Scott Aviation Service Bulletin No. 35-32	PA-31-300	8/25/70	**		3500 15E10
566	Autopilot Servo Spacer Bushing Installation	PA-31-300	11/25/70	760-473		2210 15F3
573	B F Goodrich Service Bulletin No. E-68-36B (Sealer For B F. Goodrich Deicer And Strap)	PA-31 PA-31-350 PA-31-P	3/4/71			3020 15F17
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P-350	7/27/2011	N/A	2011-26-04	7310
580	Fuel Selector Valve Packing Lubrication	PA-31/31-300 PA-31P	5/24/71	760-504		2820 15G18
593	Connector Plug, Harness Strain Relief Hood Installation	PA-31, Alt. V Or Alt. V/VD	10/11/71	760-556		2400 15H15
594	Inspection of Flap Track And Rudder Tip Rib Assemblies	PA-31-300	10/8/71	**		5750 15H19 5510
603	Hartzell Service Letter No. 70	PA-31P	2/8/72	**		6110 15I17
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
617B	Piper Automatic Locator Transmitter Replacement	PA-31 PA-31-350 PA-31P	8/30/73		72-22-03	2560 15K18
619	Inspection of Retainer Spring Piper Part No. 83302-13	PA-31 PA-31-300	6/9/72	83302 13		7330 15L5 7160
630	Lubrication of Fuel Selector Valve Mechanism	PA-31/31-300 PA-31P	9/13/72	**		2820 16A11
631A	Wiring Inspection, Alternator Switch And Circuit Breaker Panel	PA-31 PA-31-300	4/25/73	**		2430 16A13
633	Inspection And Repair of Flood Exposed Airplanes	PA-31 PA-31-350 PA-31P	10/9/72			5300 16A18
635	Lycoming Service Bulletin No. 356 (Addition of Alternator Bracket Support)	PA-31	10/16/72	**		2400 16A24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-31 PA-31-350 PA-31P	10/24/72	**		2430 16B2
639	Alternator Field Switch Guard Modification	PA-31-P	12/20/72	760-721		2430 16B11
642	Revised Alternator Inoperative Warning Light	PA-31	2/19/73	760-713		2430 16B15
643	Control Shaft Collar Restraining Strap	PA-31/31-300 PA-31P	2/5/73	760-723	76-04-11	2700 16B17
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-31	4/9/73	**		7610 16C14
654	Heater Control System Modification	PA-31-350	4/18/73	**		2140 16C17
655	Turbocharger Modification; Airesearch Service Bulletin No. 1172-1A(Reference Avco Lycoming Service Bulletin No. 361, Dated February 16, 1973)	PA-31 PA-31-350 PA-31P	4/10/73	**		8120 16C21
656	King Area Nav Operation Limitation Placard	PA-31-310 PA-31-350 PA-31-P	5/15/73	696-1109-00		3450 16D2 3400
658	Static System Line Modification	PA-31-350	6/14/73	760-750		2350 16D5
660	Revised Alternator Ground Wire Installation	PA-31-310 PA-31-350	7/6/73	760-778		2430 16D7
665A	Intake Valves, Rotator Type	PA-31/31-300 PA-31-350	10/24/73	**		7160 16D16
666	Propeller Governor Speed Adjusting Shaft, Lever And Lever Clamp Screw Replacement (Reference Woodward Service Bulletin No. 33549, Dated May 1973)	PA-31P	9/13/73	**		6120 16D18
674	Over Voltage Relay Inspection	PA-31-300/310 PA-31P	1/3/74	760-787		2430 16E16
675	Magneto Switch Guard Installation	PA-31-300/310 PA-31-350 PA-31P	9/17/73	760-789 760-790	74-26-10	2430 16E18
680	Receiver Dehydrator Relocation	PA-31-310 PA-31-350	11/29/73	760-803		2710 16F5
681	Inspection of Elevator Balance Weight Bolts	PA-31-350	10/24/73	**		2730 16F7
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-31 PA-31-350 PA-31P	4/19/74	**		7230 16F9
685	Installation Alternator Field Wire Clamp	PA-31P	10/24/73	760-807		2420 16F19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
688	Unfeathering Accumulator Maintenance And Preventive Maintenance (Reference Woodward Service Bulletin No 33551, Dated August, 1973)	PA-31P	10/24/73			6120 16G1
690A	Cylinder (Engine) Baffle Removal And Cylinder Head Temperature Probe Relocation	PA-31-350	3/4/74			7720 16G4
691	Cigar Lighter Circuit Protector Replacement	PA-31P	11/12/73	760-809		3310 16G6
692	Heater System Modification	PA-31-350	2/12/74	760-804		2140 16G8
696	Control Surface Balancing Recommendation	PA-31/31-300 PA-31-350 PA-31P	5/2/74			2700 16G20
697	Fuselage Addition of Drain Holes	PA-31-300/310 PA-31-350	3/14/74			5300 16G22
698	Ground Handling (Towing) Recommendations	PA-31-300/310 PA-31-350	2/6/74			3200 16G24
699	Fuel Vent Line Check Valve Installation (Reference Avco Lycoming Service Bulletin No. 362A; Dated December 14, 1973)	PA-31P	2/12/74	LW-13324		2810 16H2
701	Overvoltage Relays, Wiring of; Alternator Paralleling System	PA-31P	3/14/74	**		2430 16H6
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-31 PA-31-350 PA-31P	2/27/74	**		7710 16I11
709	Inspection of Pneumatic Pump Mounting Flanges	PA-31P	5/1/74			3710 16I17
711	Inspection of Submerged Fuel Pumps	PA-31P	5/30/74	48812-00		2820 16J4
712	T-Bolt Clamping Bands, High Tensile (Reference Avco Lycoming Service Bulletin No. 372A, Dated March 15, 1974)	PA-31-350	5/15/74	LW-13886		8120 16J7
713	Static Air Sump Installation	PA-31-310 PA-31-350 PA-31-P	8/21/74	760-864		3410 16J9
716	Moisture Seal, Cross Shaft Support Tube (Reference Avco Lycoming Service Bulletin No. 375A, Dated May 10, 1974)	PA-31P	6/3/74	**		7200 16J13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22. 1974)	PA-31 PA-31-350 PA-31-P	5/31/74	**		7410 16J18
719	Deicer Boot Installation Throttle Control Cable	PA-31P	8/28/74	760-874		7610 16K1
722	Fuel System Modification	PA-31-350	8/27/74	760-873		2800 16K9
723	Glideslope Indicator Placard	PA-31/31-300 PA-31-350 PA-31P	8/14/74	SK 2359		3430 16K11
725	Fuel Pressure Gauge Modification	PA-31-350	9/19/74	54209-02		7330 16K14
726	Cigar Lighter Placard	PA-31P	8/8/74	80247-02		3310 16K16
730	Air Conditioning System Modification	PA-31-350	8/20/74	760-881		2150 16K23
733	Pilot And Copilot Cabin Heat Refinement	PA-31-350	4/21/75	760-924		2140 16L7
739	Cabin Door Refinement	PA-31/31-300 PA-31-350	6/2/75	**	78-05-05	5210 17A1
741	Radome Weather Seal	PA-31P	1/23/75	760-919 760-920		5340 17A7
752A	Replacement of Alternator Ground Wire	PA-31P	10/30/75	760-988		2420 17B2
753	Propeller Feather Assist Spring Assembly Installation Reference Attached Hartzell Service Letter No. 101	PA-31-300/325 PA-31-350	7/16/76	**		6120 17B3
755C	Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	11/4/85	**		3235 17B13
755C	Part II - Landing Gear Lock Actuator Rod Replacement	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	11/4/85	764-958		3235 17B15
755C	Part III - Installation of Anti-Rotation Stops	PA-31 PA-31-325 PA-31 -350 T-1020 PA-31P-350	11/4/85	**		3235 17B16
764A	Wing Flap System Maintenance Procedure	PA-31-300/325 PA-31-350 PA-31P	7/17/79		81-11-03	2750 17C19
766	Inspection of Cleveland Brake Discs	PA-31-325 PA-31-350	1/6/77	**		3240 17D9
770	Aileron Sprocket/Chain Inspection	PA-31-300/325 PA-31-350 PA-31 P	1/27/77	**		2710 17D18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
773	Nose Cone ("Radome") Latch System Refinement	PA-31P	6/28/76	761-012		5340 17E7
778	Elevator Butt Rib Refinement	PA-31P	6/14/76	54755-02		5520 17E14
781	Cockpit Forward Bulkhead/ Floorboard Sealing	PA-31-350	10/22/76	**		5310 17E21 5320
783	Inspection of Air Conditioning System Capillary Sensor	PA-31P	9/20/76	**		2150 17F7
784	Landing Gear Hydraulic System Refinement	PA-31-300	9/27/76	491-050 484-459		2920 17F10
789	Inspection of Elevator Bellcrank And Elevator Control Rod	PA-31-300/325 PA-31-350 PA-31P	10/6/77	**		2730 17F21
798	Cabin Headliner/Oxygen Cover Panel Refinement	PA-31P	2/4/77			2520 17G13 3520
801	Goodyear Tri-Metallic Brakes, Maintenance And Operation; Ref: Goodyear Service Letter "PA-31-350/31 P/31T SL-1" Dated January 15, 1977	PA-31-350 PA-31P	2/25/77			3240 17G21
802	Main Landing Gear Door Hinge Attachment Screw Replacement	PA-31/31-325 PA-31-350 PA-31P	3/9/77	761-128		3210 17G24
803A	Cabin Door Latch System Refinement	PA-31-300/325 PA-31-350	11/3/77	55633-03	78-05-05	5210 17H1
816	Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks)	PA-31-350 PA-31P	12/19/77	763-831		2910 17I18
820	Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-31/31-300 PA-31-325 PA-31-350	7/28/80	**	79-18-05	2560 17J2
821	Right Engine Cowl Louver Installation Kit	PA-31-350	3/7/78	763-802		7110 17J6
823	Heater/Evaporator Return Air Duct Hose Replacement	PA-31P	2/10/78	49478-02		2120 17J10
829	Emergency Exit Window Latch Modification	PA-31P	11/14/77	763-809		5620 17J18
830	24 Volt Cigar Lighter Element Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	11/22/77	**		3310 17J19
833	Cabin Pressurization System Rupture Disc Elimination	PA-31P	4/10/78			2130 17J22
834	Flap Electrical System Refinement	PA-31/300/325 PA-31-350 PA-31P	3/3/78	**		2750 17J24
844	Heater System Rewiring	PA-31-350	4/24/78			2140 17K20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
847	Avionics Emergency Bus Power Switch Guard Installation	PA-31P	8/13/79	**		2450 17L2
866	Windshield Wiper Arm Retaining Wire Installation	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	12/7/79	151-295		5610 18C1
872	Alternator Wiring Inspection	PA-31/31-300 PA-31-325 PA-31-350	6/7/79	588-594		2430 18D6
873	Stall Warning System Refinement	PA-31 PA-31-325 PA-31-350	5/8/79			2700 18D9
874	Low Fuel Warning Sensor Sealing	PA-31 PA-31-325 PA-31-350	10/19/79	**		2840 18D12
875	Engine Front Baffle Replacement	PA-31 PA-31-325 PA-31-350	5/11/81	764-093	93-23-13	7230 18D16
878A	Oil Breather Tube Inspection/Alignment	PA-31/31-300 PA-31-325 PA-31-350	3/6/81			7220 18E13
879	Razor Inverter Replacement	PA-31 PA-31-325 PA-31-350	5/20/80	467-488		3320 18E18
883	Wing Flap Rivet Installation	PA-31P	10/20/79	**		5750 18F8
885	Aileron And Elevator Control Systems Hardware Replacement	PA-31/31-300 PA-31-325 PA-31-350	3/10/81	763-996		5550 18F13
886	Master Switch Replacement	PA-31 PA-31-325 PA-31-350	1/6/81	764-090		2450 18F15
887	Starter And Battery Cable Inspection	PA-31 PA-31-325 PA-31-350	5/29/81	**		8010 18F16 2430
894	Heater Modification	PA-31-350	9/4/80	764-005		2140 18G7
904	Sealing Procedures To Prevent Water Leaks	PA-31/31-300 PA-31-325 PA-31-350	3/11/81	**		5210 18H5
912	Main Landing Gear Downlock Hook Rivet Replacement	PA-31/300/325 PA-31-350	3/5/81	420-890 422-241		3230 18H24
916	Elevator Control Stop Screw Replacement	PA-31/31-300 PA-31-350 PA-31P	7/17/81	**		2730 18I8
917	Portable Fire Extinguisher Inspection	PA-31 PA-31-325 PA-31-350	7/20/81	459-839 459-848		2620 18I11
921	Main Landing Gear Lock Rod Attachment Fork Replacement	PA-31P	4/21/82	764-127		3230 18I21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
935	ELT Antenna Inspection	PA-31 PA-31-325 PA-31-350	3/26/82	**		2560 18J23
958	Flap Travel Restriction Supplementary Kit	PA-31 PA-31-300/325 PA-31-350 PA-31P	10/25/82	764-920L		5750 18L18
959	Flap System Modification	PA-31 PA-31-300/325 PA-31-350 PA-31P	6/10/83	764-957L		5750 19A1
959	Part I - Calco Flap System Installation	PA-31 PA-31-300/325 PA-31-350	6/10/83	764-938L		5750 19A1
959	Part II - Flap Transmission Replacement (Dukes 20:1 To Calco 40:1)	PA-31 PA-31-300/325 PA-31-350 PA-31P	6/10/83	764-957L		5750 19A2
987	Main Landing Gear Mount Bolt Inspection	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	7/25/86	400-384		3213 19C22
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702 20C2
1086	Propeller Blade De-ice Boots Maintenance	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020	7/16/2004	N/A		3112 20F3
1088	40336-000 Link Assembly Inspection	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	12/15/2004	40336-000		3220 20F11
1092C	Main Gear Retraction Arms Inspection, 42042-000/-002	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	7/25/2013	42042-000 42042-002		3211
1093B	Electrical Contactor Replacement Kit	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P	11/28/2017	88371		2400

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1116A	Contactator Maintenance	PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1188	Landing Gear Hydraulic System Filter Maintenance	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	3/19/2015	N/A		2912
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1316	Main Landing Gear Door Bolt Replacement	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31R-350	5/10/2023	453-204 (43972-000)		3211

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SL46

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
736	M-4D Automatic Flight Control System Modification	PA-31T1	12/3/74	**		2210 16L14
741	Radome Weather Seal	PA-31T	1/23/75	760-919 760-920		5340 17A7
743	Cabin Altitude Controller Relocation	PA-31T	2/19/75	760-921		2130 17A12
755C	Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication	PA-31T/31T1 PA-31-31T2/31T3 PA-42	11/4/85	**		3235 17B13
755C	Part II - Landing Gear Lock Actuator Rod Replacement	PA-31T/31T1 PA-31-31T2/31T3 PA-42	11/4/85	764-958		3235 17B15
755C	Part III - Installation of Anti-Rotation Stops	PA-31T1	11/4/85	**		3235 17B16
764A	Wing Flap System Maintenance Procedure	PA-31T PA-31T1	7/17/79			2750 17C19
770	Aileron Sprocket/Chain Inspection	PA-31T	1/27/77	**		2710 17D18
773	Nose Cone ("Radome") Latch System Refinement	PA-31T	6/28/76	761-012		5340 17E7
779	Heater Fuel Pressure Relief Valve Inspection	PA-31T	8/16/76	**		2140 17E16
780	New Engine Top Mounts	PA-31T	6/8/76	761-612 761-613		7120 17E19
783	Inspection of Air Conditioning System Capillary Sensor	PA-31T	9/20/76	**		2150 17F7
789	Inspection of Elevator Bellcrank And Elevator Control Rod	PA-31T	10/6/77	**		2730 17F21
790	Paralleling Relay Terminal Strip Tab	PA-31T	9/21/76			2450 17G1
794	Wing Tip Tank Drain Hose Replacement	PA-31T	1/4/77	80007-37		5720 17G7
798	Cabin Headliner/Oxygen Cover Panel Refinement	PA-31T	2/4/77			2520 17G13 3520
801	Goodyear Tri-Metallic Brakes, Maintenance And Operation; Goodyear SL-1 Dated January 15, 1977	PA-31T	2/25/77			3240 17G21
802	Main Landing Gear Door Hinge Attachment Screw Replacement	PA-31T	3/9/77	761-128		3210 17G24
804	Heater System Maintenance And Operation	PA-31T	2/8/77	**		2140 17H4
805	Engine Ignition Exciter Box Relocation	PA-31T	3/18/77	761-126		7420 17H9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
806	Air Scoop Lip Deicer Rewiring/ Hour Meter Harness Revision	PA-31T	2/22/77	456-763		3020 3120 17H10
809	Engine Oil Breather Tube Extension	PA-31T	4/6/77	55997-03		7920 17H16
816	Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks)	PA-31T	12/19/77	763-831		2910 17I18
817	Propeller Synchronizer System Refinement	PA-31T	2/13/78	560-807		6120 17I20
819A	Air Conditioning Compressor Drive Belt Alignment Procedure	PA-31T	8/31/77	49186-02		2150 17I23
820	Replacement of Lithium Sulphur Dioxide (LiSO ₂) ELT Batteries and/or Transmitters	PA-31T PA-31T1	7/28/80	**	79-18-05	2560 17J2
822	Engine Compartment Fire Extinguisher Switch Protection	PA-31T	7/12/77	**		2620 17J8
823	Heater/Evaporator Return Air Duct Hose Replacement	PA-31T	2/10/78	49478-02		2120 17J10
829	Emergency Exit Window Latch Modification	PA-31T	11/14/77	763-809		5620 17J18
830	24 Volt Cigar Lighter Element Replacement	PA-31T	11/22/77			3310 17J19
831	Heater Fuel Pressure Regulator Valve Installation	PA-31T	1/10/78	761-139		2140 17J20
833	Cabin Pressurization System Rupture Disc Elimination	PA-31T	4/10/78			2130 17J22
834	Flap Electrical System Refinement	PA-31T	3/3/78			2750 17J24
835B	Stability Augmentation System Refinement	PA-31T	6/20/80	763-896 764-031		2220 17K2
840	Air Conditioning System Refinements	PA-31T PA-31T1	8/29/80			2150 17K12
840	Part I - Condenser Fan Motor Support Bracket Replacement	PA-31T	8/29/80	764-034		17K12
840	Part II - Unpressurized Air Source Annunciator Light And Freon Pressure Limiting Device Installation	PA-31T PA-31T1	8/29/80	764-035		17K13
841	Heater Spark Plug Replacement Or Modification	PA-31T PA-31T1	1/7/80	763-495		2140 17K14
847	Avionics Emergency Bus Power Switch Guard Installation	PA-31T	8/13/79	**		2450 17L2
854	Generator Airscoop Door Replacement	PA-31T PA-31T1	1/3/79	763-875		8000 17L22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
857	Propeller Beta Switch Replacement	PA-31T PA-31T1	2/7/79	763-839		6120 18A22
866	Windshield Wiper Arm Retaining Wire Installation	PA-31T PA-31T1	12/7/79	151-295		5610 18C1
868	Wing Flap Selector Switch Positive Detent Kit Installation	PA-31T PA-31T1	3/26/79	763-894		2750 18C16
871	Pedestal Control Assembly Inspection	PA-31T PA-31T1	3/7/79			7600 18D3
883	Wing Flap Rivet Installation	PA-31T PA-31T1	10/20/79	**		5750 18F8
888	Lift Transducer Case Rewire	PA-42	7/21/81	764-098		3050 18F21
890	Janitrol Heater Conversion	PA-31T PA-31T1	10/15/79	763-963		2140 18F23
893A	Gyro Indicator Relay Replacement	PA-31T1	5/21/80	**		3420 18G5
896	Landing Gear - Left Main, Torque Link And Safety Switch Deflector Replacement	PA-31T PA-31T1	5/23/80	764-014		3210 18G11
902A	Gyro Slaving Panel Switch Modification	PA-31T PA-31T1	4/15/81	29299-R2		3420 18G24
913A	Part I - Torque Transmitter Electrical Connector Restraint	PA-31T PA-31T1	3/16/83	764-105		7710 18I3
913A	Part II - Torque Transmitter Relocation/Isolation	PA-31T PA-31T1 PA-42	3/16/83	764-126 764-947L		7710 18I3
916	Elevator Control Stop Screw Replacement	PA-31T PA-31T1	7/17/81	**		2730 18I8
917	Portable Fire Extinguisher Inspection	PA-42	7/20/81	459-839 459-848		2620 18I11
921	Main Landing Gear Lock Rod Attachment Fork Replacement	PA-31T PA-31T1 PA-31T2	4/21/82	764-127		3230 18I21
922	Autopilot Rudder Servo Motor Access	PA-42	8/2/82	420-217		5320 18I22
924	Maximum Operating Airspeed (VMO)	PA-31T1	1/20/82	764-150 764-151		3410 18J2
925	Bleed Air Line Inspection/ Generator Cooling Scoop Cam Loc Receptacle Removal	PA-42	7/21/81	**		7110 18J3
926	Deice Relay Shelf Modification And Diode Addition	PA-42	7/21/81	**		2450 18J6
928	Pedestal Support Channel Assembly Removal	PA-42	9/29/81	404-829		7600 18J11
929	Pitch Servo Bridle Clamp Instruction	PA-42	2/11/82			2210 18J13
930	Powerplant Cowl Drain Inspection/ Modification	PA-42	7/21/81			7100 18J15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
932	Pressurization Control Wiring Rework	PA-42	11/19/82	764-403		2130 18J19
935	ELT Antenna Inspection	PA-42	3/26/82	**		2560 18J23
937	Nose Gear Actuator Hose Replacement	PA-42	5/24/82	**		3210 18K1
941	Nose Wheel Shimmy Dampener Replacement	PA-31T PA-31T2	9/21/82	456-010		3250 18K5
942	Flap Handle Travel Inspection	PA-42	4/4/82	77196-03		2750 18K7
943	Pilot's Right Rudder Pedal Torque Tube Retention	PA-42	11/4/81	424-059		2720 18K9
945	Cowl Inlet Lip Screw Replacement	PA-42	2/16/82	414-468 406-561		5440 18K14
949	Elevator Trim Mechanism Modification And Enclosure Installation	PA-42	9/24/82	764-411L		2730 18K23
950	Battery Ventilation Tube Inspection	PA-42	6/8/82	420-202		2430 18K24
952	Engine Dual Drive Oil Supply Line Oil Pressure Snubber Relocation	PA-42	12/10/82	764-414		7920 18L3
954	Nose Landing Gear Strut Placard Inspection Replacement	PA-42	2/2/83	72236-02		3220 18L9
956	Cabin Door Cable Assembly Inspection And Modification	PA31T PA-31T1 PA-31T2	5/17/82	47716-04 57462-03		5210 18L11
960	Aft Fuselage Drain Holes Inspection	PA-42	12/3/82			5560 19A4
961	Environmental Control System Wiring Modification	PA-42	1/5/83	*		2100 19A7
962	Pitch Trim Drum Shaft Roll Pin Security	PA-42	3/18/83	MS20995-C32		2731 19A10
964	Avionics Bay Blanket Modification	PA-31T2	4/29/83	764-946		3400 19A14
969	Wing Tip Ground Strap Installation	PA-31T1 PA-31T3	7/11/84	**		2360 19A24
977	Dynamic Stability Improvement Kit	PA-31T	3/1/85	765-158		2730 19B21
979	Emergency Pressurization Bleed Air Valve Modification	PA-42	1/8/85	**		7530 19C1
983	Engine Air Inlet Duct Assembly Reinforcement	PA-42 PA-42-720	3/14/86	**		7161 19C12
986	Series Start Circuit Change Modification	PA-42-1000	7/22/86	765-194		2453 19C20
993	Engine Air Inlet Drain Holes	PA-42-1000	1/5/87	N/A		7162 19D13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
994	Propeller Ground Clearance	PA-42-1000	1/12/87	**		3223 19D15
998	Remote Control Circuit Breaker (RCCB) Ground Wire Installation	PA-42-1000	7/8/87	765-322		2451 19E4
1002	Overhead Panel Map Light Switch Installation	PA-42-1000	4/4/88	84112-03		3314 19E14
1003	Oxygen Shutoff Valve Assembly	PA-42-720 PA-42-720R PA-421000	8/19/88	**		3510 19E17
1013	Improved Elevator Trim Cover Replacement	PA-42 PA-42-720 PA-42-720R	10/11/94	**		5510 19G1
1014	Addition of Grease Fitting to Nose Gear Steering Arm Bracket	PA-42 PA-42-720 PA-42-720R	10/17/94	**		3250 19G1
1015	Replacement of EATON Brand Electrical Contactor Box	PA-42-1000	7/14/95	766-296 557-125		2436 19G6
1017	Engine Fire Extinguisher System Rewire and Distribution of Walter Kidde Service Bulletin 899857-26-365	PA-42 PA-42-720	3/7/97	766-617		2623 19G11
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1054	Propeller Control Arm Attachment Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	10/10/2002	51623-000		6120 20A3
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702 20C2
1088	40336-000 Link Assembly Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	12/15/2004	40336-000		3220 20F11
1092C	Main Gear Retraction Arms Inspection, 42042-000/-002	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720	7/25/2013	42042-000 42042-002		3211
1116A	Contactor Maintenance	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000	3/15/2019	N/A		2435

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1
 PA-31T2/31T3
 PA-42

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1188	Landing Gear Hydraulic System Filter Maintenance	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	3/19/2015	N/A		2912
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1316	Main Landing Gear Door Bolt Replacement	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720	5/10/2023	453-204 (43972-000)		3211

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
177	Firewalls	All Models	8/10/51			13B13
467	Alternator - Regulator System Modification	PA-32-260	1/10/66	756-992V		2430 14I5
475	Inspection of Landing Gear Strut Exposure	PA-32-260	7/6/66			3210 14I17
476	Replacement of Fuel Selector Valve	PA-32-260	4/26/66	492-104V	67-03-07	2820 14I18
484	Fuel System Operating Procedures	PA-32	12/20/66			2800 14J7
486A	Cylinder Head Temperature Probe Location	PA-32	4/16/68			7720 14J13
494	Inspection of Cherokee Landing Gears	PA-32-260/300	11/7/67			3200 14J24
495	Inspection of Control Cable-Constant Speed Propellers	PA-32-260/300	1/29/68	**		6120 14K2
499	Owners Handbook Revision	PA-32-260	3/14/68			General 14K6
527D	Inspection of Control Wheels	PA-32-260/300	6/21/78	**	69-22-02	2700 15A14
535A	Rudder Trim Locking Pin	PA-32-260/300	9/26/69			2720 15B9
566	Autopilot Servo Spacer Bushing Installation	PA-32-260/300	9/25/70	760-508V		2210 15F3
571	Flap Handle Assembly Modification	PA-32-260/300	3/30/71	760-531V		2750 15F15
576	Stabilator Balance Weight Tube Replacement	PA-32-260/300	4/20/71	**		5570 15G2
577	Servo Bridle Cable Clamp Replacement	PA-32-260/300	6/1/71	757-863V		2210 15G8
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-32-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC PA-32RT-300/300T PA-32S-300	7/27/2011	N/A	2011-26-04	7310
581	Inspection of Aileron Hinge Doublers	PA-32-260/300	7/12/71	760-540V		5550 15G20
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
612A	Fuel Leakage - Fuel Sender Unit	PA-32-260/300	6/8/72	68101-00V		7330 15K1
614	Stabilator Attachment Fittings Bolt Torque	PA-32-260/300	6/15/72		72-14-07	2740 15K6
615	Stabilator Drain Holes	PA-32-260/300	7/6/72			2740 15K8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
617B	Piper Automatic Locator Transmitter Replacement	PA-32	8/30/73		72-22-03	2560 15K18
620	Forward Cabin Door Reinforcement	PA-32-260/300	2/23/73	760-729V		5210 15L8
621	Main Landing Gear Torque Link Replacement	PA-32-260/300	11/9/72	**		3210 15L10
624	Altimatec III-1 Gyro Horizon Fitting Installations	PA-32-300	9/1/72	458 840		3420 15L17
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-32	10/24/72	**		2430 16B2
647	Seat Back Stop Modification	PA-32-260/300	3/31/73	760-740V		2510 16C1
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265, Dated December 15, 1972)	PA-32	4/9/73	**		7610 16C14
662	Engine Mount Bolt Torque	PA-32-260/300	7/6/73	AN960-616		7120 16D10
665A	Rotator Type Intake Valves	PA-32-300	10/24/73	**		7160 16D16
671	Inspection And Modification Rudder Bar Assembly	PA-32-260/300	10/5/73			2720 16E9
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-32	4/19/74	**		7230 16F9
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974)	PA-32	5/3/74	**		2210 16G13
700	Toe Brake System Modification	PA-32-260/300	4/9/74	760-842V		3240 16H5
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-32	2/27/74	**		7710 16I11
708	Nose Wheel Steering System Inspection	PA-32-260/300	6/7/74	**		3250 16I14
715	Emergency Locator Transmitter Switch Cover Modification	PA-32-260/300	9/27/74	760-876V		2560 16J12
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-32	5/31/74	**		7410 16J18
732	Steering Stop Replacement	PA-32-260/300	9/30/74	95061-129		3250 16L6
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-32-260/300	12/3/74	760-857V		3450 16L8
738A	Modification of The Overhead Fresh Air Vent System	PA-32-260/300	1/14/75	**		2120 16L20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
745	Inspection of Wing Mainspar Attach Bolts	PA-32-260/300	4/24/75	404-890		5710 17A14
747	Inspection of Throttle Mixture Control Attachments	PA-32-260/300	5/28/75	**		7610 17A18
749	Torque Link Greaser Bolt Replacement Kit	PA-32-260/300	10/14/75	760-910V		3210 17A21
750	Rain Gutter Installation	PA-32-260/300	8/15/75	760-975V		5210 17A22
756	Dual Glideslope Indicator Placard (King Radio Installations Only)	PA-32-260/300	1/6/76	69669-112V		3430 17B22
758	Inspection of Bendix Ignition Switches; Re: Bendix Service Bulletin No. 583	PA-32-260/300 PA-32R-300	5/17/76	761-065V		7410 17C2
761	Magnetic Compass Relocation Kit	PA-32-260/300	11/17/75	760-695V		3440 17C14
762	Modification of ELT Remote Switches	PA-32-260/300 PA-32R-300	1/26/76	761-009V		2560 17C15
763A	Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection	PA-32-260/300	11/14/75	**	75-24-02	2570 17C16
768	Aileron Balance Cable Pulley Support Bracket Modification	PA-32R-300	5/25/76	761-042V		2710 17D14
788	Air Conditioning Installations	PA-32-300 PA-32R-300	9/3/76	79584-02V 79589-05V		2150 17F19
791	Electrical System Refinement	PA-32R-300	2/24/77	761-087V		2400 17G3
793	Flap Warning Placard	PA-32-260/300 PA-32S-300 PA-32R-300	1/6/77	35664-02		2750 17G5
796	Lower Cowl Drain Inspection	PA-32-260	3/30/77			7100 17G10
797	Front Seat Modification (Aircraft With Club Seating Only)	PA-32-260/300 PA-32R-300	2/25/77	761-110V		2510 17G12
800	Performance Refinement of Narco ADF - 140 Installation	PA-32-260/300 PA-32R-300	2/25/77	**		3450 17G19
808	Hydraulic Pump Terminal Inspection	PA-32R-300	6/8/77	**		2910 17H14
810	Landing Gear Extender, Backup, Diaphragm Replacement	PA-32R-300	4/15/77	761-138V		3230 17H18
813	Vertically Adjustable Seat Refinement	PA-32-260/300 PA-32R-300	6/9/77	**		2510 17I8
820	Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-32-260/300 PA-32R-300 PA-32RT-300/300T	7/28/80	**	79-18-05	2560 17J2
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-32-260 PA-32-300 PA-32R-300	2/9/78	**		3450 17K4
837	Inspection of Elbow Assembly Engine Air Filter	PA-32-300 PA-32R-300	5/22/78			7160 17K7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
842	Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement	PA-32-260/300	9/26/78	760-910V		3210 17K17
861	Part I - Forward Facing Seat Back Modification	PA-32-260/300 PA-32R-300 PA-32RT-300/300T	11/13/78	763-890V		2520 18B7
861	Part II - Rear Facing (Club) Seat Back Retention	PA-32-260/300 PA-32RT-300/300T	11/13/78	408 834V		2520 18B8
862	Main Landing Gear And Strut Fairing Replacement	PA-32-260 PA-32-300	3/30/79	760-910V		3210 18B11
864	Part I - Forward Cabin Door Stop (Striker Plate) Installation	PA-32-260/300 PA-32RT-300/300T	12/8/78	**		5210 18B16
864	Part II - Cabin Heat Control Refinement	PA-32-260/300 PA-32RT-300/300T	12/8/78	763-870V 763-871V		2140 18B19
864	Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision	PA-32-260	12/08/78	763-874		3420 18B20
864	Part IV - Induction Sump Drain Valve	PA-32R-300 PA-32RT-300	12/8/78	763-887V		7160 18B21
869	Part I - Installation of Top Cowl Exhaust System Heat Shields	PA-32RT-300T	9/10/79	753-910V		7810 18C18
869	Part II - Modification of Fuel Boost Pump Outlet Fitting	PA-32RT-300T	9/10/79	**		2820 18C19
869	Part III - Tachometer Cable Rerouting	PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T	9/10/79	763-916V		7710 18C20
882A	Part I - Rudder Skin Inspection And Modification	PA-32RT-300 PA-32RT-300T	11/12/81	763-936V	79-26-04	5540 18F4
882A	Part II - Rudder Skin Replacement	PA-32RT-300 PA-32RT-300T	11/12/81	763-940V	79-26-04	5540 18F6
884	Fuel Quantity Sender Check	PA-32-260/300	9/15/80	68101-002V		2840 18F11
895A	Magneto Switch Modification	PA-32-301	3/19/81	153-010 488-396		7430 18G8
900	Air Induction Valve Assembly Support Reinforcement	PA-32R-301T	7/30/80	**		7160 18G19
901	Cabin Air Intake Duct Modification	PA-32-301/301T PA-32R-301/301T	9/2/80	764-013V		2120 18G22
903A	Alternator Belt Installation (Air Conditioned Models)	Any Textron-Lycoming Powered PA-32	3/11/96	62833-82		2431 18H2
908	Instrument Panel Lighting - Century 21 And 41 Autopilot Installation	PA-32-301/301T PA-32R-301/301T	12/20/80			3310 18H11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
920	Required Placard Adhesion Check	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	6/29/81			2500 18119
923A	Cabin Heat Cable Heatshield Installation	PA-32-301T PA-32R-301T PA-32RT-300T	2/12/82	764-138V 764-137V		2140 18124
927	Nose Landing Gear Refinement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	10/2/81	764-135V	81-24-07	3220 18J10
934	Bottom Cowl Modification	PA-32-300 PA-32-301	11/23/81	764-136V		7110 18J22
947	Pressure Switch Relocation Manifold Pressure Gauge	PA-32RT-300T PA-32R-301T PA-32-301T	2/5/82	764-216V		7710 18K19
948	Heated Windshield Panel Sealing And Gyro Filter Protection	PA-32R-301T	2/5/82	**		5610 18K20
997	Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08-08	PA-32-260 PA-32-300	5/14/87	**	87-08-08	5711 19D24
1032	Improved Fuel Quantity Senders Available	PA-32R-301 II HP PA-32R-301T II TC	3/13/2001	686-202 686-203		2842 19J1
1033	Air Conditioning Hose Replacement	PA-32R-301 II HP PA-32R-301T II TC	7/9/2001	566-419 454-868		2155 19J4
1040	Alternator Drive Belt Conversion Kit (for Aircraft Equipped with Optional Factory Installed Air Conditioning)	PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32R-301 PA-32R-301T PA-32RT-300 PA-32RT-300T	10/7/2021	767-310 (88306-000)		2410
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1043	Oil Cooler Kit	PA-32R-301T II TC	4/25/2002	767-332		7921 19K15
1049	Voltage Regulator Replacement	PA-32R-301 II HP PA-32R-301T II TC	4/30/2002	68804-007 68804-006		2424 19L9
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-11-01 CE-02-05 (SAIB)	2702 20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1074	S-TEC Autopilot Component Seating Procedure	All	11/3/2003	N/A		2210
1084	Cabin Heater Improvement Kit	PA-32-301XTC PA-32R-301T II TC	1/14/2005	767-333		2140
1089	Aircraft Painting Requirement	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	10/21/2004	N/A		1100
1093B	Electrical Contactor Replacement Kit	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/300T	11/28/2017	88371		2400
1095C	Classification and Disposition of Hail Damage	PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/300T	5/7/2024	N/A		5100
1103	Attitude Indicator Standby Battery Failure	PA-32-301FT PA-32-301XTC	4/20/2007	88411-002		3420
1105	Automatic Baggage Door Light Switch Upgrade	PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC	4/24/2007	88422-002		3300
1106A	Sky-Tec Starter Cranking Instructions	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	10/28/2009	N/A		8011
1108	Manifold Pressure Transducer Failures	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	3/4/2008	N/A		7713

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1116A	Contactator Maintenance	PA-32-260/300 PA-32S-300 PA-32R-300 PA-32RT-300/300T PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC	3/15/2019	N/A		2435
1123	Avidyne EXP5000 Software Upgrade (Mod 57)	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	9/27/2010	N/A		3420
1126A	Voltage Suppressor Advisory	PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC	3/23/2017	N/A		3400
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1165	Hydraulic Pump Identification and Servicing Requirements	PA-32R Series	10/18/2012			2910
1218A	Crew Seat Control Cable Modification	PA-32-301 PA-32-301FT PA-32-301XTC PA-32R-301 SP PA-32R-301 II HP PA-32R-301T Turbo SP PA-32R-301T II TC	8/8/2017	76356-003 554-422 487-490		2510
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1268	Hartzell 'K' Flange Propeller Hub Replacement	PA-32-300 PA-32S-300 PA-32R-300 PA-32RT-300	10/9/2019	N/A		6114
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1311	Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits'	PA-32-301 PA-32-301FT PA-32-301XTC PA-32R-301 II HP	6/7/2022	470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40		7120

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1320	Wing And Fuselage Skin Repair Limitations	PA-32-260/300 PA-32R-300 PA-32RT-300/300T PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC	12/1/2022	N/A		5100
1327G	Wing Walk Modification and Inspection	PA-32-260 PA-32-300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T	9/25/2024	N/A		5720
1331A	Improved Spring Attachment Plate	PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T	7/1/2024	67753-000		3210
1346	Spar Box Inspection	PA-32-260/-300 PA-32-301FT PA-32-301XTC PA-32-301/-301T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T PA-32S-300	11/12/2024			5711

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-34-200	7/27/2011	N/A	2011-26-04	7310
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
614	Stabilator Attachment Fittings Bolt Torque	PA-34-200	6/15/72		72-14-07	2740 15K6
615	Stabilator Drain Holes	PA-34-200	7/6/72			2740 15K8
617B	Piper Automatic Locator Transmitter	PA-34-200	8/30/73		73-07-02	2560 15K18
618	Alternator Fan Replacement	PA-34-200	10/8/73	754-827V	72-15-02	2430 15L1
620	Forward Cabin Door Reinforcement	PA-34-200	2/23/73	760-729V		5210 15L8
622	Cabin Heater/Defroster Modification	PA-34-200	8/24/72	760-692V 760-693V		2140 15L12
624	Altimatec III-1 Gyro Horizon Fitting Installation	PA-34-200	9/1/72	458-840		3400 15L17
625	Heat Exchangers And Heat Silencers Modification	PA-34-200	11/13/72	69471-21V		2140 15L20
626	Landing Gear Bolt Lubrication	PA-34-200	11/20/72			3200 15L23
647	Seat Back Stop Modification	PA-34-200	3/31/73	760-740V		2510 16C1
661	Engine Firewall Modification	PA-34-200	6/26/73	760-758V		5410 16D8
663	Stabilator Drain Hole Inspection (Deicer Equipped Aircraft Only)	PA-34-200	5/25/73			5300 16D11
664	Wing Skin/Rib Inspection And Modification	PA-34-200	4/17/74	760-771V		5710 16D13
665A	Intake Valves, Rotator Type	PA-34-200	10/24/73	**		7160 16D16
668A	Engine Cowl Modifications	PA-34-200	8/7/74	**		7110 16E4
669	Aileron/Rudder Interconnect Cable System Modification	PA-34-200	4/16/74	760-776V		2710 16E6
671	Rudder Bar Assembly Inspection And Modification	PA-34-200	10/5/73			2720 16E9
673	Exhaust System Replacement	PA-34-200	9/28/73	760-764V		7810 16E14
677A	Propeller Spinner And Propeller Damper Installation Kits	PA-34-200	11/14/73	760-766V 760-781V		6110 16E22
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-34-200	4/19/74	**		7230 16F9
684	Landing Gear Lubrication	PA-34-200	1/9/74			3200 16F18
700	Toe Brake System Modification	PA-34-200	4/9/74	760-842V		3240 16H5
704A	Inspection of Fuel Crossfeed Drain Valves	PA-34-200	11/25/74	492-202V		2820 16H10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE	
706	Propeller Damper Compression Spring (Reference Hartzell Service Bulletin No. 103 Dated 2/20/74)	PA-34-200	5/6/74	760-853V		6120	16I3
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-34-200	2/27/74	**		7710	16I11
714	Rudder Trim Modification	PA-34-200	6/4/74	760-800V	73-13-01	2720	16J11
715	Emergency Locator Transmitter Switch Cover Modification	PA-34-200	9/27/74	760-876B		2560	16J12
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-34-200	5/31/74	**		7410	16J18
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-34-200	12/3/74	760-857V		3450	16L8
737	Manifold Pressure Gauge Line Modification	PA-34-200	12/2/74	760-765V		7710	16L19
738A	Modification of The Overhead Fresh Air Vent System	PA-34-200	1/14/75	**		2120	16L20
742	Seneca II Refinement Modifications	PA-34-200T	5/9/75	**		1. 7110 2. 5200 3. 2740 4. 3400 5. 7410	17A8
747	Inspection of Throttle And Mixture Control Attachments	PA-34-200	5/28/75	**		7610	17A18
750	Rain Gutter Installation	PA-34-200	8/15/75	760-975V		5210	17A22
754	Auxiliary Fuel System Modification	PA-34-200T	7/31/75	760-926V		2810	17B12
756	Glideslope, Dual, Indicator Placard (King Radio Installation Only)	PA-34-200/200T	1/6/76	69669-112V		3430	17B22
757	Aft Wing Modification (Optional)	PA-34-200	10/22/75	**		5710	17C1
761	Magnetic Compass Relocation Kit	PA-34-200/200T	11/17/75	760-795V		3440	17C14
762	Modification of ELT Remote Switches	PA-34-200/200T	1/26/76	761-009V		2560	17C15
763A	Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection	PA-34-200/200T	11/14/75	**	75-24-02	2510	17C16
769	Cold Weather Starting Procedures	PA-34-200T	3/10/76	**		7200	17D15
792	Optional Cold Weather Priming System Installation	PA-34-200T	12/10/76	761-094V		7310	17G4
793	Flap Warning Placard	PA-34-200/200T	1/6/77	35664-02		2750	17G5
795	Oil Cooler Baffle Winterization Modification	PA-34-200T	2/8/77	**		7230	17G9
797	Front Seat Modification (Aircraft With Club Seating Only)	PA-34-200T	2/25/77	761-110V		2510	17G12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
800	Refinement of Narco ADF-140 Installation Performance	PA-34-200T	2/25/77	**		3450 17G19
808	Hydraulic Pump Terminal Inspection	PA-34-200/200T	6/8/77	**		2910 17H14
813	Vertically Adjustable Seat Refinement	PA-34-200/200T	6/9/77	**		2510 17I8
818	Outside Air Temperature Gauge Replacement	PA-34-200T	10/19/77	99479-03V		3410 17I22
820	Replacement of Lithium Sulphur Dioxide (LiSO ₂) ELT Batteries and/or Transmitters	PA-34-200 PA-34-200T	7/28/80	**	79-18-05	2560 17J2
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-34-200T	2/9/78	**		3450 17K4
839	Main Landing Gear Trunnion Bushings	PA-34-200T	9/27/78	67026-10		3210 17K10
852	Nose Gear Placard (P/N 582 943V)	PA-34-200/200T	9/14/78	582-943V		3220 17L17
858	Inspection of The Landing Gear Relay Wiring	PA-34-200T	10/10/78			3230 18A24
861	Part I - Forward Facing Seat Back Modification	PA-34-200 PA-34-200T	11/13/78	763-890V		2520 18B7
861	Part II - Rear Facing (Club) Seat Back Retention	PA-34-200T	11/13/78	408-834V		2520 18B8
881	Wiring Harness Protective Sleeve Installation	PA-34-200T	11/13/79	**		2400 18F1
889	Pneumatic Pump Inlet Filter Relocation	PA-34-200T	11/6/79	763-919V		3710 18F22
898	King KNS - 80 Area Navigation System Cooling	PA-34-200T PA-34-220T	5/28/82	764-385V		2300 18G15
920	Required Placard Adhesion Check	PA-34-200T PA-34-220T	6/29/81			2500 18I19
946B	KNS - 81 Wiring Change	PA-34-220T	9/1/82			3450 18K15
948	Heated Windshield Panel Sealing And Gyro Filter Protection	PA-34-220T	2/5/82	**		5610 18K20
963	Radio Master Relay Retrofit	PA-34-200T	11/9/83	**		2450 19A12
966	Tachometer Generator Mounting Modification	PA-34-220T	12/19/83	764-942V		7710 19A18
1020	Relocation of Signal Ground for Cylinder Head and Oil Temperature Sensors	PA-34-220T V	8/27/98	**		7701 19H4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1021	Distribution of Teledyne Continental Motors Service Bulletin SB 98-8 "Number One and Three Cylinder Intake Tube Modification" and subsequent modification of the engine installation to facilitate compliance.	PA-34-220T V	1/27/99	**		7313
1025	Replacement of Existing Cylinder Head Temperature Wires with Shielded Wiring.	PA-34-220T V	10/1/99	**		7701
1031	Fuel Pump Cooling Inlet Installation	PA-34-220T V	12/11/2000	766-678		7311
1036	Teledyne Continental Motors Service Information Letter SIL 01-2, "Precision Airmotive Corporation SIL RS-59"	PA-34-220T V	11/5/2001	554-321		7318
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1048A	DDMP May Provide Erroneous Information in the Percent Power Query Mode at High Altitudes	PA-34-220T V	5/30/2003	680-475		7700
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-11-01 CE-02-05 (SAIB)	2702
1074	S-TEC Autopilot Component Seating Procedure	All	11/3/2003	N/A		2210
1078	Improved Flap Potentiometer	PA-34-220T V	1/19/2004	100661-003		2751
1086	Propeller Blade De-ice Boots Maintenance	PA-34-200 PA-34-200T PA-34-220T III-IV-V	7/16/2004	N/A		3112
1087	Wing Aft Spar-to-Fuselage Attachment Hardware	PA-34-220T V	3/30/2005	**		5740
1089	Aircraft Painting Requirement	PA-34-220T V	10/21/2004	N/A		1100
1093B	Electrical Contactor Replacement Kit	PA-34-200 PA-34-200T PA-34-220T III-IV-V	11/28/2017	88371		2400
1095C	Classification and Disposition of Hail Damage	PA-34-200 PA-34-200T PA-34-220T III-IV-V	5/7/2024	N/A		5100
1108	Manifold Pressure Transducer Failures	PA-34-220T V	3/4/2008	N/A		7713
1116A	Contactor Maintenance	PA-34-200 PA-34-200T PA-34-220T III-IV-V	3/15/2019	N/A		2435
1123	Avidyne EXP5000 Software Upgrade (Mod 57)	PA-34-220T V	9/27/2010	N/A		3420

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1126A	Voltage Suppressor Advisory	PA-34-220T V	3/23/2017	N/A		3400
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	PA-34-200 PA-34-200T	4/27/2011	MS20995-C32		2800
1154	Engine Starter Motor Replacement	PA-34-220T V	3/28/2012	**		8010
1156	Propeller Feather Stop Product Improvement	PA-34-200 PA-34-200T PA-34-220T III-IV-V	4/2/2012	78713-003		6120
1162	Cowl Flap Replacement	PA-34-220T V	3/5/2013	**		7110
1164	Engine Front Baffle Replacement Kit	PA-34-220T V	11/6/2012	88537-001		7160
1165	Hydraulic Pump Identification and Servicing Requirements	PA-34 Series	10/18/2012			2910
1197	Propeller Spinner Bulkhead Improvement	PA-34-220T V	6/21/2016	688-023 (E-7258-5)		6113
1210	Magneto Timing Procedure	PA-34-220T IV	12/21/2016	761-888		7414
1218A	Crew Seat Control Cable Modification	PA-34-220T III-IV-V	8/8/2017	76356-003 554-422 487-490		2510
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1268	Hartzell 'K' Flange Propeller Hub Replacement	PA-34-200	10/9/2019	N/A		6114
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1284A	Aspen Avionics EFD1000 Update to Software Version 2.10.2	PA-34-220T V	5/15/2023	N/A		3420
1311	Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits'	PA-34-200	6/7/2022	470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40		7120
1320	Wing And Fuselage Skin Repair Limitations	PA-34-200 PA-34-200T PA-34-220T III-IV-V	12/1/2022	N/A		5100
1327G	Wing Walk Modification and Inspection	PA-34-200 PA-34-200T PA-34-220T III-IV-V	9/25/2024	N/A		5720
1331A	Improved Spring Attachment Plate	PA-34-200 PA-34-200T PA-34-220T III-IV-V	7/1/2024	67753-000		3210
1337	Flight Controls Maintenance Improvements	PA-34-220T	1/29/2023			2700
1346	Spar Box Inspection	PA-34-200 PA-34-200T PA-34-220T III-IV-V	11/12/2024			5711

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
--------	---------	--------------------	---------------------	-----------------	-------------	-------------

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
177	Firewalls	All Models	8/10/51			13B13
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-36-300 PA-36-375	7/27/2011	N/A	2011-26-04	7310
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
633	Inspection And Repair of Flood Exposed Airplanes	PA-36	10/9/72			5300 16A18
652A	Pilot And Maintenance Training Program	PA-36	6/14/73			500 16C11
659	Seat Back Modification	PA-36	5/9/74	760-797V		2510 16D6
678	Relocation of Throttle Control Rod End	PA-36	12/12/73			7610 16E24
682B	Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-36	4/19/74	**		7230 16F9
693	Upper Cowl Support Modification	PA-36	3/29/74	760-811V		7110 16G9
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-36	2/27/74	**		7710 16I11
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-36	5/31/74	**		7410 16J18
727	Spray Pump Windmill Assembly Modification (Reference Agronautics Service Bulletin No. SP-74-1 Dated April 30, 1974)	PA-36	8/8/74	**		910 16K17
729	Elevator Control System Modification	PA-36-285	11/6/74	760-879V		2730 16K22
746	Air Filtration	PA-36	7/10/75	**		7160 17A16
759	Fuselage Forward Bottom Panel Reinforcement	PA-36	3/26/76	760-999		5310 17C11
765	Oil Change And Pre-Start Procedures	PA-36	11/26/75			7920 17D5
767	Replacement of Parking Brake Valve	PA-36	1/28/76	98384-00		3240 17D12
771	Engine Care And Operational Tips, Tiara 6-285	PA-36	5/18/76			7200 17E1
774	Engine Cowl Modification	PA-36	5/18/76	761-062		7110 17E9
776	Fitting Installation Flap Control Bellcrank Grease	PA-36	10/11/76	761-068		2750 17E11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
820	Replacement of Lithium Sulphur Dioxide (LiSO ₂) ELT Batteries and/or Transmitters	PA-36-285/300 PA-36-375	7/28/80	**	79-18-05	2560
825	Cockpit Door Emergency Release Refinement	PA-36-285 PA-36-300	11/30/78	763-811		5210
838	Manifold Pressure Gauge Line Filter Installation	PA-36-300	3/14/78	763-835		7710
849	Stabilizer Refinement	PA-36-300	10/31/78			5530
892	Engine Air Induction System Modification	PA-36-285 PA-36-300 PA-36-375	3/21/80	99849-14 555-846		7160
897	Rudder Attachment Hardware Replacement	PA-36-285/300 PA-36-375	6/2/80	**		5540
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702
1093B	Electrical Contactor Replacement Kit	PA-36-285 PA-36-300 PA-36-375	11/28/2017	88371		2400
1116A	Contactor Maintenance	PA-36-285 PA-36-300 PA-36-375	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1268	Hartzell 'K' Flange Propeller Hub Replacement	PA-36-300 (Restricted Category Only)	10/9/2019	N/A		6114
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
177	Firewalls	All Models	8/10/51			13B13
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
820	Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-38-112	7/28/80	**	79-18-05	2560 17J2
855	Tomahawk Product Refinement Program	PA-38-112	10/20/78	**		1. 2520 18A1 2. 2510 3. 5300 4. 6110 5. 7810 6. 2520 7. 5340 8. 3210 9. 2740 2560 10. 5210 11. 2820 12. 5530 13. 2750 14. 3220 15. 5300 16. 2140
865	Elevator Trim System Inspection/Modification	PA-38-112	1/22/79	77878-02		2730 18B22
870	Upper Rudder Fairing Clearance Inspection	PA-38-112	7/5/79			5350 18C23
876	Additional Flow Strip Installation	PA-38-112	4/12/79	**	83-14-08	5720 18D17
877	Part I - Seat Cover Attachment Replacement	PA-38-112	4/30/79	455-001		2510 18D19
877	Part II - Aft Bulkhead Stiffener Channel Installation	PA-38-112	4/30/79	77554-06		5310 18D20
877	Part III - Placards Replacement	PA-38-112	4/30/79	763-932		2500 18D21
877	Part IV - Fuel Selector Handle Inspection	PA-38-112	4/30/79			2820 18D22
877	Part V - Stabilizer Drain Holes Addition	PA-38-112	4/30/79	**		5300 18D22
877	Part VI - Compass Compensation	PA-38-112	4/30/79	**		3440 18D23
877	Part VII - Main Gear Alignment	PA-38-112	4/30/79	**		3210 18D24
877	Part VIII - Elevator Stop Attachment	PA-38-112	4/30/79	**		5520 18E5
877	Part IX - Elevator Leading Edge Straps	PA-38-112	4/30/79	77618-D2 420-200		5720 18E5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
895A	Magneto Switch Modification	PA-38-112	3/19/81	153-010 488-396		7430
909	Magneto Switch Replacement	PA-38-112	6/9/81	688 178	93-05-06	7430
911	Aft Spinner Bulkhead Replacement	PA-38-112	4/22/81	77710-04 77710-06		6110
931	Nose Gear Fork Assembly Improvement	PA-38-112	8/25/81	764-213		3220
944	Fuel Selector Valve Inspection And Lubrication	PA-38-112	4/20/82	**		2820
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702
1093B	Electrical Contactor Replacement Kit	PA-38-112	11/28/2017	88371		2400
1116A	Contactor Maintenance	PA-38-112	3/15/2019	N/A		2435
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1141	Gascolator Maintenance Procedures	PA-38-112	4/27/2011	MS20995-C32		2800
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SL70

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P,
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
177	Firewalls	All Models	8/10/51			13B13
578B	Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F	PA-46-350P PA-46R-350T	7/27/2011	N/A	2011-26-04	7310
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	2/21/72			5500 15J21
938	Forward Baggage Door Modification	PA-46-310P	7/10/84	765-109V		5230 18K4
965	Hydraulic Pump Installation Modification	PA-46-310P	9/25/85	765-161		2910 19A16
967	Lower Cabin Door Modification	PA-46-310P	6/28/84	765-104V		5210 19A20
968A	Oil Filler Door/Top Cowl Modification	PA-46-310P	7/28/86	**		7250 19A22
970	Main Landing Gear Door Link	PA-46-310P	8/7/84	**		3216 19B3
971B	Engine Baffle Modification And Aftercooler Clip Installation	PA-46-310P	2/23/87	**		7230 19B6
972	PART I - Hydraulic Pressure Gauge Line Fitting Replacement	PA-46-310P	8/20/84	762-643V		2930 19B9
972	PART II - Hydraulic Pressure Gauge Line Poppet Spring Replacement	PA-46-310P	8/20/84	764-874V		2930 19B9
973	Lower Cabin Door Step Up - Stop Installation	PA-46-310P	8/20/84	765-107V		5260 19B13
974	Fiberglass Nose Cowl Replacement	PA-46-310P	8/20/84	**		5430 19B15
975	Lower Cabin Door Duct Seal & Chain Stand-off	PA-46-310P	2/13/85	765-135V		2120 19B17
976	Seat Pan Reinforcement	PA-46-310P	8/20/84	765-103V		2506 19B19
978	Cabin Heat Valve Modification	PA-46-310P	1/15/86	765-176		2140 19B23
981	Engine Tachometer Replacement	PA-46-310P	10/22/85	765-183		7710 19C7
982	Turbo Inlet Temperature Probe Wiring Modification	PA-46-310P	2/4/86	588-859		7728 19C9
984	Hydraulic Pump Annunciator And Controller Installation	PA-46-310P	7/15/86	**		2917 19C15
985	PART I - Teledyne Continental Motors Special Service Notice No. 3-86. "TSIO-520BE Engine"	PA-46-310P	4/18/86			7230 19C17
985	PART II - Alternate Air Intake Assembly Modification	PA-46-310P	4/18/86	765-198	87-04-01	7160 19C17
989	Stiffener Installation - Induction Air Panel	PA-46-310P	8/20/86	765-304		7102 19D3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
990	Engine And Airframe Operational Characteristics And Operating Limitations	PA-46-310P	11/17/86	N/A		1100 19D5
991	Pilot/Copilot Oxygen System Modification	PA-46-310P	11/18/86	**		3512 19D9
992	Stereo System Power Supply Modification	PA-46-310P	11/19/86	584-387		2334 19D11
995A	Landing Gear Actuator Switch Modification - Gar Kenyon	PA-46-310P	5/28/87	407-560		3266 19D18
996	Engine Mount Heat Shield Installation	PA-46-310P	3/5/87	765-323		7120 19D22
999	Air Conditioner Compressor Mount - Shim Installation	PA-46-310P	7/17/87	84044-10 84044-11		2152 19E6
1000	Nose Gear Door Hinge Support Modification	PA-46-310P	10/16/87	765-347		3226 19E9
1001	Engine Mount Inspection/Modification	PA-46-310P	12/9/87	84010-48		7121 19E11
1004	Addition of Main Gear Door Protection Pad	PA-46-310P PA-46-350P	5/23/89	**		3216 19E20
1005	Nose Bowl Modification	PA-46-350P	6/8/89	766-215		5422 19E23
1006	Fuel Vent Line Protection	PA-46-310P	8/25/89	63913-199 488-702		3216 19F1
1007	Engine Air/Oil Separator Improvement	PA-46-350P	9/25/89	42414-00 2565-02		7251 19F3
1008	Operational Caution: Inoperative Turbine Inlet Temperature System	PA-46-350P	6/22/90	N/A		7200 19F5
1009	Bendix/King Installation Bulletin No. 312, Water Damage to the Pitch and Yaw Capstans and Servos	PA-46-310P PA-46-350P	9/19/90	**		2212 19F7
1010	Modification of Engine Baffle	PA-46-350P	1/19/94	**		7230 19F14
1011	Nose Gear Trunnion Replacement	PA-46-310P	4/27/94	766-211		7230 19F16
1012	Aileron Control Cable Replacement	PA-46-310P PA-46-350P	11/30/94	**		2710 19F23
1018A	Improved Intercooler Attachment Clips	PA-46-350P	9/13/99	89082-05		7236 18G23
1022	Lower Cowling Assembly Modification	PA-46-350P	2/12/99	766-658		5432 19H15
1023	Improved Security of the Pressure Controls Cable	PA-46-350P	4/12/99	**		2125 19H17
1026	Storm Window Seal Improvement Kit	PA-46-350P	11/3/99	766-659		5614 19I5
1035	Concorde Lead Acid Battery Conditioning	PA-46-500TP	7/20/2001	N/A		2432 19J12
1037	Power Lever / Manual Override (MOR) Knob	PA-46-500TP	7/26/2001	N/A		7611 19J21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1039A	Replacement TIT Probe Availability	PA-46-350P	12/8/2006	686-216	2011-06-10	7726 19K4
1041A	In-Service Safety Event Reporting	All	3/17/2020	N/A		N/A
1046A	Generator Control Unit (GCU) Rewire Kit	PA-46-500TP	9/27/2002	767-329		2430 19L1
1051	Gullwing Door Rub Strip Installation	PA-46-500TP	1/21/2003	104644-004		7110 19L15
1052	Life Limited Parts Marking and Disposition	All	5/21/2002	N/A		510 19L19
1053	Engine Starter Motor Replacement	PA-46-350P	10/16/2002	767-337		8011 20A1
1055	Executive Table Stow Adjustments	PA-46-500TP	6/20/2003	N/A		2520 20A6
1056	Accessory Cooling Air Inlet Drain Hose Routing Inspection	PA-46-500TP	2/19/2003	**		7500 20A9
1057	Upper Wing Skin Inspection and Reinforcement	PA-46-310P PA-46-350P PA-46-500TP	1/29/2003	767-352 767-353		5730 20A12
1058A	Horizontal Stabilizer Maintenance Manual Correction - Torque Value	PA-46-500TP	10/16/2012	767-005		5510
1059A	Tailcone Gusset Installation Kit	PA-46-500TP	10/16/2015	767-356		5300
1062	Lower Torque Link Bolt Inspection	PA-46-500TP	2/13/2003	**		3213 20B4
1065	Aileron Rivet Inspection	PA-46-500TP	7/29/2005	522-655		2710 20B13
1067	Steering Bellows Improvement	PA-46-500TP	3/31/2003	691-527		3250 20B20
1069	Flight Control Cable Terminal Corrosion Inspection	All	3/31/2003	N/A	CE-02-05 (SAIB)	2702 20C2
1072	Possible Magnetization of ELT Antenna	PA-46-500TP	6/4/2003	762-362		2300 20C9
1074	S-TEC Autopilot Component Seating Procedure	All	11/3/2003	N/A		2210 20C14
1075	Higher Capacity Battery Availability	PA-46-500TP	10/27/2003	601-910 767-375		2432 20C19
1076	Stall Warning Computer Verification	PA-46-500TP	1/9/2004	600-517 599-161		3418 20C22
1077	Magic 1500 Autopilot Go-Around Switch Wire Security	PA-46-500TP	12/3/2003	767-376		2200 20D1
1079	ADAHRS Fault Finding Guide (Meggitt SIL No. 26, Issue 1)	PA-46-500TP	5/5/2004	N/A		3400 20D7
1082	Fuel Filter Replacement (Pall SB ADB474-72-01)	PA-46-500TP	6/25/2004	601-808 601-809		2821 20E12
1085	ADAHRS Calibration Harness	PA-46-350P PA-46-500TP	7/1/2004	101453-002		3420 20E23
1086	Propeller Blade De-ice Boots Maintenance	PA-46-310P PA-46-350P PA-46-500TP	7/16/2004	N/A		3112 20F3
1089	Aircraft Painting Requirement	PA-46-350P PA-46-500TP	10/21/2004	N/A		1100 20F15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1090	Performance Upgrade, Lower Operating Temperature Limitation	PA-46-500TP	9/26/2005	767-380 767-381		2843 20F18
1091	Door Seal Protection (Latch Stop Kit)	PA-46-350P	12/15/2005	767-387		5210 20F21
1093B	Electrical Contactor Replacement Kit	PA-46-310P PA-46-350P PA-46R-350T	11/28/2017	88371		2400
1097	Flap Bellcrank Inspection and Flap Rigging Check	PA-46-310P PA-46-350P PA-46-500TP	10/17/2005	82905-10/-11		2700 20H4
1100	Crew Seat Modification	PA-46-350P PA-46-500TP	6/18/2006	767-522		2510 20H10
1102	Oil Pressure Indication Subject to RFI/EMI	PA-46-500TP	10/9/2006	88408-002		7261 20H14
1104	Flow Sensor Assy., Mass Flow Controller and ECS Crossover Tube Assy. Replacement	PA-46-500TP	3/14/2008	88417-002 88417-003		2140 20H20
1106A	Sky-Tec Starter Cranking Instructions	PA-46-350P PA-46R-350T	10/28/2009	N/A		8011 20I2
1107A	Modification to Eliminate False "GEN INOP" Annunciation	PA-46-500TP	10/3/2007	N/A		2420 20I6
1108	Manifold Pressure Transducer Failures	PA-46-350P PA-46R-350T	3/4/2008	N/A		7713 20I10
1110A	Pratt & Whitney Canada SIL No. PT6A-206 latest revision, Compressor and Turbine Washes as an Effective Means of Preventative Maintenance	PA-46-500TP	9/3/2013	N/A		7100
1111	Autopilot Pitch Servo and Programmer / Computer Upgrade	PA-46-350P PA-46R-350T	5/29/2008	88438-002 88439-002		2212 20I23
1113	Crew Seat Back Modification	PA-46-500TP PA-46-350P PA-46R-350T	2/25/2009	88444-002 (Kit)		2510
1114	NACA Inlet Guide Vane Installation Kit	PA-46R-350T	2/16/2009	88446-002 (Kit)		2140
1115A	WAAS Compatible Autopilot	PA-46-500TP	2/19/2009	N/A		2210
1116A	Contactor Maintenance	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	3/15/2019	N/A		2435
1117	MLB 700 Remote Control Antenna Modification	PA-46R-350T	3/16/2009	561-572		2330
1118	Sky-Tec Starter Replacement	PA-46-350P PA-46R-350T	10/28/2009	**		8011

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1120	Air Conditioning Servicing	PA-46-350P PA-46-500TP PA-46R-350T	6/18/2010	**		2150
1121	RG-41 Battery Service Life Improvement	PA-46-500TP	4/1/2010	601-910		2430
1122	G1000 Split Communciations Enable	PA-46-350P PA-46R-350T	5/20/2010	N/A		2300
1123	Avidyne EXP5000 Software Upgrade (Mod 57)	PA-46-350P PA-46-500TP PA-46R-350T	9/27/2010	N/A		3420
1126A	Voltage Suppressor Advisory	PA-46-350P PA-46-500TP PA-46R-350T	3/23/2017	N/A		3400
1127	Emergency Exit Interior Panel Hook and Loop Fastener Replacement	PA-46-350P PA-46-500TP PA-46R-350T	7/2/2010	**		5220
1128	Improved Capacity Battery	PA-46-350P PA-46R-350T	3/7/2012	88495-002 601-919		2430
1129	Improved Landing Gear Service Replacement Actuators Available	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	6/27/2011	**		3230
1130	Lower Entry Door Upgrade	PA-46-350P PA-46-500TP	8/4/2010	88423-002 452-215 106611-003		5210
1131A	Aileron Sector Bearing Lubrication Requirements	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	2/11/2019	MIL-PRF-7870C		5755
1132	Fuel Tank Leaks	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	12/7/2010	N/A		5712
1135	Control Cable / Pulley Inspections	All	10/19/2010	N/A		5720
1136A	Fuel Pressure Switch Adjustment	PA-46-350P PA-46R-350T	4/28/2011	74093-002 688-192		2820
1137	Circuit Breaker Panel Modification	PA-46-500TP	11/3/2010	88482-002 88482-003		3910
1138	Safe Flight Service Letter No. 65, Lift Transducer Modification	PA-46-350P PA-46-500TP PA-46R-350T	1/17/2011	599-160 652-689		3410
1140	Garmin G1000 Software Version 720.12	PA-46-350P PA-46R-350T	6/22/2011	**		3420
1142A	Line Contactor and Generator Control Unit Replacement	PA-46-500TP	3/10/2014	602-943 PS60047-1 601-922		2430

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SL75

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1147	Garmin G1000 Software Version 720.14	PA-46-500TP	12/1/2011	**		3420
1148	Garmin G1000 Software Version 720.14	PA-46-350P PA-46R-350T	5/2/2012	**		3420
1155	Ground Idle Adjustment	PA-46-500TP	1/30/2012	N/A		7610
1157	Exterior Lighting - Led Upgrade	PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T	4/26/2012	**		3340
1158	Hubcap Upgrade	PA-46-500TP	4/26/2012	551-621		3240
1159B	Fuel Sender Upgrade	PA-46-310P PA-46-350P PA-46R-350T	10/12/2018	88535 88462		2840
1160	Interior Lighting – LED Upgrade	PA-46-350P PA-46-500TP PA-46R-350T	10/31/2017	479-000 479-001 479-002 488-770 103203-005 103203-006 103203-007		3300
1168	False Alternator Fail Annunciations	PA-46-350P PA-46R-350T	2/28/2013	N/A		2300
1170	Evaporator Module Assembly Replacement Requirements	PA-46-350P PA-46-500TP PA-46R-350T	6/27/2013	88542		2150
1178A	Garmin G1000 Software Version 720.15	PA-46-500TP	4/23/2014	**		3420
1179	Garmin G1000 Software Version 720.15	PA-46-350P PA-46R-350T	4/24/2014	**		3420
1183	Elevator Plate Assembly Rivet Inspection	PA-46-310P PA-46-350P PA-46R-350T	10/21/2014	83515-002, 83508-002		2730
1184	Stall Warning System Test Update	PA-46-350P PA-46R-350T	2/11/2015	**		2730
1185A	Stall Warning System Test Update	PA-46-500TP	3/26/2015	**		2730
1189B	Inspection of GCU Reverse Current Protection Circuit and Connector	PA-46-500TP	8/14/2015	461-659		2424
1194A	Garmin G1000 Software Update Version 720.17	PA-46-350P PA-46R-350T	9/1/2015	N/A		3420
1195	Garmin G1000 Software Update Version 720.17	PA-46-500TP	9/2/2015	N/A		3420
1196A	Availability of GTX 33ES Transponder	PA-46-350P PA-46-500TP PA-46R-350T	12/21/2017	N/A		3452
1198	Garmin G1000 Software Version 2164.03	PA-46-350P M350	2/24/2016	N/A		3420

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1199A	Garmin G1000 Software Version 2163.05	PA-46-500TP M500	7/26/2016	N/A		3420
1200A	Pratt & Whitney Canada Service Bulletin No. 3482 – Replacement/Modification of Turboprop Fuel Control Unit	PA-46-500TP	4/27/2016	N/A		7320
1201B	Garmin G1000 Software Update Version 2164.06 with Stall Heat Control	PA-46-350P M350	8/19/2016	88589-002 190-01889-00 190-01888-00		3420
1202	Main Landing Gear Actuator Hydraulic Hose Replacement	PA-46-350P PA-46-500TP PA-46R-350T	2/7/2017	187-273 102551-004		3230
1203A	Garmin G1000 Software Update Version 720.17 with Stall Heat Control	PA-46-350P PA-46R-350T	3/21/2019	88589-002 88589-003 190-01108-01 190-01107-01		3420
1204	Heated Windshield Test Procedure	PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	8/17/2016	N/A		3040
1205	Garmin G1000 Software Update Version 720.17 with Stall Heat Control	PA-46-500TP	6/27/2017	88590-002 VB-1993 R17		3420
1206	Garmin G1000 Software Update Version 2163.08 with Stall Heat Control	PA-46-500TP M500	4/14/2017	88590-003		3420
1208A	Garmin G3000 Software Update Ver. 2039.06 with Sidetone Improvement	PA-46-600TP	12/12/2016	10-01615-06		3420
1211	Audio Bus Wiring Inspection and Fuse Replacement	PA-46-350P PA-46-500TP	5/3/2017	461-685		2350
1212	Garmin G3000 Software Update Version 2039.08 with Aural Alert Improvement	PA-46-600TP	3/10/2017	10-01615-08		3420
1217	Garmin G3000 Software Update Version 2039.11 with FIKI Modification	PA-46-600TP	7/13/2017	10-01615-11 VB-2366 R03		3420
1219	Cabin Pressure Control System (CPCS) Troubleshooting Procedure Revision	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	1/5/2018	N/A		2130
1220	Garmin G1000 Software Version 2164.08	PA-46-350P M350	11/6/2017	190-01889-00 190-01888-00		3420
1221A	Wing Access Cover Clinch Nut Repair	PA-46-500TP PA-46-600TP	4/25/2024	477-899 414-779		2810
1222B	Hydraulic Pump Pressure Switch Replacement	PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	3/29/2018	102559-002 (461-751) 102559-003 (461-768) 102559-004 (461-770)		2913

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1224	Decorative Window Sealant Improvement	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP	10/9/2017	179-759		5610 5620
1227	Forward Ballast Plates Installation	PA-46-600TP	11/2/2017	46N08A000-800		5300
1228A	Engine Wiring Harness Improvement	PA-46-500TP M500 PA-46-600TP	1/23/2019	**		2497
1230B	G3000 And G3000 NG Electronic Checklist – M600	PA-46-600TP	8/13/2024	N/A		3140
1231A	Garmin G3000 Software Version 2039.12	PA-46-600TP	8/3/2018	190-01927-01 190-01928-01		3420
1232C	Garmin G1000 Software Version 2163.09	PA-46-500TP M500	8/21/2018	190-01843-01 190-01842-01		3420
1233	Wing And Flap Protective Tape Improvement	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	7/13/2020	380-066		5753
1234	Garmin GIA Software Update 2963.01 for Transponder Compatibility with ADS-B Out in G1000 Sw Ver. 720.17	PA-46-350P PA-46-500TP PA-46R-350T	1/16/2018	**		3452
1236	Channel Modification For Nose Landing Gear Trunnion Clearance	PA-46-500TP PA-46-600TP	10/2/2019	N/A		5311
1238B	Aileron Seal Removal And Aileron Replacement	PA-46-600TP	1/6/2022	46W43A001 415-533 (MS35206-243)		5751
1244	Wiring Ground Modification	PA-46-600TP	6/21/2018	N/A		2397
1245	G1000 NXi Electronic Checklist	PA-46-500TP M500	12/14/2022	N/A		3140
1246	G1000 NXi Electronic Checklist	PA-46-350P M350	1/7/2020	N/A		3140
1247A	Hydraulic System Flexible Hose Inspection And Replacement	PA-46-600TP	11/5/2019	566-670 (171001-4CR-0110)		2910 3233
1249	Control Column Plug Modification	PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	5/20/2019	85228-002		2701
1250B	Garmin G1000 Software Update - M350	PA-46-350P M350	4/12/2019	88642-001 190-01889-01 190-01888-01		3420
1251	Garmin G1000 Software Version 2163.10	PA-46-500TP	12/18/2023	88651-001		3420
1253	G1000 Electronic Checklist	PA-46-350P M350	12/11/2019	N/A		3140
1257	Servicing The Alternative Wheel Nut Configuration	PA-46-600TP	5/6/2019	N/A		3420
1259A	Garmin G3000 Software Version 2039.15	PA-46-600TP	11/17/2020	88644-001		3420
1260	Optional Nav/Com Analog Conversion Kit	PA-46-600TP	5/24/2019	88648-001		2397

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1261	Stall Warning Heat Control Inspection	PA-46-350P PA-46-350T PA-46-500TP	7/19/2019	N/A		3418
1264	Garmin G3000NG Software Version 2975.05	PA-46-600TP	8/16/2019	88637-001		3420
1265	Flight Control System Checks	All	8/6/2019	N/A		2700
1266	Piper HALO Autoland System Activation and Garmin Software Update Ver. 2975.16	PA-46-600TP	6/26/2020	88660-701 88660-702 88645-702 88680-001		
1269A	Radar Altimeter Installation	PA-46-600TP	3/6/2023	88643-701 88654-001		3444
1270	Radar Altimeter Installation	PA-46-600TP	1/28/2021	88645-702 88654-001		3444
1272	Elevator Spar Inspection	PA-46-500TP PA-46-600TP	10/25/2019	N/A		5521
1274	Hartzell Propeller Preferred Grease	All	1/6/2020	NYCO GN 3058		6110
1275	Optional Radar Altimeter Installation (Garmin GRA 55 Radar Altimeter)	PA-46-600TP	1/12/2021	88645-701 88654-001		3444
1279	High-Side Current Monitor Calibration	PA-46-600TP	7/8/2020	N/A		3420
1280	Rudder Pedal And Bar Assembly Inspection	All	2/14/2020	N/A		2720
1281B	Piper Halo Autoland System Activation	PA-46-600TP	1/7/2022	88670-701		2230
1282	Avionics Cooling Fan Advisory	PA-46-350P PA-46-500TP PA-46R-350T	6/22/2020	460-124		2120
1283A	Piper HALO Autoland System Activation	PA-46-600TP	1/7/2022	88662		2230
1284A	Aspen Avionics EFD1000 Update to Software Version 2.10.2	PA-46-350P PA-46-500TP PA-46-600TP	5/15/2023	N/A		3420
1285C	Proper Tire Pressure Maintenance	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	3/29/2022	**		3244
1286D	Nose Landing Gear Steering Components Inspection And Adjustment	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	10/15/2021	N/A		3200
1292D	Garmin G3000NG Software Version 2975.24	PA-46-600TP	8/13/2024	88680-001 88704-701		3420
1296	Flap Fail Module Assembly Replacement	PA-46-600TP	3/10/2022	602-575		2756

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	EFFECTIVITY DATE	PART/KIT NO.	A.D. NO.	ATA CODE
1297	Rudder Tube Assembly Inspection	PA-46-310P PA-46-350P PA-46R-350T PA-46-500TP PA-46-600TP	10/22/2021	82810-015 82810-016		2720
1301B	Standalone Autothrottle Enablement	PA-46-600TP	9/26/2024	88661/88663		2230
1304B	Garmin G1000 NXi Software Update - M350	PA-46-350P M350	3/11/2024	88711-701		3420
1310A	M600 Unpaved Field Operations	PA-46-600TP	11/7/2022	88596-001 88705-701		3200
1314	Oxygen Generator Inspection	PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP	8/22/2022	N/A		3500
1315	Elevator Trim Tab Pushrods Corrosion Control	PA-46-310P PA-46-350P Mirage / M350 PA-46-500TP Meridian / M500 PA-46-600TP PA-46R-350T	5/2/2023	82998-013 82998-015 82836-007 102846-005		5520
1317	GI 275 Standby Instrument Magnetic Model Update	PA-46-350P M350 PA-46-500TP M500 PA-46-600TP	11/11/2022	006-B3182-10		3420
1323	Garmin G1000 NXi Software Update Version 2785.11	PA-46-500TP M500	3/20/2023	88719-701		3420
1332C	Garmin G3000NG Software Version 2975.45	PA-46-600TP M600	10/16/2024	88739-701		3420
1336	GDL 60 Datalink Installation - M600	PA-46-600TP M600	3/27/2024	88737-701 88737-702 88737-703 88737-704 88737-705 88724-701 88724-702 88724-703 88724-704 88724-705		3425
1337	Flight Controls Maintenance Improvements	PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T	1/29/2023			2700
1338	Garmin G1000 NXi Software Update – M350	PA-46-350P M350	4/1/2024	88749-701		3420
1344	Garmin G3000 NG Software Update - M700	PA-46-701TP M700 Fury	5/31/2024	88752-701		3420
1345	Unpaved Field Operations - M700 Fury	PA-46-701TP M700 Fury	8/15/2024			3200

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.