



**SERVICE BULLETIN
AND
SERVICE LETTER**

INDEX

PIPER AIRCRAFT, INC.

Published by

Piper Aircraft, Inc.
Attn: Technical Publications
2926 Piper Drive
Vero Beach, Florida 32960
U.S.A.

© 2003–2024 Piper Aircraft, Inc.



Member
General Aviation
Manufacturers Association

SERVICE PUBLICATION AVAILABILITY

Piper terminated production of all Aerofiche (i.e., microfiche) products in 2008.

Service Publications (i.e., service bulletins, letters, etc.) are available as described in the Customer Service Information File on the Piper website.

The latest revision of this publication is also available as free downloads from the Piper Aircraft, Inc. website at:

<http://www.piper.com/technical-publications-documents/>

GENERAL

The Service Bulletin and Service Letter Index is split by publication type (i.e., SB or SL) and then arranged by aircraft model number (i.e., PA-28, etc) with similar model series grouped together (see Table of Contents). Within these series, applicable service bulletins/letters are listed in numerical order. To locate a specific bulletin or letter, select the appropriate service publication type (i.e., SB or SL) and then locate the affected aircraft series grouping. Bulletins/letters which apply are listed therein and are identified by Subject, Model(s) Affected, and the Issue Date of the Service Bulletin/Letter. Additionally, the index may list part or kit numbers and related A.D. numbers. The Air Transport Association Code (ATA Spec. 100 / iSpec 2200) is provided to assist in maintenance record keeping and researching publications.

NOTES

1. Airworthiness Directives referred to by number in the A.D. No. column and A.D. numbers listed in individual service bulletins / service letters are those which applied at the time of publication. Refer to the latest FAA Bi-weekly listing for current A.D. information. A searchable database of AD's is available on the FAA website. See the "Airworthiness Directives" link at "www.faa.gov".
2. When ** appears in the Part/Kit No. column, material requirements are too extensive to be listed in the index; refer to the appropriate service bulletin/letter for material identification.
3. When Part/Kit No. and/or A.D. No. column is left blank or indicates "N/A," no material and/or Airworthiness Directive is involved.
4. Airworthiness Directives may be issued without an associated service bulletin/letter; therefore, refer to Airworthiness Directive Listings issued by the FAA to determine all Airworthiness Directives applicable to an aircraft. See Note 1, above.
5. Type Certificates (TC's) for the following aircraft models are not held by Piper: AE-1, HE-1, J5A, J5A-80, J5B, J5C, L-14, PA-12, PA-12S, PA-14, PA-25, PA-60, and Stinson 108-3. See Supersession List for affected service bulletins / letters. The current TC holder(s) may be identified through the FAA (see the "Regulatory and Guidance Library" at <http://rgl.faa.gov/>).

SERVICE BULLETIN AND SERVICE LETTER
INDEX

TABLE OF CONTENTS

| <u>SUBJECT</u> | <u>PAGE NO.</u> |
|----------------------------------|------------------------|
| Service Publication Availability | iii |
| General | iv |
| Notes | iv |
| Table Of Contents | v |
| Supersession List | vii |

SERVICE BULLETINS

| | |
|---|------|
| CLASSIC AIRCRAFT: (B-2 thru PA-22) | SB1 |
| PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250 | SB9 |
| PA-24, PA-30/39 | SB17 |
| PA-28, PA-28R, PA-44/PA-44T | SB23 |
| PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350 | SB43 |
| PA-31T/31T1, PA-31T2/31T3, PA-42 | SB55 |
| PA-32 Series | SB65 |
| PA-34-200/200T/220T | SB79 |
| PA-36 | SB87 |
| PA-38-112 | SB91 |
| PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46-701TP, PA-46R-350T | SB95 |

SERVICE LETTER

| | |
|---|------|
| CLASSIC AIRCRAFT: (B-2 thru PA-22) | SL1 |
| PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250 | SL7 |
| PA-24, PA-30/39, PA-28, PA-28R, PA-44/PA-44T | SL23 |
| PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350 | SL37 |
| PA-31T/31T1, PA-31T2/31T3, PA-42 | SL47 |
| PA-32 Series | SL53 |
| PA-34-200/200T/220T | SL61 |
| PA-36 | SL67 |
| PA-38-112 | SL69 |
| PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46-701TP, PA-46R-350T | SL71 |

THIS PAGE INTENTIONALLY BLANK

SUPERSESSION LIST

The following service bulletins / letters have been superseded, become obsolete, were never issued, or are no longer maintained by Piper, as indicated (see Note 5).

NOTE: This list is not all inclusive. Additionally, it does not include supersessions by a normal (i.e. - A, B, C, etc.) revision within the same SB/SL number.

| <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> |
|--------------------------------------|------------------------------|--------------------------------------|------------------------------|--------------------------------------|------------------------------|
| SB 0005 | Obsolete | SB 0101 | PA-12 | SB 0670 | SB 1235 |
| SB 0006 | Obsolete | SB 0102 | PA-12 | SB 0687 | SB 1007 |
| SB 0010 | Obsolete | SB 0105 | PA-12/14 | SB 0698A | SB 0811A |
| SB 0011 | Obsolete | SB 0106 | PA-12/14 | SB 0699 (PA-34 only) | SB 0899 |
| SB 0012 | Obsolete | SB 0107 | PA-12 | SB 0716 | Not Used |
| SB 0013 | Obsolete | SB 0109 | PA-12/14 | SB 0720 | PA-60 |
| SB 0014 | Obsolete | SB 0114 | STINSON 108-3 | SB 0730 | Not Used |
| SB 0015 | Obsolete | SB 0115 | STINSON 108-3 | SB 0735 | PA-25 |
| SB 0016 | Obsolete | SB 0137 | SB 0140 | SB 0743 | PA-60 |
| SB 0017 | Obsolete | SB 0141 | SB 0354B | SB 0746A | PA-60 |
| SB 0019 | Obsolete | SB 0147 | Obsolete | SB 0750 | PA-60 |
| SB 0020 | Obsolete | SB 0154 | Obsolete | SB 0755 | PA-60 |
| SB 0022 | Obsolete | SB 0170 | Obsolete | SB 0756 | PA-60 |
| SB 0024 | Obsolete | SB 0204 | PA-25 | SB 0757 | PA-60 |
| SB 0025 | Obsolete | SB 0206 | PA-25 | SB 0761 | PA-60 |
| SB 0026 | Obsolete | SB 0215 | PA-25 | SB 0770 | PA-60 |
| SB 0027 | Obsolete | SB 0217 | PA-25 | SB 0793 | SB 0809 |
| SB 0029 | Obsolete | SB 0221 | PA-25 | SB 0815 | PA-60 |
| SB 0030 | Obsolete | SB 0227 | SB 0230A | SB 0818 | PA-60 |
| SB 0031 | J5A/B/C | SB 0241A | PA-25 | SB 0830 | PA-25 |
| SB 0032 | Obsolete | SB 0247 | PA-25 | SB 0832 | PA-60 |
| SB 0033 | Obsolete | SB 0298 (portions) | SB 0312 | SB 0833 | Not Used |
| SB 0034 | J5A/B/C | SB 0302 | Obsolete | SB 0864 | SB 1008 |
| SB 0037 | Obsolete | SB 0318A | SB 0343 | SB 0886 | SB 1372 |
| SB 0038 | Obsolete | SB 0328 | PA-25 | SB 0875 | SB 0876A |
| SB 0039 | Obsolete | SB 0341 | PA-25 | SB 0878 | PA-25 |
| SB 0041 | Obsolete | SB 0366 | SB 0456A | SB 0880A | PA-60 |
| SB 0051 | Obsolete | SB 0371 | SB 0456A | SB 0894 | SB 1087 |
| SB 0052 | Obsolete | SB 0372B | SB 0446A | SB 0898 | PA-60 |
| SB 0054 | SB 0083 | SB 0377 | SB 0456A | SB 0902 | PA-60 |
| SB 0057 | Obsolete | SB 0378 | SB 0456A | SB 0903 | PA-60 |
| SB 0059 | Obsolete | SB 0388 | SB 0456A | SB 0908 | PA-60 |
| SB 0060 | J5A/B/C | SB 0410 | PA-25 | SB 0909 | SB 0913A |
| SB 0062 | Obsolete | SB 0413 | SB 1123 | SB 0918 | PA-60 |
| SB 0064 | Obsolete | SB 0414 | PA-25 | SB 0920 | PA-60 |
| SB 0067 | Obsolete | SB 0416 | SB 0446A | SB 0942 | PA-60 |
| SB 0069 | Obsolete | SB 0426 | PA-25 | SB 0950 | PA-60 |
| SB 0070 | Obsolete | SB 0430 | SB 0492 | SB 0978A | SB 1372 |
| SB 0087 | J5A/B/C | SB 0456A | SB 1266 | SB 1011 | SB 1216 |
| SB 0090 | PA-12 | SB 0457 | SB 0479B | SB 1038 | VSP-145 |
| SB 0092 | PA-12 | SB 0532 | PA-25 | SB 1096 | Not Used |
| SB 0093 | PA-12 | SB 0534 | SB 0644E | SB 1101 | Not Used |
| SB 0094 | PA-12 | SB 0540A | Cancelled | SB 1112 | Not Used |
| SB 0096 | PA-12 | SB 0551A | PA-25 | SB 1115 | Not Used |
| SB 0097 | PA-12 | SB 0581 | Not Used | SB 1116 | Not Used |
| SB 0098 | PA-12 | SB 0605 | Obsolete | SB 1124 | Not Used |
| SB 0100 | PA-12 | SB 636A | SB 1273C | SB 1129 | Not Used |

SUPERSESSION LIST

(continued)

| <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> |
|--------------------------------------|------------------------------|--------------------------------------|------------------------------|--------------------------------------|------------------------------|
| SB 1133 | Not Used | SL 0265 | 753-755 | SL 0604 | SB 0531 |
| SB 1142 | Not Used | SL 0282 | SB 0145 | SL 0632 | PA-25 |
| SB 1148 | Not Used | SL 0308 | SSL-141 | SL 0640 | PA-25 |
| SB 1149 | Not Used | SL 0331 | PA-25 | SL 0646 | PA-25 |
| SB 1155 | Not Used | SL 0332A | PA-25 | SL 0694 | SB 0492 |
| SB 1163 | Not Used | SL 0335 | PA-25 | SL 0702 | PA-25 |
| SB 1165 | Not Used | SL 0337 | PA-25 | SL 0703 | Obsolete |
| SB 1189A | Not Used | SL 0342 | PA-25 | SL 0721A | PA-25 |
| SB 1191A | Obsolete | SL 0343 | PA-25 | SL 0724 | PA-25 |
| SB 1195 | SB 1395 | SL 0344 | PA-25 | SL 0728 | PA-25 |
| SB 1203 | SL 1117 | SL 0351 | SB 0354B | SL 0748 | Obsolete |
| SB 1206 | Not Used | SL 0357A | PA-25 | SL 0760 | SB 1131 |
| SB 1215 | SSL 436 | SL 0361 | PA-25 | SL 0775A | Obsolete |
| SB 1218A | SB 1385 | SL 0371 | SB 0209 | SL 0799 | SB 0955 |
| SB 1219 | SL 1125 | SL 0371A | SB 0209 | SL 0811 | SB 1248 |
| SB 1221 | Not Used | SL 0376 | PA-25 | SL 0812 | PA-25 |
| SB 1222 | Not Used | SL 0377 | PA-25 | SL 0914 | PA-60 |
| SB 1224 | Not Used | SL 0383 | PA-25 | SL 0918 | PA-60 |
| SB 1231 | Not Used | SL 0385 | PA-25 | SL 0919 | PA-60 |
| SB 1239 | Not Used | SL 0387 | PA-25 | SL 0953 | SB 0896 |
| SB 1249 | SB 1252 | SL 0392 | SB 0924 | SL 0955 | SB 0868 |
| SB 1263 | Not Used | SL 0396 (portions) | SL 0527D | SL 0957 | PA-60 |
| SB 1265 | Not Used | SL 0399 | PA-25 | SL 0980 | SB 0908 |
| SB 1268 | SB 1270 | SL 0403 | PA-25 | SL 1030 | SSL 435 |
| SB 1272 | Not Used | SL 0428 | SB 0222A | SL 1042 | Not Used |
| SB 1277 | Not Used | SL 0452 | SL 0486A | SL 1044 | Not Used |
| SB 1281 | SB 1285 | SL 0455 | PA-25 | SL 1050 | Not Used |
| SB 1287A | Not Used | SL 0463A | PA-25 | SL 1061 | Not Used |
| SB 1292 | Not Used | SL 0468A | PA-25 | SL 1064 | Not Used |
| SB 1294 | Not Used | SL 0479 | PA-25 | SL 1068 | Not Used |
| SB 1298 | Not Used | SL 0488 | Obsolete | SL 1070 | Not Used |
| SB 1310 | SB 1339 | SL 0489 | Obsolete | SL 1071 | Not Used |
| SB 1320 | SL 1229 | SL 0493 | Cancelled | SL 1073 | Not Used |
| SB 1321 | Not Used | SL 0496 | Obsolete | SL 1080 | Not Used |
| SB 1330 | Not Used | SL 0510 | Obsolete | SL 1083 | Not Used |
| SB 1335 | SA 46-28 | SL 0515 | PA-25 | SL 1094 | Not Used |
| SB 1345A | SB 1372 | SL 0521 | Obsolete | SL 1096 | Not Used |
| SB 1347 | Not Used | SL 0528 | Obsolete | SL 1098 | Not Used |
| SB 1348 | SA 46-31 | SL 0536 | PA-25 | SL 1099 | Not Used |
| SB 1351 | Not Used | SL 0540 | Obsolete | SL 1101 | Not Used |
| SB 1353 | SA 28-05 | SL 0551 | Obsolete | SL 1103A | Not Used |
| SB 1356 | SL 1297 | SL 0554 | Obsolete | SL 1109 | SL 1142 |
| SB 1373 | Not Used | SL 0563 | PA-25 | SL 1109A | Not Used |
| SB 1374 | Not Used | SL 0570 | SB 0343 | SL 1112 | Not Used |
| SB 1376 | Not Used | SL 0572 | Obsolete | SL 1114A | Not Used |
| SB 1394 | Not Used | SL 0583 | Obsolete | SL 1115B | Not Used |
| SB 1398 | Not Used | SL 0586 | PA-25 | SL 1119 | Not Used |
| SB 1406 | Not Used | SL 0588 | SB 0840 - PT1 | SL 1133 | Not Used |
| SL 0108 | PA-12 | SL 0590 | SB 0840 - PT2 | SL 1136B | Not Used |
| SL 0110 | PA-12 | SL 0597 | SB 0965 | SL 1139A | SL 1147 |
| SL 0113 | PA-12/14 | SL 0600 | SB 1199 | SL 1143 | Not Used |
| SL 0160 | SL 0221 | SL 0601 | SB 0356 | SL 1144 | Not Used |
| SL 0191 | SL 0233 | SL 0602 | Obsolete | SL 1145 | Not Used |

SUPERSESSION LIST

(continued)

| <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> | <u>Superseded / Obsolete Pub</u> | <u>New Pub or Reason</u> |
|---|-------------------------------------|---|-------------------------------------|---|-------------------------------------|
| SL 1146 | Not Used | SL 1341 | Not Used | | |
| SL 1150 | Not Used | SL 1342 | Not Used | | |
| SL 1151 | Not Used | | | | |
| SL 1152 | Not Used | | | | |
| SL 1155A | Not Used | | | | |
| SL 1163 | Not Used | | | | |
| SL 1166 | Not Used | | | | |
| SL 1167 | Not Used | | | | |
| SL 1169 | Not Used | | | | |
| SL 1171 | Not Used | | | | |
| SL 1173 | Not Used | | | | |
| SL 1174 | Not Used | | | | |
| SL 1176 | Not Used | | | | |
| SL 1180 | Not Used | | | | |
| SL 1181 | Not Used | | | | |
| SL 1182 | Not Used | | | | |
| SL 1186 | Not Used | | | | |
| SL 1187 | Not Used | | | | |
| SL 1190 | Not Used | | | | |
| SL 1191 | Not Used | | | | |
| SL 1192 | Not Used | | | | |
| SL 1202A | SL 1247 | | | | |
| SL 1206A | Not Used | | | | |
| SL 1207 | SL 1217 | | | | |
| SL 1209 | SB 1300 | | | | |
| SL 1215A | SL 1254 | | | | |
| SL 1223 | VSP 248 | | | | |
| SL 1225 | SSL 482 | | | | |
| SL 1235 | SB 1324 | | | | |
| SL 1237 | Not Used | | | | |
| SL 1241 | SL 1216 | | | | |
| SL 1242 | SL 1231A | | | | |
| SL 1243 | Not Used | | | | |
| SL 1248 | SSL 493 | | | | |
| SL 1258 | SB 1349 | | | | |
| SL 1266B | Not Used | | | | |
| SL 1271 | Not Used | | | | |
| SL 1272A | SB 1369 | | | | |
| SL 1287 | Not Used | | | | |
| SL 1288 | Not Used | | | | |
| SL 1289 | SB 1364 | | | | |
| SL 1290 | Not Used | | | | |
| SL 1295 | SB 1366 | | | | |
| SL 1298 | SSL 507 | | | | |
| SL 1299 | Not Used | | | | |
| SL 1303 | SL 1292A | | | | |
| SL 1305 | SB 1375 | | | | |
| SL 1306 | SL 1309 | | | | |
| SL 1307 | SL 1293A | | | | |
| SL 1312 | SB 1383 | | | | |
| SL 1315 | SB 962 | | | | |
| SL 1319 | SB 1379 | | | | |
| SL 1328 | Not Used | | | | |

THIS SPACE INTENTIONALLY BLANK

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|---------------------|-----------------|-------------|-------------|
| 1 | How to Rig Cub E2, J2, J3 Airplanes | E2, J2 & J3 | 2/15/46 | | | 2A1 |
| 2 | Special Tubing in Fuselage | All Models Manufactured thru December 1945 | 2/15/46 | | | 2A2 |
| 3 | Nose Heavy Condition | All Models Manufactured thru December 1945 | 2/15/46 | | | 2A3 |
| 4 | Maintenance of Fuel System | All Models Manufactured thru December 1945 | 2/15/46 | | | 2A4 |
| 7 | Reinforcement of Stabilizer Yoke | J2 | 2/18/46 | | | 2A5 |
| 8 | Reinforcement of Stabilizer Yoke | E2 and F2 | 2/18/46 | | | 2A7 |
| 9 | Tail Surface Bracing | E2, F2 & J2 | 2/18/46 | | | 2A9 |
| 18 | Replacement Tail Brace Wire Nipples | J2 and J3 | 2/18/46 | | | 2A11 |
| 21 | Engine Mounting Bolt Failures | J3C-65 Cubs with Continental A50 Engine Installation | 2/18/46 | | | 2A14 |
| 23 | Removal of Bug Screen | J4 | 2/18/46 | | | 2A15 |
| 28 | Electrical Wiring | J4 | 2/18/46 | | | 2A16 |
| 35 | Reinforcement of Windshield Attachment | J3 | 2/19/46 | | | 2A20 |
| 36 | Inspection of Motor Mount | J3 | 11/4/41 | | | 2A22 |
| 40 | Outlet Reinforcement on 12 Gallon Fuel Tanks | J3 | 2/19/46 | | | 2A23 |
| 42 | Elevator Bungee Installation | J3S | 2/19/46 | | | 2B1 |
| 43 | Stabilizer Link Tubes and Rear Support Bearing Bracket | J3 | 2/19/46 | | | 2B3 |
| 44 | Operation of Airplanes with Enclosure Door Open | J3 | 2/19/46 | | | 2B6 |
| 45 | Control System Interference | J3 | 2/19/46 | | | 2B7 |
| 46 | Strainer Attachment Fittings | J3F-50, J3L-50, J3L-55, J4, J4A, J4B, J4D | 2/19/46 | | | 2B9 |
| 47 | Preparation for Winter Operation | J3 Series, E2, J2, J3, 40 H.P. (not equipped with Adequate Carburetor Heater.) | 2/19/46 | | | 2B11 |
| 48 | Mufflers: 1. Failure of Inner-Baffle End Attachments 2. Inspection 3. Remedial Measures for Preventing Engine Failure | J4A and J4F | 2/19/46 | | | 2B13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------|----------|----------|
| 49 | Revised Washer for Fin Brace Rod Clevis | J3 | 2/19/46 | | | 2B16 |
| 50 | Ribstitching | E2, J2, J3 J4 | 2/19/46 | | | 2B17 |
| 53 | Fuel Shut-off Swivel Fitting | J3 | 2/20/46 | | | 2B19 |
| 55 | Fuel Tank Vents | J4E | 2/20/46 | | | 2B21 |
| 56 | Wing Aileron Bellcrank Bracket Failures | J4 | 2/20/46 | | | 2B23 |
| 58 | Steerable Tail Wheel Shock Cords | All Models Manufactured thru December 1945 | 2/20/46 | | | 2C2 |
| 61 | Aging of Protective Finish on Wood Wing Spars | J3, J4, L4 and L4A | 2/20/46 | | | 2C4 |
| 63 | Stabilizer Aluminum Yoke Casting | J3, L-4, L-4A, L-4B. | 2/20/46 | | | 2C5 |
| 65 | Fuel Tank Repairs | J4E | 2/20/46 | | | 2C7 |
| 66 | Flexible Hose End Fittings (3/8" Synthetic) | J3, J4 | 2/20/46 | | | 2C10 |
| 68 | Stabilizer Rear Bearing Bracket | J3 | 2/20/46 | | | 2C11 |
| 71 | Exhaust Muffler Inspection and Repair | J3, J4 Airplanes Incorporating Exhaust Mufflers. | 2/20/46 | | | 2C12 |
| 72 | Rudder Pedal and Floorboard Attachment Lugs | J3 | 2/20/46 | | | 2C13 |
| 73 | Cockpit Enclosure Modification | L4 | 2/20/46 | | | 2C16 |
| 74 | Rigging Procedure | J4 | 2/20/46 | | | 2C18 |
| 75 | Carburetor Heat Control | J3 Airplanes with Carburetor Heat Control | 2/20/46 | | | 2C20 |
| 76 | Windshield Replacement | J3 Airplanes with Formed Eyebrow Fairing Tubes. | 2/20/46 | | | 2C24 |
| 77 | Seats, Safety Belts and Control Cables | E2, F2, J2, J3 | 2/18/46 | | | 2D4 |
| 78 | Wing Drag Wire Inspection | E2, F2, H2, J2 | 2/18/46 | | | 2D6 |
| 79 | Reinforcing of Rib Nose Structure | J4 | 2/18/46 | | | 2D9 |
| 80 | Fuel Valve Control | J3 and J4 (Except Those with Auxiliary Fuel Tanks Installed.) | 2/18/46 | | | 2D14 |
| 81 | Motor Mount Failure | All Models Manufactured thru December 1945 | 2/20/46 | | | 2D17 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------|----------|----------|
| 82 | Safety Wire for Control System Turnbuckles | E2, J2, J3, J4 | 2/20/46 | | | 2D18 |
| 83 | Tailskid Spring Attachment Reinforcement | E2, J2, J3 | 2/20/46 | | | 2D20 |
| 84 | Winterization of J3C-65 | J3 | 5/9/46 | | | 2E1 |
| 85 | Reworking of Bottom Cowl for Replacing Airscoop EQ5259 and EQ5370 | J3 | 4/25/46 | | | 2E4 |
| 86 | J3 Lift Struts and Lift Strut Clevis Bolts | J3 | 10/16/46 | | | 2E5 |
| 88 | Relocation of J3 Scott Brake Cylinders | J3 | 10/11/46 | | | 2E10 |
| 89 | Replacement of Kem Gasoline Filter Gasket | J3 | 7/11/46 | | | 2E15 |
| 91 | Inspection of Fuel Strainer Installation | J3 | 8/6/46 | | | 2E17 |
| 95 | Defective Glass Fuel Strainer Bowls | J3 | 9/11/46 | | | 2E23 |
| 99 | Header Tank Installation on PA-11 Airplanes | PA-11 | 7/29/47 | | | 2F6 |
| 103 | Shock Strut Stop Discs | J3, PA-11 | 10/20/47 | | | 2F20 |
| 104 | Fuel Line Fitting | PA-11 | 1/30/48 | | | 2F21 |
| 108 | Model PA-11 Front and Rear Seats | PA-11 | 10/20/48 | | | 2G6 |
| 110 | Windshield Attachment | PA-15 | 11/29/48 | | | 2G11 |
| 111 | Torque Tube Connector Tube Assembly | J3, PA-11 | 3/14/49 | | | 2G12 |
| 112B | Service Inspection Notes | J3, J4, PA-11 PA-15, PA-16, PA-17 | 11/19/59 | | | 2G13 |
| 113 | Weight and Balance Form | PA-11 | 5/3/49 | | | 2G16 |
| 116 | Battery Box Lid | PA-20, 22 | 3/9/51 | | | 2G17 |
| 117B | Chafing of Master Switches | PA-20, 22 | 4/14/52 | | | 2G19 |
| 118 | Battery Box Lid Modification | PA-16-,20,22 | 9/21/51 | | | 2G20 |
| 119 | Freezing of Nose Wheels | PA-22 | 11/7/51 | | | 2G21 |
| 120 | Replacing of Front and Rear Lift Strut Forks and Barrels | J3, PA-11 | 3/28/52 | | | 2G24 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|-----------|
| 121 | Oil Radiator Lines | PA-18, PA-18A, PA-20, PA-22-135 Models | 8/25/52 | | | 2H3 |
| 122 | Fuel Grade Specification Lycoming O-290-D2 | PA-18, PA-18A, PA-18S PA-20, PA-22 | 11/21/52 | | | 2H4 |
| 123 | Front Spar Interference | PA-20, 22 | 5/7/54 | | | 2H5 |
| 124 | PA-22 Landing Gear | All PA-22's | 8/30/54 | | 55-07-02 | 2H6 |
| 135 | Fuel Selector Valve Pointer | PA-20, 22 | 3/29/55 | | | 2I1 |
| 143 | Magneto Ground Wire Terminal Attachment Fitting | J-Series, E-Series, PA-11, PA-15, PA-16, PA-17, PA-18, PA-19, PA-20, PA-22 | 10/7/55 | | | 2I12 |
| 148A | Fuel Tank Caps | PA-18, 18A 22, 23, L21 B | 5/29/57 | | | 2I17 |
| 153A | Brake Master Cylinder Diaphragm | PA-22 | 11/21/60 | 750-384 | | 3240 2J1 |
| 157D | Lift Strut Fork Inspection And/Or Replacement | J-2/J-3/NE-1/ L4/J4/PA-11/ PA-15/PA-16/PA-17/ PA-18/L-21A/L-21B/ L-18/PA-19/PA-20/ PA-22 | 4/22/86 | ** | | 5701 2J5 |
| 158 | All PA-20 Name Plates | PA-20 | 9/20/57 | | | 2J8 |
| 161A | Fire Hazard | PA-16, 20, 22 | 9/23/59 | ** | 57-22-01 | 2600 2J12 |
| 163A | Fusing of Cigar Lighter Circuit | PA-20, 22 | 7/7/58 | | 58-16-01 | 3310 2J16 |
| 165 | Aileron Hinge Reinforcing Bracket | J3, L4, L18B, PA-11, PA-15, PA-16, PA-17 | 5/22/58 | ** | 58-12-02 | 5750 2J22 |
| 166 | Chafing of Master Switch Wires | PA-22 | 8/5/58 | | | 2J24 |
| 174B | Fabric, Fuselage, Inspection and Maintenance of In Area of Windshield Top Attachment Channel | J4, PA-15/16/17 PA-20 PA-22 | 11/30/61 | | | 5300 2K15 |
| 181 | Cables, Control. 1/8" - 7 x 19 Flexible Stainless Steel, Replacement of | PA-18/18A/18S PA-18AS-150 PA-22/22S PA-22S-150 PA-22 | 11/5/59 | ** | 61-16-05 | 2700 2L4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------------------|-----------|
| 182 | Foreign Registered Airplanes- Inspection of Control Cables And Replacement of 1/8" - 7 x 19 Flexible Stainless Steel Control Cables | J3/ PA-11/11S/15/16/ 16S/17/18/20/20S/ 20-115/20-135/22/ 22S-135/22-150/ 22S-160, L-4/L-18B/L-18C/ L-21A/L-21B/ L-21B Modified | 11/5/59 | | | 2700 2L10 |
| 183 | Tie Rods - Tail Brace Streamline | PA-20, PA-22, PA-22-135/150/160 | 11/9/59 | | 60-01-07 | 5340 2L12 |
| 184 | Safety Belt Attachment | PA-22-150/160 | 12/9/59 | 754-273 | 60-05-03 | 5340 2L13 |
| 198 | Clevises, Tail Brace, Replacement of | PA-22-108 | 1/6/61 | 754-381 | | 5510 3A13 |
| 203 | Modification of Cabin Heat Box Plate | PA-22-108 | 4/21/61 | ** | | 2140 3B1 |
| 207A | Rudder Pedal Assembly, Inspection of Weld (P/N 40892-04 And 05) | PA-18, PA-18A | 5/10/62 | | 62-02-05 | 2720 3B7 |
| 218 | Vacuum Pump Spined Coupling, Replacement | PA-18 PA-22-108 | 11/11/63 | ** | | 3710 3C9 |
| 250A | Installation of Right Fuel Tank Quantity Gauge Placard | PA-22 | 1/29/70 | 15306-00 | 67-24-02 | 2840 3F8 |
| 264 | Aircraft Flight Manual Supplement, Revision To (Para 15.0) | PA-22S-135 | 12/22/67 | | | 3G10 |
| 305 | Inspection of Carburetor Drain Plugs | PA-18-150 | 11/25/69 | | | 7310 3K12 |
| 324 | Vacuum Pump Adapter Drive Assembly | PA-18-150 | 9/24/70 | | | 3710 4A9 |
| 351 | Fuel Line Replacement | PA-20 | 5/3/72 | ** | 72-21-03 | 2820 4D9 |
| 354B | Fuel Selector Valve Lubrication | PA-18/PA-20 PA-22 | 5/19/82 | ** | 60-10-08 | 2820 4D15 |
| 445 | Fuel Cap Inspection | PA-18 | 1/24/75 | 454-039 | | 2810 5A20 |
| 485 | Rerouting of Rudder Control Cables | PA-18-150 | 1/27/76 | ** | | 2720 5F2 |
| 522 | Fuel Tank Cap Modification, Wing | PA-11, PA-16, PA-18/18-150 PA-20, PA-22 | 9/28/76 | | 78-10-03 | 2810 5J4 |
| 528D | Wing Lift Strut Assembly Inspection/Replacement | J-2/J-3/NE-1/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-20/PA-22 | 10/19/90 | ** | 99-26-19 2015-08-14 | 5701 5J21 |
| 573 | Fuel Tank Cap Modification, Wing | PA-11, PA-16, PA-18/18-150, PA-20, PA-22 | 2/8/78 | | 78-10-03 | 2810 6E14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|------------------------|---------------|
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-18-150 | 2/25/80 | | | 3450 6L14 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 7H4 |
| 706B | Tail Brace Wire Support Installation | PA-18-150 | 10/9/91 | ** | 81-06-08 | 5510 7L7 |
| 759 | Exhaust Muffler Inspection and Modification, Piper Part Number 12433-00, 12433-14, 12232-00 | PA-18 | 6/22/83 | 452-093 | | 7820 8H12 |
| 771A | Parking Brake Application | PA-20, PA-22 | 9/6/2011 | 81090-002 | | 1130 |
| 819 | Fuselage Door Frame Tube Corrosion: Repair and Protection | J-4/PA-15/ PA-16/PA-17/PA-20/ PA-22 | 2/28/86 | ** | | 5300 9G13 |
| 836A | Aluminum Wire Inspection | E-2/J-2/J-3/NE-1/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22 | 8/26/86 | ** | | 2400 9J4 |
| 855 | Use of Automobile Gasoline In Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 10A7 |
| 868 | Forward Fuel Header Tank Installation | PA-11, PA-18 | 8/19/87 | 60763-02 | | 2810 10C3 |
| 910A | Wing Lift Strut Assembly Inspection | PA-18/18A/L-18/ PA-19/L-21A/L-21B | 10/10/89 | ** | 99-26-19 2015-08-14 | 5701 10L3 |
| 924 | Shimmy Dampener Replacement | PA-22 | 9/13/89 | 21701-06 | | 3250 10aB17 |
| 935 | Relocation of Aircraft Serial Number Data Plate | PA-18-150 | 3/13/90 | 765-400 | | 1125 10aE5 |
| 966 | Tail Surfaces Replacement | PA-18-150 | 1/21/94 | ** | | 5500 10aK3 |
| 979 | Installation of Fuel Cap Cover | PA-18-150 | 1/12/95 | ** | | 5500 10bB6 |
| 1020 | Inspection of the Artex 110-4 ELT and ELT Attachment Bracket | PA-18-150 | 7/10/98 | ** | | 2563 10b111 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-18 PA-18-150 PA-22 | 11/5/98 | 753-910 | | 3711 10bJ20 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements". | PA-18/18A/18S PA-18-150 PA-20/20S PA-22/22S | 9/25/2000 | ** | | 3714 10cB1 |
| 1044 | Lift Strut Attachment Fitting Inspection Access Provision and Wing Component Corrosion Inspections. | E-2/F-2/TG-8 J-2/J-3/J-4/ PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22 | 7/27/2000 | 481-096 | | 5701 10cB19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|-------------------------|----------|------------|
| 1048 | Stainless Steel Control Cables | PA-18-150 | 1/3/2001 | N/A | | 2702 10cC9 |
| 1172A | Lift Strut Attachment Bolt Inspection | PA-16/-16S PA-18/-18A/-18S PA-18 "105"/-18S "105" PA-18 "125"/-18S "125" PA-18 "135"/-18S "135" PA-18AS "135" PA-18 "150"/-18A "150" PA-18S "150"/-18AS "150" PA-18A (Restricted) PA-18A "135" (Restricted) PA-18A "150"(Restricted) PA-19/-19S/-20/-20S PA-20/-20S "115" PA-20 "135"/-20S "135"/ PA-22/-22-135/-22S-135 PA-22-150/160/-22S-150/160 PA-22-108 Colt | 12/11/2006 | NAS464-P6-11 402-830 | | 5700 10eA5 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-22 PA-22-108 PA-22-135 PA-22-150/160 | 4/12/2019 | N/A | | 7414 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1379B | Rudder Inspection | J3C-65/L-4/NE-1/NE-2 J4 PA-11/L-18B PA-15/-17 PA-16 PA-18/-19/L-18C/L-21A/L-21B PA-20 PA-22 | 5/14/2024 | N/A | | 5540 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|---------------------|-----------------|-------------|-------------|
| 125 | Fuel System Model PA-23 | PA-23 | 9/29/54 | | | 2H7 |
| 126 | PA-23 Power Plant | PA-23 | 10/18/54 | | | 2H9 |
| 127 | PA-23 Airplane Flight Manual | PA-23 | 10/15/54 | | | 2H11 |
| 128 | PA-23 Landing Gears | PA-23 | 10/28/54 | | | 2H12 |
| 129 | Carburetor Air Box | PA-23 | 12/28/54 | | | 2H13 |
| 130 | Heater Fuel Line | PA-23 | 12/31/54 | | | 2H14 |
| 131 | Addition of Rudder Extrusion Chafe Strip to Wing Root Fairing | PA-23 | 1/3/55 | | | 2H15 |
| 132 | Fuel Valve Actuator Handle Locks | PA-23 | 1/5/55 | | | 2H17 |
| 133 | Landing Gear Down Lock Latches | PA-23 | 1/18/55 | | | 2H19 |
| 134 | Main Landing Gear Attachment Point | PA-23 | 3/31/55 | | | 2H22 |
| 136 | Hydraulic System - Thermal Relief Valve | PA-23 | 4/26/55 | | | 2I3 |
| 138 | Hydraulic Actuating Cylinders | PA-23 | 5/9/55 | | | 2I6 |
| 139 | Flexible Fuel Valve Controls - right and left | PA-23 | 5/26/55 | | | 2I7 |
| 140 | Landing Gear CO2 Extension System | PA-23 | 6/8/55 | | | 2I8 |
| 142 | Wing Front Spar Attachment Fitting | PA-23 | 10/4/55 | | | 2I11 |
| 143 | Magneto Ground Wire Terminal Attachment Fitting | PA-23 | 10/7/55 | | | 2I12 |
| 144 | Hot Air Ducts | PA-23 | 4/11/56 | | | 2I13 |
| 145 | New Anti-Retracton Device | PA-23 | 12/31/56 | | | 2I14 |
| 146B | Elevator Butt Rib And Torque Tube Attachment Casting Cracks | PA-23 | 10/25/62 | | 63-12-02 | 5520 2I15 |
| 149 | Reinforcement of Aileron Balance Weights | PA-23 | 12/10/56 | | | 2I19 |
| 150 | Front Stabilizer Fittings - right and left | PA-23 | 12/21/56 | | | 2I21 |
| 151 | Elevator Push Pull Tube Rollers | PA-23 | 2/11/57 | | | 2I22 |
| 152A | Oil Pressure Line | PA-23 | 8/29/58 | 17766-07 | 57-10-02 | 7930 2I24 |
| 155B | Empennage Casting Cracks | PA-23 | 10/28/63 | | | 5500 2J2 |
| 156 | Thread Exposure on the Heim Rod End Bearing | PA-23 | 7/2/57 | | | 2J4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|------------------------------|------------------|--------------------|----------|-----------|
| 159 | Rudder Trim Tab Control Rod Attachment | PA-23 | 10/1/57 | | | 2J9 |
| 160 | Stabilizer Attachment Fitting | PA-23 | 10/7/57 | 17093-00 | | 5510 2J11 |
| 162 | Rudder Trim Tab Adjustment Screw, Part No. 18453-00 | PA-23 | 2/17/58 | 18453-02 | 58-04-03 | 2720 2J15 |
| 169 | Placard, Operating Limitations | PA-23 | 2/4/59 | 754-224 | 59-08-03 | 1100 2K3 |
| 175 | Circuit Protector, Starter Solenoid | PA-23 | 6/9/59 | 754-220 | 60-03-07 | 2400 2K17 |
| 176 | Bellcrank Attachment, Elevator Control Tube | PA-23 PA-23-160 | 7/3/59 | ** | | 2730 2K18 |
| 185A | Ribs, Wing Stations 95 And 110 Located Below the Main Wing Fuel Cell | PA-23 PA-23-160 | 9/3/63 | ** | | 5710 2L14 |
| 186 | Fuel Lines And Fuel Line Fittings, Replacement of | PA-23-250 | 4/12/60 | 492-222 492-223 | | 2810 2L16 |
| 188 | Baggage Compartment Doors, Positive Locking of | PA-23-250 | 5/12/60 | | | 5230 2L19 |
| 189 | Stabilator Tab Horn Modification | PA-23-250 | 6/22/60 | 754-329 | | 2740 2L21 |
| 194 | Instrument Panel Face Plate, Replacement of | PA-23-160 | 8/23/60 | | | 2500 3A7 |
| 195A | Baffles, Right Engine, Modification of | PA-23-250 | 9/13/60 | 754-335 | | 7230 3A8 |
| 196 | Rudder Tab Horn Bolt Installation | PA-23-250 | 9/9/60 | 754-344 | | 2720 3A10 |
| 199A | Stabilator Tab Horn Assembly, Inspection of | PA-23-250 | 4/3/61 | 754-393 | | 2740 3A15 |
| 200 | Oil Radiator Lines, Replacement of | PA-23-250 | 4/18/61 | 754-387 | | 7920 3A19 |
| 213 | Rudder Trim Tab Horn, Inspection of | PA-23/23-160 | 3/5/63 | | | 2720 3B23 |
| 214 | Carburetor Airbox Throat Vanes, Removal of | PA-23-235/23-250 | 4/19/63 | | | 7160 3C1 |
| 218 | Vacuum Pump Spined Coupling, Replacement of | PA-23-235/23-250 | 11/11/63 | ** | | 3710 3C9 |
| 219A | Heater, 940DB, Modification And Rewiring of | PA-23-250 | 9/23/64 | ** | | 2140 3C12 |
| 225 | Vacuum Pump Mounting Gasket, Replacement of | PA-23-235/23-250/ E23-250 | 11/9/65 | 751-886 | | 3710 3D12 |
| 226 | Vacuum Pump Drive Couplings, Replacement of | PA-23-235/23-250/ E23-250 | 12/20/65 | ** | | 3710 3D13 |
| 230A | Alternate Air System Modification, Engine Induction | PA-23-250/ E23-250 | 5/6/66 | 757-021 | 66-18-03 | 7160 3D21 |
| 242 | Fuel System, Modification of | PA-23-250/ E23-250 | 1/9/67 | 757-106 | | 2800 3E17 |
| 243 | Starter Vibrator, Replacement of | PA-23-250 E23-250 | 1/6/67 | 757-103 | | 8010 3E18 |
| 269 | Manifold Pressure Gauge Line Filter | PA-23-250 | 2/23/68 | 760-167 | | 7710 3G19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------------------|------------------|----------------------|----------|-----------|
| 273 | Tailpipe, Turbocharger, Clearance To Firewall, Inspection of | PA-23-250 PA-E23-250 | 5/8/68 | ** | | 8120 3H1 |
| 280 | Artificial Horizon, R.C. Allen 3", Case Leakage of | PA-23-250 | 7/10/68 | | | 3420 3H20 |
| 290 | Fuel Flow Gauge Assemblies, Replacement of | PA-23-250 "D" | 5/23/69 | 760-293 | | 7330 3J3 |
| 296 | Fuselage Aft Section Assembly, Inspection of | PA-23-250 "D" | 5/26/69 | 760-324 | | 5310 3J16 |
| 300 | Hydraulic Pump Hose Assembly Inspection | PA-23-250 | 6/3/69 | 17766-05 | | 2910 3K3 |
| 303 | Autocontrol III And Altimatic III Series Roll Servo Modification and Roll Bridle Cable Replacement | PA-23-250 PA-E23-250 | 11/10/69 | 760-364 | | 2210 3K8 |
| 306 | Alternator System Modification | PA-23-250 "D" | 1/9/70 | 760-346 | 70-22-05 | 2430 3K14 |
| 319 | Exhaust System Inspection And Modification | PA-23-250 | 4/19/71 | 33178-02 33178-03 | 72-14-05 | 7810 3L17 |
| 320A | Autopilot Servo And Bridle Cable Installations, III Series, Inspection of | PA-23-250 | 7/6/72 | | | 2210 3L23 |
| 324 | Vacuum Pump Adapter Drive Assembly | PA-23-250 | 9/29/70 | | | 3710 4A9 |
| 331 | Electric Trim Switch Inspection And Modifications | PA-23-250 | 2/5/71 | 760-505 | 71-12-05 | 2730 4B3 |
| 334 | Alternate Air Hose Replacement | PA-23-250 | 3/17/71 | 48076-02 | 71-21-06 | 7160 4B14 |
| 335A | Engine Controls Support Bracket Assembly Inspection | PA-23 PA-23-160 PA-23-250 | 11/17/71 | 16975-00 | 71-12-01 | 7610 4B16 |
| 340 | Fuel Cell Vent/Drain Lines | PA-23 PA-23-160/-235 PA-23-250 | 5/24/71 | | 88-21-07 | 2810 4C2 |
| 345 | Bungee Installation, Stabilator | PA-23-250 | 10/7/71 | 760-565 | 72-21-07 | 2740 4C21 |
| 349 | Master Switch Modification, Electrical System | PA-23-250 | 4/26/72 | 760-602 760-606 | | 2450 4D5 |
| 353 | Fuel Filter Assembly Outlet Port, Inspection of | PA-23-250 | 6/1/72 | ** | | 7310 4D13 |
| 375 | Firewall Sealing, Lower | PA-23-250 | 6/20/73 | 757-758 | | 5310 4F15 |
| 380 | Pitch Servo Bridle Cable Installation, Revised | PA-23-250 | 7/9/73 | | | 2210 4F23 |
| 385 | Wing Leading Edge Modification | PA-23-250 | 5/4/73 | ** | | 5720 4G10 |
| 389 | Bridle Cables and Bridle Cable Clamp Installation | PA-23-250 | 8/13/73 | | | 2210 4G17 |
| 401A | Heater Fuel Valve, Inspection of | PA-23 PA-23-160/-235 PA-23-250 | 5/16/2000 | 19460-00 | 74-22-05 | 2148 4H24 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------------------|------------------|--------------------|------------|----------|
| 404 | Flux Sensor Caution Placard Installation | PA-23-250 | 11/12/73 | 33564-00 | | 3420 |
| 408B | Flap Outboard Hinges, Replacement | PA-23-250 | 5/14/75 | ** | 74-10-01 | 5750 |
| 441 | Manifold Pressure Hose Clamping of | PA-23-250 | 1/2/75 | 760-602 760-606 | | 7710 |
| 451 | Throttle Control Shaft, Inspection of | PA-23-250 | 2/26/75 | | | 7610 |
| 452 | Instrument Glare Shield Panel Replacement | PA-23-250 | 3/3/75 | 760-932 | 75-11-05 | 2510 |
| 455 | Fuel Selector Valve Inspection | PA-23-250 | 4/30/75 | 492-222 492-223 | | 2820 |
| 461 | Encoding Altimeter Harness Rewiring | PA-23-250 | 4/17/75 | 760-971 | | 3410 |
| 486 | Wing Tip Navigation Light Wire Insulation | PA-23-250 "F" | 10/11/76 | 761-099 | 77-01-05 | 3340 |
| 493 | Magnetic Compass Deviation | PA-23-250 | 3/25/76 | 761-044 | 76-11-07 | 3440 |
| 498 | Fuel Cell Vent Line Assemblies, Inboard, Inspection of | PA-23-250 "F" | 4/5/76 | | | 2810 |
| 507 | Fuel System Control Cables At Swivel Fittings, Inspection of | PA-23 PA-23-160/-235 PA-23-250 | 11/10/76 | ** | 80-18-10 | 7320 |
| 511A | Oxygen System Outlet Refinement | PA-23-250 | 8/24/76 | ** | | 3510 |
| 514 | Stabilator Tab Modification | PA-23-250 "F" | 9/20/76 | 761-083 | | 2740 |
| 515 | Control Cable Ball Joint Retainer Installation | PA-23-250 | 1/17/77 | ** | | 7610 |
| 523 | Cigar Lighter Element, 24 Volt, Replacement | PA-23-250 "F" | 10/8/76 | 55674-02 | | 3310 |
| 527 | Electric Trim Switch Modification | PA-23-250 | 11/5/76 | 756-047 | 77-09-10 | 2740 |
| 530 | Fuel Crossfeed Operation | PA-23-250 PA-E23-250 | 12/10/76 | ** | 77-23-09 | 2820 |
| 540 | Stabilator Tip Tube And Weight Assembly Inspection And Reinforcement | PA-23-250 "F" | 1/4/1977 | ** | 2021-25-11 | 2740 |
| 540B | Stabilator Tip Tube And Weight Assembly Inspection And Reinforcement | PA-23-250 "F" | 2/9/21 | ** | 2021-25-11 | 5510 |
| 546 | Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection of | PA-23-250 | 5/18/77 | ** | 75-05-04 | 3340 |
| 547 | Stabilator Tip Rib, Inspection of | PA-23-250 "F" | 3/1/77 | ** | 2021-25-11 | 2740 |
| 550 | Engine Control Cable Inspection | PA-23-250 "F" | 3/29/77 | ** | | 7230 |
| 558 | Altimatec V and V F/D Series; M-4D F/D Series: And Sperry SPZ-200 F/D | PA-23-250 | 6/10/77 | | | 2210 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------------------|------------------|-------------------|------------|---------------|
| 559 | Rudder Tail Light Inspection | PA-23-250 | 8/31/77 | 472-956 | | 3340 6C3 |
| 564 | Inspection of Emergency Gear Extension Control | PA-23-250 PA-E-23-250 | 4/25/77 | | | 3200 6C16 |
| 566 | Horizontal Situation Indicator, EDO Aire Mitchell NSD-360, Modification To | PA-23-250 | 10/11/77 | ** | | 3420 6D9 |
| 569 | Stabilator Tab Horn Replacement | PA-23-250 | 8/24/77 | 761-143 | 2021-25-11 | 5510 6E2 |
| 590 | Inspection of Stabilator Tab Horn/ Stabilator Trim Control Rod Attachment | PA-23-250 | 1/20/78 | | | 2740 6G11 |
| 604A | Forward Baggage Door Locking System Modification | PA-23-250 | 6/8/79 | ** | | 5230 6I4 |
| 606 | Stabilator Assembly Lower Surface Rivet And Rib Attachment Inspection | PA-23-250 | 7/12/79 | ** | 79-26-01 | 2730 6I10 |
| 629 | Landing Gear Hose Assembly Inspection And Replacement | PA-23-250 | 11/15/78 | 17766-27 | | 3230 6L10 |
| 630A | Collins VIR-350 and VIR-351 Navigation Receiver Modification | PA-23-250 | 2/25/80 | | | 3450 6L14 |
| 635 | Landing Gear Selector Lever Inspection And Replacement | PA-23 PA-23-235 PA-23-250 | 1/3/79 | 761-213 | 79-11-06 | 3200 7A23 |
| 662 | Exhaust System Inspection And Modification | PA-23-250 | 11/1/79 | 763-975 | | 7810 7E15 |
| 663 | Fuel Line/Electrical Harness Inspection | PA-23-250 | 9/24/79 | ** | | 2810 7E17 |
| 671 | Flap Control System Inspection and Reinforcement | PA-23 PA-23-160/-235 PA-23-250 | 10/20/80 | ** | 81-04-05 | 2750 7F14 |
| 672A | Step Attachment Area Inspection/ Reinforcement | PA-23 PA-23-160/-235 PA-23-250 | 4/16/81 | | 80-26-04 | 5340 7F23 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 7H4 |
| 683 | Propeller Feathering, Minimum Engine RPM | PA-23 PA-23-160/-235 PA-23-250 | 5/16/80 | Placard ** | | 6120 7H18 |
| 721 | Heater Fuel Regulator Valve Shroud/ Drain Modification | PA-23-250 | 4/5/82 | 764-141 | | 2820 8B12 |
| 771A | Parking Brake Application | PA-23 PA-23-160/-235 PA-23-250 | 9/6/2011 | 81090-002 | 85-02-05 | 1130 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------------------|------------------|--------------|------------|---------------------|
| 797B | Fuel Port Restrictor Installation | PA-23-250 "F" | 9/1/87 | 566-500 | | 2812 9B14 |
| 798 | "TURBO" Marking Removal | PA-23-250 | 12/11/84 | N/A | | 1110 9B19 |
| 805A | TRW Hartzell Propeller Products Service Bulletin No. 142B (O-ring Deterioration) | PA-23-250 | 3/14/86 | N/A | | 6110 9D15 |
| 822 | Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138) | PA-23 PA-23-160/-235 PA-23-250 | 4/2/86 | 17766-02 | 96-21-04 | 2912 9H3 |
| 827A | Part I - Fuel System Draining Procedure - Water Contamination | PA-23 PA-23-160 | 11/4/88 | N/A | 90-23-18 | 2824 9H20 |
| 827A | Part II - Apache Dual-Fuel Drain Installation | PA-23 PA-23-160 | 11/4/88 | 765-363 | 92-13-04 | 2824 9H22 |
| 836A | Aluminum Wire Inspection/Replacement | PA-23 PA-23-160/-235 PA-23-250 | 8/26/86 | ** | | 2400 9J4 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 10A7 |
| 884 | Lock Wiring of V-Band Couplings | PA-23-250 | 4/8/88 | ** | | 7800 10G20 2100 |
| 932A | Improved Fuel System Drainage and Inspection | PA-23 PA-23-160/-235 PA-23-250 | 8/30/90 | ** | 90-23-18 | 2815 10aD16 2824 |
| 980 | Shoulder Harness Installation | PA-23 PA-23-235 PA-23-250 | 1/18/95 | ** | | 5500 10bB10 |
| 991A | Replacement or Modification of the Alternator Out Light Fuse | PA-23-250 | 1/29/96 | ** | | 2437 10bD16 |
| 1022 | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-23-235 PA-23-250 | 9/22/98 | 460-632 | 99-05-09 | 7167 10bI20 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-23-250 | 11/5/98 | 766-656 | | 5741 10bJ20 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Service Bulletin No. 101SB020, Rev. 3" | PA-23-250 PA-E23-250 | 3/22/2007 | ** | 2003-14-03 | 7311 10bL16 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements". | PA-23 Series PA-23-250 Series | 9/25/2000 | ** | | 3714 10cB1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|-------------------------------|------------|----------|
| 1051B | Flap Torque Tube Replacement | PA-23 PA-23-160/-235 PA-23-250 PA-E23-250 | 11/5/2002 | 104622-002 | 81-04-05R1 | 2755 |
| 1079 | Untested Fuel Pump | PA-23-250 Series | 7/20/2001 | 62220-005 | | 2825 |
| 1147 | Turbocharger Clamp, Incorrect Substitution | PA-23-250 | 5/14/2004 | 555-511 | | 7200 |
| 1160A | Stabilator Torque Tube Assembly Inspection | PA-23-235 PA-23-250 PA-E23-250 | 11/28/2022 | 16067-000 652-579 | | 5519 |
| 1194B | Nose Baggage Door Components, Periodic Replacement of | PA-23-250 PA-E23-250 | 4/12/2012 | ** | 2009-13-06 | 5230 |
| 1266 | Fuel Warning Placard and POH Inspection | PA-23-250 "B" PA-23-250 "C" PA-23-250 "D" PA-23-250 "E" PA-E23-250 | 12/16/2014 | ** | 2015-24-05 | 1130 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-23-150/160 | 4/12/2019 | N/A | | 7414 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-23-250 PA-E23-250 | 10/30/2015 | N/A | | 7310 |
| 1295 | Nose Baggage Door Lock Inspection | PA-23-250 PA-E23-250 | 3/24/2017 | 88409-002 | 2009-13-06 | 5230 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1299A | Periodic Replacement of Main Landing Gear Drag Link Bolt | PA-23-150 PA-23-160 PA-23-235 PA-23-250 | 12/18/2019 | 402-356 402-427 691-367 | | 3210 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|------------------------------------|------------------|--------------|----------|-----------|
| 164 | ADF Indicator Excess Wire, Battery Cable Insulation, Muffler Replacement, Nose Gear Door Retraction Rod, Control Wheel Replacement and Reinforcement Nose Wheel Steering Arm Mounting Bracket | PA-24 | 5/16/58 | | | 2J17 |
| 167 | Oil Cooler Line Clearance | PA-24 | 1/6/59 | 451-855 | 59-07-05 | 7920 2K1 |
| 168 | Nose Gear Retraction Assist Cord | PA-24 | 1/16/59 | 754-205 | 58-25-05 | 3230 2K2 |
| 171 | Weight And Balance | PA-24 PA-24-250 | 3/18/59 | | | 800 2K4 |
| 172 | Control Wheel Sprocket Mounting Hole, Inspection of | PA-24/PA-24-250 (w/Autocontrol) | 4/27/59 | ** | 59-12-09 | 2700 2K5 |
| 173 | Aileron Balance Weight Attachment, Bulkhead | PA-24 PA-24-250 | 6/23/59 | 754-233 | 59-13-02 | 2710 2K13 |
| 177 | Fuel Cell Filling Instructions | PA-24/PA-24-250 | 8/5/59 | 21994-00 | | 2810 2K20 |
| 178 | Control Tube Guide Blocks Safety Wiring of | PA-24 PA-24-250 | 9/24/59 | | | 2700 2K22 |
| 179 | Door Window, Refitting of | PA-24/PA-24-250 | 11/6/59 | | | 5630 2K24 |
| 180 | Fuel Cell Vent Tubes, Modification of | PA-24 PA-24-250 | 11/6/59 | | 59-26-02 | 2810 2L2 |
| 187 | Safety Switches. PA-24 and 24-250 Landing Gear-Service Letter 314A, Dated June 8, 1954 | PA-24 | 4/15/60 | 754-221 | | 3230 2L18 |
| 190A | Insulation-Cabin Heat Induction System | PA-24 | 3/14/60 | 754-308 | | 2140 2L23 |
| 191 | Hinge Bracket, Aileron—Part No. 20211-00 | PA-24 PA-24-250 | 6/16/60 | 20211-00 | | 5150 3A1 |
| 192 | Throttle Limit Switch Bracket | PA-24 | 6/17/60 | 754-334 | | 7610 3A3 |
| 193 | Fuel Cell Vent Tube, Modification of | PA-24 | 6/17/60 | | 60-24-03 | 2810 3A5 |
| 197 | Master Cylinder, Brake, Replacement of | PA-24 | 12/2/60 | 455-929 | | 3240 3A12 |
| 201 | Vacuum Pumps, Dry, Replacement of | PA-24 | 4/13/61 | 481-681 | | 3710 3A21 |
| 202 | Exhaust System, Comanche. Inspection of | PA-24 | 5/22/61 | 754-396 | 61-20-02 | 7810 3A22 |
| 205 | Circuit Protector Wiring, Inspection of | PA-24 | 8/15/61 | | | 2400 3B3 |
| 208 | Gascolator Bowl Drain Valve | PA-24 | 12/19/61 | | | 7310 3B9 |
| 210 | Muffler Shrouds, Replacement of | PA-24/24-250 | 10/3/62 | 754-484 | 62-26-05 | 7810 3B12 |
| 211 | Main Fuel Cell Cavity Modification | PA-24-250 | 11/2/62 | 754-492 | | 2810 3B17 |
| 212 | Engine-Driven Fuel Pump, Installation of Vent Lines (PA-24-250 W/Fuel Injection) | PA-24-250 | 12/5/62 | 756-700 | | 2820 3B20 |
| 216 | Fuel Cell Drain Modification | PA-24/24-250 | 8/5/63 | 756-756 | 68-13-03 | 2810 3C4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------------|----------|-------------------|
| 218 | Vacuum Pump Spined Coupling, Replacement of | PA-24/24-250 PA-30 | 11/11/63 | 753-865 | | 3710 3C9 |
| 219A | Heater, 940DB, Modification And Rewiring | PA-30 | 9/23/64 | 756-815 | | 2140 3C12 |
| 220 | Alternate Air Doors, Replacement of | PA-30 | 3/3/64 | 756-794 | 64-09-05 | 7160 3C14 |
| 222A | Airspeed Limits, Restriction To, Removal of (Replacement of Stabilator Torque Tube) | PA-30 | 8/10/64 | 756-827 | 64-28-03 | 3410 3C17 |
| 224 | Pitch Servo—Modification of— Mitchell Bulletin No. A55 | PA-24-250 PA-24-260 PA-24-400 PA-30 | 4/7/65 | 756-923 | 65-11-04 | 2210 3D3 |
| 228 | Fuel Purge Valve Hose Assembly, Replacement of | PA-24-400 | 1/7/66 | 756-994 | 66-30-07 | 2810 3D15 |
| 229A | Airspeed Limits, Restriction, Removal of | PA-30 | 6/17/66 | ** | 66-28-06 | 3410 3D16 |
| 231A | Fuel Tank Caps | PA-24/24-250 | 10/10/66 | 25983-00 | 68-13-03 | 2810 3D23 |
| 232 | Brake Disc Assembly, Inspection of | PA-30 | 6/8/66 | 757-039 | | 3240 3D24 |
| 235 | Airspeed Limit, Never-To-Exceed Standardization of | PA-30 | 9/16/66 | ** | 66-28-06 | 3410 3E6 |
| 236 | Oxygen Cylinder | PA-30 | 12/29/66 | 757-094 | 67-19-05 | 3510 3E8 |
| 238 | Fuel Purge Valve Hose Replacement | PA-24-400 | 12/7/66 | 757-099 | | 3420 3E10 |
| 246 | Oxygen Cylinder Rear Retaining Strap Modification of | PA-30 | 3/21/67 | 758-109 | 67-19-05 | 3510 3E22 |
| 263 | Flight Manual Revision | PA-30 | 1/15/68 | 760-168 | | General 3G9 |
| 280 | Artificial Horizon, R.C. Allen 3", Case Leakage of | PA-24-260 PA-30 | 7/10/68 | | | 3420 3H20 |
| 299 | Flight Manual Revision | PA-30 "C" | 5/29/69 | ** | | General 3K2 |
| 301A | Airplane Flight Manual And New Placards | PA-30 | 11/25/69 | 760-354 760-355 | 69-24-04 | 1100 3K5 |
| 306 | Alternator System Modification | PA-30 "C" | 1/9/70 | 760-347 | 70-22-05 | 2430 3K14 |
| 310 | Modifications, Twin Comanche (Airspeed Marking, Stall Warning Horn Installation) | PA-30 | 5/6/70 | 760-408 760-373 | | 3410 3K24 2700 |
| 314A | Selector Valve, Fuel Modification | PA-30/39 | 9/28/70 | 760-444 | | 2820 3L8 |
| 315 | Limit VNE Airspeed | PA-30 | 7/8/70 | ** | | 1100 3L10 |
| 320A | Autopilot Servo and Bridle Cable Installation, III Series, Inspection of | PA-24-260 PA-30/39 | 7/6/72 | | | 2210 3L23 |
| 324 | Vacuum Pump Adapter Drive Assembly | PA-24 PA-30/39 | 9/29/70 | | | 3710 4A9 |
| 331 | Electric Trim Switch Inspection and Modification | PA-24-260 PA-30/39 | 2/5/71 | 760-505 | 71-12-05 | 2730 4B3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------------|----------|------------------|
| 336 | Seat Frame Tube Replacement, Vertically Adjustable | PA-24-260 PA- 30/39 | 3/11/71 | | | 2510 4B18 |
| 343 | Hartzell Service Bulletin No. 96, Amended 8/18/71 And Supplement No. 1 Amended 8/18/71 | PA-30 | 9/9/71 | ** | | 6110 4C13 |
| 349 | Switch Modification, Master, Electrical System | PA-30/39 | 4/26/72 | ** | | 2450 4D5 |
| 354B | Fuel Selector Valve Lubrication | PA-24-180/24-250 | 5/19/82 | ** | 60-10-08 | 2820 4D15 |
| 362 | VNE Speed Limit | PA-24-250/24-260 | 8/14/72 | ** | | 3410 4E19 |
| 362A | Rudder Balance Weight Installation (Does not cancel Service Bulletin No 362) | PA-24-180/24-250/ 24-260 | 10/6/72 | 760-705 | | 2720 4E22 |
| 381 | Manual Revision, Pilot's Operating/Airplane Flight | PA-39 | 8/29/73 | ** | | General 4G1 |
| 394 | Rudder Pedal, Warning, Improper Use of | PA-24-180/24-250/ 24-260/24-400 PA-30/39 | 9/28/73 | 757-436 | | 2720 4H7 |
| 411A | Stabilator Torque Tube Bearing Block Attachment Fitting Rivet Replacement | PA-24-180/24-250/ 24-260/24-400 PA-30/39 | 4/10/74 | 760-835 | 94-13-10 | 2740 4J9 |
| 464A | Stabilator Torque Tube Bearing Block Attachment Fitting Rivets, Inspection of | All PA-24 Series PA-30/39 | 3/22/76 | 760-835 | 75-27-08 | 5530 5C16 |
| 496 | Stabilator Balance Weight Tube Replacement | PA-24-250/260 | 6/4/76 | 28035-00 | 76-19-07 | 2740 5G13 |
| 511A | Oxygen System Outlet Refinement | PA-24-260/ PA-24-400 PA-30/39 | 9/24/76 | 761-032 752-583 | | 3510 5I3 |
| 515 | Control Cable Ball Joint Retainer Installation | PA-24-250 PA-24-260/400 PA-30/39 | 1/17/77 | 55447-02 | | 7610 5I10 |
| 527 | Electric Trim Switch Modification | PA-24-260 PA-30/39 | 11/15/76 | 756-047 | 77-09-10 | 2740 5J18 |
| 597 | Fuel Selector Valve Replacement | PA-30/39 | 4/19/78 | 492-137 | 78-12-07 | 2840 6H10 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 7H4 15.0 |
| 751 | Spar Cap Chafing Inspection | PA-24-400 PA-24-180/250/260 PA-30/39 | 5/24/83 | ** | 83-19-03 | 5740 8G13 |
| 771A | Parking Brake Application | PA-24 PA-24-250/260 PA-24-400 PA-30/39 | 9/6/2011 | 81090-002 | 85-02-05 | 1130 |
| 798 | "TURBO" Marking Removal | PA-24 Series PA-30/39 | 12/11/84 | N/A | | 1110 9B19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--|------------|--------------|
| 805A | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration) | PA-24-260 PA-30/-39 | 3/14/86 | N/A | | 6110 |
| 836A | Aluminum Wire Inspection/Replacement | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 8/26/86 | ** | | 2400 |
| 855 | Use of Automobile Gasoline In Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 |
| 861 | Heated Alternate Air Induction System Installation | PA-24-260 | 5/4/87 | 760-516 | 91-21-09 | 7314 |
| 884 | Lock Wiring of V-Band Couplings | PA-24-260 PA-30/-39 | 4/8/88 | ** | | 7800 2100 |
| 980 | Should Harness Installation | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 1/18/95 | ** | | 5500 |
| 1022 | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-24 PA-24-250/-260 | 9/22/98 | 460-632 | 99-05-09 | 7167 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 11/5/98 | 753-910 | | 3711 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3" | PA-24-260 PA-24-400 | 3/22/2007 | ** | 2003-14-03 | 7311 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements". | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 9/25/2000 | ** | | 3714 |
| 1160A | Stabilator Torque Tube Assembly Inspection | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 11/28/2022 | 652-580 652-581 652-582 652-583 | | 5519 |
| 1189 | Stabilator Horn Assembly Inspection | PA-24 PA-24-250/-260 PA-24-400 PA-30/-39 | 4/29/2010 | ** | 2012-17-06 | 5510 |
| 1266 | Fuel Warning Placard and POH Inspection | PA-24-250/260/400 PA-30/39 | 12/16/2014 | ** | 2015-24-05 | 1130 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-24 | 4/12/2019 | N/A | | 7414 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-24-250/-260 PA-30/39 | 10/30/2015 | N/A | | 7310 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|---------------------|-----------------|-------------|-------------|
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB21

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|---|------------------|-----------------------|----------------------|------------------------------|------|
| 209 | Propeller Bolts, Replacement of | PA-28-150/160 | 4/17/62 | 754-462V | 62-19-03 | 6110 | 3B11 |
| 223 | Sender Unit, Stewart-Warner Fuel Quantity Gauge, Modification of | PA-28-140/150/160/180/235 | 2/12/65 | 756-906V | 65-06-06 | 2840 | 3D1 |
| 234 | Spinner Modification | PA-28-150/160/180 | 8/2/66 | 757-046V 757-047V | 66-20-05 | 6110 | 3E4 |
| 237 | Rudder Trim Installation Modification | PA-28-140/150/160/180/235 | 11/1/66 | 757-085V | | 2720 | 3E9 |
| 240 | Inspection of Aileron Balance Weight, Assembly, Rudder Horn Assembly And Stabilator Balance Weight Assembly For Corrosion | PA-28-140/150/160/180/235 | 12/13/66 | | 67-12-06 | 2710 | 3E12 |
| 245 | Family Seats Center Safety Attachment, Inspection of | PA-28-140 | 3/8/67 | | | 5340 | 3E20 |
| 248 | Torque Links, Main Landing Gear | PA-28-140/150/160/180/235 | 5/12/67 | 65691-00V 757-123V | 70-18-05 67-20-04 | 3210 | 3F2 |
| 249A | Fuel System Improvement Kit | PA-28-235 | 3/1/68 | 757-139V | 67-26-02 | 2800 | 3F6 |
| 251D | Fuel Tank Inspection | PA-28-140/150/160/180 PA-28-201T PA-28-235 PA-28R-180/200 PA-28R-201/201T PA-28RT-201T | 2/24/2009 | 757-572V | 67-26-03 | 2810 | 3F10 |
| 253 | Fuel Line Modification, Tip Tank | PA-28-235 | 7/7/67 | 757-151V 757-152V | 67-26-02 | 2810 | 3F14 |
| 261 | Aft Spar Wing Attachment Bolts, Inspection of | PA-28-140/150/160/180/235 | 11/10/67 | 760-162V | | 5710 | 3G5 |
| 274 | Retraction Fitting Replacement, Main Gear | PA-28R-180 | 6/3/68 | 760-208V | 68-12-04 | 3230 | 3H5 |
| 279 | Bridle Cable, Servo, Inspection | PA-28-140/150/160/180/235 PA-28R-180 | 6/24/68 | ** | | 3210 2210 | 3H16 |
| 281 | Artificial Horizon, R.C. Allen 3", Case Leakage of | PA-28-140/180/235 PA-28R-180 | 7/10/68 | | | 3420 | 3H24 |
| 285 | Fuel Selector Control Stop Assembly | PA-28-235 | 11/22/68 | 760-251V | | 2820 | 3I11 |
| 287 | Tail pipe Replacement | PA-28-140/150/160/180 | 1/15/69 | 63666-02V | | 7810 | 3I15 |
| 288 | Engine Breather Line Modification | PA-28R-180 | 1/16/69 | | | 7160 | 3I17 |
| 292 | Landing Gear Modification, Cherokee Arrow | PA-28R-180 | 3/6/69 | 760-292V 67150-00V | | 7110 3230 3200 2910 | 3J6 |
| 293 | Brace, Baggage Floor | PA-28-140"B" | 3/5/69 | 760-314V | | 5230 | 3J10 |
| 295 | Retaining Pin, Control Wheel | PA-28-180/235 PA-28R-180/200 | 4/30/69 | | 69-15-01 | 2700 | 3J14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|-----------|
| 297 | Hose Replacement, Air Induction Inlet | PA-28R-180/200 | 5/22/69 | 700-328V | 69-12-01 | 7160 3J18 |
| 298 | Carburetor Heat Control Assembly (see also SB 312) | PA-28-140"B"/ 180"D"/235"C" | 6/2/69 | 760-320V | | 7310 3J23 |
| 305 | Drain Plugs, Carburetor, Inspection of | PA-28-140/150/ 160/180/235 | 11/25/69 | | | 7310 3K12 |
| 309 | Spinner/Bulkhead Inspection And Replacement | PA-28R-180/200 | 5/8/70 | 760-410V | 70-09-02 | 6110 3K20 |
| 311A | Selector Valve, Fuel Modification | PA-28-235 | 9/28/70 | 760-438V | | 2820 3L3 |
| 312 | Carburetor Heat Cable Replacement | PA-28-140"B" | 6/9/70 | 760-387V | | 7310 3L5 |
| 313 | Terminals, Magneto Filter | PA-28-140/150/160/180/ 235 | 7/1/70 | 23969-02 | 71-14-06 | 7430 3L6 |
| 316 | Flight Manual Weight And Balance Data Revision | PA-28R-180/200 | 10/20/70 | ** | | 800 3L12 |
| 317 | Rib, Vertical Fin, Inspection | PA-28 PA-28R-180/200 | 11/18/70 | 760-451V | | 5530 3L14 |
| 322 | Vacuum Pump Adapter Drive Assembly | PA-28-140/180/235 PA-28R-180/200 | 9/29/70 | 760-477V | | 3710 4A3 |
| 326 | Selector Handle (2Tank) Fuel Valve, Inspection of The | PA-28-140/150/160/180 PA-28R-180/200 | 11/9/70 | | | 2820 4A14 |
| 327 | Stabilator Balance Weight Tube Assembly Inspection | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 12/9/70 | ** | 70-26-04 | 2740 4A16 |
| 332 | Switch, Electric Trim, Inspection And Modification | PA-28-180/235 PA-28R-180/200 | 4/16/71 | 760-517V | 72-17-05 | 2730 4B7 |
| 337 | Seat Frame Tube Replacement Vertically Adjustable | PA-28-140/180/235 PA-28R-180/200 | 3/11/71 | ** | | 2510 4B20 |
| 339 | Owner's Handbook Revision | PA-28R-180/200 | 6/16/71 | ** | | 2720 4B24 |
| 342 | Fuel System Instructions And Modification | PA-28-235 | 9/7/71 | 760-560V | 77-12-01 | 2800 4C6 |
| 348 | Air Conditioning System. Improvement | PA-28-140 | 1/25/72 | 760-581V | | 2150 4D4 |
| 350 | Stabilator Hinge Attaching Bolts, Inspection of | PA-28-140/180/235, PA-28R-200 | 3/30/72 | ** | | 5550 4D7 |
| 355 | Valve, Fuel Selector, Lubrication | PA-28-140/150/160/180 | 6/5/72 | ** | | 2820 4E1 |
| 356 | Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 9/1/72 | ** | | 7160 4E7 |
| 357A | Terminal Replacement, Alternator Output Wire | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 11/14/72 | 588-398V | | 2420 4E9 |
| 360 | Hose System, Modification, Air Induction | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 11/9/72 | ** | | 7160 4E14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------------------|----------|-----------|
| 368 | Antenna Protector, Transponder, Installation | PA-28-140/180/235 PA-28R-200 | 11/22/72 | 760-697V | | 3450 4F7 |
| 376 | Fuel Selector Control System Modification | PA-28-235 | 4/19/73 | ** | 77-12-01 | 2820 4F18 |
| 387 | Alternator Installation Modification | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 2/4/74 | 760-741V 760-742V | | 2430 4G15 |
| 393 | Seat Belt, Rear, Attachment Modification | PA-28-140/180/235 PA-28R-200 | 12/18/73 | 760-794 | 74-09-04 | 5340 4H4 |
| 395 | Rudder Pedal, Warning, Improper Use of | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 11/9/73 | 757-436 | | 2720 4H9 |
| 424 | Wing Reinforcement Modification | PA-28-151 | 6/21/74 | 760-878V | 74-14-04 | 5710 4K16 |
| 427 | Air Conditioning System Modification | PA-28-140/180 PA-28R-200 | 8/9/74 | 760-822V | | 2150 4K23 |
| 434 | Seaplane Propeller Modification | PA-28S-180 | 11/22/74 | 79528-00 | | 6110 |
| 435 | Aileron Centering—(I) Cable Inspection—(II) Modification | PA-28-151 | 11/4/74 | ** | 74-24-12 | 2710 4L15 |
| 436 | Placard Inspection, Operating Limitations | PA-28-180 | 12/10/74 | 76206-00V 76298-00V | 74-26-07 | 1110 4L18 |
| 444 | Fuel Valve Replacement | PA-28-235 | 1/15/75 | 760-895V | | 2820 5A19 |
| 448 | Cable Operation Inspection, Throttle and Mixture Control | PA-28-140/151/180/235 PA-28R-180/200 | 2/19/75 | ** | | 7320 5B4 |
| 449A | Alternator (Chrysler) Modification And Wire End Terminal Replacement | PA-28-140/151/180/235 PA-28R-200 | 5/7/75 | 558-398V | | 2430 5B8 |
| 450 | Quick Drain Valve Inspection Fuel Gascolator | PA-28-140/151/180 PA-28R-200 | 2/10/75 | | 75-08-03 | 2820 5B12 |
| 454 | Induction Air Shroud Modification | PA-28-151 | 3/10/75 | 760-922V | | 7160 5B19 |
| 474 | Carburetor Air Box Modification | PA-28-151 | 6/27/75 | 760-985V | 75-16-04 | 7160 5D21 |
| 475 | Instrument Panel Dimmer Control Assembly Modification | PA-28-140 PA-28-151 PA-28-180 PA-28-235 PA-28R-200 | 7/10/75 | | | 3310 5E1 |
| 510B | Landing Gear, Nose, Trunnion Modification | PA-28R-200 | 8/31/76 | 761-074V | 76-15-08 | 3220 5I1 |
| 519A | Fuel Selector Valve Inspection And Replacement | PA-28-235 | 9/2/76 | 492-259 492-262 | 76-18-04 | 2820 5I21 |
| 531 | Engine Oil Hose Replacement | PA-28-140 | 1/10/77 | 63901-72V | 76-25-06 | 7920 5L5 |
| 533 | Fuel Gauge Calibration Inspection | PA-28-140/180/ 151/181/235 PA-28R-200 | 1/6/77 | ** | 77-01-01 | 2840 5L8 |
| 536 | Carburetor Air Filter Box, Inspection of | PA-28-151 | 1/13/77 | | 77-01-03 | 7310 5L15 |
| 538 | Engine Control Cable Inspection | PA-28-151 | 1/14/77 | 67639-06V | | 7610 5L20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------|----------|-----------|
| 541 | Throttle Attachment Inspection | PA-28-140/151/ 181/235 PA-28R-200 | 2/15/77 | ** | | 7610 6A5 |
| 543 | Starter/Magneto Switch Inspection And Replacement | PA-28-151/181/ 235,PA-28R-200 | 2/9/77 | 757-597V | | 7410 6A9 |
| 548 | Engine Control Rod End Bearing Inspection | PA-28-140/151/ 161/180/181/235 PA-28R-200/201 PA-28R-201T | 3/7/77 | ** | 77-23-03 | 7230 6A23 |
| 556 | Electric Trim Switch Modification | PA-28-180/235 PA-28R-180/200 | 7/25/77 | | | 2730 6B20 |
| 561 | Battery Power Lead Relocation | PA-28R-201/201T | 4/6/77 | | | 2430 6C7 |
| 563 | Landing Gear, Nose, Actuator Rod End Bearing Change | PA-28R-201/201T | 5/13/77 | 452-357V | | 3230 6C14 |
| 565 | Horizontal Situation Indicator Modification To Edo Aire Mitchell, Edo Aire Mitchell Service Bulletin No. MB-13 | PA-28R-200/ 201/201T | 6/2/77 | ** | 77-12-01 | 3420 6C20 |
| 571A | Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection | PA-28-235 | 10/20/77 | ** | 77-12-01 | 2810 6E5 |
| 576 | TCM-TS10360 Series Engines, To Disseminate Information | PA-28R-201T | 11/30/77 | | | 7200 6E23 |
| 577 | Single Mask Oxygen System Turbo Arrow III | PA-28R-201T | 5/1/78 | 763-808V | | 3500 6F1 |
| 578B | Nose Landing Gear Down Lock Replacement | PA-28R-201/ 201T | 9/27/78 | 67150-04V | | 3230 6F3 |
| 580 | Engine Cowling Air Scoop Drain Hole | PA-28-181/235 | 10/19/77 | | 76-25-06 | 7100 6F13 |
| 582 | Pitot and Static Sump Drain Inspection | PA-28-161/181 | 12/6/77 | ** | | 3410 6F15 |
| 611 | Hose Assembly Inspection and Replacement | PA-28R-200 PA-28R-201T PA-44-180 | 11/14/78 | ** | | 2820 6J5 |
| 612 | Fuel Gascolator Assembly Inspection | PA-28-161 PA-28R-201T PA-28R-201 | 10/25/78 | | 79-02-05 | 7310 6J10 |
| 623 | Diode Assembly Inspection | PA-28-140/151/ 161/180/181/235 PA-28R-200 PA-28R-201 PA-28R-201T | 11/1/78 | | | 2450 6K16 |
| 625A | Fuel And Vapor Return Lines Support | PA-28R-201T PA-28RT-201T | 8/15/80 | 63882-73V | | 2810 6K22 |
| 627 | Fuel Line Inspection And Modification | PA-44-180 | 10/24/78 | 63976-34 | 79-02-02 | 2810 6L5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|--|------------------|---------------------|----------|---------------|------|
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-28-161/181 PA-28-236 PA-28R-201 PA-28R-201T PA-44-180 | 2/25/80 | | | 3450 | 6L14 |
| 631B | Battery Protection and Correct Rear Seat Installation | PA-28-151/161 | 10/29/81 | ** | 81-23-05 | 2430 2510 | 7A1 |
| 632 | Wing Tip Strobe Light Modification | PA-44-180 | 12/7/78 | 481-193 761-237V | | 3340 | 7A8 |
| 634 | Engine Primer Modification | PA-44-180 | 12/28/78 | 763-908V | 79-12-11 | 7310 | 7A21 |
| 638 | Inspection of Fuel Line Union Fitting | PA-28-161/181 PA-28-236 PA-28-201T PA-28R-201/201T PA-28RT-201/201T | 4/23/79 | ** | 79-13-03 | 2810 | 7B13 |
| 639 | Throttle Cable Installation Modification | PA-44-180 | 1/10/79 | ** | 79-05-11 | 7610 | 7B17 |
| 642 | Air Filter Seal Inspection | PA-28-140 | 2/1/79 | | | 7160 | 7C2 |
| 646A | Fuel Tank Vent Modification And Vent Hose Replacement | PA-28-161/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-201/201T PA-28RT-201/201T | 3/5/80 | 763-934V | 79-22-02 | 2810 | 7C17 |
| 650 | "P" Lead - Bendix Magneto | PA-28-236 PA-44-180 | 7/20/79 | 470-864V | | 7410 | 7D3 |
| 666 | Carburetor Air Box Rivet Replacement | PA-44-180 | 10/31/79 | 420-859 | | 7310 | 7F2 |
| 667 | Part I - Carburetor Air Box Modification | PA-28-236 | 10/3/79 | 763-926V | | 7310 | 7F4 |
| 667 | Part 11 - Engine Induction Air Scoop | PA-28-236 | 10/3/79 | 763-953V | | 7160 | 7F5 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 1 5.0 | 7H4 |
| 678 | Nose Landing Gear Down Lock Bushing Replacement | PA-44-180 | 3/24/80 | 764-010V | 80-12-03 | 3230 | 7H5 |
| 679 | Throttle Linkage Modification | PA-28-181 | 3/24/80 | 764-009V | 80-14-02 | 7610 | 7H6 |
| 681 | Boom Microphone Isolation Relay | PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201/201T PA-44-180 | 4/24/80 | 456-703 180-500 | 80-14-03 | 2350 | 7H11 |
| 689A | Aileron Push Rod Functional Check | PA-44-180 | 10/24/80 | ** | 80-21-11 | 2710 | 7J7 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|---|------------------|--------------|----------|----------|------|
| 691A | Muffler Assembly Inspection | PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201 | 10/8/80 | ** | 80-19-01 | 7820 | 7J11 |
| 694 | Throttle Rod End Assembly | PA-28R-200 PA-28R-201 PA-28RT-201 | 9/9/80 | MS-24665-132 | | 7610 | 7J22 |
| 695 | Nose Cone Spar Check / Reinforcement | PA-44-180 | 9/10/80 | 764-080V | 81-10-01 | 5350 | 7K1 |
| 696 | Master and Alternator | PA-44-180 PA-44-180T | 3/16/81 | 99377-60V | | 2450 | 7K4 |
| 699 | Rudder Torque Tube Attachment Fitting and Hardware Inspection | PA-28RT-201 PA-28RT-201T | 4/1/81 | ** | | 2720 | 7K11 |
| 702 | Aileron Reinforcement | PA-44-180 | 12/4/80 | 764-088V | 81-10-04 | 5710 | 7K19 |
| 714 | Oil Cooler Hose Installation Inspection | PA-44-180T | 6/10/81 | 35801-09V | | 7920 | 8A12 |
| 717 | Fuel Selector Line Inspection | PA-28-140/150/160/180 PA-28-151/161 PA-28-181 PA-28-236 PA-28R-180/200 PA-28R-201 PA-28RT-201 | 7/8/81 | | | 2820 | 8A22 |
| 719 | Engine Mount Reinforcement | PA-44-180 | 10/15/81 | ** | | 7120 | 8B3 |
| 724A | Nose Landing Gear Inspection, Rigging, and Modification | PA-28R-200 PA-28R-201/201T PA-28RT-201/201T | 4/20/82 | ** | 82-06-11 | 3220 | 8C1 |
| 725B | Aileron Balance Weight Attachment Inspection and Rework | PA-44-180 PA-44-180T | 11/3/97 | 764-148V | 81-16-10 | 2715 | 8C9 |
| 738 | Nose Landing Gear Actuator Rod End Inspection / Replacement | PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 4/20/82 | 452-729V | | 3230 | 8D15 |
| 738 | Addendum 1 - Nose Landing Gear Actuator Rod End Inspection / Replacement | PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 11/23/87 | 452-729 | | 3230 | 8D15 |
| 749 | Stabilator Assist Springs Inspection | PA-44-180 PA-44-180T | 11/8/82 | ** | | 2370 | 8G8 |
| 753 | Expanded Spin Recovery Procedures | PA-28-140 | 12/15/82 | 87369-44 | | 2700 | 8G18 |
| 769 | Landing Gear Back-Up Actuator Override Mechanism | PA-28R-180 PA-28R-200 | 10/19/83 | ** | | 2920 | 8I18 |
| 771A | Parking Brake Application | PA-44-180/180T | 9/6/2011 | 81090-002 | 85-02-05 | 1130 | |
| 774 | Baggage Door Latch Replacement | PA-28-150/160/180 PA-28R-180 | 2/22/84 | ** | | 5230 | 8J9 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--|------------------|---------------------------------|------------------|----------|------|
| 775 | Electrical Bus Modification | PA-44-180/180T | 6/20/84 | 764-937V | | 2430 | 8J11 |
| 787C | Main Landing Gear Trunnion Housing Inspection | PA-44-180/180T | 11/7/2000 | 2599-002 | 94-13-11 | 3211 | 8L8 |
| 789B | Aft Inboard Wing Access Panel & Aft Wing Spar Modification | PA-28-140 PA-28-150/160 PA-28-180 PA-28-235 PA-28R-180/200 | 12/3/2018 | 764-998V 765-106V N/A | SAIB CE-11-12 | 5711 | |
| 798 | "TURBO" Marking Removal | PA-28-201T PA-28R-201T PA-28RT-201T | 12/11/84 | N/A | | 1110 | 9B19 |
| 801 | King Auto Pilot Servo Bridle Clamp Installation | PA-28-161/181 PA-28-236 PA-28RT-201T | 12/11/84 | ** | | 2200 | 9C6 |
| 804 | Battery Strap Installation | PA-28-180/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-200 PA-28R-201/201T PA-28RT-201T | 4/26/85 | 765-157 | | 2430 | 9D12 |
| 805A | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration) | PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 3/14/86 | N/A | | 6110 | 9D15 |
| 811A | Ammeter Replacement | PA-28-150/160 PA-28-180 PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T | 5/12/86 | ** | 86-17-01 | 2430 | 9F4 |
| 836A | Aluminum Wire Inspection/Replacement | PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180/181 PA-28-235/236 PA-28-201T PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 8/26/86 | ** | | 2400 | 9J4 |
| 839 | Muffler/Stack Modification | PA-28-181 | 6/19/86 | 765-191 | | 7822 | 9J14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|--------------------|
| 840A | Fuel Selector Valve Cover Replacement | PA-28-140 PA-28-150/160 PA-28-180 PA-28R-180 PA-28R-200 | 11/7/2013 | ** | 71-21-08 | 2822 |
| 847 | Ammeter Replacement | PA-44-180T | 8/28/86 | 765-302 | 86-20-11 | 2430 9K23 |
| 848 | Niagara Oil Cooler Inspection/Replacement | PA-28-236 | 10/3/86 | 16599-00 | | 7921 9L1 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 10A7 |
| 856 | Stabilator Attach Fitting Corrosion Inspection | PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180 PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180 PA-28R-200 PA-28R-201/201T | 2/17/87 | ** | | 5550 10A9 |
| 866A | Back Up Landing Gear Extender Removal or Alternate Means of Compliance | PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T | 3/4/88 | 765-303 | | 3236 10B22 |
| 884 | Lock Wiring of V-Band Couplings | PA-28-201T PA-28R-201T PA-28RT-201T PA-44-180T | 4/8/88 | ** | | 7800 10G20 2100 |
| 886 | Wing Spar Inspection | PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T | 6/8/88 | ** | | 5711 10H3 |
| 896 | Shoulder Harness Installation & Usage | PA-28-140 PA-28-150/160/180 PA-28-151/161/181 PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 11/28/88 | ** | | 5340 10I13 |
| 901 | Maneuvering Airspeed Placard Replacement | PA-28-161 Cadet | 3/14/89 | 35669-143 | | 2501 10J14 |
| 905 | Auxiliary Primer Switch Replacement | PA-28-201T PA-28R-201T PA-28RT-201T | 4/6/89 | ** | | 7315 10K7 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|---------------------|------------------|-------------|
| 906 | Oildyne Hydraulic Pump Replacement | PA-28R-201 PA-28RT-201T | 4/10/89 | ** | | 2911 10K12 |
| 916B | Addition of Wing Stall Strips | PA-28-161 Cadet PA-28-161 Warrior II PA-28-181 II | 11/22/89 | ** | | 1130 10aA8 |
| 933A | Trunnion Replacement | PA-28R-201 PA-28R-201T | 2/20/90 | 67054-03 | | 3222 10aD21 |
| 937 | Engine Mount Inspection and Modification | PA-44-180 PA-44-180T | 4/2/90 | 86212-024 | | 7120 10aE11 |
| 938 | Wire Protection | PA-28R-201 PA-28R-201T | 6/12/90 | 181-531 488-698 | | 3262 10aE15 |
| 940A | Throttle Microswitch | PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T | 11/28/90 | 67210-08 487-925 | | 7613 10aE21 |
| 965 | Inspection of Flap Lever and Bolt | PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-161 Cadet PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 9/1/93 | ** | | 2750 10aJ22 |
| 975 | Aging Landing Light Seal Replacement and Landing Light Support Modification | PA-28-140 PA-28-150/160/180 | 11/2/94 | ** | | 7160 10bA5 |
| 977 | Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels | PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 12/12/94 | ** | SAIB CE-11-12 | 5740 10bA12 |
| 978A | Wing Spar Inspection | PA-28-161 Cadet PA-28-161 Warrior III PA-28-181 Archer III PA-28R-201 PA-28R-201T | 8/6/99 | ** | | 5711 10bB1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------------|------------------|-------------|
| 990 | Pacific Scientific Seat Belt Replacement | PA-28-161 PA-28-181 PA-28R-201 PA-44-180 | 1/3/96 | ** | | 5346 10bD12 |
| 991A | Replacement of Modification of the Alternator Out Light Fuse | PA-28-161 Cadet PA-28R-201 PA-28R-201T | 1/29/96 | ** | | 2437 10bD16 |
| 992 | Replacement of Spinner and Additional of New Forward Spinner Bulkhead | PA-28-181 | 3/14/96 | ** | | 6110 10bD22 |
| 996 | Missing Rivet in Upper Door Frame, Forward and Aft | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 9/12/96 | ** | | 5311 10bE16 |
| 1005 | Addition of Drain Holes to the Engine Induction Air Inlet Scoops | PA-28-181 | 8/11/97 | | | 7162 10bG1 |
| 1006A | Corrosion Inspection of Main Spar Behind Fuel Tanks | PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-181 Pilot 100i PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T | 9/25/24 | ** | SAIB CE-11-12 | 530 10bG4 |
| 1016B | Aileron Replacement | PA-44-180 PA-44-180T | 5/26/2016 | 86562-24/-28 86562-25/-29 | | 2715 |
| 1019 | Inspection of the Engine Oil Cooler | PA-28-181 III | 6/3/98 | 85472-10 | | 7925 10bI6 |
| 1020 | Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket | PA-28-161 Cadet PA-28-161 III PA-28-181 III PA-28-236 PA-28R-201 PA-44-180 | 7/10/98 | ** | | 2563 10bI11 |
| 1022 | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-28-140 PA-28-150/160/180 PA-28-181 II & III PA-28-235 PA-28-201T PA-28R-201T PA-28RT-201T | 9/22/98 | 460-632 | 99-05-09 | 7167 10bI20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|----------------------|----------|-------------|
| 1023 | Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063 | PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 10/8/98 | ** | | 2902 10bJ6 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings." | PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 CADET PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T PA-44-180 PA-44-180T | 11/5/98 | 753-910 | | 3711 10bJ20 |
| 1028 | Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips | PA-44-180 PA-44-180T | 12/2/98 | ** | | 5755 10bk12 |
| 1033A | Engine Mount Inspection and Modification | PA-44-180 | 6/12/2006 | 767-518 89361-016 | | 7121 10bL10 |
| 1036 | Garmin Service Bulletin No. 9905 "GNS430 Mod 1" | PA-28-181 III | 10/1/99 | ** | | 3426 10cA1 |
| 1037 | Inspection for Gascolator Bowl Drain Security | PA-28-161 III PA-28-181 III PA-28R-201 | 10/28/99 | ** | | 2824 10cA5 |
| 1040 | Flight Control Wheel Collar Retainer Modification | PA-28-161 III PA-28-161 Cadet PA-28-181 III PA-28R-201 PA-44-180 | 3/20/2000 | | | 2701 10cA19 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-28-140 PA-28-150/-160/-180 PA-28S-160/-180 PA-28-151/-161 PA-28-161 Cadet PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T | 9/25/2000 | ** | | 3714 10cB1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|-------------------------------|----------|-------------|
| 1048 | Stainless Steel Control Cables | PA-28-161 II/III PA-28-161 CADET PA-28-181 II/III PA-28-236 PA-28R-201 PA-28R-201T PA-44-180 | 1/3/2001 | N/A | | 2702 10cC9 |
| 1050 | Engine Baffle Assemblies, Installation of Longer Screws | PA-28-161 III PA-28-181 III | 3/7/2001 | 418-421 408-051 690-611 | | 7236 10cC15 |
| 1057 | Low Noise Muffler Replacement | PA-28-181 III | 7/12/2001 | 766-681 | | 7821 10cD24 |
| 1079 | Untested Fuel Pump | PA-28-161 III PA-28-181 III | 7/20/2001 | 62220-004 | | 2825 10cI4 |
| 1083C | S-TEC System 55X Autopilot | PA-28-181 III PA-28R-201 PA-44-180 | 5/30/2002 | 767-316 767-317 767-320 | | 2218 10cI19 |
| 1104 | Air Box Interference | PA-28-181 III | 3/22/2002 | 104606-002 | | 7160 10dA18 |
| 1109 | Gear Warning Indication | PA-44-180 | 4/12/2002 | 472-054 473-028 | | 3264 10dB14 |
| 1110 | Air Box Inspection | PA-44-180 | 5/16/2002 | 86245-034 | | 7160 10dB18 |
| 1117 | Rudder Trim System Bolt Inspection | PA-44-180 | 6/3/2002 | 402-285 691-306 | | 2721 10dC16 |
| 1118 | Alternate Air Inlet Adapter Inspection | PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201 | 4/19/2002 | 99047-000 | | 7164 10dC20 |
| 1119 | Toe Brake Installation Inspection | PA-28R-201 | 8/16/2002 | 424-184 762-587 | | 3241 10dD1 |
| 1122 | Wing Rib Inspections | PA-28-151 PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-236 PA-28-201T PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T | 3/7/2003 | 35617-001 104721-002 | | 5712 10dD14 |
| 1127B | Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110B) | PA-44-180 PA-44-180T | 4/18/2005 | 767-367 ** | 3-11-14 | 2800 10dE16 |
| 1131A | Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004) | PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 II/III PA-28-161 Cadet PA-28-235 | 1/18/2016 | 65489-002 65490-000 | | 3210 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|-------------------------------|----------|----------|
| 1134 | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105) | PA-28R-180 PA-28R-200 PA-28R-201 III PA-28R-201 PA-28RT-201 | 6/10/2003 | ** | | 2800 |
| 1135 | GMA-340 Audio Panel Wiring | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 7/16/2003 | N/A | | 2370 |
| 1136 | Auxiliary Fuel Pump Switch | PA-28-201T PA-28R-201T PA-28RT-201T | 9/2/2003 | 588-006 (99377-029) | | 2800 |
| 1137 | Stabilator Balance Weight Tube Assembly | PA-28-161 III PA-28-181 III PA-28R-201 | 11/6/2003 | N/A | | 2749 |
| 1138 | GNS-430 / GI-106 Wiring | PA-28-161 III | 10/30/2003 | N/A | | 3457 |
| 1139A | Control Wheel Attachment Inspection | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 4/9/2004 | ** | 4-14-12 | 2701 |
| 1141 | Clip Nut Replacement | PA-28-161 III PA-28-181 III PA-28R-201 | 12/9/2003 | 477-640 | | 5351 |
| 1143 | Nose Cone Spar Assy Inspection | PA-44-180 PA-44-180T | 7/13/2004 | ** | 81-10-01 | 3220 |
| 1151E | 4130N Steel Hardness Discrepancy | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 6/9/2004 | N/A | | 5741 |
| 1153 | Overhead Switch Panel Assembly Modification | PA-28-181 III | 2/8/2005 | 767-382 | | 3340 |
| 1156B | Nose Gear Drag Link Bolt Periodic Inspection & Replacement | PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 12/16/24 | 402-940 | | 3220 |
| 1161D | Rib Assembly Inspection and Modification - Aft Wing, WS 49.25 | PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 2/19/2024 | 767-397 767-398 | | 5712 |
| 1162B | European Requirements for Avidyne Entegra Equipped PA-28 and PA-32 Model Aircraft | PA-28-161 III PA-28-181 III PA-28R-201 | 9/7/2006 | 652-589 767-419 767-422 | | 3400 |
| 1164 | Propeller RPM Limitation and Tachometer Re-Marking | PA-28R-200 | 5/5/2006 | 767-510 62177-019 | | 7714 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|------------------------|------------|-------------|
| 1167 | Nose Gear Centering Springs | PA-28-161 II/III PA-28-161 Cadet PA-28-181 II/III | 5/31/2006 | 767-514 767-519 | | 3220 10dL16 |
| 1178 | Nose Gear Forging Inspection / Replacement | PA-28R-201 PA-44-180 | 9/24/2007 | 67050-007 67050-002 | | 3222 10eB10 |
| 1179 | Main Landing Gear Cylinder Assembly Inspection | PA-28-161 III PA-28-181 III | 2/1/2008 | 65490-000 | | 3213 10eB14 |
| 1186 | Aileron Handling Placard | PA-44-180 PA-44-180T | 9/7/2007 | 88428-002 (Kit) | | 2710 10eD1 |
| 1187 | Voltage Suppressor Replacement | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 2/8/2008 | 88432-002 (Kit) | | 3400 10eD4 |
| 1188 | Emergency Gear Extension Cable Routing Modification | PA-44-180 PA-44-180T | 4/14/2008 | 88433-002 (Kit) | | 3200 10eD12 |
| 1197E | Control Wheel Shaft Inspection | PA-28-140 PA-28-150/(S)-160/(S)-180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 11/2/2017 | ** | 2010-15-10 | 2710 |
| 1198A | Fuel Selector O-Ring | PA-28-235 | 4/20/2009 | 485-330 485-332 | | 2823 |
| 1199 | Main Landing Gear Torque Link Inspection | PA-28-140 PA-28-150/160/180 PA-28-235 | 2/16/2009 | 78033-000 63312-002 | 72-08-06 | 3213 |
| 1207 | Periodic Replacement of Nose Gear Downlock Pivot Bolt | PA-44-180/180T | 2/15/2010 | ** | | 3220 |
| 1209 | Nose Gear Actuator Modification | PA-44-180 | 1/5/2010 | N/A | | 3220 |
| 1213A | Emergency Gear Extension Cable Routing Inspection | PA-44-180 | 10/23/2015 | ** | | 3230 |
| 1220C | Throttle Cable Seizing | PA-44-180 | 4/27/2017 | 88501 | | 7600 |
| 1223 | Wire Screen Replacement | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 11/10/10 | ** | | 2126 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|---------------------------------|------------|----------|
| 1226 | Radio Support Plate Inspection | PA-28-161 III | 10/28/10 | 79009-000 | | 3450 |
| 1227 | Rudder Trim Tab Inspection | PA-44-180 | 11/2/10 | N/A | | 5540 |
| 1240 | Fuel Pump Coupling Inspection | PA-44-180 | 1/26/2012 | 556-406 | | 2820 |
| 1242A | Rudder Pedal Assembly Inspection | PA-28-140 PA-28-150/(S)-160/(S)-180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 5/12/2020 | 99938-000 99938-001 | | 2710 |
| 1244C | Aft Wing Attach Fitting Inspection Requirements | PA-28 Series PA-28S Series PA-28R Series PA-28RT Series PA-44 Series | 12/3/2018 | 764-998 | | 5740 |
| 1245A | Stabilator Control System Inspection | PA-28 Series PA-28S Series PA-28R Series PA-28RT Series PA-44 Series | 11/28/2012 | N/A | 2013-02-13 | 2730 |
| 1251 | Stabilator Trim Barrel Inspection | PA-28-140/150/160/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T/235/236 PA-28R-180/200 PA-28R-201/201T PA-28S-160/180 | 4/10/2013 | 63530-000 | | 5755 |
| 1253 | Firewall Inspection | PA-28-181 III | 1/7/2013 | N/A | | 7130 |
| 1259A | Engine Control Cable Mounting Bracket Replacement | PA-44-180 | 5/5/2017 | 106895-002 | | 7610 |
| 1261 | Alternator INOP Wiring Modification | PA-44-180 | 9/11/2013 | 88545-002 | | 3150 |
| 1274 | Control Wheel Bushing Inspection | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 2/9/2015 | 68273-002 | | 2701 |
| 1276A | Left Wing Root Rib Inspection | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 4/29/2016 | 88569 95639-002 95640-000 | | 5710 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|------------------------|------------|----------|
| 1278B | Left Wing Sta. 131.60 Rib Inspection | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 5/2/2019 | 35118-030 | | 5712 |
| 1279A | Wing Rib Inspection at Right Side WS 140.09 | PA-28-161 III PA-28-181 III PA-28R-201 | 3/3/2016 | N/A | 2015-20-13 | 5712 |
| 1280A | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1 | PA-28-161 Cadet PA-28-161 II-III PA-28-181 III PA-28R-201 PA-28-236 PA-44-180/-180T | 4/29/2016 | 459-887 | | 2620 |
| 1282B | Oil Pressure Pickup Port Relocation | PA-44-180 | 1/12/2016 | 88573-001 88573-002 | | 7930 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-28-140 PA-28-150/-160/-180/-235 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28R-180/-200 PA-28R-201 PA-28RT-201 PA-44-180/-180T | 4/12/2019 | N/A | | 7414 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201 PA-44-180 | 10/30/2015 | N/A | | 7310 |
| 1287 | Lower Wing Skin Inspection | PA-44-180/-180T | 6/1/2017 | 88611-701 | | 5730 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1300 | Air Box Gasket Replacement | PA-44-180 | 3/22/2017 | 44P710003-001 | | 7160 |
| 1302B | Rear Seat Inspection | PA-28-161 II-III PA-28-161 Cadet PA-28-181 III | 5/5/2017 | 110145-001 | | 2520 |
| 1303A | Diode Module Installation | PA-44-180 | 10/15/2018 | 681-020 | | 3410 |
| 1304B | Main Wing Spar Inspection | PA-28-140 PA-28-150/-160 PA-28-180 PA-28-235 | 12/2/2021 | 765-106 88692 | | 5740 |
| 1307 | Plane-Power Alternator Mounting Hardware Replacement | PA-28-181 III PA-44-180 | 6/28/2017 | 88617-001 88616-001 | | 2410 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|---|------------|----------|
| 1309A | Fuel Tank Selector Placards Inspection | PA-28-140 PA-28-150/-160 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T | 3/6/2018 | 581-685 581-686 581-687 581-890 581-891 582-693 582-694 | 2018-02-05 | 2822 |
| 1311 | Baggage Compartment Closeout Inspection | PA-28-151/-161 PA-28-161 Cadet PA-28-181 III | 12/11/2017 | 65667-000 | | 2550 |
| 1312 | Emergency Exit Inspection | PA-44-180 | 6/20/2017 | N/A | | 5220 |
| 1313A | Stabilator Trim Pulley Bracket Inspection | PA-28-140 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-201T PA-28-235 PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T | 1/17/2018 | 65636-801 | | 2700 |
| 1316 | Plane-Power Alternator Idler Pulley Bracket Improvement | PA-28-181 III | 11/3/2017 | 88619-001 | | 2410 |
| 1323 | Fuel Injection Servo Vapor Return Fitting Replacement (Lycoming S.I. 1572, Plug Replacement of Vapor Return Fitting on Piper Installation of IO-360-B4A) | PA-28-181 III | 9/27/2018 | ** | | 7322 |
| 1324 | Winterization Kit Replacement (Fuel Injected Engines) | PA-28-181 III | 3/22/2018 | 85470-005 | | 7900 |
| 1325 | K400 Relay Wiring Inspection and Mod | PA-44-180 | 6/19/2018 | N/A | | 3297 |
| 1331A | Stabilator Idler Arm Assembly Inspection | PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T | 9/27/2018 | N/A | | 5520 |
| 1340C | Plane-Power Alternator Support Replacement | PA-28-181 III | 7/15/2022 | 106972-004 | | 2430 |
| 1342A | Stabilator Fitting Inspection | PA-28-140 PA-28-150/-160 PA-28-151/-161 PA-28-161 Cadet PA-28-180 PA-28-181 II-III PA-28-201T PA-28-235 PA-28-236 PA-28R-180/-200 PA-28R-201/-201T | 11/2/2021 | 62645-004 | | 5510 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------|-----------|
| 1345A | Main Wing Spar Inspection | PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T | 9/17/2021 | ** | 2020-26-16 | 5711 |
| 1354 | Fuselage Station 247 Bulkhead Inspection | PA-44-180 PA-44-180T | 10/18/2023 | 88686-701 | | 5310 |
| 1355B | Tee Bar Assembly Inspection | PA-28-140 PA-28-150/-160/-180/-235 PA-28S-150/-160 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T | 8/18/2022 | 28F40A003 | | 2701 |
| 1357 | Wing Rib Inspections at WS 106.19 and WS 123.15. | PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-236 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T | 10/27/2020 | N/A | | 5712 |
| 1362 | Aft Wing Rib Inspection at Wing Stations 36.92 and 49.25 | PA-28-181 III | 11/2/2020 | N/A | | 5712 |
| 1363 | Rivet Dimple Inspection For Tool Marks | PA-28-181 III PA-44-180 | 11/13/2020 | N/A | | 5700/5300 |
| 1365A | Pilot and Copilot Seat Upholstery Inspection | PA-28-181 III PA-28-181 Piper Pilot 100i PA-44-180 | 7/22/2021 | 484-829 | | 2510 |
| 1366 | Main Wing Spar Hardware Inspection | PA-28-140 PA-28-150/-160/-180/-235 PA-28S-150/-160 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-236 PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T | 5/14/21 | 96352 | | 5711 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|------------------------|----------|-------------|
| 1368 | Heater Fuel Pump Leak Inspection and Replacement (Hartzell ASB 85) | PA-44-180 | 7/14/21 | ** | | 2140 |
| 1372A | Main Wing Spar Inspection | PA-28-151 PA-28-161 II-III / Cadet PA-28-181 II-III / Pilot 100i PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/-201T PA-28RT-201/-201T | 12/11/2024 | 88731-701 / -702 | Pending | 5711 |
| 1375D | Periodic Replacement of Main Landing Gear Attachment Hardware | PA-28-140 PA-28-150/-160/-180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-201T PA-28-235 PA-28-236 | 1/29/2023 | ** | | 3210 |
| 1377B | Main Wing Spar Inspection at the Landing Gear Truss Bracket | PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 9/24/2024 | | | 5740 |
| 1378 | Fuselage Skin Rivet Inspection | PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-181 Pilot 100i PA-28-236 | 8/30/2022 | ** | | 5330 |
| 1381 | Lower Fuselage Skin Rivet Insp. | PA-44-180/180T | 6/9/2022 | MS20470AD4 | | 5300 |
| 1383 | Microphone And Headphone Jack Improvement | PA-28-181 III PA-28-181 Pilot 100i | 9/8/2022 | ** | | 2340 |
| 1386 | Archer Diesel Cowling Inspection | PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC. | 8/22/2022 | STC SA03303AT | | 7110 |
| 1387 | Archer Diesel Instructions For Continued Airworthiness (ICA) | PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC. | 10/17/2022 | STC SA03303AT | | 0400 |
| 1388A | Archer Diesel Fuel System Inspection | PA-28-181 (DX/DTX/DLX) or any other Archer modified by Piper per subject STC. | 5/10/2024 | STC SA03303AT | | 2820 |
| 1389A | Fuselage Skin and Wing Rib Inspection | PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 2/19/2024 | 86486-006 67681-806 | | 5300 / 5710 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--|----------|----------|
| 1391C | GFC 500 Autopilot Pitch Trim | PA-28-181 Pilot 100i | 1/8/2024 | 88730-701 | | 2216 |
| 1393 | Engine Control Cables Inspection | PA-28-181 III PA-28-181 Pilot 100i PA-44-180 | 12/22/2022 | 455-350 653-946 | | 7600 |
| 1396 | Propeller Spinner Modification | PA-28-181 III PA-28-181 Pilot 100i | 4/1/2024 | | | 6113 |
| 1397 | Lower Cockpit Channel Inspection | PA-44-180 | 4/27/2023 | 189-625 | | 5300 |
| 1399 | Wing Rib Modification | PA-28-151/-161 PA-28-181 PA-28-201T PA-28R-201/-201T PA-28-236 PA-28RT-201/-201T | 3/16/2023 | 35615-001 35615-003 | | 5700 |
| 1405A | Fuselage Skin Rivet Inspection, FS 156 | PA-28-236 PA-28-151 PA-28-161 PA-28-161 II PA-28-161 III PA-28-181 II PA-28-181 III PA-28-181 Pilot 100i PA-28-201T PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 10/25/2023 | | | 5330 |
| 1411A | Autopilot Rigging Inspection | PA-28-181 III PA-28-181 Pilot 100i PA-44-180 | 7/2/2024 | | | 2700 |
| 1412 | Main Wing Spar Inspection | PA-28-140 PA-28-150/-160/-180 PA-28S-160/-180 PA-28-236 PA-28-201T | 5/9/2024 | | | 5711 |
| 1413 | Aft Wing Spar Attach Fitting Inspection | PA-28-181 III PA-PA-181 Pilot PA-28R-201 PA-44-180 | 4/18/2024 | 66762-000 62448-002/-003 68621-002/-003 88365-002 / 87584-000 | | 5741 |
| 1415 | Rivet Inspection Near FS 104.70 | PA-28-181 Pilot 100i | 5/14/2024 | | | 5300 |
| 1416B | Fuel Flow Transducer Inspection | PA-28-181 Archer III PA-28-181 Pilot 100i PA-44-180 Seminole | 12/9/2024 | | | 2840 |

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------|------------------|--------------------|----------|---|
| 254 | Oil Cooler Hoses, Engine Replacement & Rerouting of | PA-31 | 8/17/67 | 757-167 | 67-25-06 | 7920 3F16 |
| 255 | Emergency Exit Window Mechanism, Modification of | PA-31 | 8/9/67 | 757-159 | | 5220 3F17 |
| 256 | Pneumatic Pump Hose, Replacement | PA-31 | 8/25/67 | 757-175 | | 3710 3F18 |
| 257 | Modifications, Piper Navajo (Five Sections) | PA-31 | 10/10/67 | ** | | 7720 3F19 3210 6110 7920 2810 2910 3200 |
| 258 | Alternate Air Box Assembly | PA-31 | 11/1/67 | 757-189 | | 7160 3F24 |
| 262 | Terminals, Solenoid, Insulation of | PA-31 | 12/19/67 | 757-185 | | 3310 3G8 |
| 265 | Louvered Access Plates, Wing Fillet | PA-31 | 2/5/68 | ** | | 5710 3G11 |
| 266 | Fasteners, Engine Cowling | PA-31 | 2/23/68 | 760-190 757-179 | | 7110 3G13 |
| 267A | Flight Manual Revision | PA-31 | 5/28/68 | ** | | General 3G15 |
| 268 | Valve Assembly, Manifold And Check | PA-31 | 2/28/68 | 760-174 | | 7710 3G18 |
| 270 | Deicer Boot Installation, Elevator Tip | PA-31 | 2/23/68 | 757-200 | | 3010 3G20 |
| 271 | Filter, Inline, Pneumatic System | PA-31 | 3/1/68 | 460-866 | | 3710 3G21 |
| 272A | Terminal Screws, Electrical, Security of - Voltage Regulator Selector Switch And Master Switch | PA-31 | 5/6/68 | ** | | 2430 3G22 |
| 276 | Channel Clearance, Aileron Cable/Floorboard Support | PA-31 | 5/23/68 | ** | | 2710 3H11 |
| 277 | Level, Fuel Selector, Cable Attachment Assembly | PA-31-300 | 7/10/68 | 760-214 | 77-26-02 | 2820 3H13 |
| 278 | Control Panel (Fuel) Area, Rerouting And Securing of Wire In The, And Clearance of The Cross Feed Line | PA-31-300 | 5/27/68 | 760-216 | 68-13-01 | 2800 3H15 |
| 280 | Artificial Horizon, R.C. Allen 3", Case Leakage of | PA-31-300 | 7/10/68 | | | 3420 3H2 |
| 283 | Warning System, Landing Gear, Modification To The | PA-31-300 | 10/4/68 | 760-250 | | 3260 3I5 |
| 284 | Torque Tube Assembly, Elevator, Inspection of - Section I; Replacement of The Steel Elevator Torque Tube Assembly, Part Numbers 40070-00 or 40070-04 With Aluminum Elevator Torque Tube Assembly, Part Number 40070-05 - Section II | PA-31/300 | 9/27/68 | 40070-05 | | 2740 3I6 |
| 286 | Hinge Attaching Rivets, Door, Main Landing Gear (In Board) | PA-31/300 | 10/29/68 | 420-236 | | 3210 3I13 |
| 289 | Friction, Elevator Control System | PA-31/300 | 2/17/69 | | 69-06-04 | 2730 3I19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|----------------------------|------------------|----------------------|----------|----------|------|
| 294 | Stall Strips | PA-31/300 | 5/16/69 | 760-321 760-322 | 69 11 05 | 5720 | 3J12 |
| 304 | Stall Strip Inspection | PA-31/300 | 11/17/69 | ** | | 5720 | 3K9 |
| 306 | Alternator System Modification | PA-31/300 | 1/9/70 | 760-349 760-358 | 70-22-05 | 2430 | 3K14 |
| 307 | Electrical System Modification, Wing Flap | PA-31/300 | 3/23/70 | 760-381 | | 2750 | 3K16 |
| 308A | Seats, Aft Facing | PA-31/300 | 5/4/70 | ** | | 2570 | 3K17 |
| 320A | Autopilot Servo And Bridle Cable Installations, III Series, Inspection of | PA-31/300 PA-31P | 7/6/72 | | | 2210 | 3L23 |
| 323 | Spar Assemblies, Rudder And Elevator, Modification of The | PA-31/300 | 9/21/70 | ** | 70-26-06 | 5520 | 4A6 |
| 325 | Battery Drain Relocation | PA-31/300 | 11/23/70 | 760-436 | 71-01-04 | 2430 | 4A12 |
| 330 | Selector Mechanism Modification Landing Gear 11A | PA-31 | 1/20/71 | 760-510 | | 3200 | 4B1 |
| 331 | Switch, Electric, Trim Inspection And Modification | PA-31/300 PA-31P | 2/5/71 | 760-505 | 71-12-05 | 2730 | 4B3 |
| 333 | Safety Strap, Cabin Entrance Door, Inspection And Replacement | PA-31 | 2/18/71 | ** | | 5210 | 4B10 |
| 338 | Rivet Installation, Longitudinal Bulkhead | PA-31P | 4/21/71 | ** | | 5300 | 4B22 |
| 344 | Emergency Gear Extension Operation Information, Revised | PA-31 PA-31P | 10/12/71 | 760-570 | | 3200 | 4C19 |
| 346 | Flight Manual, Airplane, Mandatory Revision | PA-31 | 3/23/72 | ** | | 2430 | 4C22 |
| 347 | Weldon Service Bulletin WPSB-2 (Electric Fuel Pumps) | PA-31 | 11/17/71 | 760-573 760-574 | | 2820 | 4C24 |
| 361 | Elevator Hinge Bracket Reinforcement, Inspection | PA-31 | 8/17/72 | 43757-17 43757-18 | | 5550 | 4E16 |
| 363 | Cowl Shield Installation | PA-31/300/310 PA-31-350 | 2/19/73 | 760-689 | | 7110 | 4E24 |
| 365 | Torquemeter Oil Pump, Replacement of (Reference Avco Lycoming Service Bulletin No. 350 Dated July 21, 1972) | PA-31P | 8/29/72 | LW12637 | | 7920 | 4F3 |
| 379A | Rudder Control Cable Routing, Inspection of | PA-31-350 | 10/25/74 | 41953-03 41953-04 | 75-06-04 | 2720 | 4F20 |
| 383 | Fuel Selector Valve Control Handle, Modification of | PA-31-350 PA-31P | 4/25/73 | 760-755 | | 2820 | 4G4 |
| 384 | Propeller Blade Shank, Inspection of (Hartzell Service Bulletin No. 94A Dated March 1, 1973) | PA-31/300/310 | 4/25/73 | ** | | 6110 | 4G5 |
| 386 | Moisture Shield Installation, Circuit Probe | PA-31-310 PA-31-350 | 9/11/73 | 760-772 | | 2450 | 4G13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------------------|------------------|---------------------|----------|-----------|
| 389 | Bridle Cable And Bridle Cable Clamp Installation | PA-31-310 PA-31-350 PA-31P | 8/13/73 | | | 2210 4G17 |
| 391 | Loading Instructions, Cargo | PA-31-310 | 6/6/74 | ** | | 5230 4G23 |
| 392 | Automatic Flight Control System (V Series) Precautionary Operating Placard And System Modification | PA-31-310 PA-31-350 PA-31P | 7/11/73 | 760-793 | | 2210 4H2 |
| 394 | Rudder Pedal, Warning, Improper Use of | PA-31/300/310 PA-31-350 PA-31P | 9/28/73 | 757-436 | | 2720 4H7 |
| 398 | Copilot Gyro Operation - Altimatic V Series Automatic Flight Control System | PA-31-310 PA-31-350 PA-31P | 9/13/73 | ** | | 2210 4H15 |
| 399 | High Altitude Operation. Ignition System For (Avco Lycoming Service Instruction No. 1291, Dated November 2. 1973) | PA-31-350 | 10/29/73 | ** | | 7420 4H16 |
| 400 | Alternator Pulley And Belt Replacement | PA-31-310 PA-31-350 | 2/6/74 | 760-805 | | 2430 4H21 |
| 405 | Fuel Crossfeed Control Mod | PA-31-350 | 10/31/73 | 760-814 | | 2820 4I13 |
| 407 | Ball Joint Assemblies Control Attachment, Inspection of | PA-31/300 PA-31-350 PA-31-P | 11/14/73 | 469-142 | | 5340 4I22 |
| 409 | Elevator Control Tube, Inspection of | PA-31P | 6/7/74 | 40847-04 | 75-09-10 | 2730 4J4 |
| 415 | MAA Plate Replacement And Tailpipe Gasket Installation | PA-31-310 | 1/21/74 | 462-062 | | 7810 4J19 |
| 417 | Heater (Manual) Fuel Shut-off Valve, Removal of | PA-31-300 | 8/26/74 | | 74-26-04 | 2140 4J22 |
| 419 | Elevator Control Tube Attachment, Inspection of | PA-31-310 PA-31-350 PA-31P | 2/20/74 | | | 2730 4K2 |
| 420 | Windshield, Heated, Inspection of | PA-31P | 8/7/74 | 760-882 | | 3040 4K4 |
| 421 | Fuel Selector Valve Replacement | PA-31P | 3/18/74 | 492-239 | | 2820 4K9 |
| 422 | Fuel Selector Valve Control Handle, Inspection of | PA-31-350 | 3/11/74 | | | 2820 4K11 |
| 423 | Deicer (Propeller Electric) Solenoid Replacement | PA-31P | 3/13/74 | 487-167 | | 6110 4K13 |
| 431 | Placard, Electric Razor Outlet | PA-31-350 | 8/5/74 | SK-23601 SK-2361 | | 3320 4L8 |
| 432 | Fuselage Bulkhead, Modification To The | PA-31-310 PA-31-350 | 9/6/74 | 760-295 | | 5310 4L9 |
| 433 | Elevator Control Tube Inspection of | PA-31/300/310 PA-31-350 | 12/17/74 | ** | 75-09-10 | 2730 4L11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|----------|-------------------|
| 442 | Circuit Breaker Rewiring, Emergency Fuel Pump | PA-31/300/310 PA-31-350 | 1/22/75 | 760-905 | | 2820 5A15 |
| 443 | Fuel Cell Fitting (Main) Inspection of | PA-31/300 | 4/4/75 | 760-929 40518-00/01 | | 2810 5A16 |
| 446A | Cable Replacement, Rudder/Nose Gear Steering | PA-31P | 7/8/75 | 760-923 | 75-16-02 | 2720 5A23 3250 |
| 458 | Propeller Air Charge Loss, Aircraft Operating Advisory | PA-31P | 4/11/75 | ** | 75-22-14 | 6100 5C3 |
| 460A | Battery Drain And Vent Relocation | PA-31-350 | 1/23/76 | 761-029 760-941 | 76-04-10 | 2430 5C8 |
| 461 | Encoding Altimeter Harness Rewiring | PA-31-310 PA-31-350 PA-31P | 4/17/75 | ** | | 3410 5C10 |
| 462A | Tailpipe Support Bracket Installation | PA-31P | 11/3/75 | 760-974 | 76-06-09 | 7810 5C12 |
| 470 | Propeller Feather Assist Spring Assembly Installation | PA-31P | 10/27/75 | | | 6110 5D6 |
| 473 | Alternator Switch Bus Bar Link Installation | PA-31P | 3/24/76 | 49167-03 | 76-11-06 | 2450 5D19 |
| 478A | Airspeed Limitation Placard, Installation of | PA-31P | 8/20/76 | 761-075 | 76-11-01 | 3410 5E7 |
| 479B | Alternate Air Door Magnetic Catch Assembly Modification/Replacement; Engine Induction Air System | PA-31-325 PA-31-350 | 3/23/76 | 761-037 761-038 | 80-13-06 | 7160 5E9 |
| 480 | Emergency Fuel Pump Circuit Breaker Placards, Inspection of | PA-31-310/325 PA-31-350 | 10/10/75 | ** | | 2820 5E11 |
| 487 | Control Shaft Collar Attachment Modification | PA-31-300/310 PA-31-325 PA-31-350 PA-31P | 11/7/75 | 401-264 407-584 | 76-04-11 | 2710 5F7 |
| 488 | Landing Gear Selector Cable Forward Attachment Pin, Modification of | PA-31-310/325 PA-31-350 PA-31P | 10/24/75 | ** | 96-24-13 | 3200 5F10 |
| 492A | Exhaust System Modification TIG0-541 -E1A | PA-31P | 5/29/2012 | ** | 76-06-09 | 7800 |
| 494B | Flap Control System, Inspection of | PA-31-300/325 PA-31-350 PA-31P | 7/17/79 | ** | 82-27-13 | 2750 5G6 |
| 497 | Throttle And Propeller Pitch Control Attachment Modification | PA-31P | 3/29/76 | 761-031 | | 7610 5G16 6120 |
| 500 | Elevator Balance Weight Modification | PA-31-325 PA-31-350 | 4/23/76 | 761-040 761-041 | 76-15-07 | 2730 5G23 |
| 507 | Fuel System Control Cables At Swivel Fittings, Inspection of | PA-31/300/325 PA-31P | 11/10/76 | ** | 80-18-10 | 7320 5H15 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------------------|------------------|--------------------|----------|-----------|
| 509 | Engine Mount Assembly Attachment Nuts, Replacement of | PA-31-310/325 PA-31-350 | 6/25/76 | 404-890 | | 7120 5H22 |
| 511A | Oxygen System Outlet Refinement | PA-31/300/325 PA-31-350 PA-31P | 9/24/76 | 761-032 752-583 | | 3510 5I3 |
| 512 | Seat Track Modification | PA-31/325 | 10/21/76 | 761-086 | | 5340 5I5 |
| 515 | Control Cable Ball Joint Retainer Installation | PA-31/300/325 PA-31/350 | 1/17/77 | 55447-02 | | 7610 5I10 |
| 521 | Stabilizer Stringer Attachment, Inspection of | PA-31/325 PA-31/350 | 9/20/76 | 522-881 | 77-01-06 | 5530 5J1 |
| 523 | Cigar Lighter Element Replacement, 24 Volt | PA-31/325 PA-31-350 PA-31P | 10/8/76 | 55674-02 | | 3310 5J7 |
| 525 | Seat Latch Mechanism Modification, Pilot/Copilot | PA-31/300 PA-31-350 PA-31P | 11/15/76 | 55842-02 | | 5340 5J12 |
| 526A | Microphone And Phone Jack Relay Modification, Pilot/Copilot | PA-31/300/325 PA-31-350 PA-31P | 7/25/77 | 48757-02 | 77-08-02 | 2350 5J15 |
| 527 | Electric Trim Switch Modification | PA-31/300 PA-31-350 PA-31P | 11/5/76 | 756-047 | 77-09-10 | 2740 5J18 |
| 529 | Aircraft Data (MAA) Plate Inspection And Replacement | PA-31 | 11/5/76 | 53750-02 | 77-03-03 | 5330 5K3 |
| 535 | Radio Power Relay Cover Spacer Bushings, Replacement of | PA-31/325 PA-31-350 | 12/15/76 | | 77-07-03 | 2450 5L13 |
| 544 | Airspeed Placard Installation | PA-31-325 | 3/8/77 | 761-125 | 77-10-09 | 3410 6A11 |
| 546 | Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection of | PA-31/325 PA-31-350 PA-31P | 5/18/77 | ** | | 3340 6A16 |
| 549 | Elevator Bungee Link Modification | PA-31/325 PA-31-350 | 2/16/77 | | 78-01-02 | 2730 6B2 |
| 550 | Engine Control Cable Inspection | PA-31/325 PA-31-350 | 3/29/77 | ** | | 7230 6B4 |
| 554 | Spar Reinforcement, Front, Right Wing | PA-31/325 PA-31-350 | 3/7/77 | | 77-14-14 | 5710 6B15 |
| 558 | Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D | PA-31/325 PA-31-350 PA-31P | 6/10/77 | | | 2210 6C1 |
| 560 | Flap Condition. Asymmetric, Recommended Operating Procedure | PA-31/300/325 PA-31-350 PA-31P | 4/4/77 | ** | | 2750 6C5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|----------------------|--------------------------|------------------|
| 566 | Horizontal Situation Indicator, Modification To Edo-Aire Mitchell NSD-360 | PA-31/325 PA-31-350 | 10/11/77 | ** | | 3420 6D9 |
| 567 | Flap Solenoid Repositioning | PA-31/300/325 PA-31-350 | 6/7/77 | | 77-19-06 | 2750 6D20 |
| 574 | Fuel Crossfeed Control Shaft Security | PA-31-350 | 7/13/77 | ** | | 2820 6E17 |
| 575 | Inspection of Horizontal, Stabilizer And Vertical Fin Stringer Attachment Rivets | PA-31/325 PA-31-350 | 8/3/77 | 522-881 | 77-24-01 | 5510 6E19 |
| 591 | Inspection of Goodyear BTC-39 Fuel Cells | PA-31/300 PA-31-350 PA-31P | 3/22/78 | ** | | 2810 6G13 |
| 592 | Inspection of Fuel Selector Lever Assembly Installation | PA-31/325 | 2/16/78 | | 78-08-10 | 2820 6G24 |
| 595 | Elevator Outboard Hinge Bracket Rivets Replacement | PA-31/325 PA-31-350 | 6/5/78 | 762-575 | | 5550 6H4 |
| 604A | Forward Baggage Door Locking System Modification | PA-31/300/325 PA-31-350 PA-31P | 6/8/79 | ** | | 5230 6I4 |
| 621 | Elevator Cable Inspection And Cable Guard Installation | PA-31-350 | 10/13/78 | 71045-02 189-545 | 78-26-11 | 2730 6K10 |
| 626C | Elevator Down Spring Inspection/Replacement | PA-31/300 PA-31-325 PA-31-350 | 2/28/97 | ** | 98-08-18 79-01-04 | 2730 6L1 |
| 629 | Landing Gear Hose Assembly Inspection And Replacement | PA-31-325 PA-31-350 | 11/15/78 | 17766-27 | | 3230 6L10 |
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-31 PA-31-325 PA-31-350 PA-31P | 2/25/80 | | | 3450 6L14 |
| 636A | Superseded by SB 1273 and Atlanta ACO AMOC letter dated Jun 10, 2015 | | | | 96-12-12 | |
| 641 | Heater Fuel Drain Hose Modification | PA-31/300/325 PA-31-350 | 4/5/79 | ** | | 2140 7B22 |
| 643A | Oil And Manifold Pressure Tubes Inspection | PA-31 PA-31-325 PA-31-350 | 12/8/80 | 41907-00 41913-00 | | 7930 7C4 7710 |
| 644E | Turbo-Charger Exhaust Coupling Inspection/Replacement | PA-31/31-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 5/9/2012 | ** | 2014-23-03 2013-10-04 | 8123 |
| 645A | Crossfeed Valve Inspection | PA-31/31-325 PA-31-350 | 7/2/79 | ** | | 2820 7C14 |
| 647A | Outboard Flap Track Inspection Inspection And Reinforcement | PA-31 PA-31-325 PA-31-350 PA-31P | 11/24/80 | 763-986 | 80-14-06 81-23-06 | 2750 7C19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--|------------------|--------------|----------|--------------|------|
| 648A | Part I - Scott Fuel Selector Valve Inspection | PA-31 PA-31-300 PA-31-350 PA-31P | 4/27/87 | 760-504 | 80-18-10 | 7324 | 7C21 |
| 648A | Part II - Fuel Selector Valve Control Cable Inspection | PA-31 PA-31-300/325 PA-31P | 4/27/87 | ** | | 7324 | 7C23 |
| 648A | Part III - Fuel Selector Valve Control Cable Replacement | PA-31 PA-31-300/325 PA-31P | 4/27/87 | ** | | 7324 | 7C24 |
| 649 | Elevator Control Stop Inspection | PA-31/31-300 PA-31-325 PA-31-350 | 3/29/79 | | 79-12-02 | 2730 | 7D1 |
| 651 | Control Shaft Roll Pin Inspection | PA-31/31-300 PA-31-325 PA-31-350 PA-31P | 5/11/79 | 480-732 | 79-14-02 | 2710 | 7D6 |
| 653 | Modification of Weight and Balance Plotters | PA-31 PA-31-325 PA-31-350 | 12/3/79 | Placard** | | 800 | 7D11 |
| 654 | Cigar Lighter Installation Modification | PA-31 PA-31-325 PA-31-350 | 6/23/80 | ** | | 3310 | 7D13 |
| 658 | Elevator Inspection And Reinforcement | PA-31P | 7/31/79 | 763-943 | 80-02-15 | 2730 | 7E5 |
| 659 | Rudder And Aileron Trim Tab Attachment Inspection | PA-31P | 7/19/79 | 406-829 | | 2710 2720 | 7E7 |
| 664 | Elevator Torque Tube Attachment Inspection | PA-31 PA-325 PA-31-350 | 12/14/79 | ** | | 2730 | 7E20 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA | 7H4 |
| 682 | Main Landing Gear Inboard Door Hinge Inspection/Replacement | PA-31 PA-31-325 PA-31-350 PA-31P | 7/24/80 | ** | 80-26-05 | 3210 | 7H15 |
| 684 | PA-31-350 Chieftain/Takeoff Flaps | PA-31-350 | 4/14/80 | ** | 80-08-05 | 2750 | 7I16 |
| 685 | Elevator Bellcrank Assembly Inspection | PA-31 PA-31-325 PA-31-350 | 9/23/80 | ** | | 2730 | 7I18 |
| 688 | Placards Installation Check | PA-31 PA-31-325 PA-31-350 | 7/1/80 | Placard** | 80-17-06 | 1130 | 7I24 |
| 690 | Elevator Balance Weight Inspection | PA-31 PA-31-325 PA-31-350 | 7/7/80 | ** | 80-17-02 | 2730 | 7J9 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|---|------------------|--------------|----------|-------------|------|
| 693 | Engine Baffle Seats Inspection/Modification | PA-31/31-300 PA-31-350 | 7/28/80 | ** | 80-20-04 | 7230 | 7J16 |
| 697 | PA-31, PA-31-325 Takeoff Flaps | PA-31 PA-31-325 | 8/11/80 | ** | 80-21-07 | 2750 | 7K7 |
| 700A | Nose Wheel Inspection/Replacement | PA-31 PA-31-325 PA-31-350 PA-31P | 10/12/81 | 551-791 | 97-07-03 | 3240 | 7K14 |
| 704 | Cabin Fan Fuse Installation | PA-31 PA-31-325 PA-31-350 | 6/7/82 | ** | | N/A 2120 | 7L1 |
| 705 | Main Landing Gear Door Actuator Fitting | PA-31P | 6/30/81 | | | 3250 | 7L5 |
| 707 | PA-31-350 Chieftain Takeoff Flaps | PA-31-350 | 2/4/81 | 764-101 | | 2750 | 7L11 |
| 708 | PA-31 and PA-31-325 Takeoff Flaps (Refer to SB 697) | PA-31 PA-31-325 | 4/7/81 | 764-101 | | 2750 | 7L16 |
| 737 | Elevator Outboard Hinge Installation Inspection | PA-31P | 4/23/82 | 764-381 | | 5550 | 8B12 |
| 739 | Restriction of Flap Travel and Inspection of Wing Flap Flexible Drive Shaft | PA-31 PA-31-325 PA-31-350 PA-31P | 3/1/82 | ** | 82-27-13 | 2750 | 8D19 |
| 752 | Cigar Lighter Circuit Modification | PA-31P | 10/18/82 | 454-656 | | 3310 | 8G16 |
| 771A | Parking Brake Application | PA-31P | 9/6/2011 | 81090-002 | 85-02-05 | 1130 | |
| 779B | Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection | PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P | 10/12/87 | ** | 85-08-05 | 3200 | 8K1 |
| 797B | Fuel Port Restrictor Installation | PA-31, 31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P | 9/1/87 | ** | 87-21-01 | 2812 | 9B14 |
| 798 | "TURBO" Marking Removal | PA-31, 31-310 PA-31-325 PA-31-350 PA-31P | 12/11/84 | N/A | | 1110 | 9B19 |
| 802 | Aft Bulkhead (Fuselage Station 332 0) Inspection | PA-31P | 12/12/84 | 764-983 | 85-05-01 | 5310 | 9C10 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|----------|--------------------|
| 805A | TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration) | PA-31 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P | 3/14/86 | N/A | | 6110 9D15 |
| 822 | Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138) | PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P | 4/2/86 | 17766-02 | 96-21-04 | 2912 9H3 |
| 825 | Crossover Fuel Line Inspection | PA-31-300 PA-31-310 | 4/8/86 | | | 2823 9H14 |
| 826A | Elevator Hinge Inspection/Replacement | PA-31P | 9/22/86 | 45253 03 | | 5550 9H17 |
| 829 | Oil Separator Assembly Replacement | PA-31P-350 | 4/18/86 | 2564-02 | | 7250 9I9 |
| 836A | Aluminum Wire Inspection/Replacement | PA-31-300 PA-31-310 PA-31-325 PA-31-350 PA-31P | 8/26/86 | ** | | 2400 9J4 |
| 845A | Main Landing Gear Forward Side Brace Inspection/Replacement | PA-31/PA-310/325 PA-31-350 T1020 PA-31P PA-31P-350 | 10/9/87 | | 88-05-05 | 3218 9K16 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 10A7 |
| 859 | Nose Gear Shuttle Valve Bracket Installation | T-1020 | 3/30/87 | 765-315 | | 3225 10A18 |
| 860 | Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement | PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P | 4/14/87 | ** | | 3210 10A20 |
| 884 | Lock Wiring of V-Band Couplings | PA-31 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350 | 4/8/88 | ** | | 7800 10G20 2100 |
| 897B | Elevator Butt Rib Refinement | PA-31P | 7/15/97 | ** | | 5520 10I21 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------|-------------|
| 907 | Windshield Heat Fuse Installation | PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 | 4/11/89 | ** | | 3047 10K15 |
| 923 | Main Landing Gear Actuator Reinforcement Bracket Replacement | PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350 | 8/16/89 | 73786-02 | 96-21-11 | 5740 10aB13 |
| 926A | Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs | PA-31 PA-31-325 PA-31-350 PA-31P-350 | 3/7/94 | ** | 94-17-13 | 6113 10aC1 |
| 927 | Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs | PA-31-300 | 12/4/89 | ** | 2001-23-08 | 6113 10aC18 |
| 967 | Aileron Hinge Inspection and Replacement | PA-31P | 1/24/94 | ** | 96-21-03 | 5750 10aK15 |
| 974 | Aileron Hinge Inspection and Replacement | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31P-350 | 10/19/94 | ** | 96-21-03 | 5750 10bA1 |
| 991A | Replacement or Modification of the Alternator Out Light Fuse | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P | 1/29/96 | ** | | 2437 10bD16 |
| 998A | Elevator Spar Inspection | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P-350 | 8/4/97 | ** | 99-12-05 | 2730 10bDF1 |
| 1002 | Elevator Down Spring Inspection /Replacement | PA-31P | 6/5/97 | ** | 98-08-18 | 2739 10bF17 |
| 1003 | Wing Spar Splice Plate Replacement | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 | 6/16/97 | ** | 98-09-25 | 5711 10bF20 |
| 1004 | Inspection of the E303 Electrical Connector and Heater Blower Power Wire | PA-31-350 PA-31-350 T 1020 | 6/6/97 | ** | | 2451 10bF22 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------|------------|-------------|
| 1007 | Horizontal Stabilizer Spar and Outboard Hinge Inspection and Modification | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350 | 9/30/97 | 766-646 | 99-06-01 | 5511 10bG13 |
| 1008 | Elevator Butt Rib Refinement | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350 | 9/30/97 | 766-642 | | 5521 10bG15 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 | 11/5/98 | 753-910 | | 3711 10bJ20 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3" | PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 3/22/2007 | ** | 2003-14-03 | 7311 10bL16 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 9/25/2000 | ** | | 3714 10cB1 |
| 1045 | Forward Wing Spar Attach Bracket Inspection | PA-31 PA-31-300 | 9/18/2000 | ** | | 5741 10cB23 |
| 1105A | Rudder Torque Tube Assembly Inspection | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 9/22/2003 | 767-349 | | 2725 10dA22 |
| 1125 | Elevator Trim Wheel Replacement | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 4/15/2003 | 43751-000 | | 2733 10dE11 |
| 1134 | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105) | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 6/10/2003 | ** | | 2800 10dG5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--|------------|-------------|
| 1174 | Lock Assembly Inspection / Modification (Cabin Door, Baggage Doors, Nacelle Locker Door) | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 2/15/2007 | 473-146 88406-002 | | 5200 10eA13 |
| 1194B | Nose Baggage Door Components, Periodic Replacement of | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 4/12/2012 | ** | 2009-13-06 | 5230 |
| 1233C | Periodic Replacement of Main Landing Gear Rod Ends | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 6/15/2023 | 762-554 758-440 | | 3210 |
| 1246 | Emergency Exit Window Inspection | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 | 10/29/2012 | 41307-000 41307-003 53181-000 453-694 | | 5220 |
| 1257A | Fuel Hose Inspection | PA-31-350 PA-31-350 T-1020 | 8/4/2015 | 39995-034 LW-18302 | | 7310 |
| 1260A | Front Spar Attachment Bulkhead Inspection | PA-31-350 PA-31-350 T-1020 | 5/12/2020 | 88614-701 44758-000 44758-001 | | 5312 |
| 1266 | Fuel Warning Placard and POH Inspection | PA-31 PA-31-300 PA-31P | 12/16/2014 | ** | 2015-24-05 | 1130 |
| 1273C | Bulkhead Modification at FS 317.75 | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 | 11/9/2022 | 764-028 | 2016-05-01 | 5300 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-31-300 | 10/30/2015 | N/A | | 7310 |
| 1289A | Bulkhead Inspection, Fuselage Station 332.00 | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 | 10/26/2016 | 88578-001 | | 5312 |
| 1295 | Nose Baggage Door Lock Inspection | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 3/24/2017 | 88409-002 | 2009-13-06 | 5230 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1301 | Wiring Inspection | PA-31P-350 | 1/6/2017 | N/A | | 2497 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------|------------------|--------------------|----------|--|
| 440 | Refinement Modifications, Cheyenne | PA-31T | 12/17/74 | ** | | 2750 5A9 6110 3420 2150 6140 |
| 446A | Cable Replacement, Rudder/Nose Gear Steering | PA-31T | 7/8/75 | 760-923 | 75-16-02 | 2720 5A23 3250 |
| 453A | Scoop Modification, Engine Air Inlet | PA-31T | 4/7/75 | 760-942 | | 7160 5B18 |
| 456A | Warning Placard Replacement | PA-31T | 5/28/75 | ** | | 2840 5B24 |
| 459 | Servo Cable Clamp Replacement, Aileron And Rudder, M-4D Automatic Flight Control System | PA-31T | 4/22/75 | 33078-03 | | 2210 5C6 |
| 465 | Fuel Vent Line, Inspection of | PA-31T | 5/21/75 | | | 2810 5C20 |
| 466 | Air Conditioning System Modification | PA-31T | 6/2/75 | 760-979 | | 2150 5C22 |
| 468 | Elevator Trim Tab Attachment Hinges And Screw Assembly, Inspection of | PA-31T | 5/9/75 | ** | | 5550 5D2 |
| 476 | Elevator Trim Control Cable Turnbuckles, Inspection of | PA-31T | 10/9/75 | 454-867 | | 2730 5E4 |
| 477A | Elevator Control Tube And Trim Tab System Modification | PA-31T | 11/3/75 | 760-989 | 76-03-01 | 2730 5E6 |
| 481A | Elevator Assembly Inspection And Elevator Butt Rib Replacement | PA-31T | 11/3/75 | ** | 76-03-01 | 5520 5E14 |
| 484 | Starter Generator System Modification | PA-31T | 12/5/75 | 761-019 | | 8010 5E24 |
| 487 | Control Shaft Collar Attachment Modification | PA-31T | 11/7/75 | 401-264 407-584 | 76-04-11 | 2710 5F7 |
| 488 | Landing Gear Selector Cable Forward Attachment Pin, Modification of | PA-31T | 10/24/75 | ** | 96-24-13 | 3200 5F10 |
| 494B | Flap Control System, Inspection of | PA-31T | 7/17/79 | ** | 82-27-13 | 2750 5G6 |
| 504 | Elevator Hinge System Modification | PA-31T | 6/1/76 | 761-056 | 76-18-06 | 5550 5H8 |
| 511A | Oxygen System Outlet Refinement | PA-31T | 9/24/76 | 761-032 752-583 | | 3510 5I3 |
| 515 | Control Cable Ball Joint Retainer Installation | PA-31T | 1/17/77 | 55447-02 | | 7610 5I10 |
| 517 | Engine Oil Temperature Gauge Placard Installation | PA-31T | 10/5/76 | 757-487 | | 7930 5I17 |
| 523 | Cigar Lighter Element Replacement, 24 Volt | PA-31T | 10/8/76 | 55674-02 | | 3310 5J7 |
| 525 | Seat Latch Mechanism Modification, Pilot/Copilot | PA-31T | 11/15/76 | 55842-02 | | 5340 5J12 |
| 526A | Microphone And Phone Jack Relay Modification, Pilot/Copilot | PA-31T | 11/30/76 | 48757-02 | 77-08-02 | 2350 5J15 |
| 546 | Whelen Wing Tip Lights, Reference FAA Airworthiness Directive, Inspection of | PA-31T | 5/18/77 | ** | | 3340 6A16 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-------------------|------------------|--------------------|----------|-----------|
| 558 | Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D | PA-31T | 6/10/77 | | | 2210 6C1 |
| 560 | Flap Condition, Asymmetric, Recommended Operating Procedure | PA-31T | 4/4/77 | ** | | 2750 6C5 |
| 562 | Annunciator Panel Oil Temperature Indicator System Modification | PA-31T | 10/4/77 | ** | | 3310 6C10 |
| 568 | Nose Wheel Replacement (High Flotation Tire Option) | PA-31T | 4/26/77 | 45520-07 | | 3240 6E1 |
| 570A | Inspection of Main Landing Gear Actuating Cylinder Rod End Bearing Assy. | PA-31T | 8/30/78 | 762-554 | 78-02-01 | 3230 6E3 |
| 572 | Pilot's Operating Manual/Pilot's Operating Handbook Revision | PA-31T | 6/9/77 | ** | | 800 6E12 |
| 585 | Air Control Cable Stand-off Installation | PA-31T | 3/9/78 | 763-821 | | 2130 6F22 |
| 588 | Pilot's Operating Manual (POM) / Pilot's Operating Handbook (POH) Revision, Flap Selector Operation | PA-31T | 11/24/78 | ** | | 2750 6G7 |
| 589B | Inspection of Turn And Bank Suction System Check Value/ Vacuum System Modification | PA-31T | 9/25/79 | ** | | 3420 6G8 |
| 591 | Inspection of Goodyear BTC-39 Fuel Cells | PA-31T | 3/22/78 | ** | | 2810 6G13 |
| 594A | Modification of Left And Right Circuit Protector Mounting Board Installation | PA-31T/31T1 | 7/7/78 | 763-873 | | 3910 6H2 |
| 598A | Inspection of Main Landing Gear Brake Discs (Cleveland) | PA-31T | 6/13/78 | 754-618 754-626 | | 3240 6H12 |
| 599A | Replacement of Cleveland High Flotation Nose Wheel Assembly | PA-31T PA-31T1 | 10/4/78 | 551-782 | | 3240 6H14 |
| 604A | Forward Baggage Door Locking System Modification | PA-31T | 6/8/79 | ** | | 5230 6I4 |
| 629 | Landing Gear Hose Assembly Inspection And Replacement | PA-31T PA-31T1 | 11/15/78 | 17766-27 | | 3230 6L10 |
| 630A | Collins VIR-305 And VIR-351 Navigation Receiver Modification | PA-31T PA-31T1 | 2/25/80 | | | 3410 6L14 |
| 640 | Electroluminescent Panel Inverter Replacement And/Or Relocation | PA-31T PA-31T1 | 6/22/79 | 763-929 763-944 | 79-19-09 | 3910 7B20 |
| 647A | Outboard Flap Track Inspection and Modification | PA-31T PA-31T1 | 11/24/80 | 763-986 | 81-23-06 | 2750 7C19 |
| 651 | Control Shaft Roll Pin Inspection | PA-31T PA-31T1 | 5/11/79 | 480-732 | 79-14-02 | 2710 7D6 |
| 658 | Elevator Inspection And Reinforcement | PA-31T PA-31T1 | 7/31/79 | 763-943 | 80-02-15 | 2730 7E5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|------------------------------|------------------|---------------------|--------------------|---------------------|
| 659 | Rudder And Aileron Trim Tab Attachment Inspection | PA-31T PA-31T1 | 7/19/79 | 406-829 | | 2710 2720 7E7 |
| 660 | Gyro Inverter Power Selector Switch Guard Installation | PA-31T1 | 9/26/79 | 29321-02 | | 3940 7E9 |
| 665A | Throttle Control Ball Joint Connector and Rod End | PA-31T PA-31T1 | 5/30/80 | ** | | 7320 7E23 |
| 674 | Rudder Trim Mechanism Modification And Trim Tab Rigging | PA-31T PA-31T1 | 1/23/80 | ** | | 2720 7G13 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 7H4 |
| 680 | Ground Clearance Switch Fuse Installation | PA-31T PA-31T1 | 4/23/80 | ** | | 3450 7H7 |
| 682 | Main Landing Gear Inboard Door Hinge Inspection/Replacement | PA-31T PA-31T1 | 7/24/80 | ** | -25-01 80-26-05 | 3210 7H15 |
| 692 | Oxygen Mask Replacement | PA-31T | 8/6/80 | 474-108 | | 3510 7J14 |
| 704 | Cabin Fan Fuse Installation | PA-31T2 PA-42 | 6/7/82 | ** | | 2120 7L1 |
| 705 | Main Landing Gear Door Actuator Fitting | PA-31T PA-31T1 | 6/30/81 | | | 3250 7L5 |
| 715A | Elevator Control Tube Inspection | PA-31T PA-31T1 PA-31T2 | 4/25/83 | ** | | 2730 8A15 |
| 722 | Avionics Cooling Fan Inspection/Replacement | PA-31T PA-31T1 | 4/16/82 | 764-375 | | 2300 8B14 |
| 726 | Razor Inverter Wiring Inspection | PA-42 | 7/21/81 | | | 3320 8C11 |
| 727 | Powerplant Firewall Inspection | PA-42 | 7/21/81 | 411-583 404-559 | | 5410 8C13 |
| 728 | Hydraulic Pump Replacement | PA-42 | 9/17/82 | ** | | 2910 8C15 |
| 731 | Heater Air Distribution Box Thermal Switch Installation | PA-31T PA-31T1 | 3/17/82 | 764-227 764-228 | | 2140 8C21 |
| 733 | Emergency Exit Window Installation | PA-31T PA-31T1 PA-31T2 | 1/25/82 | 189-743 | 82-11-04 | 5630 8D3 |
| 734 | Fuel Scavenge Pump Check Valves Relocation | PA-31T PA-31T1 PA-31T2 | 12/11/81 | | | 2820 8D6 |
| 736 | Nacelle Fuel Tank Check Valve Installation | PA-42 | 12/17/82 | 492-233 57761-06 | | 2820 8D10 |
| 740 | Ice Vane and Control Circuit Breaker Replacement | PA-42 | 4/15/83 | 454-722 | | 3020 8E18 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------------|-----------------|----------|
| 741 | Part I - Wing Flap Travel Restriction and Inspection of Wing Flap Flexible Drive Shaft | PA-31T | 3/1/82 | ** | | 2750 |
| 741 | Part II - Wing Flap Operating Procedures | PA-31T PA-31T1 | 3/1/82 | ** | | 2750 |
| 742 | Engine Oil Hose and Fitting Replacement | PA-42 | 10/12/82 | 764-407 | | 7920 |
| 754 | Air Conditioning Condenser Fan Impeller Replacement | PA-31T PA-31T1 | 2/14/83 | 460-102 506-501 | | 2100 |
| 764 | Pilot's Side Window Inspection | PA-42 | 7/27/83 | ** | | 5610 |
| 765 | Rivet Installation/Replacement, Tail Fin Fuselage | PA-42 | 7/11/83 | ** | | 5530 |
| 766A | Main Landing Gear Slotted Up Lock Hook Brackets Replacement | PA-31T2 PA-31T3 | 8/15/2017 | 40616 | | 3210 |
| 767 | Cleveland 40-106 Main Landing Gear Wheels Replacement | PA-31T PA-31T1 | 10/25/83 | 551-775 | | 3240 |
| 768A | Main Landing Gear Pivot Shaft Assy Bolts Inspection/Replacement | PA-42 PA-42-720 PA-42-1000 | 5/24/85 | ** | | 3210 |
| 773A | Bulkhead (Fuselage Station 332.0) Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 | 5/3/84 | ** | 96-10-13 | 5310 |
| 776A | Part I - Fuel Quantity Placards Replacement | PA-31T/T1 PA-31T2 | 2/16/88 | ** | | 1100 |
| 776A | Part II-Weight And Balance Plotter Replacement | PA-31T/T1 PA-31T2 | 2/16/88 | ** | | 1100 |
| 777 | Fuel Quantity Placards | PA-42 | 3/19/84 | ** | | 1100 |
| 778 | Aileron Trim Tab Control Tube & Rudder Cable Retainer Hardware Inspection | PA-42 | 4/24/84 | ** | | 2700 |
| 779B | Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection | PA-31T/T1 PA-31T2/T3 PA-42 | 10/12/87 | ** | 85-08-05 N/A | 3200 |
| 779B | Part II - Landing Gear Upper Bearing And Strut Assembly Inspection | PA-42 | 10/12/87 | ** | | 3200 |
| 785 | Inline Fuel Filter Mod - Janitrol | PA-42 PA-42-720 | 7/19/84 | ** | | 7312 |
| 788 | Avionics (Copilot) Bus Lead Hardware Replacement | PA-42 PA-42-720 | 7/19/84 | ** | | 2457 |
| 795A | Electrical Connector Improvement | PA-31T/T1 PA-31T2 | 4/29/85 | ** | | 2430 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|-----------|
| 806 | Revision of Airspeed Markings Due To Position Error Change | PA-42-720 | 7/1/85 | 765-181 | | 3412 9E1 |
| 807 | Flow Strip Position Inspection | PA-42 PA-42-720 | 6/19/85 | N/A | | 5721 9E4 |
| 812 | Rudder Stop Inspection And Replacement | PA-42-1000 | 11/4/85 | 75695-05 | | 2720 9F11 |
| 814 | Generator Control Unit Sleeve Installation | PA-42-1000 | 3/14/86 | 765-190 | | 2430 9F18 |
| 816C | Ignition Select Mode During Approach and Landing | PA-42-1000 | 3/28/89 | 765-306 | 86-21-10 | 7428 9G1 |
| 817D | Main Landing Gear Forward Side Brace Inspection/Replacement | PA-42-1000 | 1/15/2015 | ** | | 3218 |
| 821A | Special Inspection of Fuel Quantity Probes | PA-31T/PA-31T1 PA-31T2/PA-31T3 | 5/14/86 | ** | | 2842 9G23 |
| 822 | Special Inspection of Hydraulic Hose, Piper Part Number 17766-02 (465-138) | PA-31T/T1/T2 PA-31T3 PA-42 PA-42-720 | 4/2/86 | 17766-02 | 96-21-04 | 2912 9H3 |
| 823 | Engine Control Cables Modification | PA-42-1000 | 3/19/86 | 765-195 | | 7324 9H6 |
| 826A | Elevator Hinge Inspection/Replacement | PA-31T/31T1 PA-31T2/31T3 | 9/22/86 | 45253-03 | | 5550 9H17 |
| 831 | Ice Deflector Vane Modification | PA-31T1 PA-31T3 | 4/18/86 | 765-156 | | 7250 9I16 |
| 835 | Wing - Nose Rib, Station 0.50, Modification And Wire Harness Inspection | PA-42-1000 | 5/15/86 | 765-305 | | 5712 9J1 |
| 836A | Aluminum Wire Inspection/Replacement | PA-31T/T1 | 8/26/86 | ** | | 2400 9J4 |
| 838 | Fuel Vent System Installation-Wing Panel Modification | PA-42-1000 | 6/23/86 | 765-192 | | 2814 9J11 |
| 841A | Main Landing Gear, Forward Side Brace Inspection/Replacement | PA-31T3 PA-42 PA-42-720/720R | 10/8/87 | ** | | 3218 9J19 |
| 842 | Rudder Trailing Edge Rework | PA-42-1000 | 6/23/86 | 765-200 | | 5523 9K1 |
| 843 | Part I - Garrett Service Bulletin No TPE331-72-7029 | PA-42-1000 | 3/27/87 | ** | | 7201 9K4 |
| 843 | Part II - Starter/Generator Bracket Retrofit Installation | PA-42-1000 | 3/27/87 | ** | | 7201 9K4 |
| 844 | Stick Pusher Relay Box Modification | PA-42-1000 | 7/28/86 | 765-307 | | 2201 9K12 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|--|------------------|--------------------|----------|----------|-------|
| 845A | Main Landing Gear Forward Side Brace Inspection/Replacement | PA-31T/31T1 PA-31T2 | 10/9/87 | ** | 96-10-14 | 3218 | 9K16 |
| 846A | Wing Tip Tank Vent Line Assembly Inspection (Piper Part Number 75389-02) | PA-42-1000 | 9/19/86 | ** | 86-18-10 | 2813 | 9K21 |
| 849 | Improved Brake Piston/Insulator And Pressurized Brake Reservoir Installation | PA-42-1000 | 10/8/86 | ** | | 3243 | 9L5 |
| 850 | Part I - Garrett Service Bulletin No. TPE331-75-7001 | PA-42-1000 | 10/8/86 | ** | | 7120 | 9L7 |
| 850 | Part II - Left Engine Mount Inspection | PA-42-1000 | 10/8/86 | ** | | 7120 | 9L7 |
| 857 | Tailcone Drain Holes, Fuselage Station 332.00 | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 3/10/87 | N/A | | 5305 | 10A12 |
| 859 | Nose Gear Shuttle Valve Bracket Installation | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 3/30/87 | 765-315 | | 3225 | 10A18 |
| 860 | Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement | PA-31T/31T1/31T2 PA-31T3 PA-42 | 4/14/87 | ** | | 3210 | 10A20 |
| 867 | Fuel Quantity Sensor Replacement | PA-42-1000 | 6/24/87 | 765-335 | | 2840 | 10C1 |
| 869 | Fire Extinguisher Annunciator Circuit Modification | PA-42 PA-42-720 PA-42-1000 | 9/9/87 | ** | | 2600 | 10C5 |
| 870 | Lear Siegler Power Equipment Corporation (LSPEC) Service Information Letter No. 23090-004-01 | PA-42-1000 | 9/25/87 | ** | | 2400 | 10C7 |
| 873 | Part I - Engine Mount Inspection And Barrel Nut Replacement | PA-42-1000 | 12/22/87 | ** | | 7100 | 10D13 |
| 873 | Part II - Engine Inlet Inspection And Modification | PA-42-1000 | 12/22/87 | ** | | 7100 | 10D14 |
| 874 | Nacelle Rework | PA-42-1000 | 2/8/88 | 765-320 765-334 | | 5410 | 10E4 |
| 877 | Control Column Chain Inspection | PA-42-720 PA-42-720R PA-42-1000 | 1/6/88 | 472-684 | | 2702 | 10F19 |
| 881B | TPE 331-14 Engine Idler Gear Bearing Replacement | PA-42-1000 | 2/19/88 | ** | | 7261 | 10G10 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|----------------------|----------|--------------------|
| 882 | Outboard Flap Transmission Clearance Inspection/Modification | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 3/8/88 | 89140-02 89141-02 | | 2758 10G14 |
| 884 | Lock Wiring of V-Band Couplings | PA-31T/31T1 PA-31T2/31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 4/8/88 | ** | | 7800 10G20 2100 |
| 885 | Main Landing Gear Actuator Attach Bolt | PA-42-1000 | 5/4/88 | ** | | 3213 10H1 |
| 887 | Elevator Skin/Stringer Inspection/Modification | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 6/29/88 | ** | | 2730 10H10 |
| 888 | Rudder Pedal Torque Tube Attach Bracket Modification | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 7/12/88 | ** | | 2721 10H13 |
| 889 | Main Landing Gear Uplock Hook Bracket Inspection and Roller Modification | PA-31T1 | 7/1/88 | 41413-79 | | 3230 10H17 |
| 897B | Elevator Butt Rib Refinement | PA-31T/31T1 PA-31T2 | 7/15/97 | ** | | 5520 10I21 |
| 911 | Tip Tank Tailcone Attachment Improvement | PA-42-1000 | 5/30/89 | 765-379 | | 5722 10L9 |
| 912 | Rework of Plug - Main Landing Gear Oleo Tube | PA-42-1000 | 6/9/89 | ** | | 3212 10L11 |
| 914 | Bleed Air Hose Replacement | PA-42 PA-42-720 PA-42-720R | 7/12/89 | ** | | 2181 10aA1 |
| 922 | Main Landing Gear Actuator Attach Bracket Replacement | PA-42 PA-42-720 PA-42-720R | 8/16/89 | 765-372 | | 5740 10aB11 |
| 923 | Main Landing Gear Actuator Reinforcement Bracket Replacement | PA-31T PA-31T1/31T2 PA-31T3 | 8/16/89 | 73786-02 | 96-21-11 | 5740 10aB13 |
| 925 | Addition of Check Valve To Motive Flow Supply Line | PA-42 PA-42-720 PA-42-720R | 11/13/89 | ** | | 2823 10aB20 |
| 929A | Main Landing Gear Upper Strut Housing Inspection | PA-42-1000 | 8/9/94 | 75215-04 | | 3211 10aD3 |
| 931 | Elevator Trim Wheel Shaft Roll Pin Safety Wire Installation | PA-42-720 PA-42-720R PA-42-1000 | 1/9/90 | ** | | 2733 10aD13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------|----------|-------------|
| 945 | Cheyenne Rudder Torque Tube Assembly | PA-42 PA-42-720 PA-42-720R PA-42-1000 | 10/19/90 | ** | | 5541 10aG8 |
| 954 | Instrument Static Line Installation | PA-31T/31T1 PA-31T2//31T3 | 3/3/92 | ** | | 3410 10aH20 |
| 957 | Engine Fuel Pump Overboard Drain Line Installation | PA-42 PA-42-720 PA-42-720R | 2/24/92 | 766-257 | | 2820 10aI9 |
| 967 | Aileron Hinge Inspection and Replacement | PA-31T PA-31T1 PA-31T2 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 1/24/94 | ** | 96-21-03 | 5750 10aK15 |
| 969A | Upper Main Gear Housing Inspection and Replacement | PA-42 PA-42-720 PA-42-720R | 5/19/2022 | 57680-09 | | 3211 |
| 972 | Emergency Exit Window Inspection and Replacement | PA-42-1000 | 9/21/94 | ** | | 5620 10aL10 |
| 974 | Aileron Hinge Inspection and Replacement | PA-31T3 | 10/19/94 | ** | 96-21-03 | 5750 10bA1 |
| 984 | Inspection and Replacement of Outer Side Windows | PA-42 PA-42-720 PA-42-720R | 7/14/95 | ** | | 5750 10bC10 |
| 1032 | Elevator Spar Refinement | PA-31T PA-31T1 PA-31T2 | 7/15/99 | 766-655 | | 2730 10bL6 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 9/25/2000 | ** | | 3714 10cB1 |
| 1047 | Elevator Spar Refinement | PA-31T3 (T1040) | 12/4/2000 | 766-655 | | 2730 10cC6 |
| 1048 | Stainless Steel Control Cables | PA-42 PA-42-720 PA-42-1000 | 1/3/2001 | N/A | | 2702 10cC9 |
| 1105A | Rudder Torque Tube Assembly Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 | 9/22/2003 | 767-349 | | 2725 10dA22 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|----------------------|------------|-------------|
| 1125 | Elevator Trim Wheel Replacement | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 4/15/2003 | 43751-000 | | 2733 10dE11 |
| 1128 | Engine Fuel Valve Inspection (Honeywell OIL OI331-19) | PA-42-1000 | 2/21/2003 | N/A | | 2800 10dE24 |
| 1174 | Lock Assembly Inspection / Modification (Cabin Door, Baggage Doors, Nacelle Locker Door) | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 2/15/2007 | 473-146 88406-002 | | 5200 10eA13 |
| 1194B | Nose Baggage Door Components, Periodic Replacement of | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000 | 4/12/2012 | ** | 2009-13-06 | 5230 |
| 1233C | Periodic Replacement of Main Landing Gear Rod Ends | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000 | 6/15/2023 | 762-554 758-440 | | 3210 |
| 1235 | Data Plate Inspection | PA-31T PA-31T1 | 11/3/2011 | N/A | | 1120 |
| 1248 | Engine Oil Cooler Inlet Hose Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 | 9/5/2012 | 565-484 565-936 | | 7900 |
| 1295 | Nose Baggage Door Lock Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000 | 3/24/2017 | 88409-002 | 2009-13-06 | 5230 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1301 | Wiring Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 | 1/6/2017 | N/A | | 2497 |
| 1380 | Structural Rework and Inspection | PA-42-1000 | 1/3/2024 | See SB | | 5100 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1
PA-31T2/31T3
PA-42

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | DATE | PART/KIT NO. | A.D. NO. | ATA CODE | GRID |
|--------|---------|--------------------|------|-----------------|-------------|-------------|------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB64

SERVICE BULLETIN INDEX

PA-32 SERIES

| NUMBER | SUBJECT | MODELS AFFECTED | DATE | PART/KIT NO. | A.D. NO. | ATA CODE | GRID |
|--------|--|---|-----------|----------------------|----------------------|----------|------|
| 233 | Brake Disc Assembly, Inspection of | PA-32-260 | 6/8/66 | 757-039V | | 3240 | 3E2 |
| 237 | Rudder Trim Installation Modification | PA-32-260 | 11/1/66 | 757-085V | | 2720 | 3E9 |
| 239 | Windshield Collars, Inner And Outer, Replacement of | PA-32-260 | 12/12/66 | 757-095 | | 5610 | 3E11 |
| 240 | Balance Weight Assembly Aileron And Stabilator, Inspection of, For Corrosion | PA-32-260 | 12/13/66 | | 67-12-06 | 2710 | 3E12 |
| 244 | Heater Duct Tunnel Modification Cabin | PA-32-260/300 | 2/2/67 | 757-110V | | 2140 | 3E19 |
| 248 | Torque Links, Main Landing Gear | PA-32-260/300 | 5/12/67 | ** | 67-20-04 70-18-05 | 3210 | 3F2 |
| 249A | Fuel System Improvement Kit | PA-32-260/300 | 3/1/68 | 757-139V | 67-26-02 | 2800 | 3F6 |
| 251D | Fuel Tank Inspection | PA-32-260/300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T | 2/24/2009 | 757-572V | 67-26-03 | 2810 | 3F10 |
| 252 | Mixture Control Cable, Inspection of | PA-32-300 | 5/15/67 | 65451-05V | | 7320 | 3F12 |
| 253 | Fuel Line Modification, Tip Tank | PA-32-260/300 | 7/7/67 | 757-151V 757-152V | 67-26-02 | 2810 | 3F14 |
| 259 | Storm Window Placard, PA-32-260 Cherokee | PA-32-260 | 11/7/67 | 757-314V | | 5610 | 3G2 |
| 260 | Duct, Engine Air Inlet, Replacement of The | PA-32-300 | 11/8/67 | 760-159V | 67-30-06 | 7160 | 3G4 |
| 261 | Aft Spar Wing Attachment Bolts, Inspection of | PA-32-260/300 | 11/10/67 | 760-162V | | 5710 | 3G5 |
| 275 | Electrical System, Modification of The | PA-32-260/300 | 6/19/68 | ** | | 2400 | 3H8 |
| 279 | Bridle Cable, Servo. Inspection of And Modification To | PA-32 | 6/24/68 | ** | | 2210 | 3H16 |
| 281 | Artificial Horizon, R.C. Allen 3", Case Leakage of | PA-32-260/300 | 7/10/68 | ** | | 3420 | 3H24 |
| 282 | Mixture Control Cable, Replacement | PA-32-300 | 8/12/68 | 760-235V | | 7320 | 3I4 |
| 285 | Stop Assembly, Fuel Selector Control | PA-32-260 | 11/22/68 | 760-251V | | 2820 | 3I11 |
| 291 | Flight Manual Revision | PA-32S-300 PA-32-260/300 | 3/28/69 | 760-313V | | 3250 | 3J5 |
| 295 | Pin, Retaining, Control Wheel | PA-32-260 "B" PA-32-300 "B" | 4/30/69 | ** | 69-15-01 | 2700 | 3J14 |
| 305 | Carburetor Drain Plugs Inspection | PA-32-260 | 11/25/69 | | | 7310 | 3K12 |
| 311A | Selector Valve, Fuel, Modification | PA-32-260/300 PA-32S-300 | 4/28/70 | 760-438V | | 2820 | 3L3 |
| 317 | Rib Inspection, Vertical Fin | PA-32-260/300 | 11/18/70 | 760-451V | | 5530 | 3L14 |
| 321A | Throttle Knob Roll Pin Retaining Ring | PA-32-260/300 | 11/2/70 | 756-044V | | 7610 | 4A1 |
| 322 | Vacuum Pump Adapter Drive Assembly | PA-32-260/300 | 9/29/70 | 760-477V | | 3710 | 4A3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-----------------------------|------------------|--------------|----------|-----------|
| 327 | Stabilator Balance Weight Tube Assembly Inspection | PA-32-260/300 PA-32S-300 | 12/9/70 | ** | 70-26-04 | 2740 4A16 |
| 329A | Belt Attachment Modification, Seat | PA-32-260/300 PA-32S-300 | 3/25/71 | 760-515V | 71-09-05 | 5340 4A23 |
| 332 | Switch, Electric Trim, Inspection And Modification | PA-32-260/300 | 4/16/71 | 760-517V | 72-17-15 | 2730 4B7 |
| 337 | Seat Frame Tube Replacement, Vertically Adjustable | PA-32-260/300 | 3/11/71 | ** | | 2510 4B20 |
| 342 | Fuel System Instructions And Modification | PA-32-260/300 PA-32S-300 | 9/7/71 | 760-560V | 77-12-01 | 2800 4C6 |
| 350 | Stabilator Hinge Attaching Bolts, Inspection of | PA-32-260/300 | 3/30/72 | ** | | 5550 4D7 |
| 356 | Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement | PA-32-260/300 PA-32S-300 | 9/1/72 | ** | | 7160 4E7 |
| 357A | Terminal Replacement, Alternator Output Wire | PA-32-260/300 | 11/14/72 | 588-398V | | 2420 4E9 |
| 360 | Hose System Modification, Air Induction | PA-32-260/300 PA-32S-300 | 11/9/72 | ** | | 7160 4E14 |
| 368 | Antenna Protector, Transponder, Installation | PA-32-260/300 | 11/22/72 | 760-697V | | 3450 4F7 |
| 376 | Fuel Selector Control System Modification | PA-32-260/300 PA-32S-300 | 4/19/73 | ** | 77-12-01 | 2820 4F18 |
| 387 | Alternator Installation Modification | PA-32-260/300 | 2/4/74 | 760-742V | | 2430 4G15 |
| 395 | Rudder Pedal, Warning Improper Use of | PA-32-260/300 | 11/9/73 | 757-436V | | 2720 4H9 |
| 403 | Stall Warning Light Relocation | PA-32-260/300 | 1/29/74 | 760-808V | 74-09-02 | 2780 4I9 |
| 412 | Glove Compartment Modification | PA-32-260/300 | 4/9/74 | 581-025 | | 2510 4J12 |
| 427 | Air Conditioning System Modification | PA-32-300 | 8/9/74 | 760-822V | | 2150 4K23 |
| 428 | Steering System Modification | PA-32-260/300 | 7/30/74 | 760-885V | 74-18-13 | 3250 4L1 |
| 444 | Fuel Valve Replacement | PA-32-260/300 | 1/15/75 | 760-895V | | 2820 5A19 |
| 448 | Cable Operation Inspection, Throttle And Mixture Control | PA-32-260/300 | 2/19/75 | ** | | 7320 5B4 |
| 449A | Alternator (Chrysler) Modification And Wire End Terminal Replacement | PA-32-260/300 | 5/7/75 | 558-398V | | 2430 5B8 |
| 463 | Door Forward Baggage, Inspection And Modification | PA-32-260/300 | 4/17/75 | 760-972V | 75-10-03 | 5230 5C14 |
| 469A | Oil Cooler Assembly Inspection | PA-32-300 | 9/5/75 | ** | | 7920 5D4 |
| 475 | Instrument Panel Dimmer Control Assembly Modifications | PA-32-260/300 | 7/10/75 | | | 3310 5E1 |
| 503A | Fuel Tank Line Assembly, Inboard, Inspection of | PA-32R-300 | 10/11/77 | ** | 76-11-09 | 2810 5H5 |
| 510B | Landing Gear, Nose, Trunnion Modification | PA-32R-300 | 8/31/76 | 761-074V | 76-15-08 | 3220 5I1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------------------|------------------|----------------------|----------------------|-------------------|
| 519A | Fuel Selector Valve Inspection And Replacement | PA-32-260/300 PA-32R-300 | 9/2/76 | ** | 76-18-04 | 2820 5I21 |
| 520 | Muffler Shroud Inspection | PA-32-300 PA-32R-300 | 10/18/76 | ** | | 7810 5I23 |
| 524 | Induction Air Box Bolt Replacement | PA-32-300 PA-32R-300 | 2/2/77 | ** | | 7160 5J9 |
| 533 | Fuel Gauge Calibration Inspection | PA-32-260/300 | 1/6/77 | ** | 77-01-01 | 2840 5L8 |
| 537 | Throttle Linkage Bolt Replacement | PA-32-300 PA-32R-300 | 1/12/77 | ** | 80-14-02 | 7610 5L17 |
| 538 | Engine Control Cable Inspection | PA-32-260/300 PA-32R-300 | 1/14/77 | ** | | 7610 5L20 |
| 541 | Throttle Attachment Inspection | PA-32-260 | 2/15/77 | ** | | 7610 6A5 |
| 543 | Starter/Magneto Switch Inspection And Replacement | PA-32-260/300 PA-32R-300 | 2/9/77 | 757-597V | | 7410 6A9 |
| 548 | Engine Control Rod End Bearing Inspection | PA-32-260/300 PA-32R-300 | 3/7/77 | ** | 77-23-03 | 7230 6A23 |
| 556 | Electric Trim Switch Modification | PA-32-260/300 | 7/25/77 | 756-047 | | 2730 6B20 |
| 557 | Fuel Line Modification | PA-32-260 | 5/19/77 | 63882-17V | | 2810 6B23 |
| 563 | Landing Gear, Nose, Actuator Rod End Bearing Change | PA-32R-300 | 5/13/77 | 452-357V | | 3230 6C14 |
| 565 | Horizontal Situation Indicator, Modification To Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13 | PA-32-260/300 PA-32R-300 | 6/2/77 | ** | | 3420 6C20 |
| 571A | Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection | PA-32-260 PA-32-300 PA-32S-300 | 10/20/77 | ** | 77-12-01 | 2810 6E5 |
| 580 | Engine Cowling Scoop Drain Hole | PA-32-260 | 10/19/77 | | | 7100 6F13 |
| 586B | Engine Oil Coolers (Left and Right), Inspection | PA-32R-300 PA-32RT-300 | 7/24/78 | 763-859V | 78-01-03 78-16-08 | 7920 |
| 593 | Nose Landing Gear Lock Hook Replacement | PA-32R-300 | 6/9/78 | | | 3230 6H1 |
| 616 | Hydraulic Pressure Switch Inspection And Nose Gear Actuator Rod End Bearing Replacement | PA-32RT-300 PA-32RT-300T | 5/1/79 | | | 2930 3230 6J19 |
| 619 | Control Column Stop Modification | PA-32RT-300 PA-32RT-300T | 9/22/78 | 763-895V | 78-22-07 | 2710 6K4 |
| 622 | Pitch Trim Re-Wiring On Aircraft Equipped With Altimatic IIIC | PA-32-260/300 PA-32R-300 | 9/28/78 | 35669-60 35669-61 | | 2210 6K14 |
| 624 | Loading Limitation Placard And Manual Change | PA-32-260/300 PA-32S-300 | 5/24/79 | 763-911V | | 800 6K19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|--------------------|----------------------|----------|---------------------|
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T | 2/25/80 | | | 3450 6L14 |
| 646A | Fuel Tank Vent Modification And Vent Hose Replacement | PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T | 3/5/80 | ** | 80-14-01 | 2810 7C17 |
| 652 | Fuel Flow Indicator Line- Replacement | PA-32RT-300T | 6/15/79 | 67700-348 | 79-13-04 | 7330 7D9 |
| 655 | Firewall Reinforcement | PA-32RT-300T | 8/27/79 | 763-935V | | 5410 7D15 |
| 656 | Window Curtain Rod Support Area Inspection | PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T | 9/13/79 | ** | | 5520 7D17 |
| 657A | Turbo-Charger Exhaust Coupling And Tailpipe Flange Inspection | PA-32RT-300T | 8/14/79 | 556-108 | | 7810 7E1 |
| 669 | Altimatec IIC Autopilot Trim Servo Cable Alignment Modification | PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T | 1/14/80 | ** | | 2210 7F10 |
| 675 | Throttle Operation Pre-And Post-Flight Check | PA-32RT-300T PA-32R-301T | 2/19/80 | 67639-013V | | 7610 7G21 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 7H4 |
| 681 | Boom Microphone Isolation Relay | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 4/24/80 | 456-703 | 80-14-03 | 2350 7H11 |
| 701 | Rudder/Aileron Interconnect Bracket Interference | PA-32-301 PA-32-301T | 12/4/80 | 68525-08V 419-948 | | 2720 2710 7K16 |
| 703 | Aileron Balance Weight Attachment Inspection and Rework | PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T | 3/4/81 | 764-091V | | 2710 7K20 |
| 738 | Nose Landing Gear Actuator Rod End Replacement | PA-32R-300 PA-32R-301 SP PA-32R-301T SP PA-32RT-300 PA-32RT-300T | 4/20/82 4/20/82 | 452-729V 452-729V | | 3230 3230 8D14 8D15 |
| 738 | Addendum 1 - Nose Landing Gear Actuator Rod End Inspection / Replacement | PA-32R-300 PA-32R-301 SP PA-32R-301T SP PA-32RT-300 PA-32RT-300T | 11/23/87 | 452-729 | | 3230 8D15 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|---|------------------|-----------------------|------------------|--------------|-------|
| 747 | Nose Landing Gear Actuator Attach Bolt Replacement | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 9/17/82 | 86700-46V 402-869V | | 3230 | 8G3 |
| 772 | Fuel Selector Inspection/Replacement | PA-32R-300 PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T | 4/6/84 | 69735-05V | | 2820 | 8J3 |
| 789B | Aft Inboard Wing Access Panel & Aft Wing Spar Modification | PA-32-260 PA-32-300 | 12/3/2018 | 764-998V 765-106V | SAIB CE-11-12 | 5711 | |
| 798 | "TURBO" Marking Removal | PA-32RT-300T | 12/11/84 | N/A | | 1110 | 9B19 |
| 801 | King Auto Pilot Servo Bridle Clamp Installation | PA-32-301/301T PA-32R-301/301T | 12/11/84 | ** | | 2200 | 9C6 |
| 804 | Battery Strap Installation | PA-32-301T | 4/26/85 | 765-157 | | 2430 | 9D12 |
| 805A | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration) | PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T | 3/14/86 | N/A | | 6110 | 9D15 |
| 811A | Ammeter Replacement | PA-32-260 PA-32-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T | 5/12/86 | ** | 86-17-01 | 2430 | 9F4 |
| 836A | Aluminum Wire Inspection/Replacement | PA-32-301T | 8/26/86 | ** | | 2400 | 9J4 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 | 10A7 |
| 856 | Stabilator Attach Fitting Corrosion Inspection | PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32R-301/301T | 2/17/87 | ** | | 5550 | 10A9 |
| 866A | Part I - Back Up Landing Gear Extender Removal | PA-32R-300 PA-32RT-300/300T PA-32R-301/301T | 3/4/88 | 765-199 | | 3236 | 10B22 |
| 866A | Part II - Alternate means of Compliance | PA-32R-300 PA-32RT-300/300T PA-32R-301/301T | 3/4/88 | N/A | | 3236 | 10B22 |
| 884 | Lock Wiring of V-Band Couplings | PA-32-301T PA-32R-301T PA-32RT-300T | 4/8/88 | ** | | 7800 2100 | 10G20 |
| 886 | Wing Spar Inspection | PA-32-260/300 | 6/8/88 | ** | | 5711 | 10H3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------------|------------|-------------|
| 896 | Shoulder Harness Installation & Usage | PA-32-260/300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T | 11/28/88 | ** | | 5340 10I13 |
| 904 | Textron Lycoming Service Bulletin No. 484 | PA-32-301T PA-32RT-300T PA-32R-301T | 3/20/89 | ** | | 7821 10K1 |
| 906 | Oildyne Hydraulic Pump Replacement | PA-32R-301 PA-32R-301T | 4/10/89 | ** | | 2911 10K12 |
| 926A | Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs | PA-32-301T PA-32R-301T | 3/7/94 | ** | 94-17-13 | 6113 10aC1 |
| 927 | Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs | PA-32-300 PA-32S-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T | 12/4/89 | ** | 2001-23-08 | 6113 10aC18 |
| 933A | Trunnion Replacement | PA-32R-301 | 2/20/90 | 67054-03 | | 3222 10aD21 |
| 938 | Wire Protection | PA-32R-301 PA-32R-301T | 6/12/90 | 189-531 488-698 | | 3262 10aE15 |
| 946 | Forward Left Fuselage Frame Inspection and Replacement | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 3/4/91 | 766-244 | | 5311 10aG11 |
| 952 | Textron Lycoming Service Bulletin No. 499 "Installation of One-Piece Exhaust Pipe" | PA-32RT-300T PA-32-301T PA-32R-301T | 5/9/91 | ** | | 7821 10aH11 |
| 955 | Engine Mount and Nose Landing Gear Attachment | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 3/3/92 | 766-252 766-253 | 93-05-10 | 7120 10aH23 |
| 965 | Inspection of Flap Lever and Bolt | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 9/1/93 | ** | | 2750 10aJ22 |
| 968 | Exhaust System Hardware and Gasket Replacement | PA-32R-301 | 3/11/94 | ** | | 7810 10aK21 |
| 970 | Defrost System Modification | PA-32R-301 | 4/18/94 | ** | | 7810 10aL2 |
| 971 | Exhaust System Inspection and Replacement | PA-32R-301 | 9/2/94 | ** | | 7810 10aL5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|------------------------|------------------|-------------|
| 973 | Engine Lower Cowling Modification | PA-32R-301 | 9/30/94 | ** | | 7810 10aL19 |
| 977 | Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 12/12/94 | ** | SAIB CE-11-12 | 5740 10bA12 |
| 986 | Inspection for Proper Orientation of Battery Vent Tube Assembly | PA-32R-301 II HP | 9/6/95 | | | 2430 10bC22 |
| 990 | Pacific Scientific Seat Belt Replacement | PA-32R-301 II HP | 1/3/96 | ** | | 5346 10bD12 |
| 993 | KLN-90B GPS Wiring Modification | PA-32R-301 | 3/18/96 | ** | | 3441 10bE4 |
| 996 | Missing Rivet in Upper Door Frame, Forward and Aft | PA-32R-301 II HP | 9/17/96 | ** | | 5311 10bE16 |
| 1005 | Addition of Drain Holes to the Engine Induction Air Inlet Scoops | PA-32R-301 II HP | 8/11/97 | | | 7162 10BG4 |
| 1006A | Corrosion Inspection of Main Spar Behind Fuel Tanks | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T PA-32R-301T II TC | 9/25/24 | ** | SAIB CE-11-12 | 530 10bG4 |
| 1009 | Replacement of the Engine Induction Air Inlet Elbow at the Fuel Injector Servo | PA-32R-301 II HP | 10/6/97 | ** | | 7161 10bG18 |
| 1015A | Replacement of the Ammeter Shunt Wire Fuse Assemblies | PA-32R-301 II HP | 6/11/98 | 101166-10 101166-11 | | 2434 10bH14 |
| 1018A | Product Improvement, Winterization Plate Kit(Revised) | PA-32R-301T II TC | 6/7/99 | 766-653 | | 7921 10bI2 |
| 1020 | Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket | PA-32R-301 II HP PA-32R-301T II TC | 7/10/98 | 758-696 | | 2563 10bI11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------|-----------------|
| 1022 | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32R-301 SP PA-32R-301 II HP | 9/22/98 | 460-632 | 99-05-09 | 7167 10bI20 |
| 1023 | Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063 | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 10/8/98 | ** | | 2902 10bJ6 |
| 1024 | Replacement of Control System Spacers and Inspection of Aileron Cables | PA-32R-301 II HP PA-32R-301 II TC | 10/1/98 | ** | | 2712 10bJ12 |
| 1025 | Replacement of the Alternate Air Door | PA-32R-301T II TC | 10/21/98 | ** | | 7164 10bJ16 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 11/5/98 | 753-910 | | 3711 10bJ20 |
| 1028 | Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips | PA-32R-301 II HP PA-32R-301T II TC | 12/2/98 | ** | | 5755 10bK12 |
| 1030A | Distribution of Textron Lycoming Service Bulletin 538A, "Air Inlet tube Replacement" and Drain Improvement | PA-32R-301T II TC | 9/10/99 | ** | | 7168 10bK21 |
| 1031 | Horizon Engine Instruments Repair or Replacement | PA-32R-301 II HP PA-32R-301T II TC | 7/14/99 | ** | | 7710/7720 10bL3 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529B, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3" | PA-32-301T PA-32R-301T SP PA-32R-301T II TC PA-32RT-300T | 3/22/2007 | ** | 2003-14-03 | 7311 10bL16 |
| 1036 | Garmin Service Bulletin No. 9905 'GNS430 Mod. 1" | PA-32R-301 II HP PA-32R-301T II TC | 10/1/99 | | | 3426 10cA1 |
| 1039 | Manifold Pressure Gauge (MAP) Wiring Modification | PA-32R-301 II HP PA-32R-301T II TC | 2/14/2000 | | | 7715 10cA15 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------------------------------|----------|-------------|
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-32-260 PA-32-300/-32S-300 PA-32-301 PA-32-301T PA-32RT-300 PA-32RT-300T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 9/25/2000 | ** | | 3714 10cB1 |
| 1048 | Stainless Steel Control Cables | PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC | 1/3/2001 | N/A | | 2702 10cC9 |
| 1049 | Engine Baffle Brace Installation | PA-32R-301 II HP PA-32R-301T II TC | 4/9/2001 | 766-684 | | 7236 10cC13 |
| 1081A | Horizon Aerospace Analog Instrument Pointer Calibration | PA-32R-301 II HP PA-32R-301T II TC | 12/9/2002 | N/A | | 7700 10cl12 |
| 1083C | S-TEC System 55X Autopilot | PA-32R-301 II HP PA-32R-301T II TC | 5/30/2002 | 767-318 | | 2218 10cl19 |
| 1092B | Engine Mount Inspection | PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC | 4/28/2003 | 38729-021 38729-022 104642-002 | | 7121 10cK22 |
| 1131A | Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004) | PA-32-260 | 1/18/2016 | 65489-002 65490-000 | | 3210 |
| 1134 | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105) | PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 6/10/2003 | ** | | 2800 10dG5 |
| 1135 | GMA-340 Audio Panel Wiring | PA-32R-301 II HP PA-32R-301T II TC | 7/16/2003 | N/A | | 2370 10dG13 |
| 1137 | Stabilator Balance Weight Tube Assembly | PA-32R-301 II HP PA-32R-301T II TC | 11/6/2003 | N/A | | 2749 10dG20 |
| 1139A | Control Wheel Attachment Inspection | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 4/9/2004 | ** | 4-14-12 | 2701 10dH4 |
| 1141 | Clip Nut Replacement | PA-32R-301 II HP PA-32R-301T II TC | 12/9/2003 | 477-640 | | 5351 10dH15 |
| 1145A | Autopilot Installation and Testing | PA-32-301FT PA-32-301XTC | 2/17/2004 | 600-520 692-411 | | 2210 10dl4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|-------------------------------|------------|-------------|
| 1151E | 4130N Steel Hardness Discrepancy | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 6/9/2004 | ** | | 5741 10dJ4 |
| 1161D | Rib Assembly Inspection and Modification - Aft Wing, WS 49.25 | PA-32R-300 PA-32RT-300/300T PA-32R-301 SP PA-32R-301T Turbo SP PA-32R-301 II HP PA-32R-301T II TC | 2/19/2024 | 767-397 767-398 | | 5712 10dK19 |
| 1162B | European Requirements for Avidyne Entegra Equipped PA-28 and PA-32 Model Aircraft | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 9/7/2006 | 652-591 767-418 767-422 | | 3400 10dL1 |
| 1169A | Tailcone Pressure Duct Support Strap | PA-32-301FT PA-32-301XTC | 1/17/2007 | 767-547 | | 2100 10dL22 |
| 1171 | Stormscope Erroneous Strike Indication | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 9/20/2006 | 767-548 | | 3400 10eA3 |
| 1178 | Nose Gear Forging Inspection / Replacement | PA-32R-301 II HP PA-32R-301T II TC | 9/24/2007 | 67050-002 | | 3222 10eB10 |
| 1179 | Main Landing Gear Cylinder Assembly Inspection | PA-32-301FT PA-32-301XTC | 2/1/2008 | 65490-000 | | 3213 10eB14 |
| 1180A | V-Band Exhaust Coupling Inspection | PA-32R-301T II TC | 3/14/2007 | ** | | 7200 10eB18 |
| 1187 | Voltage Suppressor Replacement | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 2/8/2008 | 88432-002 (Kit) | | 3400 10eD4 |
| 1197E | Control Wheel Shaft Inspection | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32S-300 | 11/2/2017 | ** | 2010-15-10 | 2710 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|------------------------|------------|----------|
| 1198A | Fuel Selector O-Ring | PA-32-260 PA-32-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 4/20/2009 | 485-330 485-332 | | 2823 |
| 1199 | Main Landing Gear Torque Link Inspection | PA-32-260 PA-32-300 | 2/16/2009 | 78033-000 63312-002 | 72-08-06 | 3213 |
| 1216B | Aileron Rib Inspection | PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 9/5/2012 | 38650-007 38650-008 | | 5755 |
| 1242A | Rudder Pedal Assembly Inspection | PA-32-260 PA-32(S)-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 5/12/2020 | 99938-000 99938-001 | | 2710 |
| 1244C | Aft Wing Attach Fitting Inspection Requirements | PA-32 Series PA-32R Series PA-32RT Series PA-32S Series | 12/3/2018 | 764-998 | | 5740 |
| 1245A | Stabilator Control System Inspection | PA-32 Series PA-32R Series PA-32RT Series PA-32S Series | 11/28/2012 | N/A | 2013-02-03 | 2730 |
| 1247B | Garmin SafeTaxi® Limitation | PA-32-301FT PA-32R-301T II TC | 3/13/2019 | N/A | | 3420 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|------------------|----------|----------|
| 1251 | Stabilator Trim Barrel Inspection | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32S-300 | 4/10/2013 | 63530-000 | | 5755 |
| 1280A | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1 | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 4/29/2016 | 459-887 | | 2620 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-32-300 PA-32-301 PA-32-301FT PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32RT-300 | 10/30/2015 | N/A | | 7310 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1304B | Main Wing Spar Inspection | PA-32-260 PA-32-300 | 12/2/2021 | 765-106 88692 | | 5740 |
| 1342A | Stabilator Fitting Inspection | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 11/2/2021 | 62645-004 | | 5510 |
| 1355B | Tee Bar Assembly Inspection | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T | 8/18/2022 | 28F40A003 | | 2701 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|------------------|----------|----------|
| 1366 | Main Wing Spar Hardware Inspection | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T PA-32S-300 | 5/14/21 | 96352 | | 5711 |
| 1372A | Main Wing Spar Inspection | PA-32-260/300 PA-32S-300 | 12/11/2024 | 88731-701 / -702 | Pending | 5711 |
| 1375D | Periodic Replacement of Main Landing Gear Attachment Hardware | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC | 1/29/2023 | ** | | 3210 |
| 1377B | Main Wing Spar Inspection at the Landing Gear Truss Bracket | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC | 9/24/2024 | | | 5740 |
| 1412 | Main Wing Spar Inspection | PA-32-300 PA-32-301FT PA-32-301XTC PA-32-301/-301T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T | 5/9/2024 | | | 5711 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------|------------------|------------------------|----------|-----------|
| 251D | Fuel Tank Inspection | PA-34-200 | 2/24/2009 | 757-572V | | 2810 3F10 |
| 350 | Stabilator Hinge Attaching Bolts Inspection of | PA-34-200 | 3/30/72 | ** | | 5550 4D7 |
| 352 | Pitot Static System Lines Replacement | PA-34-200 | 6/13/72 | 760-614V 760-615V | | 3030 4D12 |
| 357A | Terminal Replacement, Alternator Output Wire | PA-34-200 | 11/14/72 | 588-398V | | 2420 4E9 |
| 358 | Induction Air Box Valve Inspection | PA-34-200 | 7/31/72 | 96776-00V | 72-17-01 | 7160 4E11 |
| 359 | Pitot Static System Instrument Lines Modification | PA-34-200 | 10/10/72 | 760-679V | | 3410 4E13 |
| 364A | Circuit Breaker Replacement, Fuel Pump, Electric | PA-34-200 | 11/16/72 | 454-707 | | 2820 4F1 |
| 367 | Stabilator Tip Balance Weight Inspection | PA-34-200 | 8/25/72 | ** | 72-18-06 | 2740 4F5 |
| 368 | Antenna Protector, Transponder Installation | PA-34-200 | 11/22/72 | 760-697V | | 3450 4F7 |
| 369 | Wing Assembly, Aft, Inspection and Modification of | PA-34-200 | 9/8/72 | 760-696V | 73-11-02 | 5110 4F8 |
| 370 | Fuel Injector Servo Mounting Nut Inspection | PA-34-200 | 9/12/72 | | | 7310 4F10 |
| 373A | Exhaust System Inspection | PA-34-200 | 6/12/73 | ** | 73-14-02 | 7810 4F12 |
| 374 | Induction Air Box Replacement | PA-34-200 | 2/2/73 | 760-722V | 72-17-01 | 7160 4F14 |
| 382 | Fuel Tank Vent Systems, Inspection | PA-34-200 | 8/22/73 | | | 2810 4G2 |
| 390A | Trim Tab, Rudder Servo, Inspection | PA-34-200 | 5/30/73 | ** | 73-13-01 | 2210 4G20 |
| 395 | Rudder Pedal, Warning, Improper Use of | PA-34-200 | 11/9/73 | 757-436 | | 2720 4H9 |
| 406 | Oleo Struts, Main Landing Gear, Inspection and Maintenance of | PA-34-200 | 11/16/73 | ** | 73-11-02 | 3210 4I15 |
| 412 | Glove Compartment Modification | PA-34-200 | 4/9/74 | 581-025 | | 2510 4J12 |
| 429 | Fuel Line Chafing—Engine Nacelles, Prevention of | PA-34-200 | 8/12/74 | 760-877V 760-886V | 74-17-08 | 2810 4L3 |
| 437A | Spar Straps, Inspection of Seneca | PA-34-200 | 10/16/75 | | | 5710 5A1 |
| 438 | Fuel Quantity, Revised Usable | PA-34-200/200T | 8/6/75 | ** | 75-20-03 | 2840 5A6 |
| 447 | Baggage Door Inspection and Modification to the Forward | PA-34-200/200T | 2/7/75 | | | 5230 5B1 |
| 475 | Instrument Panel Dimmer Control Assembly Modification | PA-34-200/200T | 7/10/75 | | | 3310 5E1 |
| 483 | Turbocharger Oil Hose Modification, Seneca II | PA-34-200T | 11/12/75 | 761-023V | 75-25-03 | 8010 5E23 |
| 491 | Pneumatic Deicer Tubing Inspection | PA-34-200T | 2/19/76 | 761-018V | | 3700 5F16 |
| 502A | Heated Lift Detector Inspection | PA-34-200T | 7/1/76 | 69669-156V 472-890V | | 3260 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-------------------------|---------------------|--------------------|-------------|-------------------|
| 542 | Induction Air Box Filter Locator Change | PA-34-200T | 2/25/77 | 761-130V | | 7160 6A7 |
| 545 | Fuselage Rivets, Inspection and Installation | PA-34-200/200T | 2/23/77 | 522-898 | | 5330 6A13 |
| 548 | Engine Control Rod End Bearing Inspection | PA-34-200/200T | 3/7/77 | 452-557 | 77-23-03 | 7230 6A23 |
| 553 | Avionics Bus Bar Inspection and Modification | PA-34-200/200T | 4/15/77 | 761-133V | | 2450 6B13 |
| 555 | Rudder Cable Guard Inspection, Seneca II | PA-34-200T | 3/9/77 | 62701-72V | | 2720 6B17 |
| 565 | Horizontal Situation Indicator Modification to Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13 | PA-34-200T | 6/2/77 | ** | | 3420 6C20 |
| 576 | TCM TS10360 Series Engines To Disseminate Information | PA-34-200T | 11/30/77 | | | 7200 6E23 |
| 579 | Inspection of Vertical Fin and Stabilator Attachment Fittings | PA-34-200/200T | 11/14/77 | ** | 80-09-04 | 5550 6F5 |
| 584 | Engine Instruments and Fuel Flow Line Inspection and Modification | PA-34-200T | 12/13/77 | ** | | 7330 6F20 7700 |
| 596A | Fuel Line Inspection and Modification | PA-34-200T | 9/22/78 | ** | 78-21-03 | 2810 6H6 |
| 601 | Inspection of Battery Box Vent | PA-34-200T | 8/11/78 | | 78-21-03 | 2430 6H20 |
| 602 | Inspection of the Main Wing Spar Attaching Nuts | PA-34-200T | 7/3/78 | 404-532V | | 5750 6I1 |
| 611 | Hose Assembly Inspection and Replacement | PA-34-200T | 11/14/78 | ** | | 2820 6J5 |
| 630A | Collins VIR-350 and VIR-351 Navigation Receiver Modification | PA-34-200T | 2/25/80 | | | 3450 6L14 |
| 633B | Forward Baggage Door Inspection and Modification | PA-34-200 PA-34-200T | 10/3/80 | 36521-02V | 88-04-05 | 5230 7A10 |
| 656 | Window Curtain Rod Support Area Inspection | PA-34-200T | 9/13/79 | ** | | 5520 7D17 |
| 668 | Avionics Master Relay Wiring Inspection | PA-34-200T | 11/12/79 | | | 2450 7F6 |
| 669 | Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification | PA-34-200T | 1/14/80 | ** | | 2210 7F10 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15 0 7H4 |
| 681 | Boom Microphone Isolation Relay | PA-34-200T | 4/24/80 | 456-703 180-500 | 80-14-03 | 2350 7H11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--|------------------|------------------------|----------|--------------|-------|
| 711 | Missing Rivets, Left Hand Fuselage Station 108 | PA-34-220T | 3/27/81 | ** | | 5330 | 8A3 |
| 712A | Fuel Selector Valve Inspection and Cable Clevis Replacement | PA-34-220T | 4/20/81 | 491-960V 764-121V | | 2820 | 8A7 |
| 718A | Seneca III Surface Deicer System | PA-34-220T | 10/29/81 | 764-222V | | 3000 | 8B1 |
| 732 | Landing Gear Selector Switch Shield | PA-34-220T | 11/11/81 | 87431-02V 488-702V | 82-04-08 | 3200 | 8C23 |
| 758 | Radio Master Relay Replacement | PA-34-220T | 2/14/83 | | | 2450 | 8H10 |
| 762 | Exhaust System Heat Exchanger Inspection | PA-34-200 | 5/26/83 | 78463-10V 78463-18V | 83-14-05 | 7810 | 8H21 |
| 787C | Main Landing Gear Trunnion Housing | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T IV | 11/7/2000 | 2599-002 | 94-13-11 | 3211 | 8L8 |
| 798 | "TURBO" Marking Removal | PA-34-200T | 12/11/84 | N/A | | 1110 | 9B19 |
| 801 | King A/P Servo Bridle Clamp Installation | PA-34-220T | 12/11/84 | ** | | 2200 | 9C6 |
| 805A | TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration) | PA-34-200 PA-34-200T PA-34-220T | 3/14/86 | N/A | | 6110 | 9D15 |
| 811A | Ammeter Replacement | PA-34-200T | 5/12/86 | ** | 86-17-01 | 2430 | 9F4 |
| 836A | Aluminum Wire Inspection/Replacement | PA-34-200 PA-34-200T PA-34-220T | 8/26/86 | ** | | 2400 | 9J4 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 | 10A7 |
| 856 | Stabilator Attach Fitting Corrosion Inspection | PA-34-200 PA-34-200T PA-34-220T | 2/17/87 | ** | | 5550 | 10A9 |
| 872 | Forward Baggage Compartment Door Latch Spring Installation And Door Assembly Inspection | PA-34-200 PA-34-200T PA-34-220T | 11/9/87 | 765-330 | 88-04-05 | 5230 | 10D5 |
| 884 | Lock Wiring of V Band Couplings | PA-34-200T PA-34-220T | 4/8/88 | ** | | 7800 2100 | 10G20 |
| 893 | Nose Gear Centering Attach Belt | PA-34-200 PA-34-200T | 10/11/88 | 400-910 | 92-13-05 | 3220 | 10I3 |
| 896 | Shoulder Harness Installation & Usage | PA-34-200 PA-34-200T PA-34-220T | 11/28/88 | ** | | 5340 | 10I13 |
| 899 | Rudder Torque Tube Fitting Replacement | PA-34-200 PA-34-200T PA-34-220T | 2/10/89 | ** | 92-08-04 | 2720 | 10J8 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------------|------------------|-------------|
| 905 | Auxiliary Primer Switch Replacement | PA-34-200T PA-34-220T | 4/6/89 | ** | | 7315 10K7 |
| 906 | Oildyne Hydraulic Pump Replacement | PA-34-200T PA-34-220T | 4/10/89 | ** | | 2911 10K12 |
| 938 | Wire Protection | PA-34-220T | 6/12/90 | 189-531 488-698 | | 3262 10aE1 |
| 956 | Main Landing Gear Trunnion Attach Fittings | PA-34-200 PA-34-200T PA-34-220T | 3/3/92 | ** | | 3211 10aH10 |
| 965 | Inspection of Flap Lever and Bolt | PA-34-200 PA-34-200T PA-34-220T | 9/1/93 | ** | 96-10-03 | 2750 10aJ3 |
| 976 | Inspection for and Replacement of Components with Suspect "O" Rings | PA-34-220T | 12/9/94 | ** | | 2911 10bA10 |
| 977 | Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels | PA-34-200 PA-34-200T PA-34-220T | 12/12/94 | ** | SAIB CE-11-12 | 5740 10bA12 |
| 983 | Station 49.5 Frame Inspection | PA-34-220T | 5/25/95 | ** | | 5310 10bC4 |
| 987 | Prop Deice Timer Wiring Inspection | PA-34-220T III PA-34-220T IV | 9/11/95 | ** | | 3000 10bD1 |
| 988 | Pneumatic Deice Switch Relocation | PA-34-220T III PA-34-220T III (28V) PA-34-220T IV | 11/9/95 | 558-790 179-771 | | 3013 10bD4 |
| 989 | Inspection for Stabilator Trim Screw Assembly Attachment Hardware | PA-34-220T IV | 12/20/95 | ** | | 2791 10bD8 |
| 990 | Pacific Scientific Seat Belt Replacement | PA-34-220T IV | 1/3/96 | ** | | 5346 10bD12 |
| 993 | KLN-90B GPS Wiring Modification | PA-34-220T IV | 3/18/96 | ** | | 3441 10bE4 |
| 996 | Missing Rivet in Upper Door Frame, Forward and Aft | PA-34-220T (IV) | 9/12/96 | ** | | 5311 10bE16 |
| 1005 | Addition of Drain Holes to the Engine Induction Air Inlet Scoops | PA-34-220T (V) | 8/11/97 | | | 7162 10bG1 |
| 1010 | Replacement of Fuel Selector Levers | PA-34-220T V | 11/3/97 | 766-645 | | 2822 10bG21 |
| 1013 | Replacement of Crankcase Breather System | PA-34-220T V | 2/5/98 | ** | | 7925 10bH6 |
| 1014 | Replacement of Battery Power Fuse | PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 3/2/98 | 461-681 | | 2436 10bH11 |
| 1017 | Alternator Regulator Wiring Diagram | PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 4/10/98 | ** | | 2436 10bH21 |
| 1020 | Inspection of the Artex 110-4 ELT and ELT Attachment Bracket | PA-34-220T IV PA-34-220T V | 7/10/98 | ** | | 2563 10bI11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|------------------------|----------|--------------------|
| 1022 | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 9/22/98 | 460-632 | 99-05-09 | 7167 10bI20 |
| 1023 | Inspection of Landing Gear Cylinder and Distribution of Parker Hannifin Service Bulletin SB7063 | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 10/8/98 | ** | | 2902 10bJ6 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-34-200 PA-34-200T PA-34-220T III(28V) PA-34-220T IV | 11/5/98 | 753-910 | | 3711 10bJ20 |
| 1031 | Horizon Engine Instruments Repair or Replacement | PA-34-220T V | 7/14/99 | ** | | 7710 10bL3 7720 |
| 1039 | Manifold Pressure Gauge (MAP) Wiring Modification | PA-34-220T V | 2/14/2000 | | | 7715 10cA15 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 9/25/2000 | ** | | 3714 10cB1 |
| 1042 | Heated Deice Panel Inspection | PA-34-220T V | 6/9/2000 | 31637-003 | | 3041 10cB10 |
| 1043 | Deice Control Valve Replacement | PA-34-220T V | 7/13/2000 | ** | | 3014 10cB15 |
| 1048 | Stainless Steel Control Cables | PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 1/3/2001 | N/A | | 2702 10cC9 |
| 1081A | Horizon Aerospace Analog Instrument Pointer Calibration | PA-34-220T V | 12/9/2002 | N/A | | 7700 10cI12 |
| 1083C | S-TEC System 55X Autopilot | PA-34-220T V | 5/30/2002 | 767-319 | | 2218 10cI19 |
| 1097A | Pneumatic Deicer Deflate Valve Assembly Replacement | PA-34-220T V | 2/25/2002 | 592-676 | | 3010 10cL16 |
| 1100A | Stabilator Trim Link Assembly | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 10/31/2001 | 96003-000 | | 5511 10cL12 |
| 1113 | Nose Gear Down Lock Pin Inspection | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 6/5/2002 | 95829-000 95830-000 | | 3235 10dC3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--|--------------------------|-------------|
| 1123D | Nose Gear Inspection and Product Improvements | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 1/26/2022 | 767-357 767-358 767-359 767-368 693-215 95394-005 | 2005-13-16 2022-09-13 | 3220 |
| 1127B | Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110b) | PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 4/18/2005 | 767-367 ** | 3-11-14 | 2800 10dE16 |
| 1130 | Vertical Fin Contour / Rivet Check | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 11/11/2003 | 767-369 | | 5300 10dF8 |
| 1134 | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105) | PA-34-200 | 6/10/2003 | ** | | 2800 10dG5 |
| 1135 | GMA-340 Audio Panel Wiring | PA-34-220T V | 7/16/2003 | N/A | | 2370 10dG13 |
| 1136 | Auxiliary Fuel Pump Switch | PA-34-200T | 9/2/2003 | 588-006 (99377-029) | | 2800 10dG17 |
| 1137 | Stabilator Balance Weight Tube Assembly | PA-34-220T V | 11/6/2003 | N/A | | 2749 10dG20 |
| 1139A | Control Wheel Attachment Inspection | PA-34-220T V | 4/9/2004 | ** | 4-14-12 | 2701 10dH4 |
| 1141 | Clip Nut Replacement | PA-34-220T V | 12/9/2003 | 477-640 | | 5351 10dH15 |
| 1146 | Vertical Fin Aft Spar Reinforcing Angle Low Edge Distance Inspection | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 11/5/2004 | ** | | 5300 10dI10 |
| 1151E | 4130N Steel Hardness Discrepancy | PA-34-220T V | 6/9/2004 | N/A | | 5741 10dJ4 |
| 1157A | Pressurized Magnetos & Tachometer Sensor Assemblies; Field Upgrade | PA-34-220T V | 6/20/2005 | ** | | 7414 10dK1 |
| 1161D | Rib Assembly Inspection and Modification - Aft Wing, WS 49.25 | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 2/19/2024 | 767-397 767-398 | | 5712 10dK19 |
| 1184 | Inspection of Engine Mount for Evidence of Contact with Oil Line Fitting | PA-34-220T V | 6/15/2007 | 37105-000 | | 7120 10eC12 |
| 1187 | Voltage Suppressor Replacement | PA-34-220T V | 2/8/2008 | 88432-002 (Kit) | | 3400 10eD4 |
| 1197E | Control Wheel Shaft Inspection | PA-34-200 PA-34-200T PA-34-220T III | 11/2/2017 | ** | 2010-15-10 | 2710 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|------------------------|------------|----------|
| | | PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | | | | |
| 1223 | Wire Screen Replacement | PA-34-220T V | 11/10/2010 | ** | | 2126 |
| 1225 | Inaudible Traffic Information System (TIS) or Traffic Advisory System (TAS) Aural Alerts | PA-34-220T V | 7/26/2011 | N/A | | 3440 |
| 1241 | Wastegate Clearance Inspection | PA-34-220T V | 5/10/2012 | ** | | 7120 |
| 1242A | Rudder Pedal Assembly Inspection | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 5/12/2020 | 99938-000 99938-001 | | 2710 |
| 1244C | Aft Wing Attach Fitting Inspection Requirements | PA-34 Series | 12/3/2018 | 764-998 | | 5740 |
| 1245A | Stabilator Control System Inspection | PA-34 Series | 11/28/2012 | N/A | 2013-02-03 | 2730 |
| 1247B | Garmin SafeTaxi® Limitation | PA-34-220T V | 3/13/2019 | N/A | | 3420 |
| 1252 | Garmin G600 Systems Software Upgrade to Version 0942.40 | PA-34-220T V | 10/2/2013 | N/A | | 3420 |
| 1254 | Stabilator Drain Hole Inspection | PA-34-220T V | 1/14/2013 | N/A | | 5755 |
| 1270A | Re-enablement of GDL 69, GSR 56, and/or GTS 825 for EASA Importation | PA-34-220T V | 6/4/2014 | N/A | | 3420 |
| 1274 | Control Wheel Bushing Inspection | PA-34-220T V | 2/9/2015 | 68273-002 | | 2701 |
| 1280A | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1 | PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 4/29/2016 | 459-887 | | 2620 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-34-200 | 4/12/2019 | N/A | | 7414 |
| 1285 | Propeller Deice Timer Inspection | PA-34-220T IV PA-34-220T V | 8/14/2015 | N/A | | 3060 |
| 1286A | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-34-200 | 10/30/2015 | N/A | | 7310 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|---------------------|--|-------------|-------------|
| 1303A | Diode Module Installation | PA-34-220T V | 10/15/2018 | 681-020 | | 3410 |
| 1337 | Emergency Power Supply Modification | PA-34-220T V | 2/15/2019 | 107279-002 | 2020-24-09 | 2497 |
| 1355B | Tee Bar Assembly Inspection | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 8/18/2022 | 28F40A003 | | 2701 |
| 1366 | Main Wing Spar Hardware Inspection | PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 5/14/2021 | 96352 | | 5711 |
| 1368 | Heater Fuel Pump Leak Inspection and Replacement (Hartzell ASB 85) | PA-34-220T III (28V) PA-34-220T IV PA-34-220T V | 7/14/2021 | ** | | 2140 |
| 1377B | Main Wing Spar Inspection at the Landing Gear Truss Bracket | PA-34-200 PA-34-200T II PA-34-220T III PA-34-220T IV PA-34-220T V | 9/24/2024 | | | 5740 |
| 1402 | Airworthiness Directive 2021-08-15 | PA-34-220T V | 7/2/2024 | | 2021-08-15 | 3445 |
| 1411A | Autopilot Rigging Inspection | PA-34-220T V | 12/4/2023 | | | 2700 |
| 1413 | Aft Wing Spar Attach Fitting Inspection | PA-34-220T V | 4/18/2024 | 66762-000 62448-002/-003 68621-002/-003 88365-002 / 87584-000 | | 5741 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|----------------------------|---------------------|--------------------|-------------|-----------------------------------|
| 396 | Propeller Stop, Low Pitch | PA-36-285 | 1/29/74 | | | 6110 4H11 |
| 397 | Fuel Quantity Placards, Revised | PA-36-285 | 5/2/74 | ** | 74-13-07 | 2840 4H12 |
| 402 | Starter Shaft Inspection Tiara (Continental Aircraft Engine Service Bulletin #M73-20) | PA-36-285 | 10/5/73 | ** | | 8010 4I4 |
| 418 | Lift Detector Relocation And Modification | PA-36-285 | 8/13/74 | 760-843V | 74-21-02 | 2700 4K1 |
| 425 | Wing Spar Center Section Bolts, Replacement of | PA-36-285 | 6/14/74 | 760-871V | 74-14-06 | 5750 4K18 |
| 439 | Flap Control System, Modification of The | PA-36-285 | 12/27/74 | 760-903V | 75-01-02 | 2750 5A8 |
| 467 | Spray Pump Windmill Assembly Modification | PA-36-285 | 10/29/75 | ** | | 910 5C24 |
| 471A | Wing Attachment Fittings, Forward And Aft, Inspection And Modification | PA-36-285 | 7/16/76 | ** | 77-02-06 | 5750 5D15 |
| 472 | Main Spar Center Section Carry Through Assembly Modification of | PA-36-285 | 6/6/75 | 760-978 | | 5310 5D18 |
| 482 | Control Stick Torque Tube Inspection of | PA-36-285 | 10/22/75 | ** | | 7610 5E21 |
| 489 | Muffler Clamp Installation | PA-36-285 | 3/12/76 | 761-017 | | 7810 5F13 |
| 490 | Safety Harness Installation Modification | PA-36-285 | 6/30/76 | 761-022 761-057 | | 5340 5F14 |
| 495B | Rudder Control Horn Attachment Bolts, Inspection of | PA-36-285/300 PA-36-375 | 7/13/81 | ** | 76-05-07 | 2720 5G11 |
| 499 | Induction Air Filter Cover Assembly | PA-36-285 | 3/18/76 | | | 7160 5G20 |
| 501 | Wing Main Spar Lower Bolt Replacement | PA-36-285 | 4/27/76 | 761-058 | 76-25-02 | 5750 5H1 |
| 505 | Precautionary Operating Placard Installation | PA-36-285 | 4/29/76 | 98000-62 | | 1130 5H10 |
| 506 | Tail Structure Modification | PA-36-285 | 8/23/76 | 761-034 761-067 | 77-04-02 | 3270 5H12 |
| 508 | Fuel Tank Vents, Inspection of | PA-36-285 | 6/15/76 | | | 2810 5H19 |
| 513 | Engine Air Induction System Modification | PA-36-285 | 7/15/76 | 761-053 | | 7160 5I6 |
| 516 | Control Rod End Bearing | PA-36-285 | 1/20/77 | 761-095 | | 7200 2140 2730 2710 5I13 |
| 518 | Rudder Spar Hinge Inspection | PA-36-285 | 2/22/77 | 98125-04 | 77-21-03 | 5550 5I19 |
| 539 | Fuel Quantity Gauge Inspection | PA-36-285 | 1/27/77 | 76784-02 | | 2840 5L23 |
| 546 | Whelen Wing Tip Strobe Lights Reference FAA Airworthiness Directive, Inspection of | PA-36-285/300 | 5/18/77 | ** | | 3340 6A16 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-------------------------------------|------------------|--------------|------------|-----------|
| 552A | Wing Spar Carry Through Assembly Inspection | PA-36-285 PA-36-300 | 8/3/2018 | ** | 2021-11-16 | 5700 |
| 583 | Voltage Regulator/Over Voltage Relay Rewiring | PA-36-300 | 10/31/77 | ** | | 2430 |
| 587 | Exhaust Stack Modification | PA-36-300 | 2/6/78 | ** | | 7810 |
| 608A | Inspection/Replacement of Elevator And Aileron System Control Rod End Bearings | PA-36-285/300 PA-36-375 | 9/29/78 | ** | 78-26-05 | 2710 |
| 615 | Inspection of Engine Mount And Modification If Required | PA-36-285 | 9/21/78 | 763-887 | 79-12-09 | 7120 |
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-36-300 PA-36-375 | 2/25/80 | | | 3450 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 |
| 713 | Fuel Cell Inspection | PA-36-285/300 | 5/11/81 | 97989-00 | | 2810 |
| | and Servicing | PA-36-375 | | 97989-01 | | |
| 729 | Rudder Cable and Seat Belt Attachment Shackle Inspection | PA-36-285/300 PA-36-375 | 9/22/81 | 486-566 | | 2720 |
| 744 | Wing Spar and Wing Spar Carry-Through Assembly and Components Replacement | PA-36-285/300 PA-36-375 | 5/12/82 | ** | | 5710 |
| 771A | Parking Brake Application | PA-36-285/300/375 | 9/6/2011 | 81090-002 | 85-02-05 | 1130 |
| 797B | Fuel Port Restrictor Installation | PA-36-285/300 PA-36-375 | 9/1/87 | 566-502 | | 2812 |
| 805A | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration) | PA-36-285/300 PA-36-375 | 3/14/86 | N/A | | 6110 |
| 828 | Fuselage Tubing Crack Inspection | PA-36-300 PA-36-375 | 4/7/86 | ** | 92-15-15 | 5345 |
| 836A | Aluminum Wire Inspection/Replacement | PA-36-285/300 PA-36-375 | 8/26/86 | ** | | 2400 |
| 855 | Use of Automobile Gasoline In Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 |
| 926A | Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs | PA-36-285 PA-36-300 PA-36-375 | 3/7/94 | ** | | 6113 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529A, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2" | PA-36-375 | 3/22/2007 | ** | | 7311 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-36-285 PA-36-300 PA-36-375 | 9/25/2000 | ** | | 3714 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

PA-36

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|---------------------|-----------------|-------------|-------------|
| 1286 | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement | PA-36-285/300 | 9/22/2015 | N/A | | 7310 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB89

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SB90

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|--------------------|---------------------|--------------------|-------------|--------------|------|
| 600A | Aft Fuselage/Tail Cone Area Rivet Replacement | PA-38-112 | 4/28/78 | | | 5350 | 6H16 |
| 603 | Fuel Gauges And Instrument Cluster Grounding Harness Installation | PA-38-112 | 7/25/78 | ** | 79-17-05 | 2840 3310 | 6I2 |
| 607A | Part I - Inspect And Attain Clearance Between The Rudder Leading Edge And The Vertical Fin Trailing Edge | PA-38-112 | 6/2/78 | | | | 6I13 |
| 607A | Part II - Install Straps To Maintain Clearance Between Rudder Leading Edge And Vertical Fin Trailing Edge | PA-38-112 | 6/2/78 | | | 2730 | 6I14 |
| 607A | Part III - Inspect And Attain Clearance Between Elevator Leading Edge And Stabilizer Trailing Edge | PA-38-112 | 6/2/78 | 763-872 | | 2720 | 6I15 |
| 609A | Pilot And Copilot Control Wheel Replacement Modification | PA-38-112 | 7/31/78 | ** | | 2700 | 6I23 |
| 610 | Gascolator Fuel Line Installation Inspection | PA-38-112 | 7/18/78 | 462-049 | | 7310 | 6J2 |
| 613A | Installation of Bearing Retention Plates On Bottom Rudder Hinge Bracket Assembly | PA-38-112 | 1/11/80 | 763-881 | 79-03-02 | 5550 | 6J12 |
| 614 | Inspection of Throttle And Mixture Control Placards For Proper Placement | PA-38-112 | 8/11/78 | ** | | 7610 7320 | 6J14 |
| 617B | Engine Mount Inspection/ Replacement | PA-38-112 | 1/30/81 | ** | 81-23-07 | 7120 | 6J22 |
| 618 | Inspection of Left And Right Wing Rear Spar Attach Fittings | PA-38-112 | 9/5/78 | ** | | 5110 | 6K1 |
| 620 | Tomahawk Magneto Replacement | PA-38-112 | 10/26/78 | ** | | 7410 | 6K6 |
| 628A | Inspection of Vertical Fin Forward Spar Attachment Plate | PA-38-112 | 11/8/78 | 77553-05 | | 5530 | 6L7 |
| 630A | Collins VIR-350 And VIR-351 Navigation Receiver Modification | PA-38-112 | 2/25/80 | | | 3450 | 6L14 |
| 637 | Part I - Inspection of Upper Forward Vertical Fin Spar Attach Fitting | PA-38-112 | 12/29/78 | 77615-07 | 79-08-02 | 5510 | 7B5 |
| 637 | Part II - Inspection of Vertical Fin/Fuselage And Horizontal Tail/Vertical Fin Spar Attach Fitting Bolt | PA-38-112 | 12/29/78 | | 79-08-02 | 5510 | 7B7 |
| 661 | Control Column Installation Modification | PA-38-112 | 8/22/79 | | 85-11-06 | 2700 | 7E12 |
| 673B | Replacement of Main Landing Gear Attachment Clamp, Bolts, And Barrel Nuts | PA-38-112 | 10/2/86 | 765-171 765-172 | 90-19-03 | 3210 | 7G11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|------------------------------|---------------------|-----------------|----------------------|--------------|-------|
| 676 | Nose Gear Strut Modification | PA-38-112 | 6/5/80 | 764-007 | | 3220 | 7H1 |
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 | 7H4 |
| 686 | Upper Rudder Hinge Bracket Replacement | PA-38-112 | 5/23/80 | ** | 98-03-16 80-22-13 | 5550 | 7I20 |
| 709 | Aileron Torque Tube Bearing Inspection | PA-38-112 | 7/13/81 | ** | | 2710 | 7L21 |
| 710 | Vertical Fin Forward Spar Attachment Plate Replacement Life Limits | PA-38-112 | 10/10/82 | ** | 82-27-08 | 5530 | 8A1 |
| 723 | Aileron Balance Weight Rib Inspection/Reinforcement | PA-38-112 | 8/19/81 | ** | 82-02-01 | 2710 | 8B18 |
| 745 | Part I - Forward Fin Spar Inspection Piper Part No. 77601-03 | PA-38-112 | 10/10/82 | 764-427 | 82-27-08 | 5510 | 8F19 |
| 745 | Part II-Fuselage Bulkhead Assembly Inspection, Piper Part No. 77553-02 | PA-38-112 | 10/10/82 | 77553-06 | 82-27-08 | 5310 | 8F20 |
| 745 | Part III - Fin Spar Attachment Plate Replacement Piper Part No. 77553-05 | PA-38-112 | 10/10/82 | 77553-05 | 82-27-08 | 5510 | 8F20 |
| 745 | Part IV-Aft Vertical Fin Spar Inspection, Piper Part No. 77601-02 | PA-38-112 | 10/10/82 | ** | 82-27-08 | 5510 | 8F21 |
| 748 | Radio Support Installation | PA-38-112 | 8/4/82 | 477-673 | | 2320 | 8G6 |
| 760 | Throttle Cable Inspection Replacement of Jam Nut | PA-38-112 | 4/16/84 | 2458-02 | | 7610 | 8H15 |
| 763A | Upper Forward and Aft Vertical Fin Spar Inspection and Reinforcement | PA-38-112 | 7/25/83 | 764-965 | 83-19-01 | 5530 | 8I1 |
| 800 | Elevator Control Travel Modification | PA-38-112 | 11/19/84 | 76193-02 | 85-11-06 | 2730 | 9C4 |
| 813 | Throttle Cable Installation Inspection | PA-38-112 | 1/3/86 | 77907-002 | | 7612 | 9F14 |
| 834 | Rear Spar Frame Stiffener Installation (Fuselage Station 99.29) | PA-38-112 | 4/22/86 | 765-177 | | 5310 | 9I23 |
| 836A | Aluminum Wire Inspection/Replacement | PA-38-112 | 8/26/86 | ** | | 2400 | 9J4 |
| 851 | Carburetor Air Box Valve Assembly Inspection/Modification | PA-38-112 | 10/9/86 | ** | | 7163 | 9L16 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 | 10A7 |
| 879 | Rivet Inspection - Wing Skin To Spar, Top Inboard | PA-38-112 | 1/22/88 | ** | | 5730 | 10G3 |
| 890 | Forward Tunnel Inspection and Flap Handle Cover Rework | PA-38-112 | 7/7/88 | 765-358 | | 2752 | 10H20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------|---------------------|-----------------|-------------|-------------|
| 891 | Wiring Modification Wing To Main Wire Harness Connectors | PA-38-112 | 7/15/88 | 764-530 | | 2453 |
| 936 | Replacement of a 90 Degree Fitting and Inspection of the Tee Fitting and Nipple at the Oil Pressure Transducer | PA-38-112 | 3/16/90 | ** | | 7257 |
| 991A | Replacement or Modification of the Alternator Out Light Fuse | PA-38-112 | 1/29/96 | ** | | 2437 |
| 1026 | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings." | PA-38-112 | 10/5/98 | 753-910 | | 3711 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-38-112 | 9/25/2000 | ** | | 3714 |
| 1200 | Landing Gear Modification and Hardware Replacement | PA-38-112 | 5/29/2009 | 88455-002 | 90-19-03 | 3207 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-38-112 | 4/12/2019 | N/A | | 7414 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P,
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------|---------------------|----------------------|-------------|------------------|
| 677 | Publications for Aircraft Operation | All Piper Models | 5/20/80 | | | PARA 15.0 7H4 |
| 780A | Part I - Flap Drive Mechanism Modification | PA-46-310P | 10/10/85 | 765-118V | | 2910 8K7 |
| 780A | Part II - Flap Selector Valve Replacement | PA-46-310P | 10/10/85 | 83729-04 | | 2910 8K8 |
| 781 | Aft Rudder Cable Inspection | PA-46-310P | 6/25/84 | ** | | 2720 8K10 |
| 782A | Magneto Switch Guard Installation | PA-46-310P | 4/24/85 | N/A | | 7410 8K12 |
| 783 | Interference of Elevator to Stabilizer | PA-46-310P | 6/13/84 | 765-132V | | 5520 8K15 |
| 784 | Pressure Outflow & Safety Valve Routing Inspection | PA-46-310P | 8/7/84 | 557-114 | | 2130 8K17 |
| 786 | Toe Brake Cylinder Clevis Rework | PA-46-310P | 8/20/84 | N/A | | 3241 8L6 |
| 790A | Part I - Turbo Oil Scavenge Reservoir Inspection | PA-46-310P | 2/14/85 | ** | | 7250 9A1 |
| 790A | Part II - Turbo Oil Scavenge Oil Line Support | PA-46-310P | 2/14/85 | ** | | 7250 9A2 |
| 790A | Part III - Lower Cowl Modification | PA-46-310P | 2/14/85 | N/A | | 7250 9A3 |
| 791 | Oxygen System Electrical Wiring Rerouting | PA-46-310P | 8/20/84 | N/A | | 3529 9A7 |
| 792 | Fuel Supply Line Replacement & Wing Rib Modification | PA-46-310P | 8/7/84 | ** | | 2814 9A13 |
| 794 | Electric Fuel Pump Circuitry Modification | PA-46-310P | 8/30/84 | ** | | 2820 9A20 |
| 796B | Part I - Lower Wing Rivet Replacement | PA-46-310P PA-46-350P | 1/25/95 | ** | | 5733 9B8 |
| 796B | Part II - Wing to Fuselage Fairing Replacement | PA-46-310P | 1/25/95 | ** | | 5733 9B9 |
| 796B | Part III - Upper Inboard Wing Rivet Replacement | PA-46-310P | 1/25/95 | ** | | 5733 9B9 |
| 799 | Landing Gear Control Lever Safety Tab Modification | PA-46-310P | 10/26/84 | ** | | 3260 9C1 |
| 803A | Pneumatic Surface Deice Pressure Control Valve | PA-46-310P | 3/21/86 | 765-159 84523-805 | | 3014 9C18 |
| 805A | TRW Hartzell Propeller Service Bulletin No. 142 (O-ring Deterioration) | PA-46-310P | 3/14/86 | N/A | | 6110 9D15 |
| 808 | Main And Nose Landing Gear Actuator Seal Replacement | PA-46-310P | 7/10/85 | ** | | 2930 9E10 |
| 809 | Nose Landing Gear Steering Rotator Inspection And Replacement | PA-46-310P | 7/1/85 | ** | | 3251 9E21 |
| 810 | Gear Safety Solenoid Installation Modification | PA-46-310P | 7/9/85 | 422-166 406-385 | | 3200 9F1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---------------------------|------------------|--------------------|----------|--------------------|
| 820A | Aft Wing Attach Fitting Fastener Inspection/Replacement | PA-46-310P | 4/20/2011 | 680-660 557-501 | | 5741 |
| 824 | Electric Flap Motor - Actuator Installation Rework | PA 46-310P | 3/21/86 | ** | | 2753 9H11 |
| 837 | Main Landing Gear Lower Torque Link Bolt Inspection | PA-46-310P | 5/21/86 | 424-052 | | 3213 9J8 |
| 852 | Alternate Air Control Linkage Adjustment | PA-46-310P | 11/14/86 | N/A | 87-04-01 | 7164 9L19 |
| 853 | Fuel Drain Replacement | PA-46-310P | 11/17/86 | 765-317 | | 2823 10A1 |
| 854A | Deice Timer Protection - Electrical Circuit Change | PA-46-310P | 10/28/87 | ** | | 3016 10A3 |
| 855 | Use of Automobile Gasoline in Piper Aircraft | All Piston Powered Models | 1/14/87 | N/A | | 2800 10A7 |
| 858 | Nose Landing Gear Steering Rotator Horn Attach Bolt Replacement | PA-46-310P | 4/1/87 | 401-302 407-565 | | 3251 10A15 |
| 862A | Electrically Operated Flap System, Actuator Tube Replacement | PA-46-310P | 8/11/87 | 85070-02 | | 2753 10B3 |
| 863A | Part I - Aileron Cable Routing - Wing | PA-46-310P | 1/31/89 | 765-331 | | 2712 10B6 |
| 863A | Part II - Phenolic Fairlead Installation | PA-46-310P | 1/31/89 | ** | | 2712 10B7 |
| 865A | Part I - Freon Compressor Drive Pulley Nut Inspection And Belt Removal | PA-46-310P | 7/14/87 | ** | 87-12-12 | 2513 10B13 |
| 865A | Part II - TCM Mandatory Service Bulletin M87-13 "Broken Starter Adapter Shafts" | PA-46-310P | 7/14/87 | ** | | 2513 10B14 |
| 871 | Airframe And Powerplant Operational Limitations | PA-46-310P | 10/13/87 | ** | | 7100 10C15 |
| 876B | Part I -Malibu Return To Service | PA-46-310P | 4/14/88 | ** | 87-14-02 | 7200 10E8 |
| 876B | Part II - Teledyne Continental Motor Service Bulletin M88-5 "Broken Starter Adapter Shafts" | PA-46-310P | 4/8/88 | ** | 88-17-03 | 7200 10E9 |
| 883 | Additional Post Lighting - Flight and Engine Instrumentation | PA-46-310P | 3/10/88 | 765-353 | | 3311 10G18 |
| 884 | Lock Wiring of V-Band Couplings | PA-46-310P | 4/8/88 | ** | | 7800 2100 10G20 |
| 892A | Powerplant Cooling Improvement | PA-46-310P | 5/17/89 | 765-365 | 88-25-08 | 7520 10I1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------|---------------------|-------------------------------|-------------|---------------------|
| 895 | Alternate Air Box Bearing Block Modification | PA-46-310P | 11/17/88 | 420-219 | | 7160 10I10 |
| 896 | Shoulder Harness Installation & Usage | PA-46-310P | 11/28/88 | ** | | 5340 10I13 |
| 900 | Missing Upper Fuselage Rivets | PA-46-310P | 2/13/89 | 522-601 | | 5333 10J11 |
| 913A | Malibu Return to Service | PA-46-310P | 6/29/89 | N/A | 89-14-01 | 7226 10L15 |
| 915 | Lycoming Service Bulletin No. 487 (Included with Lycoming Kit) | PA-46-350P | 7/8/89 | ** | 89-15-10 | 7311 10aA5 |
| 917 | Angle Support Forward Baggage Compartment | PA-46-310P | 7/19/89 | 765-367 | | 2551 10aA14 |
| 919 | Carpet Runner Retainer Installation | PA-46-310P | 8/3/89 | 765-369 | | 2520 10aB2 |
| 921 | Aileron Inspection | PA-46-310P PA-46-350P | 8/15/89 | ** | | 2715 10aB9 |
| 928A | Textron Lycoming Service Bulletin No. 491A, Inspection of Exhaust Transition Bolts | PA-46-350P | 3/22/90 | ** | | 7800 10aC12 |
| 930 | Inspection of Emergency Exit Window Fit | PA-46-350P | 12/14/89 | N/A | | 5621 10aC20 |
| 934 | Inspection and Rerouting of the Manifold Pressure Line | PA-46-350P | 2/8/90 | ** | | 7716 10aD12 |
| 939 | Weight and Balance Plotter | PA-46-350P | 6/8/90 | N/A | | 1110 10aE4 |
| 941 | Improved Engine Baffle Support | PA-46-350P | 7/17/90 | ** | | 7236 10aE9 |
| 943A | Landing Gear Locking Actuator End Gland Replacement | PA-46-310P | 8/15/90 | 763-060 | | 3235 10aF1 |
| 944 | Empennage Rivet Replacement | PA-46-310P PA-46-350P | 10/5/90 | ** | | 5510 10aF12 5530 |
| 947A | Low Vacuum Annunciator Light Operation | PA-46-310P PA-46-350P | 10/29/91 | ** | | 3720 10aF23 |
| 948 | Inboard Wing Rib Inspection, Modification, Replacement | PA-46-310P PA-46-350P | 1/25/91 | ** | | 5710 10aG3 |
| 949 | Wing Rib Reinforcement | PA-46-310P PA-46-350P | 2/18/91 | 766-247 766-248 766-249 | | 5712 10aG10 |
| 951 | Mixture Control Cable Inspection and Routing | PA-46-350P | 2/18/92 | | | 7320 10aG14 |
| 953 | Elevator Trim Cable Guide Tube Splice | PA-46-310P PA-46-350P | 10/29/91 | 766-272 | | 2730 10aG23 |
| 958 | Horizontal Stabilizer Drain Hole Installation | PA-46-310P PA-46-350P | 9/22/92 | | | 5510 10aH17 |
| 959 | Fuselage Rivet Installation | PA-46-310P PA-46-350P | 3/31/93 | ** | | 5310 10aH20 |
| 960 | Engine Mount Heat Shield | PA-46-310P PA-46-350P | 3/31/93 | 766-267 766-268 | | 7120 10aI3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|---------------------|------------|---------------|
| 961 | Alternate Air Door Replacement and Control Linkage Inspection | PA-46-310P PA-46-350P | 10/21/92 | ** | | 7160 10a15 |
| 962 | Corrosion Inspection and Protection | PA-46-310P PA-46-350P | 9/29/93 | ** | | 5510 10aJ4 |
| 963 | Electric Flap Cam Assembly Modification | PA-46-310P PA-46-350P | 6/11/93 | 766-245 | | 2750 10a17 |
| 964B | Hydraulic Power Pak Pressure Switch Replacement | PA-46-310P PA-46-350P | 5/24/96 | 766-278 766-277 | | 2911 10aJ14 |
| 976 | Inspection for and Replacement of Components with Suspect "O" Rings | PA-46-350P | 12/9/94 | ** | | 2911 10bA10 |
| 981 | Hydraulic Power Pak Lower Manifold Inspection | PA-46-310P PA-46-350P | 1/17/95 | ** | | 2911 10bB15 |
| 982 | Installation of Limitations Placard | PA-46-350P | 4/3/95 | ** | | 1100 10bC1 |
| 985 | Hydraulic System Power Pak Pressure Switch Replacement | PA-46-310P PA-46-350P | 6/16/95 | 765-457 | | 2911 10bC17 |
| 990 | Pacific Scientific Seat Belt Replacement | PA-46-350P | 1/3/96 | ** | | 5346 10bD12 |
| 993 | KLN-90B GPS Wiring Modification | PA-46-350P | 3/18/96 | ** | | 3441 10bE4 |
| 994 | Intermittent Main Landing Gear Indication (Parker Hannifin SB7049) (Attached) | PA-46-310P PA-46-350P | 3/8/96 | ** | | 2911 10bE6 |
| 995C | Turbine Inlet Temperature (T.I.T.) System Calibration and Probe Replacement | PA-46-310P PA-46-350P PA-46R-350T | 11/17/2009 | ** | 2011-06-10 | 7726 (10bE11) |
| 997 | Inspection of Jack Pad attachment Area at Wing Cutout for Radar | PA-46-310P PA-46-350P | 2/7/97 | 766-628 | | 5740 10bE20 |
| 999 | Modification of Inertia Reel Shoulder Harness Mounting Brackets | PA-46-310P PA-46-350P | 3/5/97 | 766-638 | | 5346 10bF9 |
| 1000 | Inspection of Engine Electrical Harness and Installation of Chafing Protection | PA-46-350P | 4/25/97 | 49990-36 488-702 | | 2436 10bF11 |
| 1001 | Inspection for Missing Washers at Nose Gear Steering Arm Rod End | PA-46-350P | 6/16/97 | ** | | 3251 10bF14 |
| 1012 | Distribution of Textron Lycoming Service Bulletin 531, Inspection of turbochargers and Tailpipes | PA-46-350P | 2/4/98 | ** | | 7800 10bH3 |
| 1014 | Replacement of Battery Power Fuse | PA-46-350P | 3/2/98 | 461-681 | | 2436 10bH11 |
| 1017 | Alternator Regulator Wiring Mod | PA-46-350P | 4/10/98 | ** | | 2436 10bH21 |
| 1020 | Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket | PA-46-350P | 7/10/98 | ** | | 2563 10bI11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|--|---|---------------------|------------------------|-------------|-------------|--------|
| 1021 | Modification of Control Wheel Quadrant Stop and Inspection of Forward Pressure Bulkhead | PA-46-310P PA-46-350P | 8/4/98 | 766-654 | | 5346 | 10b111 |
| 1027 | Modification of Forward and Aft Wing Attach Fittings | PA-46-350P | 11/19/98 | 766-656 766-657 | 99-16-06 | 5741 | 10bK4 |
| 1029 | Distribution of Textron Lycoming Service Bulletin 534, Turbocharger Oil Drain Tank Inspection/Replacement | PA-46-350P | 4/30/99 | | | 7164 | 10b17 |
| 1034 | Battery Master Contactor Wiring Modification | PA-46-350P | 8/17/99 | 84350-11 84350-12 | | 2454 | 10bL13 |
| 1035A | Distribution of Textron Lycoming Service Bulletin 529B, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3" | PA-46-350P | 3/22/2007 | ** | 2003-14-03 | 7311 | 10bL16 |
| 1041 | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-46-310P PA-46-350P | 9/25/2000 | ** | | 3714 | 10cB1 |
| 1046 | POH Supplement Installation | PA-46-350P | 11/28/2000 | ** | | 2212 | 10cC4 |
| 1048 | Stainless Steel Control Cables | PA-46-350P | 1/3/2001 | N/A | | 2702 | 10cC9 |
| 1052 | Nose Gear Steering Bungee Assy Modification | PA-46-500TP | 2/26/2001 | 766-690 | | 3255 | 10cC23 |
| 1053 | Outside Air Temperature Probe Relocation | PA-46-500TP | 4/3/2001 | 766-688 | | 3416 | 10cD2 |
| 1054 | Pilot and Co-Pilot Seat Inspection and Modification | PA-46-310P PA-46-350P PA-46-500TP | 4/12/2001 | ** | | 2514 | 10cD6 |
| 1055 | Engine Control Quadrant Inspection and Modification | PA-46-500TP | 5/29/2001 | 82995-003 | | 7601 | 10cD9 |
| 1056 | Fuel Drain Valve Inspection and Replacement | PA-46-500TP | 4/4/2001 | 766-691 | | 7319 | 10cD21 |
| 1058 | Overhead Switch Panel Replacement | PA-46-500TP | 5/31/2001 | 680-839 688-497 | | 3110 | 10cE3 |
| 1059 | Low Pressure Engine Driven Pump Leakage Inspection | PA-46-500TP | 6/11/2001 | 461-752 | | 7311 | 10cE6 |
| 1060 | Brake Pedal Binding | PA-46-310P PA-46-350P PA-46-500TP | 5/15/2001 | ** | | 3241 | 10cE9 |
| 1061 | Nose Landing Gear Strut Tube Snap Ring Inspection | PA-46-500TP | 6/19/2001 | N/A | | 3223 | 10cE13 |
| 1062 | Inboard Flap Drive Bellcrank Inspection and Replacement | PA-46-310P PA-46-350P PA-46-500TP | 5/11/2001 | 82905-002 82905-003 | 1-12-01 | 2755 | 10cE16 |
| 1063 | Circuit Breaker Panel Modifications | PA-46-500TP | 6/11/2001 | 581-657 | | 2451 | 10cE22 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SB99

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|-------------------------------------|----------|-------------|
| 1064 | Mass Flow Control Valve Support Clip Installation | PA-46-500TP | 6/14/2001 | 102501-002 | | 2125 10cF4 |
| 1065 | Primary Elevator Control Cable Replacement | PA-46-500TP | 7/25/2001 | ** | | 2735 10cF10 |
| 1066 | Cabin Door Latch Mechanism | PA-46-350P PA-46-500TP | 7/10/2001 | 767-305 | | 5213 10cF14 |
| 1067A | Entertainment Console (Small Cabinet) Voltage Dropping Resistor Shroud Installation | PA-46-350P PA-46-500TP | 8/8/2001 | 767-301 767-302 | | 2507 10cF17 |
| 1068 | Fuel System Line Fitting Leakage | PA-46-500TP | 7/19/2001 | ** | | 2823 10cF20 |
| 1069 | Fuel System Trim Fitting and Solenoid Valve Modification | PA-46-500TP | 7/19/2001 | 766-682 | | 2825 10cG2 |
| 1070 | Lightning Protection Rivets Installation | PA-46-500TP | 7/16/2001 | 767-303 | | 2816 10cG5 |
| 1071 | Main Landing Gear Squat Switch Safelying | PA-46-500TP | 7/2/2001 | N/A | | 3237 10cG8 |
| 1072 | Mass Air Control Valve Recall | PA-46-500TP | 8/13/2001 | 592-640 | | 2138 10cG12 |
| 1073 | Magnetic Flux Detector Connector | PA-46-500TP | 8/13/2001 | 599-693 | | 3427 10cG15 |
| 1074 | Cabin Bleed Air Restriction | PA-46-500TP | 7/23/2001 | N/A | | 2182 10cG20 |
| 1075A | Steering Horn Modification | PA-46-310P PA-46-350P | 5/5/2003 | 85154-002 85154-012 | | 3251 10cH1 |
| 1076 | GI-106 NAV/GS Indicator Wiring Harness Inspection / Modification | PA-46-500TP | 7/19/2001 | N/A | | 3316 10cH6 |
| 1077 | P&WC PT6A-42A Engine Oil-to-Fuel Heater Inspection | PA-46-500TP | 7/13/2001 | 762-156 | | 7200 10cH11 |
| 1078 | Stall Warning Microswitch Bracket | PA-46-500TP | 8/13/2001 | 767-306 | | 2226 10cI1 |
| 1080 | Lear Romec Fuel Pump | PA-46-500TP | 7/26/2001 | 461-757 | | 2820 10cI7 |
| 1082 | Aft Stowage Compartment Drain | PA-46-500TP | 8/13/2001 | 766-693 | | 2550 10cI16 |
| 1084 | Flight Into Known Icing (FIKI) Certification | PA-46-500TP | 9/20/2001 | ** | | 3010 10cJ1 |
| 1085 | Nose Landing Gear Steering Arm Chafing | PA-46-500TP | 10/26/2001 | 767-304 | | 3220 10cJ6 |
| 1086 | Generator Ammeter Relay Kit | PA-46-500TP | 10/3/2001 | 767-308 | | 2434 10cJ10 |
| 1087B | Nose Gear Emergency Downspring Mechanism Replacement | PA-46-310P PA-46-350P PA-46-500TP | 5/27/2003 | 766-211 104723-002 104723-003 | | 3235 10cJ13 |
| 1088 | Aft Spar Splice Cap Inspection | PA-46-500TP | 12/10/2001 | 767-321 | | 2751 10cJ18 |
| 1089 | Nose Gear Squat Switch Adjustment | PA-46-500TP | 11/12/2001 | N/A | | 3265 10cJ22 |
| 1090 | Fuel Restrictor Assy / Fuel Return Solenoid Removal | PA-46-500TP | 8/23/2001 | 767-324 | | 2825 10cK1 |
| 1091 | Pratt & Whitney PT6A-42A Engines - Turboprop Engine Oil-to-Fuel Heater Thermal Element Replacement | PA-46-500TP | 9/20/2001 | N/A | | 7200 10cK4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--|----------|----------|
| 1093 | Alternator Isolation Diode Installation | PA-46-500TP | 12/5/2001 | 767-307 | | 2430 |
| 1094 | Fuel System Check Valve Replacement | PA-46-500TP | 10/19/2001 | 592-670 | | 2813 |
| 1095 | Gear Warning Horn Mute Switch | PA-46-500TP | 1/18/2002 | 766-697 | | 3260 |
| 1098 | Pneumatic Deice System Line Inspection and Replacement | PA-46-500TP | 2/1/2002 | 102437-086 | | 3015 |
| 1099 | Feather Solenoid Suppression Diode Kit | PA-46-500TP | 1/18/2002 | 767-328 | | 6123 |
| 1102 | Master Electrical Panel Mounting Plate Inspection and Fuse Block Protective Cover Installation | PA-46-500TP | 3/8/2002 | 767-327 | | 2400 |
| 1103F | Engine Mount Inspection | PA-46-310P PA-46-350P PA-46R-350T | 9/1/2015 | 84010-002 89137-041 89137-042 89137-043 | | 7120 |
| 1106 | Nose Gear Steering System Improvement | PA-46-500TP | 1/28/2002 | 767-336 767-338 | | 3220 |
| 1107 | Maneuvering Speed Placard Replacement | PA-46-500TP | 3/7/2002 | 692-721 | | 1100 |
| 1108 | Flux Detector Relocation | PA-46-350P PA-46-500TP | 3/11/2002 | 767-335 767-334 | | 3429 |
| 1111 | Float Switch Wiring Inspection | PA-46-500TP | 8/19/2002 | 602-501 | | 2424 |
| 1114 | No. 1 GNS 530 Lighting Rewiring | PA-46-500TP | 4/24/2002 | 766-696 | | 3457 |
| 1121 | Installation of Missing Rivets on Lower Surface of Horizontal Stabilizer Spar | PA-46-500TP | 10/3/2002 | MS20470AD5 | | 5510 |
| 1126A | Emergency Gear Extension Cable Bracket Modification | PA-46-350P PA-46-500TP | 2/21/2005 | 767-364 | | 3237 |
| 1132 | Electronic Control Module Failures | PA-46-500TP | 6/4/2003 | 102226-002 102227-002 102227-006 102228-002 102228-006 | 4-03-32 | 2400 |
| 1134 | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105) | PA-46-350P | 6/10/2003 | ** | | 2800 |
| 1135 | GMA-340 Audio Panel Wiring | PA-46-350P PA-46-500TP | 7/16/2003 | N/A | | 2370 |
| 1139A | Control Wheel Attachment Inspection | PA-46-350P PA-46-500TP | 4/9/2004 | ** | 4-14-12 | 2701 |
| 1140 | Oxygen Generator Protective Cap Removal | PA-46-310P PA-46-350P PA-46-500TP | 9/16/2003 | 471-025 | | 3500 |
| 1144 | Nose Gear Door Hinge Modification | PA-46-500TP | 3/10/2004 | ** | | 5280 |
| 1150 | Standby Airspeed and Altimeter Indicator Pitot/Static Lines Replacement | PA-46-500TP | 12/9/2004 | 767-377 | | 3411 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--|------------|-------------|
| 1151E | 4130N Steel Hardness Discrepancy | PA-46-350P PA-46-500TP | 6/9/2004 | ** | | 5741 10dJ4 |
| 1152 | Fuel Restrictor Replacement | PA-46-500TP | 1/5/2005 | 767-386 | | 2821 10dJ8 |
| 1154C | Engine Mount Inspection | PA-46-500TP | 1/3/2008 | 102460-036 102460-002 767-515 401-509 (AN7-15A) | | 7121 10dJ14 |
| 1158A | Accessory Drive Pulley Improvement | PA-46-500TP | 1/30/2006 | 102406-006 | | 7260 10dK7 |
| 1159 | Fuel System Check Valve | PA-46-500TP | 11/10/2005 | 592-670 | | 2813 10dK10 |
| 1166 | Electronic Control Module Replacement | PA-46-500TP | 1/5/2007 | 102227-007 | 4-03-32 | 3418 10dL12 |
| 1168 | Elevator Trim Tab Hinge Rivets | PA-46-350P | 9/1/2006 | 767-544 | | 2711 10dL20 |
| 1170 | Louvered Cover Assembly | PA-46-500TP | 10/6/2006 | 767-545 | | 2100 10eA1 |
| 1173B | Engine Oil Hose Assemblies | PA-46-500TP | 11/16/2011 | 88407-002 | | 7920 |
| 1175B | Pilot's Side Window Inspection | PA-46-310P PA-46-350P PA-46-500TP | 9/30/2010 | ** | | 5610 |
| 1176 | Rudder Quadrant / Torque Tube Inspection - Tailcone | PA-46-350P PA-46-500TP | 1/16/2007 | ** | | 2720 10eA22 |
| 1177 | Nose Wheel Assembly (Cleveland SB 7083A) | PA-46-500TP | 11/14/2006 | 40-77B 767-569 | | 3246 10eB3 |
| 1178 | Nose Gear Forging Inspection / Replacement | PA-46-350P PA-46-500TP | 9/24/2007 | 67050-005 67050-006 | | 3222 10eB10 |
| 1180A | V-Band Exhaust Coupling Inspection | PA-46-350P | 3/14/2007 | ** | | 7200 10eB18 |
| 1181B | Flap Track/Splice Strap Inspection and Modification | PA-46-350P PA-46-500TP PA-46R-350T | 9/10/2009 | 104469-002 | | 2750 |
| 1182 | Wing Inspection Light | PA-46-350P | 8/22/2007 | 84579-002 | | 3340 10eC1 |
| 1183 | Emergency Exit Door Inspection | PA-46-500TP | 5/15/2007 | 82650-004 102919-002 | | 5220 10eC5 |
| 1185 | Placard Replacement | PA-46-350P PA-46-500TP | 8/30/2007 | 684-762 684-761 | | 2440 10eC21 |
| 1187 | Voltage Suppressor Replacement | PA-46-350P PA-46-500TP | 2/8/2008 | 88432-002 (Kit) | | 3400 10eD4 |
| 1190B | Aileron Quadrant Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 1/22/2009 | 82858-002 | | 2710 |
| 1192 | Stall Warning Heat Control Modification | PA-46-350P PA-46-500TP PA-46R-350T | 9/15/2008 | 88452-002 (Kit) | 2008-26-11 | 3418 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------------------------------|----------|----------|
| 1193 | Nose Gear Down Spring Replacement | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 3/3/2009 | 687-931 | | 3230 |
| 1195B | Comm 1 and Comm 2 Antenna and Skin Inspection | PA-46-350P PA-46-500TP | 4/15/2010 | ** | | 2312 |
| 1196 | Collector Tank Fuel Drain Inspection | PA-46-350P PA-46R-350T | 10/23/2008 | 84029-018 84029-017 | | 2830 |
| 1201 | Tie Bus Circuit Breaker Inspection | PA-46R-350T | 2/16/2009 | N/A | | 2400 |
| 1202 | Beta / Reverse Lockout Lever Inspection | PA-46-500TP | 3/18//2009 | ** | | 7600 |
| 1204 | Re-Calculation of Wing Structure Life Limit Due To Unique Usage | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 12/18/2009 | N/A | | 5711 |
| 1205 | Relocation of the PY Heater Ground Wire Termination | PA-46-500TP | 3/24/2010 | 106798-002 | | 3230 |
| 1208 | Lightning Diverter Inspection | PA-46-350P PA-46-500TP PA-46R-350T | 2/15/2010 | ** | | 5180 |
| 1210 | TWX670 Antenna Inspection | PA-46R-350T | 12/21/2009 | ** | | 3450 |
| 1211 | Aft Bulkhead Sealing Modification | PA-46R-350T | 3/2/2010 | PR-1422-A2 PR-1422-B4 | | 5110 |
| 1212 | Inspection of Flap Position Indicator Placard | PA-46-350P PA-46-500TP PA-46R-350T | 1/5/2010 | ** | | 1130 |
| 1214A | Compressor Turbine Blade Inspection | PA-46-500TP | 3/4/2010 | N/A | | 7231 |
| 1217A | Starter Contactor Replacement | PA-46-350P PA-46R-350T | 1/14/2011 | 88465-002 | | 2400 |
| 1218 | Rudder Skin Inspection | PA-46-500TP | 10/13/10 | 83403-003 88471-002 106884-002 | | 5540 |
| 1223 | Wire Screen Replacement | PA-46-350P PA-46R-350T | 11/10/10 | ** | | 2126 |
| 1228 | Autopilot Circuitry Modification | PA-46R-350T | 1/21/2011 | 88485-002 | | 2210 |
| 1229 | Avox Systems Service Bulletin No. 36758-35-01 (O ₂ Cylinder Bracket Latch Inspection) | PA-46-500TP | 4/21/2011 | 453-528 | | 3510 |
| 1230 | Nose Wheel Grommet Inspection | PA-46-500TP | 6/6/2011 | 463-526 | | 3240 |
| 1232 | Cabin Door Handle Placard Inspection | PA-46-350P PA-46-500TP PA-46R-350T | 5/16/2011 | 100700-014 | | 1120 |
| 1234 | Engine Oil Cooler Control Valve Replacement | PA-46-500TP | 6/23/2011 | 592-712 | | 7920 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--|------------|----------|
| 1236 | Landing Gear Servicing and Placard Replacement | PA-46-500TP | 10/6/2011 | 100700-084 100700-085 100700-086 | | 1210 |
| 1237 | Static Discharger Replacement | PA-46-350P PA-46-500TP PA-46R-350T | 8/10/2011 | 456-904 | | 2360 |
| 1238 | Landing Gear Servicing and Placard Replacement - Meridian G1000 airplanes registered in Brazil | PA-46-500TP | 7/23/2013 | 106787-072 106787-073 | | 1210 |
| 1243C | Potential Landing Gear Malfunction | PA-46-350P PA-46-500TP PA-46R-350T | 3/7/2012 | 102559-804RBL | | 3200 |
| 1247B | Garmin SafeTaxi® Limitation | PA-46-350P PA-46-500TP PA-46R-350T | 3/13/2019 | N/A | | 3420 |
| 1250A | Pilot Operating Handbook Permanent Revision | PA-46-350P PA-46R-350T | 12/16/2013 | ** | | 7320 |
| 1255 | Boost Pump Wiring Rerouting | PA-46-500TP | 3/4/2013 | 88541-001 | | 2820 |
| 1256 | Nose Landing Gear Torque Link Hardware Replacement | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 1/23/2013 | 603-816 (MS14144-4) | | 3220 |
| 1258 | Fuel Vent Valve Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 6/5/2013 | 106927-001 | 2013-13-01 | 2810 |
| 1262B | Wing Inspection | PA-46-500TP | 4/23/2015 | ** | | 5713 |
| 1269A | GWX 68 Ground Rewire | PA-46-350P PA-46R-350T | 3/10/2014 | N/A | | 3440 |
| 1267A | Empennage Rivets Inspection | PA-46-500TP | 12/18/2015 | 484-911 | | 5500 |
| 1271A | Wing Spar Inspection | PA-46-310P PA-46-350P PA-46-500TP | 12/12/2019 | ** | | 5711 |
| 1275 | Nose Landing Gear Service Placard Replacement | PA-46-500TP | 6/26/2015 | 100700-125 | | 1130 |
| 1280A | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1 | PA-46-350P PA-46-500TP PA-46R-350T | 4/29/2016 | 459-887 | | 2620 |
| 1283A | Cabin Altitude Encoder Installation Modification | PA-46-350P PA-46-500TP | 10/19/2016 | Sandia P/N 305216-02 | | 2130 |
| 1284B | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick assemblies | PA 46-350P PA 46-500TP PA-46-600TP | 4/12/2019 | N/A | | 7414 |
| 1288A | Aft Vertical Fin Spar Inspection | PA-46-350P PA-46-500TP PA-46R-350T | 5/18/2017 | 404-532 MS21042-6 | | 5500 |
| 1290B | Flap Bracket Inspection, Inboard Bellcrank | PA-46-350P PA-46-500TP | 12/14/2017 | N/A | | 2750 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|---|------------|--------------|
| | | PA-46R-350T | | | | |
| 1291A | Executive Table Placards Replacement | PA-46-350P PA-46-500TP PA-46R-350T | 12/11/2024 | 88581-701 or 88581-702 | | 2520 |
| 1293C | Engine Mount Doubler Installation and Towing Placards Replacement | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 3/9/2017 | 88582-701 88582-702 88584-701 (if required) | | 1100 7120 |
| 1296 | Fuel Control Unit Manual Override Inspection – Pratt & Whitney Canada Service Bulletin A3487 | PA-46-500TP | 3/31/2016 | N/A | | 7600 |
| 1297 | Altimeter Inspection and Replacement (United Instruments SB No. 13) | All | 5/10/2016 | N/A | | 3416 |
| 1303A | Diode Module Installation | PA-46-600TP | 10/15/2018 | 681-020 | | 3410 |
| 1305 | Flight Into Known Icing (FIKI) Modification | PA-46-600TP | 7/13/2017 | 88592 | | 3000 |
| 1306 | Wing Rib Modification | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 1/10/2018 | 88609-001 88609-002 | | 5712 |
| 1308 | Wet-Wing Fuel Access Cover Inspection | PA-46-600TP | 5/10/2017 | Loctite 222MS 279-051 | | 2810 |
| 1310 | K303 Relay Relocation | PA-46-600TP | 5/18/2017 | 584-423 | | 2430 |
| 1314 | Cabin Door Frame Inspection | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 3/12/2018 | N/A | | 5311 |
| 1315 | Cabin Door Threshold Rivet Replacement | PA-46-600TP | 12/21/2017 | N/A | | 5310 |
| 1317C | Aft Wing Spar Inspection | PA-46-600TP | 8/9/2017 | N/A | 2017-16-03 | 5711 |
| 1318B | Fuselage Station 144.25 Rivet Replacement | PA-46-600TP | 6/7/2018 | 88623-701 88624-701 | 2018-14-01 | 5330 |
| 1322 | Stall Warning Heat Ground Wire Inspection | PA-46-500TP M500 | 2/28/2018 | ** | | 3418 |
| 1326A | Propeller Heat Sensor Wiring Modification | PA-46-600TP | 1/3/2019 | 465-258 461-654 | | 3060 |
| 1327 | Aileron Control Cable Protection Tube Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 6/26/2018 | 88630-701 | | 2710 |
| 1328 | Aileron Quadrant Cable Guard Replacement | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 6/26/2018 | 46F44A701-701 | | 2710 |
| 1329 | Canted Frame Rivets Replacement | PA-46-600TP | 2/3/2020 | 46F53A004 46F53A005 | | 5310 |
| 1332A | Bulkhead Rivet Replacement | PA-46-600TP | 1/29/2019 | N/A | | 5312 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--|----------|--------------|
| 1333A | Forward Wing Spar Attach Fitting Inspection | PA-46-600TP | 4/18/2019 | | | 5741 |
| 1334A | EL Panel Inverter And Windshield Heat Relay Ground Wiring Relocation | PA-46-600TP | 12/5/2018 | N/A | | 3040 3310 |
| 1336 | Aileron-Rudder Interconnect Inspection | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 1/18/2019 | 83287-006 | | 2700 |
| 1338 | Main Gear Actuator Attach Fitting Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 3/25/2020 | 467-496 | | 3211 |
| 1339A | Generator Relay (K303) Replacement | PA-46-600TP | 9/9/2019 | 88646-002 | | 2430 |
| 1341A | Lift Transducer Replacement | PA-46-600TP | 5/1/2023 | 585-720 | | 3418 |
| 1343 | Canted Frame Doubler Inspection | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 2/3/2020 | 82279-002 | | 5300 |
| 1344 | Generator Relay (K303) Replacement | PA-46-500TP | 10/23/2019 | 88647-002 | | 2430 |
| 1349 | Fuel Return Valve Wiring Modification | PA-46-500TP M500 | 2/14/2020 | N/A | | 3425 |
| 1350A | Nose Landing Gear Steering Horn and Arm Assemblies Inspection | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 2/10/2021 | 46N32A009-801 83626-004 (85154-012) | | 3200 |
| 1352 | Garmin G3000NG Software Version 2975.15 | PA-46-600TP | 4/10/2020 | 88678-001 190-02446-00 190-02447-00 | | 3420 |
| 1358 | Fuel Probe Modification | PA-46-350P M350 | 3/24/21 | 88667-701 | | 2840 |
| 1360A | Aileron Drive Sector Inspection | PA-46-600TP | 1/13/2021 | 46W440005 | | 2710 |
| 1361 | Autothrottle Potentiometer Wiring Inspection | PA-46-600TP | 3/12/2021 | 46F34A021-002 | | 2230 |
| 1364A | Fuel Quantity Capacitance Probe Inspection | PA-46-350P M350 PA-46-600TP | 4/14/2021 | ** | | 2840 |
| 1367 | Aft Rib Assembly Rivets Replacement | PA-46-600TP | 9/17/21 | MS20426AD-4 | | 5712 |
| 1369 | Elevator Spar Inspection | PA-46-500TP PA-46-600TP | 8/12/21 | 88694-701 88694-702 | | 5521 |
| 1370A | Inertial Separator Duct Shredder Angle Modification or Replacement | PA-46-500TP M500 PA-46-600TP | 3/28/2022 | 46P710003-003 46P710015-003 88700-701/-702 | | 7160 |
| 1371 | M600 Wing Assembly Serialization Marking | PA-46-600TP | 1/4/2022 | 46W57A100-001 | | 1100 |
| 1385 | Rudder Skin Strap installation | PA-46-500TP | 10/25/2022 | 83403 | | 5540 |
| 1395 | Garmin G1000 Software Update Version 720.18 | PA-46-500TP | 2/20/2023 | 88681-001 | | 3420 |
| 1390 | Nose Landing Gear Emergency Down Spring Inspection | PA-46-350P, PA-46-500TP PA-46-600TP, PA-46R-350T | 7/20/2023 | 487-399 | | 3230 |
| 1392A | Frame Assembly Inspection and Repair, Fuselage Station 282.00 | PA-46-310P, PA-46-350P, PA-46-500TP, PA-46-600TP, PA-46R-350T | 12/5/2024 | 84201-004 46F53A213-001 | | 5322 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--|------------|----------|
| 1401 | Steering Arm Modification | PA-46-600TP M600 | 10/23/23 | | | 3250 |
| 1402 | Airworthiness Directive 2021-08-15 | PA-46-350P M350 PA-46-500TP M500 PA-46-600 M600 | 8/24/2023 | | 2021-08-15 | 3445 |
| 1403 | Airfram Doubler Inspection | PA-46-500TP M500 PA-46-600TP M600 | 5/23/2024 | | | 5320 |
| 1404 | Flap Drive Bracket Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 4/2/2024 | | | 5754 |
| 1407A | Piper Halo Autoland Brake Mechanism Modification | PA-46-600TP M600 | 10/17/2024 | | | 3240 |
| 1408A | Replacement of Main Landing Gear Door Support Structure | PA-46-600TP M600 | 12/2/2024 | 46W57A730-701 46W57A730-702 | | 5280 |
| 1409A | Control Column Assembly Inspection | PA-46-350P M350 PA-46-500TP M500 PA-46-600 M600 | 11/22/2023 | 485-083 (MS16625-2075) | | 2701 |
| 1410B | Vertical Stabilizer Installation Improvement | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 12/11/2024 | | | 5340 |
| 1411A | Autopilot Rigging Inspection | PA-46-350P Mirage/M350 PA-46-500TP Meridian/M500 PA-46-600TP M600 PA-46R-350T Matrix | 7/2/2024 | | | 2700 |
| 1414A | Main Landing Gear Attachment Fitting Inspection Near WS 61.00 | PA-46-600TP M600 | 7/1/2024 | 575-124 557-737 861-180 99G000002-701 | | 3211 |
| 1416B | Fuel Flow Transducer Inspection | PA-46-350P M350 | 12/9/2024 | | | 2840 |
| 1417 | Flight Into Known Icing (FIKI) Modification - M700 | PA-46-701TP M700 Fury | 5/31/2024 | N/A | | 3000 |
| 1419 | Flap Bracket Gap Inspection | PA-46-600TP M600 PA-46-701TP M700 Fury | 10/14/24 | | | 5754 |
| 2000A | Current Limiter Inspection | PA-46-350P / M350 PA-46R-350T | 3/10/2022 | 572-599 461-681 | 2009-07-08 | 2400 |

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

SB108

SERVICE LETTER INDEX

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-------------------------|---------------------|-------------------------------|-------------|-------------|
| 32 | Aileron Cable Pulley Installation | J3 | 6/15/42 | | | 13A1 |
| 100 | Tie Rod Nipples- J3, 8-36 Type A | J3 | 11/23/43 | | | 13A2 |
| 107 | Plexiglass One Piece Windshield For J3 Series | J3 | 10/15/45 | | | 13A3 |
| 109 | Winter Operation Recommendations | J3, PA-11 | 10/15/47 | | | 13A5 |
| 114 | Top Cowl Rivets | PA-16 | 6/13/49 | | | 13A10 |
| 129 | Inspection of Landing Gear Shock Strut End Fittings | PA-15/17 | 10/28/49 | | | 13A11 |
| 131 | Muffler Tail Pipe Inspection | PA-11 | 12/30/49 | | | 13A12 |
| 136A | Chafing of Fuel Line and Fuel Valve Operation | PA-20/22 | 9/2/52 | | | 13A13 |
| 138 | Rudder Pedal Tube Attachment | PA-20 | 3/9/50 | | | 13A15 |
| 140 | Rudder Cable Rub Block | PA-20 | 3/24/50 | | | 13A16 |
| 143 | Stabilizer Adjustment Cable Pulley Modification | PA-20 | 5/5/50 | | | 13A18 |
| 144 | Fuselage Doors | PA-15/17 | 5/5/50 | | | 13A19 |
| 145 | Auxiliary Fuel Line | PA-20 | 6/1/50 | | | 13A20 |
| 146 | Front Seat Frame Revision | PA-20 | 6/1/50 | | | 13A21 |
| 150 | Bungee Cable PA-18-105 | PA-18 | 7/10/50 | | | 13A22 |
| 153 | PA-20 Windshield Supports | PA-20 | 7/12/50 | | | 13A24 |
| 154 | Addition of Felt Strips on Wing Tank Covers | PA-11/16 PA-18/20 | 7/12/50 | | | 13B1 |
| 155 | Muffler Tail Pipe Shroud | PA-18 | 7/14/50 | | | 13B2 |
| 157 | Loose Connections | PA-16/20 | 8/1/50 | | | 13B4 |
| 159 | PA-20 Baffle Seal | PA-20 | 10/24/50 | | | 13B5 |
| 161 | Duraclad Finish | PA-18/20/22 | 2/13/51 | | | 13B6 |
| 162 | Control Sticks | PA-18 | 3/6/51 | | | 13B8 |
| 165 | Oil Radiator Hoses | PA-18 PA-20 PA-22 | 3/23/51 | 465-132 465-133 465-134 | | 7920 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|------------------|--------------|----------|----------|
| 169 | Manifold Pressure Gauge Installation | All 1951 Models | 4/20/51 | | | 13B9 |
| 175 | Nose Wheel Bumper Block Spacer Plate | PA-22 | 8/1/51 | | | 13B10 |
| 176 | Stabilizer Adjustment Mechanism | PA-20/22 | 8/10/51 | | | 13B11 |
| 177 | Firewalls | All Models | 8/10/51 | | | 13B13 |
| 178 | Optional Oil Radiator Installation | PA-18 | 8/24/51 | | | 13B14 |
| 180 | Nose Wheel Mount Stiffener Brace | PA-22 | 9/20/51 | | | 13B15 |
| 183A | Tail Wire Fittings | PA-18 | 11/12/51 | | | 13B16 |
| 186 | Clearance Between Engine Mount and Tail Pipe/Clearance In Nose Wheel Steering Mechanism | PA-22 | 4/21/52 | | | 13B17 |
| 187 | Brake Lever | PA-22 | 3/13/52 | | | 13B19 |
| 188 | Flap Cable Installation | PA-18A | 4/11/52 | | | 13B20 |
| 189 | Tail Wheel Springs | PA-18A | 4/17/52 | | | 13B22 |
| 194 | Sealing of Firewalls | PA-20/22 | 9/2/52 | | | 13B23 |
| 195 | Battery Cable And Rudder Cable Interference | PA-18A | 10/6/52 | | | 13B24 |
| 196 | Chafing of Oil Pressure Line | PA-18 | 10/6/52 | | | 13C2 |
| 203 | Weight & Balance Form | PA-12 | 5/7/53 | | | 13C3 |
| 207 | Oil Quick Drain Valve Assembly, Part No. 12956-04 | PA-18 PA-22 | 6/18/53 | | | 13C4 |
| 209 | Navigation Light Switch | All Classic Models | 8/18/53 | | | 13C5 |
| 210 | PA-18A Agricultural Airplane | PA-18A | 8/24/53 | | | 13C6 |
| 212 | Nose Wheel Shimmy Dampener, Part No. 13086-00 | PA-22 | 10/7/53 | | | 13C8 |
| 213 | Primer Lines | PA-18, 20, 22 | 10/7/53 | | | 13C10 |
| 214 | Navigation Light Switch | All Classic Models | 11/17/53 | | | 13C12 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

CLASSIC AIRCRAFT:
 B-2/E-2/F-2/J-2/J-3/
 J-4/L-21/L-18/PA-11/NE-1/
 PA-15/PA-16/PA-17/PA-18/
 PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|----------|----------|
| 216A | Replacement of Aileron Hinge Bearing Blocks Part No. 10921 | All Classic Models | 12/14/1953 | | | |
| 220 | .040 Brass Safety Wire | All Classic Models | 3/29/1954 | | | |
| 221 | Carburetor Air Filter | All Classic Models | 5/13/1957 | | | |
| 223 | Engine Support Bushing | PA-12, 16 PA-18, 18A PA-20, 22 | 5/17/1954 | | | |
| 228 | Two Person Safety Belts | PA-12, 14, 15 PA-16, 17, 20, 22 | 9/29/1954 | | | |
| 233 | Fuel Selector Valve | PA-18, 20, 22 | 10/22/1954 | | | |
| 241 | Cigarette Lighters | PA-22 | 1/24/1955 | | | |
| 242A | Special Air Filter Kits | PA-18A | 2/20/1959 | ** | | 7160 |
| 243 | Engine Mount | PA-22 | 2/8/1955 | | | |
| 247 | Tail Reinforcement Agricultural Airplane | PA-18A | 4/15/1955 | | | |
| 248 | Auxiliary Fuel Tank | PA-22 | 5/13/1955 | | | |
| 258 | Fuel Tank Cap | PA-22 | 11/30/1955 | | | |
| 259 | RPM Restriction Placard | PA-18, 18A | 11/30/1955 | | | |
| 260 | Brake System | PA-22 (1956 Models Only) | 11/30/1955 | | | |
| 283A | Inspection Forms, 100, 500, 1000 Hour | PA-18, 18A PA-22 | 2/26/1958 | | | General |
| 295A | Aircraft Finishes | All Classic Models | 1/3/1964 | | | |
| 298C | Obsolete Airplanes | B-2/E-2/F-2/J-2/J-3/J-4 L-4/L-18B/L-18C/ NE-1 PA-11/15/16/17/18/19/ PA-20/22/TG-8 | 6/7/2021 | | | General |
| 303A | Aircraft Finish | PA-15/16/17 PA-18/20 PA-22 *** | 9/23/1959 | | | 5300 |
| 312 | Tooling - Piper Auto Control | PA-22 | 11/24/1958 | ** | | 2210 |
| 318 | Air Filter, Carburetor, System Modification | PA-18/18A | 4/6/1959 | 754-223 | | 7160 |
| 321 | Piper Autocontrol | PA-18, 22 *** | 7/8/1959 | | | 2210 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--------------------------------------|------------------|--|----------------------|----------|-------|
| 324C | Maintenance And Inspection of Exhaust Systems And Heat Exchanges | PA-18, 22 | 1/22/69 | | 62-26-05 68-05-01 | 7810 | 13I1 |
| 327 | FAA Bureau of Flight Standards Release No. 434 | All Models *** | 12/28/59 | | | General | 13I11 |
| 328 | Lycoming Service Letter #L126 Dated 1/24/60 | PA-22 | 2/17/60 | | | 7200 | 13I19 |
| 329A | Oil Cooler Lines, Inspection of | PA-22 | 5/17/60 | ** | | 7920 | 13J3 |
| 348 | Airspeed Indicators, Replacement of | PA-22-108 | 12/9/60 | 11339-16 | | 3410 | 13K11 |
| 349 | Bushings, Engine Support, Adjustment of | PA-18/18A PA-22 | 12/14/60 | ** | 61-16-05 | 7100 | 13K12 |
| 353A | Propeller Decal | PA-22-108 | 2/20/61 | | | 6100 | 13K16 |
| 355 | Stainless Steel Control Cables | PA-18/18A PA-20 PA-22 | 2/23/61 | ** | 61-16-05 | 2700 | 13K19 |
| 358B | Mount Assemblies, Engine And Nose Wheel Inspection | PA-22 | 6/7/66 | | | 7120 | 13K23 |
| 362B | Windshield Top Attachment, Modification of | PA-15 PA-16/17 PA-20 PA-22 | 12/11/74 | 754-404 760-799 754-404 754-404 | 74-17-04 | 5610 | 13L7 |
| 369 | Inspection of Brake Cable And Pulleys | PA-22 PA-22-108 | 3/7/62 | | | 3240 | 14A5 |
| 373 | Dry Vacuum Pumps (Airborne Mechanisms), Models 113A1 And 113A5 Installation of Oil Shields | PA-22-108 | 3/29/62 | 756-143 | | 3710 | 14A11 |
| 400 | Tail Brace Rods | PA-20 PA-22 | 3/20/63 | 10555-02 10556-02 | 60-01-07 | 5510 | 14C11 |
| 405 | Bearing, Nose Gear Upper Oleo, Inspection of | PA-22 | 10/1/63 | 452-419 | 64-05-04 | 3220 | 14C20 |
| 406 | Revision To Owners Handbook | PA-20 PA-22 | 9/26/63 | | | General | 14C22 |
| 410 | Inspection And Lubrication of Stabilizer | PA-22 Series | 10/16/63 | | | 5500 | 14D6 |
| 423 | Muffler And Tailpipe Support Kits | PA-22-108 | 5/5/64 | 756-803 756-804 | | 7810 | 14E13 |
| 485 | Scott Aviation Corporation Modification Instructions 1-298 For Constant Flow (Semi-Disposable) Mask, Scott PN 28302 | All Aircraft With Subject Mask Assy. | 2/8/67 | 756-332 | | 3510 | 14J9 |
| 486A | Cylinder Head Temperature Probe Location | PA-18 PA-22 | 4/16/68 | | | 7720 | 14J13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------|----------|--------------|
| 491 | Aeromarine Instrument Company Service Bulletin No. 201 | Aeromarine Airspeed Indicator Equipped Aircraft | 8/8/67 | | | 3400 14J18 |
| 513 | Service Memos And Service Aids | All Models | 8/30/68 | | | General 14L2 |
| 529A | Autopilot Gyro Instrument Overhaul Centers | Piper Autopilot Equipped Aircraft | 1/14/70 | | | 3400 15A17 |
| 544 | Revised Gyro Service Procedure | 3" D.G. 1 Attitude Gyros | 1/5/70 | | | 3420 15C7 |
| 573 | B.F. Goodrich Service Bulletin No. E-68-36B (Sealer For B.F. Goodrich Deicer And Strap) | B. F. G. Deicer Systems | 3/4/71 | | | 3020 15F17 |
| 608 | Covering, Aircraft Ceconite | PA-18-150 | 1/31/72 | | | 5300 15J10 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 617B | Piper Automatic Locator Transmitter Replacement | PA-18 | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 633 | Inspection And Repair of Flood Exposed Airplanes | PA-18 *** | 10/9/72 | | | 5300 16A18 |
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-18, 22 | 10/24/72 | ** | | 2430 16B2 |
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972) | PA-15 PA-16, 18, 20, 22 | 4/9/73 | ** | | 7610 16C14 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D) | PA-22 | 4/19/74 | | | 7230 16F9 |
| 695 | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974) | PA-22 | 5/3/74 | ** | | 2210 16G13 |
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-11 | 5/31/74 | ** | | 7410 16J18 |
| 740 | Fuel Requirements | PA-16, 18, 20, 22 | 4/20/76 | | | 2800 17A3 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-18-150 | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 828 | Electrical System Refinement | PA-18-150 | 8/28/78 | | | 2400 17J16 |
| 944 | Fuel Selector Valve Inspection And Lubrication | PA-18-150 | 4/20/82 | ** | | 2820 18K11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:
B-2/E-2/F-2/J-2/J-3/
J-4/L-21/L-18/PA-11/NE-1/
PA-15/PA-16/PA-17/PA-18/
PA-19/PA-20/PA-22**

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------------|--------------------|----------|
| 1016 | Strut Cuff & Door Catch Attachment Improvement | PA-20,22 | 11/11/95 | 766-269 766-270 | | 5701 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 |
| 1093B | Electrical Contactor Replacement Kit | PA-18 Series PA-22 Series | 11/28/2017 | 88371 | | 2400 |
| 1116A | Contactor Maintenance | PA-18 Series PA-22 Series | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | J-2 Series J-3 Series J-4 Series NE-1 L-4 PA-11 PA-15/17 PA-16 PA-18 Series PA-20 Series PA-22 Series | 4/27/2011 | MS20995-C32 | | 2800 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1302 | Replacement Of Locking Gascolator Drain Valve | PA-11 PA-15 PA-16 PA-17 PA-18 Series PA-20 Series PA-22 Series | 12/1/2022 | 492-022 492-312 | | 2821 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|---------------------|-----------------|-------------|-------------|
| 220 | .040 Brass Safety Wire | PA-23 | 3/29/54 | | | 13C14 |
| 221 | Carburetor Air Filter | PA-23 | 5/13/57 | | | 13C17 |
| 227 | Service Publication To The Field | PA-23 | 9/24/54 | | | 13C19 |
| 229 | Balancer For The Hartzell HC-82XG-2 Propeller | PA-23 | 10/7/54 | | | 13C21 |
| 231 | Electrical System | PA-23 | 10/11/54 | | | 13D1 |
| 235 | Flap Spar And Stabilizer Spar Reinforcement | PA-23 | 10/28/54 | | | 13D4 |
| 236 | Cabin Heater Modification | PA-23 | 10/28/54 | | | 13D6 |
| 239 | Cabin Draft | PA-23 | 1/3/55 | | | 13D7 |
| 240 | Landing Gear Actuating Lever | PA-23 | 1/17/55 | | | 13D8 |
| 246 | Engine Oil Thermostat Kit | PA-23 | 4/15/55 | | | 13D12 |
| 249 | Heater Fuel Line | PA-23 | 5/24/55 | | | 13D15 |
| 250 | Reference Service Bulletin #138 - Hydraulic Actuating Cylinders | PA-23 | 6/8/55 | | | 13D17 |
| 251 | Carburetor Air Boxes | PA-23 | 9/16/55 | | | 13D19 |
| 252 | Primer Pump | PA-23 | 9/16/55 | | | 13D20 |
| 255 | Cabin Door Handle Bracket | PA-23 | 10/24/55 | | | 13D22 |
| 256 | Heater Fuel Shutoff Valve | PA-23 | 11/21/55 | | | 13D24 |
| 266 | Throttle, Prop And Mixture Control Levers | PA-23 | 2/19/56 | | | 13E6 |
| 270 | Electrically Heated Airspeed Pitot Head | PA-23 | 3/9/56 | | | 13E7 |
| 271 | Landing Gear Door Hinges And Hinge Brackets | PA-23 | 3/19/56 | | | 13E8 |
| 274 | Ground Wire For Audio Speaker - Phone Selector Switch | PA-23 | 3/23/56 | | | 13E9 |
| 277 | Brake Bleeding | PA-23 | 3/29/56 | | | 13E11 |
| 278A | Landing Gear Drag Link Assemblies | PA-23 | 2/28/57 | | | 13E18 |
| 280 | Rerouting of Engine Breather And Oil Separator Discharge | PA-23 | 9/11/56 | | | 13E20 |
| 281 | Engine Nacelle Air Baffle | PA-23 | 9/12/56 | | | 13E22 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-----------------------|------------------|--------------|----------------------|------------|
| 283A | Inspection Forms, 100, 500, 1000 Hour | PA-23 | 2/26/58 | | | 500 13E24 |
| 286 | Auxiliary Fuel Valve Control Modification | PA-23 | 10/8/56 | | | 13F1 |
| 288B | Accessories, Optional Equipment And Modification Kits | PA-23 | 1/6/58 | | General | 13F2 |
| 289 | Engine Breather And Oil Separator Discharge Line Stoppage | PA-23 | 1/18/57 | | | 13F5 |
| 290 | Elevator Horn Bushing Wear | PA-23 | 1/21/57 | | | 13F6 |
| 291 | Wheels And Brakes | PA-23 | 6/5/57 | | | 13F7 |
| 292 | Drag Link Assemblies | PA-23 | 9/5/57 | | | 13F8 |
| 293A | Cabin Heaters | PA-23 | 12/13/57 | | | 13F11 |
| 295A | Aircraft Finishes | PA-23 | 1/3/64 | | | 13F12 |
| 300B | Propeller Feathering | PA-23 | 3/30/59 | | | 6120 13F17 |
| 303A | Aircraft Finishes | PA-23 | 9/23/59 | | | 13F23 |
| 306 | Carburetor Heat Shroud Support Modification | PA-23 | 10/10/58 | 754-192 | | 7310 13G19 |
| 307 | Nacelle Fairing Installation | PA-23 | 10/10/58 | 754-175 | | 5450 13G20 |
| 312 | Tooling-Piper Autocontrol | PA-23 | 11/24/58 | ** | | 2210 13H4 |
| 313 | Elevator Control Tube Nylon Sleeve Installation Kit | PA-23 | 1/6/59 | 754-215 | | 2730 13H5 |
| 319 | Draining of Apache Fuel Strainers | PA-23 | 4/13/59 | | | 7310 13H20 |
| 320 | Nacelle Fairing Installation | PA-23 | 4/23/59 | | | 5450 13H21 |
| 321 | Piper Autocontrol | PA-23 | 7/8/59 | | | 13H22 |
| 322A | Fuel System Control Valves | PA-23 | 10/12/59 | ** | 60-03-08 | 7320 13H23 |
| 324C | Maintenance And Inspection of Exhaust Systems And Heat Exchanges | PA-23/23-250 | 1/22/69 | | 62-26-05 68-05-01 | 7810 13I1 |
| 326 | PA-23 Elevator Tabs | PA-23 | 12/28/59 | | | 5520 13I10 |
| 330 | South Wind Bulletin Dated February 22, 1960 | PA-23 | 5/5/60 | 751-776 | | 2140 13J5 |
| 333C | Radio Shelf Capacities | PA-23-235/250 UO-1 | 1/28/63 | | | 3400 13J13 |
| 334 | Fuel Cell Filler Neck Reinforcement | PA-23-250 UO-1 | 6/16/60 | 754-332 | | 2810 13J14 |
| 336 | Modification of Oil Pressure Lines | PA-23 | 6/17/60 | 19148-00 | | 7930 13J17 |
| 338 | Locking of Main Cabin Door | PA-23-250 | 7/12/60 | | | 5210 13J20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---------------------------|------------------|----------------------|----------|------------|
| 340 | Sealing of Fuel Cell Filler Neck Riveted Seam | PA-23-250 | 6/29/60 | | | 2810 13J24 |
| 345 | Hartzell Service Bulletin #75- Inspection of Hartzell Governor For Presence of Vent Hole | PA-23-250 | 9/14/60 | | | 6120 13K5 |
| 350 | Installation of Brush And Retainer Plate Assembly, (Electric Propeller) Deicer B.F. Goodrich | PA-23/23-250 UO-1 | 12/19/60 | | | 6110 13K13 |
| 354 | Reinforcement of Aztec Stabilator Leading Edge | PA-23-250 | 5/25/61 | 30334-00 | | 2730 13K17 |
| 359 | Modification of Fuel Cell Vent Tubes | PA-23 | 8/16/61 | | | 2810 13L1 |
| 363 | Inspection And Modification of Flaps | PA-23-250 UO-1 | 11/30/61 | ** | | 2750 13L10 |
| 367 | "Thermos Bottle" Type Fuel Cell Caps | PA-23/23-250 | 2/1/62 | | 68-13-03 | 2810 13L21 |
| 368 | Lycoming Service Instruction No. 1049 Dated December 29, 1961 | PA-23 | 2/7/62 | ** | | 7200 14A1 |
| 388 | Removal of Carburetor Heat Shroud Screen | PA-23-235 PA-23-250 | 11/2/62 | | | 7160 14B12 |
| 398 | Replacement of Fuel Control Valves "O" Rings | PA-23-235 PA-23-250 | 3/6/63 | 755-837 | | 7320 14C7 |
| 404 | Inspection of Pitch Servo Assembly Chain Adjustment Screw, Altimatic And Altimatic II | PA-23/23-235 PA-23-250 | 9/16/63 | ** | | 2210 14C17 |
| 407 | Rudder Trim Tab Control Rod, Installation of Roll Pin In, And Inspection of | PA-23 | 10/4/63 | 480-728 | 63-24-03 | 2720 14C23 |
| 425 | Lycoming Service Bulletin No. 298 | PA-23-235 PA-23-250 | 5/13/64 | ** | | 7200 14E17 |
| 432 | Inspection of Auxiliary Power Plug Solenoid | PA-23-250 | 8/25/64 | 487-153 | | 2400 14F10 |
| 438 | Priority Valve Actuating Cable, Clamping | PA-23-250 | 11/4/64 | 756-878 | | 3250 14F21 |
| 441 | Fuel System, Modification of, And Replacement of Electric Fuel Booster Pumps | PA-23-250 | 1/20/65 | 756-880 | | 2820 14G6 |
| 449A | Fuel Cells | PA-23-235 PA-23-250 | 2/18/69 | | 72-11-01 | 2810 14G16 |
| 454 | Pitch Breakaway Ball Bracket (Altimatic II) | PA-23-250 | 7/1/65 | 756-954 | | 2210 14G21 |
| 462 | Inspection of Engine Mount Tubes | PA-23-250 | 12/9/65 | 31215-00 31215-01 | 68-07-04 | 7120 14H13 |
| 464A | Fuel Injection, Bendix RS | PA-23 PA-E23-250 | 11/12/65 | | | 7310 14I1 |
| 466A | Stewart-Warner Heater Modification Kit | PA-23 PA-E23-250 | 8/8/67 | 756-995 | | 2140 14I4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------------------|------------------|--------------------|----------|------------|
| 472 | Conduct Installation Modification, B.F. Goodrich Service Bulletin No. E-65-30 | PA-23 PA-E23-250 | 3/16/66 | 757-017 | | 3020 14I12 |
| 474 | Increase In Flap Extension Speeds | PA-23-235/250 PA-E23-250 | 4/21/66 | 757-000 | | 2750 14I16 |
| 480 | FAA Aircraft Specification No. 1A10 Item 1(1) | PA-23/E23-250 | 7/8/66 | | General | 14J1 |
| 482 | Altitude Limitation, 25,000 Ft. Removal of | PA-23 PA-E23-250 | 9/20/66 | 757-063 | | 3410 14J2 |
| 483 | Airesearch Service Information Letter No. S. I. L. P-08 | PA-23 PA-E23-250 | 8/17/66 | | | 7200 14J5 |
| 486A | Cylinder Head Temperature Probe Location | PA-23/23-235 PA-23-250 | 4/16/68 | | | 7720 14J13 |
| 487 | Test Unit, Hydraulic Part Number 753-080 And Stand | PA-23 PA-235/250 | 2/13/67 | 753-080 | | 710 14J14 |
| 504 | B.F. Goodrich Service Bulletin No. E-67-34 | PA-23 PA-E23-250 | 4/8/68 | | | 3240 14K14 |
| 511 | Auxiliary Power Receptacle Installation, Modification To The | PA-23-250 | 8/30/68 | 760-180 | | 2400 14K23 |
| 519 | Alternator Ground Wire, Replacement And Relocation of | PA-23-250 | 12/31/68 | 760-282 | | 2430 14L17 |
| 520 | Inspection of Turbocharger Plenum Exhaust Welds | PA-23-250 | 2/3/69 | ** | | 7230 14L19 |
| 522 | Fuel Pump Restrictor Fitting | PA-23-250 | 1/14/69 | 760-275 | | 2820 15A1 |
| 525 | Addition of Lock Washers To Electrical Switch Installations | PA-23-250 | 2/28/69 | 407-103 407-133 | | 2450 15A8 |
| 532 | Voltage Regulation Component Grounding | PA-23-250 | 7/7/69 | 760-331 | | 2430 15B2 |
| 533 | Exhaust Stack Assembly | PA-23-250 | 11/10/69 | 32907-07 | | 7810 15B5 |
| 545 | Turbo (Lycoming) Aztec Owners Handbook And Power Setting Chart | PA-23-250 | 2/2/70 | ** | | 7220 15C10 |
| 547 | Lycoming Turbocharger Aztec, Modification | PA-23-250 | 3/25/70 | ** | | 8120 15C15 |
| 550B | Density Control Adjustment, Turbocharger (Ref. Avco-Lycoming Dated 4/5/74) | PA-23-250 | 7/10/74 | | | 8120 15C21 |
| 559 | Alternate Air System, Inspection of | PA-23-250 | 8/3/70 | 32343-00 | | 7160 15E4 |
| 560 | Scott Fuel Selector Valves | PA-23-250 | 8/7/70 | 757-520 | | 2820 15E6 |
| 562 | Scott Aviation Service Bulletin No. 35-32 | PA-23-235/250 PA-E23-250 | 8/25/70 | ** | | 2820 15E10 |
| 564 | Revised Hartzell Propellers | PA-23-250 PA-E23-250 | 9/28/70 | ** | | 6120 15E18 |
| 566 | Spacer Bushing Installation, Autopilot Servo | PA-23 PA-E23-250 | 11/25/70 | 760-472 | | 2210 15F3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------------------|------------------|--------------------|------------|-------------------|
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-23-250 PA-E23-250 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 579 | Heavy Duty Brake Disc Replacement | PA-23-250 PA-E23-250 | 5/26/71 | 760-538 | | 3240 15G16 |
| 580 | Fuel Selector Valve Packing Lubrication | PA-23-235 PA-23-250 PA-E23-250 | 5/24/71 | | | 2820 15G18 |
| 582A | Exhaust System (Turbocharger) Inspection And Modification (Lycoming S.B. #339A) | PA-23-250 | 6/3/74 | ** | 2008-14-07 | 8100 15G23 |
| 584 | Circuit Breaker Switch Inspection, 90 Amp Alternator | PA-23-250 | 7/8/71 | | | 2430 15H4 |
| 585 | Inspection of Hydraulic Lines | All Apache/Aztecs | 7/9/71 | | | 2910 15H6 |
| 591 | Inspection And Reinforcement Spar, Wing Front | PA-23-235 PA-23-250 | 8/31/71 | 760-521 760-524 | | 5710 15H12 |
| 592 | Mounts, Engine Shock (Lord) | PA-23-250 | 10/6/71 | 475-116 475-117 | | 7120 15H14 |
| 593 | Connector Plug, Harness, Strain Relief Hood Installation | PA-23-250 with Alt. V & VF/D | 10/11/71 | 760-555 | | 2400 15H15 |
| 606A | Fuel System, Inspection And Modification | PA-23-235 PA-23-250 | 8/23/72 | ** | 72-11-01 | 2800 15J3 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 613 | Brake Disc Inspection, Heavy Duty (Cleveland Aircraft Products S. B. #ESB-7002) | PA-23-250 | 5/11/72 | 760-538 | | 3240 15K4 |
| 617B | Piper Automatic Locator Transmitter Replacement | PA-23-250 | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 619 | Retainer Spring, Piper Part Number 83302-13, Inspection of | PA-23-235 PA-23-250 | 6/9/72 | | | 7330 15L5 7160 |
| 627 | Propeller Installation | PA-23-250 | 9/1/72 | | | 6100 16A1 |
| 628 | Control System Inspection, Stabilator Trim | PA-23-250 | 9/18/72 | 31970-03 | | 2740 16A4 |
| 629 | Fuselage Frame Tube Corrosion Inspection | All Apache/Aztecs | 9/5/72 | 760-703 | | 5320 16A8 |
| 630 | Lubrication of Fuel Valve Selector Mechanism | PA-23-250 | 9/13/72 | ** | | 2820 16A11 |
| 633 | Inspection And Repair of Flood Exposed Airplanes | PA-23 | 10/9/72 | | | 5300 16A18 |
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-23 | 10/24/72 | ** | | 2430 16B2 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---------------------------------|------------------|--------------------|----------|------------|
| 638A | Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos) | PA-23 | 2/8/73 | | | 2210 16B7 |
| 641 | Replacement Exhaust Stack Support Assembly | PA-23-250 | 2/26/73 | 760-702 | | 7810 16B13 |
| 642 | Alternator Inoperative Warning Light, Revised | PA-23-250 | 2/19/73 | 760-711 760-712 | | 2730 16B15 |
| 645 | Starter Vibrator Wiring Inspection | PA-23-250 | 4/12/73 | 492-431 492-644 | | 8010 16B20 |
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972) | PA-23 PA-23-235 PA-23-250 | 4/9/73 | ** | | 7610 16C14 |
| 655 | Airesearch Service Bulletin No. 1172-1A; Reference Avco Lycoming Service Bulletin No. 361 | PA-23-250 Turbocharged | 4/10/73 | ** | | 7200 16C21 |
| 667A | Stabilator Attachment Bolts | PA-23-235 PA-23-250 | 3/4/74 | ** | 74-13-03 | 2740 16E1 |
| 672 | Wing Rear Spar Inspection | PA-23-150/160 | 9/18/73 | ** | | 5710 16E12 |
| 674 | Overvoltage Relay Inspection | PA-23-250 | 1/3/74 | 760-787 | | 2430 16E16 |
| 676 | Weight And Balance/Equipment List Correction | PA-23-250 | 10/4/73 | | | 3200 16E20 |
| 682B | Reference Lycoming Service Bulletin 367D | PA-23-250 | 4/19/74 | ** | | 7230 16F9 |
| 683 | Stabilator Control Cable Attachment Fittings Inspection | PA-23-250 | 10/3/73 | | | 2740 16F16 |
| 695 | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974) | PA-23 PA-23-235 PA-23-250 | 5/3/74 | ** | | 2210 16G13 |
| 696 | Control Surface Balancing Recommendation | PA-23-250 | 5/2/74 | | | 2700 16G20 |
| 705 | Oil Tanks, Turbocharger Modification of, And Related Installation (Airesearch Service Bulletin No. 14.1.10 And 14.1.11 Dated February 6, 1974) | PA-23-250 | 4/16/74 | ** | | 8100 16H13 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-23 PA-23-235 PA-23-250 | 2/27/74 | ** | | 7710 16I11 |
| 710 | Inspection of Stabilator Control Cable And Rudder Control Cable Attachments | PA-23-250 | 5/2/74 | | | 2740 16J1 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-23/PA-23-160
PA-23-235/PA-23-250
PA-E23-250

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------|-----------------|------------|
| 717 | Brake Assembly Cylinder Retract, Improved (Cleveland Aircraft Products Service Letter No. 7000-5) | PA-23-250 | 9/18/74 | 751-507 | | 3240 16J16 |
| 723 | Glideslope Indicator Placard | PA-23-250 | 8/14/74 | ** | | 3430 16K11 |
| 726 | Cigar Lighter Placard 24 Volt | All PA-23-235/ 23-250 | 8/8/74 | 80247-02 | | 3310 16K16 |
| 740 | Fuel Requirements | PA-23 | 4/20/76 | | | 2800 17A3 |
| 786A | Refined Engine Mount Assembly | PA-23-250 | 8/31/76 | ** | | 7120 17F15 |
| 807A | Stabilator Outboard Nose Rib Installation | PA-23-250 | 9/8/77 | 761-141 | 2021-25-11 | 5570 17H13 |
| 815 | Radar Antenna Mounting Plate Inspection And Modification | PA-23-250 | 3/8/78 | 48881-02 | | 3440 17I15 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters | PA-23-250 | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 830 | 24 Volt Cigar Lighter Element Replacement | PA-23-250 | 11/22/77 | ** | | 3310 17J19 |
| 846 | Stabilator Assembly Lower Surface Rivet Inspection | PA-23-250 | 5/3/78 | ** | | 2740 17K23 |
| 853 | Inspection For Cracked Flap Spars At Hinge Area | PA-23 PA-23-235 PA-23-250 | 6/8/79 | ** | 81-04-05 | 2750 17L20 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 20C2 |
| 1086 | Propeller Blade De-ice Boots Maintenance | PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250 | 7/16/2004 | N/A | | 3112 20F3 |
| 1093B | Electrical Contactor Replacement Kit | PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250 | 11/28/2017 | 88371 | | 2400 |
| 1116A | Contactor Maintenance | PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250 | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | PA-23 PA-23-160 PA-23-235 PA-23-250 PA-E23-250 | 4/27/2011 | MS20995-C32 | | 2800 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | DATE | PART/KIT NO. | A.D. NO. | ATA CODE | GRID |
|--------|---|---|-----------|-----------------|-------------|-------------|------|
| 1175 | POH Report 1948 Equipment List | PA-23-250 Aztec "F" | 12/2/2013 | N/A | | 2500 | |
| 1188 | Landing Gear Hydraulic System Filter Maintenance | PA-23-150/160 PA-23-235 PA-23-250 | 3/19/2015 | N/A | | 2912 | |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 | |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 | |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 | |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | DATE | PART/KIT NO. | A.D. NO. | ATA CODE | GRID |
|--------|---|------------------------|----------|--------------------|----------------------|----------------------|-------|
| 177 | Firewalls | All PA-24 Models | 8/10/51 | | | | 13B13 |
| 207 | Oil Quick Drain Valve Assembly, Part No 12956-04 | PA-24 | 6/18/53 | | | | 13C4 |
| 283A | Inspection Forms 100/500/1000 Hour | PA-24 | 2/26/58 | | | 500 | 13E24 |
| 295A | Aircraft Finishes | PA-24 PA-30 | 1/3/64 | | | | 13F12 |
| 299 | Cabin Door Lower Hinge Reinforcement, Cabin Door Holder And Landing Gear Oil Level Instructions | PA-24-180 PA-24-250 | 6/10/58 | ** | | 5210 | 13F15 |
| 301 | PA 24 Comanche Landing Gear | PA-24 | 8/12/58 | | | 3200 | 13F20 |
| 302 | Fuel Gauge Ground Wire | PA-24-180/250 | 8/19/58 | | | 2840 | 13F21 |
| 303A | Aircraft Finish | PA-24 | 9/23/59 | | | 5300 | 13F23 |
| 305 | Miscellaneous Modifications; Door Latch, Oil Separator Inlet Hose, Landing Gear Retraction Tube Arm | PA-24-180/250 | 10/1/58 | ** | 58-25-05 | 5200 7920 3230 | 13G14 |
| 310 | Locking of Landing Gear Motor Release Arm | PA-24-180/250 | 11/10/58 | | | 3230 | 13H1 |
| 311 | PA-24 1959 Owners Handbook | PA-24 | 11/22/58 | | | General | 13H3 |
| 312 | Tooling - Piper Autocontrol | PA-24 | 11/24/58 | ** | | 2210 | 13H4 |
| 314A | Landing Gear Warning System | PA-24-180/250 | 6/8/59 | 754-221 754-217 | | 3260 | 13H6 |
| 315 | PA-24 Comanche Landing Gear Transmission Assembly | PA-24 | 2/4/59 | | | 3200 | 13H7 |
| 316 | Cabin Sealing | PA-24-180/250 | 4/7/59 | ** | | 5300 | 13H16 |
| 317 | 50 Ampere Generator Installation | PA-24-180/250 | 4/6/59 | 754-230 | | 2400 | 13H18 |
| 321 | Piper Autocontrol | PA-24 | 7/8/59 | | | 2210 | 13H22 |
| 323 | Defroster Operation | PA-24-180/250 | 11/23/59 | | | 2140 | 13H24 |
| 324C | Maintenance And Inspection of Exhaust Systems And Heat Exchanger | PA-24 | 1/22/69 | | 62-26-05 68-05-01 | 7810 | 13I1 |
| 325 | Front Cabin Window Defroster Kit | PA-24-180/250 | 12/24/59 | 754-293 | | 2140 | 13I9 |
| 333C | Radio Shelf Capacities | All PA-24 | 1/28/63 | | | 3400 | 13J13 |
| 339 | Insulation of Wiring At Starter Solenoid Switch | PA-24-180/250 | 7/12/60 | 13586-94 | | 8010 | 13J21 |
| 345 | Hartzell Service Bulletin #75 - Inspection of Hartzell Governor For Presence of Vent Hole | PA-24-250 | 9/14/60 | | | 6110 | 13K5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------|------------------|--------------|----------|------------|
| 346 | Relocation of Safety Belt Buckle - Right Front Seat Only | PA-24-180/250 | 9/29/60 | | | 5340 13K8 |
| 347 | Installation of Dry Vacuum Pump, Exhaust Tube | PA-24-180/250 | 12/2/60 | 754-358 | | 3710 13K9 |
| 352 | Modification of Windshield Defroster System | PA-24-180/250 | 12/28/60 | 754-380 | | 2140 13K14 |
| 356 | Installation of Landing Gear Retraction System, 30 Amp Circuit Protector | PA-24-180/250 | 3/31/61 | 454-661 | 63-27-03 | 3230 13K21 |
| 360 | Flap Retractor | PA-24-180/250 | 9/5/61 | 754-413 | | 2750 13L3 |
| 364A | Rubatex Blocks In Detached Or Loose Wing Panels | PA-24-180/250 | 3/14/62 | | | 5700 13L15 |
| 365 | Special Bolt For Nose Gear Drag Link | PA-24-180/250 | 1/3/62 | 22066-00 | | 3200 13L17 |
| 366 | Nose Gear Clevis | PA-24-180/250 | 1/3/62 | 20859-03 | 65-25-03 | 3220 13L19 |
| 367 | Caps, Fuel Cell, "Thermos Bottle" Type | PA-24-180/250 | 2/1/62 | | 68-13-03 | 2810 13L21 |
| 368 | Lycoming Service Instruction #1049 Dated 12/29/61 | PA-24-250 | 2/7/62 | ** | | 7200 14A1 |
| 370 | Modification To Engine Breather Line | PA-24/24-250 | 2/23/62 | | | 7200 14A7 |
| 372 | Landing Gear Switch | PA-24-250 | 3/8/62 | | | 3230 14A10 |
| 373 | Dry Vacuum Pumps (Airborne Mechanisms) Models 113A1 And 113A5, Installation of Oil Shields On | PA-24-180/250 | 3/29/62 | 756-143 | | 3710 14A11 |
| 379 | Landing Gear Safety Switch Harness | PA-24-180/250 | 8/10/62 | 754-475 | 64-22-03 | 3200 14A20 |
| 380 | Door Hinges, Main Landing Gear, And Nose Gear Door Hinge Bushings | PA-24-180/250 | 8/8/62 | ** | | 3210 14A22 |
| 382 | Redesigned Landing Gear Selector Switch Knob | PA-24-250 | 9/27/62 | ** | | 3200 14B1 |
| 393 | Replacement of Bendix Fuel Pump | PA-24-250 | 2/1/63 | 481-686 | | 2820 14B22 |
| 395 | Flap Retraction Springs | PA-24-250 | 2/11/63 | 83302-54 | | 2750 14C1 |
| 397 | Inspection of Alternate Air Door Hinge Pin | PA-24-250 | 2/21/63 | | | 7160 14C5 |
| 404 | Inspection of Pitch Servo Assembly Chain Adjustment Screw Altimatec And Altimatec II | PA-24-180/250 | 9/16/63 | ** | | 2210 14C17 |
| 408 | Installation of Fuel Valve Control Stop | PA-30 | 10/9/63 | 756-774 | | 7320 14D1 |
| 409 | Replacement of Nose Gear Retraction Tube | PA-30 | 10/9/63 | 21109-05 | 64-16-06 | 3230 14D4 |
| 411 | Drain Holes In PA-30 Cowling | PA-30 | 10/17/63 | | | 7110 14D8 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------|------------------|--------------------|----------|------------|
| 412A | Muffler And Tailpipe Support | PA-24-250 | 5/6/64 | 756-775 | 68-05-01 | 7810 14D11 |
| 414 | Modification of Right Side Exhaust Stack | PA-24-250 | 11/27/63 | 756-777 756-778 | | 7810 14D15 |
| 415 | Sealing of The Nose Wheel Well | PA-30 | 12/3/63 | | | 3240 14D18 |
| 416 | Heater Valve Friction Spring Installation | PA-30 | 12/3/63 | 756-779 | | 2140 14D20 |
| 417 | Replacement of Fuel Injector Inlet Screens | PA-30 | 12/16/63 | 756-782 | | 7310 14E1 |
| 418 | Replacement of Fuel Flow Gauge | PA-30 | 12/16/63 | 24536-00 | | 7330 14E3 |
| 419 | Inspection of Heater Air Distribution Box Attachment Screws | PA-30 | 2/24/64 | ** | | 2140 14E4 |
| 420A | Removal of Vanes From Throat of Carburetor Air Box | PA-24-250 | 3/10/72 | | 64-10-04 | 7200 14E6 |
| 422 | Rework of Propeller Spinner Assembly | PA-30 | 3/10/64 | 756-796 | | 6110 14E11 |
| 424 | Installation of "Generators On" Placard | PA-30 | 4/20/64 | ** | | 2430 14E15 |
| 425 | Lycoming Service Bulletin No. 298 | PA-24-180/250 | 5/13/64 | ** | | 7200 14E17 |
| 426 | Propeller Flange Inspection, Crankshaft (Per Lycoming Service Bulletin No. 300) And Propeller Blades, Inspection of (Per Hartzell Service Bulletin No. 86) | PA-30 | 6/26/64 | | | 6110 14E22 |
| 430 | Inspection of Nose Gear Drag Link Assembly | PA-30 | 8/17/64 | | | 3220 14F6 |
| 431 | Insulation of Motor Mounts | PA-24-250 | 9/2/64 | 756-831 | | 7120 14F8 |
| 433 | Installation of Placard, (Cowl Flaps Open) | PA-24-400 PA-30 | 9/9/64 | 755-881 | | 7110 14F12 |
| 434 | Lycoming Service Instruction #1110 | PA-24-250 | 9/30/64 | 25006-00 | | 7200 14F14 |
| 435 | Relocation of Nose Wheel Steering Tube Boot | PA-24-250 | 9/30/64 | 21378-00 | | 3250 14F15 |
| 437 | Replacement of Fuel Gauge Assembly | PA-24-400 | 11/4/64 | 450-771 | | 2820 14F19 |
| 439 | Lycoming Service Bulletin No.300A | PA-30 | 11/13/64 | | | 6110 14G1 |
| 440 | Engine Compartment Changes | PA-24-400 | 12/3/64 | ** | | 7200 14G4 |
| 444 | Installation of Special Steel Fittings On Auxiliary Fuel Pumps | PA-24-250 | 2/24/65 | 751-268 | | 2810 14G9 |
| 445 | Installation of Nose Gear Drag Link Clevis Reinforcement Bracket | PA-24-180/250 | 4/21/65 | 756-911 | | 3270 14G11 |
| 446 | Fuel Leakage At the Fuel Cell Gauge | PA-24-400 | 3/1/65 | 756-902 | | 2810 14G13 |
| 447 | Inspection of Landing Gear Transmission Retract Spring | All PA-24 PA-30 | 3/26/65 | ** | | 3230 14G14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|----------------------------|------------------|--------------------|----------|------------|
| 449A | Fuel Cells | PA-24-180/250/400 PA-30 | 2/18/69 | | | 2810 14G16 |
| 451 | Fuel System Purging Valve | PA-24-400 | 5/14/65 | 756-922 | 66-30-07 | 2810 14G18 |
| 453 | Engine Mount Refinishing | PA-24-400 | 8/23/65 | 756-306 | | 7110 14G19 |
| 459 | Mixture Control Cable Shield | PA-24-400 | 10/6/65 | 25079-00 | | 7320 14H8 |
| 460 | Revision To PA-30 Service Manual And Owner's Handbook | PA-30 | 9/17/65 | | | 3260 14H10 |
| 461 | Inspection of Propeller Blades | PA-30 | 9/28/65 | | | 6110 14H11 |
| 464A | Bendix RS Fuel Injection | PA-24-250/260 PA-30 | 11/12/65 | ** | | 7310 14I1 |
| 465 | Airworthiness Directive No. 65-25-03 | PA-24/24-250 | 12/20/65 | | | 1617 14I3 |
| 469 | Replacement of Allowance Placard, Baggage/Passenger | PA-24-260 | 2/11/66 | 756-997 | | 5430 14I7 |
| 470 | Starter Vibrating | PA-24-400 | 4/1/66 | 492-671 | | 8010 14I8 |
| 477 | FAA Airworthiness Directive No. 66-12-2 (Temporary Revision To Airspeed Limits) | PA-30 | 5/18/66 | | | 3410 14I19 |
| 478 | Inspection of Baggage Door Latch Enlargements | PA-24-260 | 6/13/66 | | 66-18-04 | 5210 14I22 |
| 481 | Muffler And Tailpipe Support | PA-24-250 | 9/15/66 | 757-058 | 68-05-01 | 7810 14J2 |
| 486A | Cylinder Head Temperature Probe Location | PA-24 | 4/16/68 | | | 7720 14J13 |
| 490 | Rajay Corporation Service Letter No. 10 (Relocation of Turbocharger Low Oil Pressure Warning Light Wire) | PA-30 | 6/28/67 | 757-312 | | 7930 14J16 |
| 511 | Modification To The Auxiliary Power Receptacle Installation | PA-24-260 PA-39 | 8/30/68 | 760-181 760-711 | | 2400 14K23 |
| 516 | Modification Fuel Cell Vent System | PA-24-180/250 | 3/7/69 | 760-277 760-281 | 68-13-03 | 2810 14L11 |
| 518 | Modification of Exhaust Mufflers | PA-24-260 | 1/22/69 | 760-289 | 68-05-01 | 7820 14L14 |
| 525 | Addition of Lock Washers To Electrical Switch Installations | PA-30 | 2/28/69 | ** | | 2400 15A8 |
| 532 | Voltage Regulator Component Grounding | PA-30 | 7/7/69 | 760-332 | | 2430 15B2 |
| 539 | Fuel Selector Valve Control Handle Replacement | PA-30 | 2/18/70 | 760-356 760-357 | | 2820 15B20 |
| 541 | Fuselage Nose Cone Drain Holes | PA-30 | 12/4/69 | | | 5350 15C1 |
| 542 | Control Surface Travel And Cable Tension | PA-30 | 2/17/70 | | | 2700 15C3 |
| 543 | Induction System Drain Tube Relocation | PA-24-260 "C" | 11/17/69 | 760-351 | | 7160 15C5 |
| 546A | Nose Gear Push-Pull Rod Assembly | PA-24-180/250 PA-24-400 | 3/10/70 | 757-352 | | 3250 15C12 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------|---------------|
| 549 | New Owner's Handbook | PA-30 | 3/20/70 | ** | | General 15C19 |
| 552 | Counter Rotating Power Plant Conversion-Kit | PA-30 | 5/1/70 | 760-368 | | 7100 15D3 |
| 556A | Turbocharger Waste Gate Return Spring | PA-30/39 | 9/21/70 | ** | | 8120 15D17 |
| 557 | Rajay Oil Scavenge Pump | PA-30 | 6/16/70 | ** | | 7250 15D19 |
| 558 | Air Flow Modification Kit | PA-30 | 7/1/70 | 760-409 | | 2700 15E1 |
| 564 | Revised Hartzell Propellers | PA-30/39 | 9/28/70 | ** | | 6120 15E18 |
| 565 | Rear Cabin Dome Light Mounting Screw | PA-24-260 PA-30/39 | 10/13/70 | | | 3320 15F1 |
| 566 | Autopilot Servo Spacer Bushing Installation | PA-24-260 PA-30/39 | 11/25/70 | 760-472 | | 2210 15F3 |
| 569 | Engine Compartment Modifications | PA-24-260 | 12/28/70 | 760-463 | | 7200 15F14 |
| 574 | Revision To Emergency Gear Checklist | PA-24-260 PA-30/39 | 3/22/71 | | | 3200 15F20 |
| 575 | Landing Gear (Nose) System Inspection | PA-30/39 | 4/8/71 | | | 3220 15F23 |
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-24-250/260 PA-24-400 PA-30/39 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 584 | 90 Amp Alternator Circuit Breaker Switch Inspection | PA-30/39 | 7/8/71 | | | 2430 15H4 |
| 589 | Stainless Steel Fuel Selector Valve Housing | PA-30 | 8/18/71 | 757-187 | 83-10-01 | 2820 15H10 |
| 595 | Wing Flap System Maintenance | PA-24-250/260 PA-24-400 PA-30/39 | 10/11/71 | | | 2750 15I1 |
| 596A | Nose Landing Gear System Product Advancement Information | All PA-24 PA-30/39 | 9/5/75 | ** | | 3220 15I3 |
| 598 | Adjustable Duct Micro Switch Inspection | PA-39 | 11/16/71 | 487-940 | | 2140 15I9 |
| 599 | Exhaust Wing Panel Corrosion Protection | PA-30/39 | 11/23/71 | | | 5750 15I10 |
| 605 | Reissue of Owner's Handbook | PA-24-260T | 2/7/72 | ** | | 8100 15J1 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 610 | Tail Control Surface Inspection, Maintenance And Repair Information PA-24 Comanche Service Manual Temporary Revision TR 720127 | All PA-24 | 2/28/72 | ** | | 2700 15J23 |
| 617B | Piper Automatic Locator Transmitter Replacement | PA-24 PA-39 | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 623 | Inspection of Rajay Alternate Air Valve Bracket | PA-30/39 T.C. | 8/9/72 | ** | | 7160 15L14 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|----------|-------------------|
| 627 | Propeller Installation | PA-24-260 PA-30/39 | 9/1/72 | | | 6100 16A1 |
| 633 | Inspection And Repair of Flood Exposed Airplanes | PA-24 PA-39 | 10/9/72 | | | 5300 16A18 |
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-24 PA-30 | 10/24/72 | ** | | 2430 16B2 |
| 637 | Rajay Service Letter No. 19, Dated September 5, 1972 | PA-30/39 T.C. | 10/31/72 | ** | | 7160 16B5 |
| 638A | Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication—Rack And Pinion Type Servos) | PA-24 PA-30 | 2/8/73 | | | 2210 16B7 |
| 642 | Revised Alternator Inoperative Warning Light | PA-39 | 2/19/73 | 760-711 | | 2430 16B15 |
| 648 | Battery Ground Inspection And Modification | PA-24-260 "C" | 3/8/73 | | | 2430 16C2 |
| 650 | Inspection of Transmission Assemblies, Landing Gear Retraction And Flap Control | PA-24-180/250 PA-24-260/400 PA-30/39 | 9/27/73 | ** | | 3230 16C5 2750 |
| 651 | Rudder Balance Weight Arm Attachment Angle Installation Kit | PA-24-180/250 PA-24-260 | 2/27/73 | 760-732 | | 2720 16C10 |
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972) | PA-24 PA-30 | 4/9/73 | ** | | 7610 16C14 |
| 657 | Fuel Selector Valve Control Handle Modification | PA-30/39 | 9/13/73 | 760-788 | | 2820 16D3 |
| 665A | Intake Valves; Rotator Type (Reference Avco Lycoming Service Instruction No. 1280 A. 9/28/73) | PA-24-400 | 10/24/73 | ** | | 7160 16D16 |
| 667A | Stabilator Attachment Bolts | PA-24-260/400 PA-30 | 30/4/74 | ** | 74-13-03 | 2740 16E1 |
| 679 | Fuselage Aft Bulkhead Inspection | PA-30/39 | 1/21/74 | 760-783 | 74-16-08 | 5310 16F2 |
| 682B | Reference Lycoming Service Bulletin 367D | PA-24-250 PA-24-400 PA-30 | 4/19/74 | ** | | 7230 16F9 |
| 686 | Inspection of Fuel Pressure Hose Assembly | PA-24-250/260 | 1/3/74 | 17766-43 | | 7330 16F20 |
| 687 | Stabilator Modification | PA-24-250/260 | 6/19/74 | 760-747 | 72-22-05 | 2740 16F23 |
| 695 | Roll Servo Inspection, Maintenance And Sheer Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38 Dated March 18, 1974) | PA-24 PA-30 | 5/3/74 | ** | | 2210 16G13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-24
PA-30/39

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------|-----------------|------------|
| 696 | Control Surface Balancing Recommendation | PA-24 PA-30/39 | 5/2/74 | | | 2700 16G20 |
| 707 | Flyball Assembly To Improve RPM Control. Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-24 PA-30/39 | 2/27/74 | ** | | 7710 16I11 |
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-24 | 5/31/74 | ** | | 7410 16J18 |
| 751 | Fin Front Spar Modification | PA-24-180-250 PA-24-260/400 | 7/7/75 | | | 5520 17A23 |
| 758 | Bendix Ignition Switches, Inspection of; Ref: Bendix Service Bulletin No. 583 | PA-24-180/250 PA-24-260/400 | 5/17/76 | 761-065V | | 7410 17C2 |
| 772 | Stabilator Attachment Bolts | PA-39 | 2/16/76 | ** | 74-13-03 | 2740 17E4 |
| 777 | Fin Front Spar Modification | PA-30/39 | 6/16/76 | | 76-18-05 | 2740 17E12 |
| 782B | Landing Gear Manual Extension System And Nose Gear Down Lock Spring Installation | PA-24 PA-24-250/260 PA-24-400 PA-30/39 | 12/1/77 | ** | 77-13-21 | 3230 17E23 |
| 787 | Aileron Spar Inspection And Reinforcement | PA-24/24-250/260 PA-24-400 PA-30/39 | 12/1/76 | 760-914 | 77-08-01 | 5750 17F17 |
| 850 | Aileron Nose Rib Inspection/Reinforcement | PA-24 PA-24-250/260 PA-24-400 PA-30/39 | 4/18/79 | | 79-20-10 | 5750 17L8 |
| 851 | PART A - Fuel Valve Internal Leak Check | PA-24-400 PA-30/39 | 8/31/78 | ** | 79-12-08 | 2810 17L11 |
| 851 | PART B - Fuel System Draining Procedure-Water Contamination | PA-30/39 | 8/31/78 | ** | 79-12-08 | 2810 17L12 |
| 851 | PART C - Fuel System Draining Procedures-Water Contamination | PA-24-400 | 8/31/78 | | 79-12-08 | 2810 17L14 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 20C2 |
| 1093B | Electrical Contactor Replacement Kit | PA-24 PA-24-250/260 PA-24-400 PA-30 | 11/28/2017 | 88371 | | 2400 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|---------------------|-----------------|-------------|-------------|
| 1116A | Contactora Maintenance | PA-24 PA-24-250/260 PA-24-400 PA-30/39 | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | PA-24 PA-24-250/260 PA-24-400 | 4/27/2011 | MS20995-C32 | | 2800 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|------------------------------------|------------------|----------------------|----------------------|---------------------------|
| 177 | Firewalls | All PA-28/28R Models | 8/10/51 | | | 13B13 |
| 295A | Aircraft Finishes | All | 1/3/64 | | | 13F12 |
| 324C | Maintenance And Inspection of Exhaust Systems And Heat Exchanges | PA-28-140/150/160/180/235 | 1/22/69 | | 62-26-05 68-05-01 | 7810 1311 |
| 373 | Installation of Oil Shields On Dry Vacuum Pumps (Airborne Mechanisms, Models 113A1 And 113A5) | PA-28-150/160 | 3/29/62 | | | 3710 14A11 |
| 374 | Modification of Bulkhead To Prevent Control Cable Interference | PA-28-150/160 | 4/10/62 | 754-461V | | 5310 14A13 |
| 375 | Control Shaft-Left Hand, Installation of Micarta Sleeve On | PA-28-150/160 | 4/12/62 | 62852-00V | | 2700 14A15 |
| 381 | Replacement of Wing Panels Service | PA-28-150/160 | 7/9/62 | ** | | 5730 14A23 |
| 386 | Miscellaneous Airframe Modifications | PA-28-150/160 | 9/4/62 | ** | | 5300 14B7 5320 5550 |
| 389 | Inspection of Exhaust Stacks | PA-28-150/160 | 12/11/62 | ** | 62-26-05 | 7810 14B13 |
| 390 | Cherokee Gas Cap Placard | PA-28-150/160/180 | 1/3/63 | 62142-00V | | 2810 14B16 |
| 391 | Cherokee Sun Visors | PA-28-150/160/180 | 1/11/63 | 63230-00V | | 2510 14B18 |
| 394 | Radio And Auto Control Cooling Kits | PA-28-150/160/180 | 2/4/63 | 754-477V 754-494V | | 2300 14B23 |
| 396 | Inspection of Shaft Assembly (On Control T-Bar And Control Wheels), Double Sprocket | PA-28-150/160 | 2/14/63 | 62818-00V | 64-06-06 | 2710 14C2 |
| 402 | Installation of Heat Shield Kit | PA-28-150/160/180 | 5/22/63 | 756-727 | | 2140 14C13 |
| 413 | Inspection of Nose Gear (Upper) Oleo Bearing | PA-28-150/160/180 | 11/25/63 | 452-419 | | 3230 14D13 |
| 421 | Inspection of Oil Coolers | PA-28-235 | 3/4/64 | 18622-00 | | 7920 14E9 |
| 425 | Lycoming Service Bulletin No. 298 (Ac Fuel Pump Vent Restriction) | PA-28-140/150/160 PA-28-180/235 | 5/13/64 | ** | | 2800 14E17 |
| 427 | Fuel Cooling Modification | PA-28-150/160/180 | 6/29/64 | ** | | 2820 14F2 |
| 429 | Replacement of Oil Coolers | PA-28-235 | 8/10/64 | ** | | 7920 14F3 |
| 436 | Check of Alternator Through Bolts | PA-28-140/150/160 PA-28-180/235 | 10/9/64 | 753-210V | | 2430 14F17 |
| 442 | Lycoming Service Instruction No. 1110 (Ac Fuel Pump Replacement) | PA-28-140/150/160 PA-28-180/235 | 12/14/64 | ** | | 2820 14G7 |
| 443 | Oil Line Relocation Kit | PA-28-150/160/180 | 1/27/65 | 756-905V | | 7920 14G8 |
| 450 | Stabilator Trim Installation | PA-28-140/150/160 PA-28-180/235 | 9/24/65 | ** | | 2740 14G17 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|------------------------|----------|------------|
| 456 | Cherokee 235 Constant Speed Propeller Control | PA-28-235 | 6/4/65 | 756-959V | | 6120 14H2 |
| 457 | Plastic On The Cherokee C Spinners | PA-28-150/160/180 | 6/29/65 | 756-963V | 66-20-05 | 6110 14H3 |
| 458 | Throttle Clamp | PA-28-140/150/160 PA-28-180/235 | 10/8/65 | 554-860V | | 7610 14H5 |
| 471A | Inspection of Propeller Spinner And Spinner Attaching Bulkhead | PA-28-150/160/180 | 5/23/66 | ** | 66-20-05 | 6110 14I9 |
| 473 | Sensenich Service Bulletin No. R-11 (Inspection of Mid-Blade Area of 76 EMM And 76 EMMS Propellers) | PA-28-180 | 3/1/66 | | | 6110 14I14 |
| 484 | Fuel System Operating Procedures | PA-28-235 | 12/20/66 | | | 2800 14J7 |
| 486A | Cylinder Head Temperature Probe Location | PA-28-140/150/160/180/ 235 | 4/16/68 | | | 7720 14J13 |
| 494 | Inspection of Cherokee Landing Gears | PA-28-140/150/160 PA-28-180/235 | 11/7/67 | ** | | 3200 14J24 |
| 495 | Inspection of Constant Speed Propeller Control Cable | PA-28-235 | 1/29/68 | ** | | 6120 14K2 |
| 501 | Oil Sump Drain Valve | PA-28R-180 | 5/2/68 | 756-517 | | 7160 14K10 |
| 503 | Inspection of Oil Cooler Hose | PA-28-140 | 4/18/68 | | | 7920 14K13 |
| 526 | Sensenich Service Bulletin No. R-13 | PA-28-140/150/160/180/ 235 | 5/15/69 | 760-325V | | 6100 15A11 |
| 527D | Inspection of Control Wheels | PA-28-140/150/160 PA-28-180/235 | 6/21/78 | ** | 69-22-02 | 2700 15A14 |
| 534A | Availability of Engine Oil Quick Drain Valve | PA-28R-200 | 1/7/70 | 492-172V | | 7920 15B7 |
| 535A | Rudder Trim Locking Pin | PA-28-140/180/235 PA-28R-180/200 | 9/26/69 | | | 2720 15B9 |
| 561 | Inspection of Cherokee Muffler Assembly | PA-28-140/150/160/S160 PA-28-180/S180 | 8/12/70 | 99482-00V 99482-02V | | 7820 15E8 |
| 566 | Autopilot Servo Spacer Bushing Installation | PA-28-140/180/235 PA-28R-180/200 | 11/25/70 | ** | | 2210 15F3 |
| 567 | Flight Manual Supplement (Expanded Center of Gravity Range) | PA-28-180/235 | 1/25/71 | ** | | 3200 15F6 |
| 568 | Inspection of Engine Mount Tubes | PA-28R-180/200 | 1/5/71 | ** | | 7120 15F8 |
| 571 | Flap Handle Assembly Modification | PA-28-140/150/160/180/ 235 PA-28R-180/200 | 3/30/71 | 400-673 | | 2750 15F15 |
| 576 | Stabilator Balance Weight Tube Replacement | PA-28-140/150/160 PA-28-180/S180/235 PA-28R-180/200 | 4/20/71 | | | 5510 15G2 |
| 577 | Replacement Bridle Cable Servo Clamp | PA-28-140/150/160 PA-28-180/235 PA-28R-180 | 6/1/71 | 757-863V | | 2210 15G8 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|------------|------------|
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-28R-180/200 PA-28R-201 PA-28RT-201 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 581 | Inspection of Aileron Hinge Doublers | PA-28-140/150/160/180/235 PA-28R-180/200 | 7/12/71 | 760-540V | | 5550 15G20 |
| 587 | Engine Baffle Modification | PA-28R-200 | 9/16/71 | 760-558V | | 7230 15H9 |
| 607 | Emergency Gear Lever Knob | PA-28R-180/200 | 2/18/72 | 66980-02V | 72-04-03 | 3200 15J9 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 611 | Repositioning of Oil Cooler Hose | PA-28-140 | 4/28/72 | 760-599V | | 7920 15J24 |
| 612A | Fuel Leakage - Fuel Sender Unit | PA-28-140/150/160/180/235 PA-28R-180/200 | 6/8/72 | 68101-00V | | 7330 15K1 |
| 614 | Stabilator Attachment Fittings Bolt Torque | PA-28-140/150/160/180/235 PA-28R-180/200 | 6/15/72 | | 72-14-07 | 2740 15K6 |
| 615 | Stabilator Drain Holes | PA-28-140/150/160/180/235 PA-28R-180/200 | 7/6/72 | | | 2740 15K8 |
| 616 | Main Landing Gear Trunnion Repair | PA-28R-180/200 | 8/3/72 | ** | | 3210 15K14 |
| 617B | Piper Automatic Locator Transmitter Replacement | PA-28-140/180/235 PA-28R | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 620 | Forward Cabin Door Reinforcement | PA-28-140/150/160 PA-28-180/235/28S-180 PA-28R-180/200 | 2/23/73 | 760-729V | | 5210 15L8 |
| 621 | Main Landing Gear Torque Link Replacement | PA-28-140/150/160/180/235 | 11/9/72 | 78032-00V | | 3210 15L10 |
| 626 | Landing Gear Bolt Lubrication | PA-28R-180/200 | 11/20/72 | | | 3200 15L23 |
| 634 | Revision Pilot's Operating Manual | PA-28R-200 | 12/14/72 | ** | | 1200 16A23 |
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-28-180 PA-28R-200 | 10/24/72 | ** | | 2430 16B2 |
| 638A | Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos) | PA-28-150/160/180/235 | 2/8/73 | | | 2210 16B7 |
| 644 | Precautionary Throttle Operating Placard | PA-28-140/150/160 | 2/8/73 | 76406-00V | 72-24-02 | 7610 16B19 |
| 647 | Seat Back Stop Modification | PA-28-140/180/235 PA-28R-200 | 3/31/73 | 760-740V | | 2510 16C1 |
| 649 | Airplane Flight Manual/Weight And Balance Revision | PA-28-235 | 5/3/73 | ** | | 800 16C4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|-------------------------------|----------|---|
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972) | PA-28-140/150/160/180/235 | 4/9/73 | ** | | 7610 16C14 |
| 662 | Engine Mount Bolt Torque | PA-28-140/150/160/180/235 PA-28R-180/200 | 7/6/73 | AN960-616 | | 7120 16D10 |
| 665A | Inspection of Intake Valves, Rotator Type Knob, Emergency Gear Lever | PA-28R-200 | 10/24/73 | ** | | 7160 16D16 |
| 670A | Throttle Control Modification | PA-28-140 | 6/24/74 | 760-780V 760-872V | 74-13-04 | 7610 16E7 |
| 671 | Rudder Bar Assembly Inspection And Modification | PA-28-140/150/160/180/235 PA-28R-180/200 | 10/5/73 | | | 2720 16E9 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No 367D) | PA-28 PA-28R | 4/19/74 | | | 7230 16F9 |
| 684 | Landing Gear Lubrication | PA-28R-200 | 1/9/74 | | | 3200 16F18 |
| 695 | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No ML-38, Dated March 18, 1974) | PA-28-150/160/235 | 5/3/74 | ** | | 2210 16G13 |
| 700 | Toe Brake System Modification | PA-28-140/151 PA-28-180/235 PA-28R-200 | 4/9/74 | 760-842V | | 3240 16H5 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No 75, Dated November 16, 1973) | PA-28-235 PA-28R-180/200 | 2/27/74 | ** | | 7710 16I11 |
| 715 | Emergency Locator Transmitter Switch Cover Modification | PA-28-140/151 PA-28-180/235 PA-28R-200 | 9/27/74 | 760-876V | | 2560 16J12 |
| 718 | Bendix Magneto Bulletin No 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-28R | 5/31/74 | ** | | 7410 16J18 |
| 720 | Fuel Quantity Placard Inspection, Section I, Landing Light WIRE Rerouting, Section II | PA-28-235 | 6/26/74 | ** | 74-18-06 | 2840 16K2 3340 |
| 731 | Cherokee Warrior Product Refinement Program | PA-28-151 | 10/15/74 | 760-854 760-855 760-856 | | 2800 16L1 3340 6110 7110 7160 7230 7920 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|----------------------------------|----------|------------|
| 734 | Bendix ADF-T-12 C/D Installation Inspection And Modification | PA-28-140/151/180/235 PA-28R-200 | 12/3/74 | 760-857V | | 3450 16L8 |
| 735 | Muffler Shroud Modification | PA28-151/180 | 12/11/74 | | | 7820 16L11 |
| 738A | Modification of The Overhead Fresh Air Vent System | PA-28-140/180/235 PA-28-151 PA-28R-200 | 1/14/75 | 760-900V 760-901V 760-902V | | 2120 16L20 |
| 740 | Fuel Requirements | PA-28-140/150/151/160/ 180/181/235 | 4/20/76 | | | 2800 17A3 |
| 744 | Steering System Modification | PA-28-140/151 PA-28-180/235 | 4/29/75 | | | 3250 17A13 |
| 745 | Inspection of Wing Main Spar Attach Bolts | PA-28-140/151/180/ 235 (Crated) PA-28R-200 (Crated) | 4/24/75 | 404-890 | | 5710 17A14 |
| 747 | Inspection of Throttle And Mixture Control Attachments | PA-28-180/235 PA-28R-200 | 5/28/75 | ** | | 7610 17A18 |
| 749 | Torque Link Greaser Bolt Replacement Kit | PA-28-140/150/151 PA-28-160/180/181/235 | 10/14/75 | 760-910V | | 3210 17A21 |
| 756 | Glideslope Indicator Placard, Dual (King Radio Installations Only) | PA-28-151/180/235 PA-28R-200 | 1/6/76 | 69669-112V | | 3430 17B22 |
| 758 | Bendix Ignition Switches. Inspection of; Re: Bendix Service Bulletin No 583 | PA-28-140/151 PA-28-180/181/235 PA-28R-180/200 | 5/17/76 | 761-065V | | 7410 17C2 |
| 761 | Magnetic Compass Relocation Kit | PA-28-140/150/151 PA-28-180/235 PA-28R-180/200 | 11/17/75 | 760-795V | | 3440 17C14 |
| 762 | Modification of ELT Remote Switches | PA-28-140/151/180 PA-28-181/235 PA-28R-200 | 1/26/76 | 760-009V | | 2560 17C15 |
| 763A | Seat Retention Mechanism Inspection, Rear Leg Quick-Disconnect | PA-28-180/235 PA-28R-180/200 | 11/14/75 | ** | 75-24-02 | 2510 17C16 |
| 785 | Carburetor Induction Air Shroud Modification | PA-28-151 | 9/15/76 | ** | | 7160 17F13 |
| 788 | Air Conditioning Installation | PA-28-140/180/181 PA-28R-200 | 9/3/76 | 79584-02V 79589-05V | | 2150 17F19 |
| 793 | Flap Warning Placard | PA-28-140/150/151/160/ 180/181/235 PA-28R-180/200 PA-28R-201/201T | 1/6/77 | 35664-02 | | 2750 17G5 |
| 796 | Lower Cowl Drain Inspection | PA-28-150/160 PA-28-180/181/235 | 3/30/77 | | | 7100 17G10 |
| 800 | Refinement of Narco ADF-140 Installation Performance | PA-28-140/151 PA-28-180/181/235 PA-28R-200 | 2/25/77 | ** | | 3450 17G19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|------------|
| 808 | Hydraulic Pump Terminal Inspection | PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T | 6/8/77 | ** | | 2910 17H14 |
| 810 | Backup Diaphragm Replacement Landing Gear Extender | PA-28R-180/200 PA-28R-201/201T | 4/15/77 | 761-138V | | 3230 17H18 |
| 813 | Vertically Adjustable Seat Refinement | PA-28-140/151/161 PA-28-180/181 PA-28R-200/201/201T PA-28R-235 | 6/9/77 | ** | | 2510 17I8 |
| 814 | Refinement Program Cherokee III And Turbo Arrow III | PA-28R-201 PA-28R-201T | 9/26/77 | | | 5300 17I10 |
| 814 | Part I - Engine Mount Painting | PA-28R-201T | 9/26/77 | 763-415V | | 7100 17I10 |
| 814 | Part II - Aileron Bellcrank Stop Assembly | PA-28R-201 PA-28R-201T | 9/26/77 | 761-142V | | 2710 17I11 |
| 814 | Part III - Winterization Plate | PA-28R-201T | 9/26/77 | 37793-02V | | 7200 17I11 |
| 814 | Part IV - Landing Light Wire Rework | PA-28R-201T | 9/26/77 | | | 3340 17I12 |
| 814 | Part V - Exhaust Heat Shield | PA-28R-201T | 9/26/77 | 486-648V | | 7810 17I12 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-28-140/151/161 PA-28-180/181 PA-28-235 PA-28-236 PA-28R-200/201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 826 | Spinner Bulkhead Doubler | PA-28-151/161 | 8/25/77 | 35667-02V | | 6110 17J14 |
| 832 | Wheel Well Reinforcement | PA-28R-180/200/201 PA-28R-201T | 1/25/78 | | | 3240 17J21 |
| 836 | Inspection And Modification Narco ADF-140/141 Antenna | PA-28-140/180/235 PA-28-151/161 II/181 II PA-28R-200 PA-28R-201/201T | 2/9/78 | ** | | 3450 17K4 |
| 842 | Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement | PA-28-140/150/151 PA-28-160/161 PA-28-180/181 PA-28-235 | 9/26/78 | 760-910V | | 3210 17K17 |
| 845 | Engine Breather Tube Winterization Kit | PA-28-140/150/160/180 PA-28-151/161 II/181 II PA-28R-180/200 PA-28R-201 | 7/7/78 | 763-828V | | 7250 17K22 |
| 848 | Exhaust Heat Shield | PA-28R-201T | 6/21/78 | 763-843V | | 7810 17L4 |
| 856 | Fuel Drain Cover Replacement | PA-28-235 | 9/15/78 | 763-883V | 78-23-01 | 2810 18A21 |
| 859 | Landing Light Installation Modification | PA-28-151/161 | 11/8/78 | 760-854V | | 3340 18B2 |
| 860 | Engine Exhaust System Modification | PA-44-180 | 12/4/79 | ** | | 7810 18B4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|----------------------|----------|------------|
| 861 | Part I - Forward Facing Seat Back Modification | PA-28-140/151/161 PA-28-180/181/235/236 PA-28R-200/201 PA-28R-201T PA-44-180 | 11/13/78 | 763-890V | | 2520 18B7 |
| 862 | Main Landing Gear And Strut Fairing Replacement | PA-28-161/181 PA-28-236 | 3/30/79 | 763-918V | | 3210 18B11 |
| 863 | Master Relay Diode Assembly - Refinement | PA-28-181 PA-28R-201 PA-28R-201T | 11/17/78 | | | 2450 18B13 |
| 864 | Part I - Forward Cabin Door Stop (Striker Plate) Installation | PA-28-140/151/161 PA-28-181/235/236 PA-28R-200/201 PA-28R-201T | 12/8/78 | ** | | 5210 18B16 |
| 864 | Part II - Cabin Heat Control Refinement | PA-28-140/151 PA-28-161/180/181 PA-28-235/236 PA-28R-180/200/201 PA-28R-201T | 12/8/78 | 763-870V 763-871V | | 2140 18B19 |
| 864 | Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision | PA-28-140/150 PA-28-160/180 PA-28-235 | 12/8/78 | 763-874 | | 3420 18B20 |
| 867 | Part I - Engine Baffles Reinforcement | PA-44-180 | 10/10/79 | ** | | 7230 18C4 |
| 867 | Part II - Replacement of Nose Landing Gear Micro Switch Bracket | PA-44-180 | 10/10/79 | 763-925V | | 3230 18C5 |
| 867 | Part III - Cowl Fastener Relocation | PA-44-180 | 10/10/79 | 420-690 | | 7110 18C5 |
| 867 | Part IV - Cabin Heater Air Inlet Valve Modification | PA-44-180 | 10/10/79 | ** | | 2140 18C6 |
| 867 | Part V - Battery Box Drain Clamp Replacement | PA-44-180 | 10/10/79 | 454-983 | | 2430 18C7 |
| 867 | Part VI - Tachometer And Manifold Pressure Gauges Available Light Increase | PA-44-180 | 10/10/79 | | | 7710 18C7 |
| 867 | Part VII - Landing Light Grounding Strap Installation | PA-44-180 | 10/10/79 | ** | | 3340 18C8 |
| 891 | Air Induction Filter Retainer Improvement | PA-28-151/161 | 3/4/81 | 87349-02V | | 7160 18F24 |
| 895A | Magneto Switch Modification | PA-28R-201 PA-28RT-201T | 3/19/81 | 153-010 488-396 | | 7430 18G8 |
| 899 | Part I - Aft Spinner Bulkhead Refinement | PA-28-161 | 10/3/80 | 36757-003V | | 6110 18G16 |
| 899 | Part II - Forward Spinner Bulkhead Refinement | PA-28-161 | 10/3/80 | ** | | 6110 18G17 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|-----------------------|----------|------------|
| 901 | Cabin Air Intake Duct Modification | PA-28-161/181/236 PA-28RT-201/201T PA-44-180 | 9/2/80 | 764-013V | | 2120 18G22 |
| 903A | Alternator Belt Installation (Air Conditioned Models) | Any Textron-Lycoming Powered PA-28 | 3/11/96 | 62833-82 | | 2431 18H2 |
| 905 | Compass Deviation-Battery Ground Wire Replacement | PA-28RT-201 | 1/21/81 | 764-087V | | 2430 18H7 |
| 906 | Lower Cowl Exhaust Fairing Replacement | PA-44-180 | 4/21/81 | ** | | 7110 18H8 |
| 907 | Weight And Balance Plotter Modification | PA-44-180 | 1/22/81 | 764-040V | | 800 18H10 |
| 908 | Instrument Panel Lighting - Century 21 And 41 Autopilot Installation | PA-28-161/181 PA-28-236 PA-28RT-201 PA-28RT-201T | 12/20/80 | | | 3310 18H11 |
| 910 | Engine Oil Quick Drain Valve | PA-28R-200/201 PA-28RT-201 | 12/29/80 | 87369-26V 492-172V | 81-11-02 | 7920 18H17 |
| 915 | Firewall Reinforcement | PA-44-180 | 4/14/81 | 764-103V | | 5410 18I7 |
| 920 | Required Placard Adhesion Check | PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 6/29/81 | | | 2500 18I19 |
| 933 | Engine Baffle Seal Security | PA-44-180 PA-44-180T | 11/23/81 | 189-780 | | 7230 18J20 |
| 951 | Aft Fuselage Moisture Drain | PA-28-236 PA-28RT-201 | 10/6/82 | 764-386V | | 2120 18L2 |
| 988 | Nose Landing Gear Modification | PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180 PA-44-180T | 7/29/86 | ** | 94-14-14 | 3225 19D1 |
| 997 | Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08 08 | PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T | 5/14/87 | ** | 87-08-08 | 5711 19D24 |
| 1019A | Alternator Support Bracket Improvement | PA-28-181 III | 1/22/98 | 101103-02 418-421 | | 2412 19H1 |
| 1024 | Induction Airbox Air Valve Bushing Improvement | PA-28-181 | 8/4/99 | ** | | 7164 19H20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|-----------------------------------|--------------------------------|------------|
| 1027 | Manifold Pressure Line Filters Addition | PA-44-180 | 11/5/99 | 560-686 ** | | 7164 19I7 |
| 1028A | Induction Airbox Inspection/Repair and Inlet Air Duct Replacement | PA-28-181 III | 1/14/2000 | 766-666 85479-003 85489-011 | | 7164 19I11 |
| 1029A | Recognition Light Circuit Breaker Inspection/Replacement | PA-28R-201 | 1/24/2005 | 454-708 87369-053 | | 2454 19I15 |
| 1033 | Air Conditioning Hose Replacement | PA-28-181 III | 7/9/2001 | 566-419 454-868 | | 2155 19J4 |
| 1034A | Compass Accuracy Improvement Modification | PA-44-180 | 11/7/2013 | 766-699 | | 3447 |
| 1038A | Combustion Heater Fuel Pump Replacement | PA-44-180 PA-44-180T | 2/16/2011 | 88476-002 | | 2148 |
| 1040A | Alternator Drive Belt Conversion Kit (for Aircraft Equipped with Optional Factory Installed Air Conditioning) | PA-28-180 PA-28-181 II/III PA-28R-200 PA-28R-201 PA-28RT-201 | 10/7/2021 | 767-310 (88306-000) | | 2410 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1045 | Electric Fuel Pump Upgrade | PA-28R-201 | 3/26/2002 | 461-758 | | 2825 19K21 |
| 1047 | Pilot Sidepost Handgrip Kit | PA-28-161 Cadet PA-28-161 PA-28R-201 PA-44-180 PA-44-180T | 5/28/2002 | 767-343 | | 2510 19L3 |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1060 | Engine Primer Hose Improvement | PA-44-180 | 2/11/2003 | 63901-200 63901-201 | | 7300 20A23 |
| 1063 | Stabilator Bellcrank Bracket Assembly Inspection | PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T | 4/21/2003 | N/A | | 2792 20B7 |
| 1066 | Ignition Harness Routing Inspection | PA-28-181 III | 4/24/2003 | 189-549 | | 7420 20B17 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-11-01 CE-02-05 (SAIB) | 2702 20C2 |
| 1074 | S-TEC Autopilot Component Seating Procedure | All | 11/3/2003 | N/A | | 2210 20C14 |
| 1081 | Rib Inspection at W.S. 36.22 R.H. | PA-28-161 III PA-28-181 III | 7/1/2005 | 767-363 62066-000 | | 5712 20E7 |
| 1087 | Wing Aft Spar-to-Fuselage Attachment Hardware | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 3/30/2005 | ** | | 5740 20F6 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|------------------------|----------|----------|
| 1089 | Aircraft Painting Requirement | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 10/21/2004 | N/A | | 1100 |
| 1093B | Electrical Contactor Replacement Kit | PA-28-140/150/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 11/28/2017 | 88371 | | 2400 |
| 1095C | Classification and Disposition of Hail Damage | PA-28-140/150/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 5/7/2024 | N/A | | 5100 |
| 1103 | Attitude Indicator Standby Battery Failure | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 4/20/2007 | 88410-002 88414-002 | | 3420 |
| 1106A | Sky-Tec Starter Cranking Instructions | PA-28-161 II-III PA-28-181 III PA-28R-201 PA-44-180 | 10/28/2009 | N/A | | 8011 |
| 1108 | Manifold Pressure Transducer Failures | PA-28R-201 PA-44-180 | 3/4/2008 | N/A | | 7713 |
| 1116A | Contactor Maintenance | PA-28-140/150/160/180 PA-28-151/161/181 PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 3/15/2019 | N/A | | 2435 |
| 1123 | Avidyne EXP5000 Software Upgrade (Mod 57) | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 9/27/2010 | N/A | | 3420 |
| 1124 | Air Conditioning Servicing | PA-28-181 III | 12/6/2010 | 197-511 | | 2150 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------------|----------|----------|
| 1125 | Stall Horn Bracket Replacement | PA-28-160/180 PA-28S-160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-201/201T PA-28RT-201/201T | 7/27/2010 | 88472-002 | | 2730 |
| 1126A | Voltage Suppressor Advisory | PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180 | 3/23/2017 | N/A | | 3400 |
| 1134 | Wing Tip Inspection Requirements | PA-44-180/180T | 10/7/2010 | N/A | | 5720 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | PA-28-140/150/160/180 PA-28-151/161/181 PA-28-161 Cadet PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-28S-160/180 | 4/27/2011 | MS20995-C32 | | 2800 |
| 1149 | Nose Cone Fastener Inspection | PA-44-180/180T | 2/8/2012 | ** | | 5330 |
| 1153 | Auxiliary Vacuum Pump Elapsed Time Indicator (ETI) Replacement | PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28R-201 | 6/12/2012 | 88509-002 | | 3710 |
| 1156 | Propeller Feather Stop Product Improvement | PA-44-180/180T | 4/2/2012 | 78713-003 | | 6120 |
| 1161 | Fuel Quantity Gauge Installation and Calibration Requirements | PA-28-161 III PA-28-181 III | 1/10/2013 | 88536-001 | | 2840 |
| 1165 | Hydraulic Pump Identification and Servicing Requirements | PA-28R Series PA-44 Series | 10/18/2012 | | | 2910 |
| 1193 | Garmin G1000 Software Update, Versions 1648.04 and 1983.02 | PA-44-180 | 7/16/2015 | | | 3420 |
| 1213 | Garmin G1000 NXi Software Update Version 2698.04 | PA-28-181 III | 9/29/2017 | 190-02130-00 190-02131-00 | | 3420 |
| 1214 | Garmin G1000 NXi Software Update Version 2694.04 | PA-44-180 | 6/25/2018 | 190-02198-01 190-02199-01 | | 3420 |
| 1215 | Garmin G1000 Software Update Version 1618.05 | PA-28-181 III | 1/15/2019 | 190-01459-00 190-01460-00 | | 3420 |
| 1216A | Garmin Software Update With Oil Pressure Transducer | PA-44-180 | 1/10/2020 | 88610-002 | | 3420 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|---------------------------------|----------|----------|
| 1218A | Crew Seat Control Cable Modification | PA-28-161 II-III PA-28-161 Cadet PA-28-181 II-III PA-28-236 PA-28R-201/201T PA-44-180/180T | 8/8/2017 | 76356-003 554-422 487-490 | | 2510 |
| 1226 | Auxiliary Power Harness Inspection | PA-44-180 | 8/3/2018 | 88629-002 | | 2440 |
| 1229 | Control Quadrant Inspection | PA-28 Series PA-28R Series PA-44 Series | 1/3/2019 | 408-815 | | 7603 |
| 1239 | One-Piece Propeller Spinner Kit (Optional) | PA-44-180 | 2/11/2019 | 44P61A701-001 | | 6113 |
| 1240 | Garmin G1000 NXi Software Update Ver. 3080.04 | PA-28-181 III | 7/18/2018 | N/A | | 3420 |
| 1252 | Improved Front Exhaust Assemblies | PA-44-180 | 9/5/2019 | 44P78A000-001 44P78A000-002 | | 7800 |
| 1254 | Oil Pressure Transducer Kit Installation And Garmin G1000 Sw Ver. 1618.05 Update | PA-28-181 III | 12/19/2019 | 88608-002 | | 3420 |
| 1255 | Propeller Unfeathering System Accumulator Maintenance | PA-44-180/180T | 3/20/2019 | N/A | | 6123 |
| 1256 | Gascolator Bracket Assembly Inspection | PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-236 PA-28R-201/201T III PA-28RT-201/201T IV | 7/9/2019 | N/A | | 2821 |
| 1262 | Garmin G1000 NXi Software Update Version 3080.05 | PA-28-181 III | 5/30/2019 | 88650-001 | | 3420 |
| 1263 | Main Landing Gear Piston Tube Inspection | PA-44-180/180T | 12/23/2020 | 67037-006 | | 3213 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1267 | Garmin G1000 NXi Software Update Version 3080.09 | PA-28-181 III | 1/21/2020 | 88664-002 | | 3420 |
| 1268 | Hartzell 'K' Flange Propeller Hub Replacement | PA-28-235 PA-28R-180 PA-28R-200, II PA-28R-201 III PA-28RT-201 IV | 10/9/2019 | N/A | | 6114 |
| 1273A | Fuel Selector Valve Maintenance Requirements | PA-28-140/150/160/180 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201 | 10/6/2021 | 491-947 (6S122) | | 2823 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-28
PA-28R
PA-44/PA-44T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|---|----------|----------|
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1277C | Garmin G1000 NXi Software Update - Seminole | PA-44-180 | 10/23/2023 | 88695-701 | | 3420 |
| 1278C | Garmin G1000 Software Update - Archer | PA-28-181 III | 1/23/2024 | 88675-001 | | 3420 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1284A | Aspen Avionics EFD1000 Update To Software Version 2.10.2 | PA-28-181 III PA-44-180 | 5/15/2023 | N/A | | 3420 |
| 1291 | ADAHRS Support Modification | PA-28-181 III | 2/24/2021 | 88685-701 | | 5320 |
| 1293B | Garmin G1000 NXi Software Update - Archer | PA-28-181 III | 1/23/2024 | 88683-701 | | 3420 |
| 1302 | Replacement Of Locking Gascolator Drain Valve | PA-28-140/150/160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II PA-28-181 II PA-28-201T PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T | 12/1/2022 | 492-022 492-312 | | 2821 |
| 1309 | Nose Landing Gear Steering Horn Inspection | PA-28-140/150/160/180 PA-28-181 | 2/13/2023 | 63300-004 | | 3250 |
| 1311 | Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits' | PA-28-151/161 PA-28-161 Cadet PA-28-180 PA-28-181 Archer II-III/Pilot PA-28-236 PA-28R-180-200 PA-28R-201 PA-28RT-201 PA-44-180/180T | 6/7/2022 | 470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40 | | 7120 |
| 1313 | Interior Panel Attachment Mod | PA-28-181 Pilot | 6/3/2022 | 289-765 28F250003-001 | | 2510 |
| 1318A | Brake Line Modification | PA-28-161 Warrior II PA-28-181 Archer III PA-28-181 Pilot PA-28R-201 Arrow III / Arrow | 3/24/2023 | 454-934 | | 3240 |
| 1320 | Wing And Fuselage Skin Repair Limitations | PA-28-140/150/160/180 PA-28-151 PA-28-161 Cadet PA-28-161 II-III PA-28-181 II-III PA-28-201T PA-28-235/236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T | 12/1/2022 | N/A | | 5100 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|----------|
| 1321 | Garmin G5 EFI Standby Display Software Update Version 8.00 | PA-28-181 Archer III PA-44-180 | 2/23/2023 | 88728-701 | | 3420 |
| 1322A | Garmin G1000 Software Update Version 1983.04 | PA-44-180 | 6/11/2024 | 88716-701 | | 3420 |
| 1324A | Garmin G1000 NXi Software Update – Seminole | PA-44-180 | 1/8/2024 | 88717-707 | | 3420 |
| 1325 | Garmin G1000 Software Update Version 1648.06 | PA-44-180 | 3/13/2023 | 88710-707 | | 3420 |
| 1326A | Garmin G1000 NXi Software Update – Archer | PA-28-181 | 1/24/2023 | 88717-707 | | 3420 |
| 1327G | Wing Walk Modification and Inspection | PA-28-140 PA-28-150 PA-28-160 PA-28-180 PA-28-235 PA-28-236 PA-28R-180 PA-28R-200 PA-28-151 PA-28-161 PA-28-181 PA-28-201/-201T PA-28R-201/-201T PA-28RT-201/-201T | 9/25/2024 | N/A | | 5720 |
| 1330B | Garmin G3X Software Update - Piper Pilot | PA-28-181 Pilot | 4/1/2024 | 487-402 | | 3420 |
| 1331A | Improved Spring Attachment Plate | PA-28R-180/200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T | 7/1/2024 | 67753-000 | | 3210 |
| 1334 | Improved Nose Landing Gear Down Spring | PA-44-180 | 3/4/2024 | | | 3230 |
| 1337 | Flight Controls Maintenance Improvements | PA-28-181 Pilot PA-28-181 Archer III PA-44-180 | 1/29/2023 | | | 2700 |
| 1346 | Spar Box Inspection | PA-28-140 PA-28-150 PA-28-160/PA-28S-160 PA-18-180/PA-28S-180 PA-28-161 PA-28-181 PA-28-201T PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T | 11/12/2024 | | | 5711 |
| 1347 | Brake Pedal Assembly Inspection | PA-28-181 Archer III PA-28-181 Pilot PA-44-180 | 12/2/2024 | | | 2720 |

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------|------------------|--------------------|----------|--------------------|
| 487 | Test Unit, Hydraulic (And Fabricated Jack Stand) | PA-31 PA-31-300 | 2/13/67 | 753-080 | | 710 14J14 |
| 492 | Replacement of: (I) Landing Gear Selector Handle (And Associated Link Rod To Power Pak), General Instructions For Inspection And Operation of, And (II) Nose Gear Idler Link Assy. | PA-31 | 9/6/67 | ** | | 3200 14J20 3220 |
| 497 | Manifold Pressure Gauge Filter Assembly | PA-31 | 1/30/68 | 760-171 | | 7710 14K4 |
| 498 | Nose Gear Idler Link Assembly (Identification Tag) | PA-31 | 3/1/68 | 760-170 | | 3230 14K5 |
| 500 | Altimatec III Series- (I) Radio Coupler (II) Amplifier Replacement | PA-31 | 3/22/68 | 760-191 760-192 | | 3400 14K7 |
| 502 | Navajo Cabin Heat Modification | PA-31 | 3/18/68 | 760-187 760-188 | | 2140 14K12 |
| 504 | B. F. Goodrich Service Bulletin No. E-67-34 | PA-31 | 4/8/68 | | | 3240 14K14 |
| 505A | Fuselage Drain Holes | PA-31 | 5/2/68 | | | 5300 14K16 |
| 506 | Main Landing Gear (Outboard) Door Actuator Bracket | PA-31 | 5/2/68 | 757-178 | | 3210 14K18 |
| 507 | ADF Installation Spacer | PA-31 | 5/22/68 | 760-211 | | 3400 14K19 |
| 508 | Propeller Counterweight Attachment Bolt Clearance | PA-31 PA-31-300 | 7/9/68 | 43556-00 | | 6120 14K20 |
| 509 | Pneumatic Pump Air Inlet Relocation | PA-31 | 6/24/68 | 760-200 | | 3710 14K22 |
| 512 | Attachment of Rudder Tab Hinge Brackets | PA-31 PA-31-300 | 10/8/68 | 760-243 | | 2720 14L1 |
| 514 | Flight Control Cable Systems | PA-31/31-300 | 9/19/68 | | | 2210 14L3 |
| 517 | Beacon (Rotating) Attachment Screws-Shock Mounted Beacon | PA-31 PA-31-300 | 10/23/68 | | | 3340 14L13 |
| 523 | Modification To The Fuselage Bulkhead | PA-31 PA-31-300 | 4/9/69 | 760-295 | | 5310 15A3 |
| 524 | Weldon Electric Fuel Pump Modification | PA-31 PA-31-300 | 5/20/69 | 760-316 760-317 | | 2810 15A5 |
| 530 | Hydraulic Fluid Level Gauge "O" Ring Replacement | PA-31 PA-31-300 | 5/23/69 | 484-815 | | 2910 15A22 |
| 531 | Cowl Flap Support Assembly | PA-31/31-300 | 8/22/69 | 760-330 | | 7110 15A24 |
| 532 | Voltage Regulation Component Grounding | PA-31 PA-31-300 | 7/7/69 | 760-333 | | 2430 15B2 |
| 537 | Landing Gear Door Hinge Bracket Reinforcement | PA-31 PA-31-300 | 10/16/69 | 760-348 | | 3230 15B15 |
| 538 | Inspection of Propeller Blade Shank (Hartzell Service Bulletin No. 94) | PA-31 (2 Blade Props) | 10/23/69 | | | 6110 15B17 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|------------|--------------------|
| 548 | Inspection of The Right Engine Control System Installation | PA-31 PA-31-300 | 3/16/70 | | | 7610 15C17 |
| 550B | Turbocharger Density Control Adjustment | PA-31 PA-31-350 | 7/10/74 | | | 8120 15C21 |
| 553 | Equipment (Required) Pressurized Navajo Service Support | PA-31P | 5/20/70 | ** | | 2130 15D12 |
| 555 | Inspection of Nose Gear Idler Link Assembly | PA-31 PA-31-300 | 7/8/70 | | | 3220 15D15 |
| 562 | Scott Aviation Service Bulletin No. 35-32 | PA-31-300 | 8/25/70 | ** | | 3500 15E10 |
| 566 | Autopilot Servo Spacer Bushing Installation | PA-31-300 | 11/25/70 | 760-473 | | 2210 15F3 |
| 573 | B F Goodrich Service Bulletin No. E-68-36B (Sealer For B F. Goodrich Deicer And Strap) | PA-31 PA-31-350 PA-31-P | 3/4/71 | | | 3020 15F17 |
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P-350 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 580 | Fuel Selector Valve Packing Lubrication | PA-31/31-300 PA-31P | 5/24/71 | 760-504 | | 2820 15G18 |
| 593 | Connector Plug, Harness Strain Relief Hood Installation | PA-31, Alt. V Or Alt. V/VD | 10/11/71 | 760-556 | | 2400 15H15 |
| 594 | Inspection of Flap Track And Rudder Tip Rib Assemblies | PA-31-300 | 10/8/71 | ** | | 5750 15H19 5510 |
| 603 | Hartzell Service Letter No. 70 | PA-31P | 2/8/72 | ** | | 6110 15I17 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 617B | Piper Automatic Locator Transmitter Replacement | PA-31 PA-31-350 PA-31P | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 619 | Inspection of Retainer Spring Piper Part No. 83302-13 | PA-31 PA-31-300 | 6/9/72 | 83302 13 | | 7330 15L5 7160 |
| 630 | Lubrication of Fuel Selector Valve Mechanism | PA-31/31-300 PA-31P | 9/13/72 | ** | | 2820 16A11 |
| 631A | Wiring Inspection, Alternator Switch And Circuit Breaker Panel | PA-31 PA-31-300 | 4/25/73 | ** | | 2430 16A13 |
| 633 | Inspection And Repair of Flood Exposed Airplanes | PA-31 PA-31-350 PA-31P | 10/9/72 | | | 5300 16A18 |
| 635 | Lycoming Service Bulletin No. 356 (Addition of Alternator Bracket Support) | PA-31 | 10/16/72 | ** | | 2400 16A24 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------------------|------------------|--------------------|----------|-------------------|
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-31 PA-31-350 PA-31P | 10/24/72 | ** | | 2430 16B2 |
| 639 | Alternator Field Switch Guard Modification | PA-31-P | 12/20/72 | 760-721 | | 2430 16B11 |
| 642 | Revised Alternator Inoperative Warning Light | PA-31 | 2/19/73 | 760-713 | | 2430 16B15 |
| 643 | Control Shaft Collar Restraining Strap | PA-31/31-300 PA-31P | 2/5/73 | 760-723 | 76-04-11 | 2700 16B17 |
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972) | PA-31 | 4/9/73 | ** | | 7610 16C14 |
| 654 | Heater Control System Modification | PA-31-350 | 4/18/73 | ** | | 2140 16C17 |
| 655 | Turbocharger Modification; Airesearch Service Bulletin No. 1172-1A(Reference Avco Lycoming Service Bulletin No. 361, Dated February 16, 1973) | PA-31 PA-31-350 PA-31P | 4/10/73 | ** | | 8120 16C21 |
| 656 | King Area Nav Operation Limitation Placard | PA-31-310 PA-31-350 PA-31-P | 5/15/73 | 696-1109-00 | | 3450 16D2 3400 |
| 658 | Static System Line Modification | PA-31-350 | 6/14/73 | 760-750 | | 2350 16D5 |
| 660 | Revised Alternator Ground Wire Installation | PA-31-310 PA-31-350 | 7/6/73 | 760-778 | | 2430 16D7 |
| 665A | Intake Valves, Rotator Type | PA-31/31-300 PA-31-350 | 10/24/73 | ** | | 7160 16D16 |
| 666 | Propeller Governor Speed Adjusting Shaft, Lever And Lever Clamp Screw Replacement (Reference Woodward Service Bulletin No. 33549, Dated May 1973) | PA-31P | 9/13/73 | ** | | 6120 16D18 |
| 674 | Over Voltage Relay Inspection | PA-31-300/310 PA-31P | 1/3/74 | 760-787 | | 2430 16E16 |
| 675 | Magneto Switch Guard Installation | PA-31-300/310 PA-31-350 PA-31P | 9/17/73 | 760-789 760-790 | 74-26-10 | 2430 16E18 |
| 680 | Receiver Dehydrator Relocation | PA-31-310 PA-31-350 | 11/29/73 | 760-803 | | 2710 16F5 |
| 681 | Inspection of Elevator Balance Weight Bolts | PA-31-350 | 10/24/73 | ** | | 2730 16F7 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D) | PA-31 PA-31-350 PA-31P | 4/19/74 | ** | | 7230 16F9 |
| 685 | Installation Alternator Field Wire Clamp | PA-31P | 10/24/73 | 760-807 | | 2420 16F19 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-------------------------------------|------------------|--------------|----------|------------|
| 688 | Unfeathering Accumulator Maintenance And Preventive Maintenance (Reference Woodward Service Bulletin No 33551, Dated August, 1973) | PA-31P | 10/24/73 | | | 6120 16G1 |
| 690A | Cylinder (Engine) Baffle Removal And Cylinder Head Temperature Probe Relocation | PA-31-350 | 3/4/74 | | | 7720 16G4 |
| 691 | Cigar Lighter Circuit Protector Replacement | PA-31P | 11/12/73 | 760-809 | | 3310 16G6 |
| 692 | Heater System Modification | PA-31-350 | 2/12/74 | 760-804 | | 2140 16G8 |
| 696 | Control Surface Balancing Recommendation | PA-31/31-300 PA-31-350 PA-31P | 5/2/74 | | | 2700 16G20 |
| 697 | Fuselage Addition of Drain Holes | PA-31-300/310 PA-31-350 | 3/14/74 | | | 5300 16G22 |
| 698 | Ground Handling (Towing) Recommendations | PA-31-300/310 PA-31-350 | 2/6/74 | | | 3200 16G24 |
| 699 | Fuel Vent Line Check Valve Installation (Reference Avco Lycoming Service Bulletin No. 362A; Dated December 14, 1973) | PA-31P | 2/12/74 | LW-13324 | | 2810 16H2 |
| 701 | Overvoltage Relays, Wiring of; Alternator Paralleling System | PA-31P | 3/14/74 | ** | | 2430 16H6 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-31 PA-31-350 PA-31P | 2/27/74 | ** | | 7710 16I11 |
| 709 | Inspection of Pneumatic Pump Mounting Flanges | PA-31P | 5/1/74 | | | 3710 16I17 |
| 711 | Inspection of Submerged Fuel Pumps | PA-31P | 5/30/74 | 48812-00 | | 2820 16J4 |
| 712 | T-Bolt Clamping Bands, High Tensile (Reference Avco Lycoming Service Bulletin No. 372A, Dated March 15, 1974) | PA-31-350 | 5/15/74 | LW-13886 | | 8120 16J7 |
| 713 | Static Air Sump Installation | PA-31-310 PA-31-350 PA-31-P | 8/21/74 | 760-864 | | 3410 16J9 |
| 716 | Moisture Seal, Cross Shaft Support Tube (Reference Avco Lycoming Service Bulletin No. 375A, Dated May 10, 1974) | PA-31P | 6/3/74 | ** | | 7200 16J13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------------|----------|------------|
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22. 1974) | PA-31 PA-31-350 PA-31-P | 5/31/74 | ** | | 7410 16J18 |
| 719 | Deicer Boot Installation Throttle Control Cable | PA-31P | 8/28/74 | 760-874 | | 7610 16K1 |
| 722 | Fuel System Modification | PA-31-350 | 8/27/74 | 760-873 | | 2800 16K9 |
| 723 | Glideslope Indicator Placard | PA-31/31-300 PA-31-350 PA-31P | 8/14/74 | SK 2359 | | 3430 16K11 |
| 725 | Fuel Pressure Gauge Modification | PA-31-350 | 9/19/74 | 54209-02 | | 7330 16K14 |
| 726 | Cigar Lighter Placard | PA-31P | 8/8/74 | 80247-02 | | 3310 16K16 |
| 730 | Air Conditioning System Modification | PA-31-350 | 8/20/74 | 760-881 | | 2150 16K23 |
| 733 | Pilot And Copilot Cabin Heat Refinement | PA-31-350 | 4/21/75 | 760-924 | | 2140 16L7 |
| 739 | Cabin Door Refinement | PA-31/31-300 PA-31-350 | 6/2/75 | ** | 78-05-05 | 5210 17A1 |
| 741 | Radome Weather Seal | PA-31P | 1/23/75 | 760-919 760-920 | | 5340 17A7 |
| 752A | Replacement of Alternator Ground Wire | PA-31P | 10/30/75 | 760-988 | | 2420 17B2 |
| 753 | Propeller Feather Assist Spring Assembly Installation Reference Attached Hartzell Service Letter No. 101 | PA-31-300/325 PA-31-350 | 7/16/76 | ** | | 6120 17B3 |
| 755C | Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication | PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P | 11/4/85 | ** | | 3235 17B13 |
| 755C | Part II - Landing Gear Lock Actuator Rod Replacement | PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P | 11/4/85 | 764-958 | | 3235 17B15 |
| 755C | Part III - Installation of Anti-Rotation Stops | PA-31 PA-31-325 PA-31 -350 T-1020 PA-31P-350 | 11/4/85 | ** | | 3235 17B16 |
| 764A | Wing Flap System Maintenance Procedure | PA-31-300/325 PA-31-350 PA-31P | 7/17/79 | | 81-11-03 | 2750 17C19 |
| 766 | Inspection of Cleveland Brake Discs | PA-31-325 PA-31-350 | 1/6/77 | ** | | 3240 17D9 |
| 770 | Aileron Sprocket/Chain Inspection | PA-31-300/325 PA-31-350 PA-31 P | 1/27/77 | ** | | 2710 17D18 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------------|----------|--------------------|
| 773 | Nose Cone ("Radome") Latch System Refinement | PA-31P | 6/28/76 | 761-012 | | 5340 17E7 |
| 778 | Elevator Butt Rib Refinement | PA-31P | 6/14/76 | 54755-02 | | 5520 17E14 |
| 781 | Cockpit Forward Bulkhead/ Floorboard Sealing | PA-31-350 | 10/22/76 | ** | | 5310 17E21 5320 |
| 783 | Inspection of Air Conditioning System Capillary Sensor | PA-31P | 9/20/76 | ** | | 2150 17F7 |
| 784 | Landing Gear Hydraulic System Refinement | PA-31-300 | 9/27/76 | 491-050 484-459 | | 2920 17F10 |
| 789 | Inspection of Elevator Bellcrank And Elevator Control Rod | PA-31-300/325 PA-31-350 PA-31P | 10/6/77 | ** | | 2730 17F21 |
| 798 | Cabin Headliner/Oxygen Cover Panel Refinement | PA-31P | 2/4/77 | | | 2520 17G13 3520 |
| 801 | Goodyear Tri-Metallic Brakes, Maintenance And Operation; Ref: Goodyear Service Letter "PA-31-350/31 P/31T SL-1" Dated January 15, 1977 | PA-31-350 PA-31P | 2/25/77 | | | 3240 17G21 |
| 802 | Main Landing Gear Door Hinge Attachment Screw Replacement | PA-31/31-325 PA-31-350 PA-31P | 3/9/77 | 761-128 | | 3210 17G24 |
| 803A | Cabin Door Latch System Refinement | PA-31-300/325 PA-31-350 | 11/3/77 | 55633-03 | 78-05-05 | 5210 17H1 |
| 816 | Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks) | PA-31-350 PA-31P | 12/19/77 | 763-831 | | 2910 17I18 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-31/31-300 PA-31-325 PA-31-350 | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 821 | Right Engine Cowl Louver Installation Kit | PA-31-350 | 3/7/78 | 763-802 | | 7110 17J6 |
| 823 | Heater/Evaporator Return Air Duct Hose Replacement | PA-31P | 2/10/78 | 49478-02 | | 2120 17J10 |
| 829 | Emergency Exit Window Latch Modification | PA-31P | 11/14/77 | 763-809 | | 5620 17J18 |
| 830 | 24 Volt Cigar Lighter Element Replacement | PA-31 PA-31-325 PA-31-350 PA-31P | 11/22/77 | ** | | 3310 17J19 |
| 833 | Cabin Pressurization System Rupture Disc Elimination | PA-31P | 4/10/78 | | | 2130 17J22 |
| 834 | Flap Electrical System Refinement | PA-31/300/325 PA-31-350 PA-31P | 3/3/78 | ** | | 2750 17J24 |
| 844 | Heater System Rewiring | PA-31-350 | 4/24/78 | | | 2140 17K20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------------|----------|--------------------|
| 847 | Avionics Emergency Bus Power Switch Guard Installation | PA-31P | 8/13/79 | ** | | 2450 17L2 |
| 866 | Windshield Wiper Arm Retaining Wire Installation | PA-31/31-300 PA-31-325 PA-31-350 PA-31P | 12/7/79 | 151-295 | | 5610 18C1 |
| 872 | Alternator Wiring Inspection | PA-31/31-300 PA-31-325 PA-31-350 | 6/7/79 | 588-594 | | 2430 18D6 |
| 873 | Stall Warning System Refinement | PA-31 PA-31-325 PA-31-350 | 5/8/79 | | | 2700 18D9 |
| 874 | Low Fuel Warning Sensor Sealing | PA-31 PA-31-325 PA-31-350 | 10/19/79 | ** | | 2840 18D12 |
| 875 | Engine Front Baffle Replacement | PA-31 PA-31-325 PA-31-350 | 5/11/81 | 764-093 | 93-23-13 | 7230 18D16 |
| 878A | Oil Breather Tube Inspection/Alignment | PA-31/31-300 PA-31-325 PA-31-350 | 3/6/81 | | | 7220 18E13 |
| 879 | Razor Inverter Replacement | PA-31 PA-31-325 PA-31-350 | 5/20/80 | 467-488 | | 3320 18E18 |
| 883 | Wing Flap Rivet Installation | PA-31P | 10/20/79 | ** | | 5750 18F8 |
| 885 | Aileron And Elevator Control Systems Hardware Replacement | PA-31/31-300 PA-31-325 PA-31-350 | 3/10/81 | 763-996 | | 5550 18F13 |
| 886 | Master Switch Replacement | PA-31 PA-31-325 PA-31-350 | 1/6/81 | 764-090 | | 2450 18F15 |
| 887 | Starter And Battery Cable Inspection | PA-31 PA-31-325 PA-31-350 | 5/29/81 | ** | | 8010 18F16 2430 |
| 894 | Heater Modification | PA-31-350 | 9/4/80 | 764-005 | | 2140 18G7 |
| 904 | Sealing Procedures To Prevent Water Leaks | PA-31/31-300 PA-31-325 PA-31-350 | 3/11/81 | ** | | 5210 18H5 |
| 912 | Main Landing Gear Downlock Hook Rivet Replacement | PA-31/300/325 PA-31-350 | 3/5/81 | 420-890 422-241 | | 3230 18H24 |
| 916 | Elevator Control Stop Screw Replacement | PA-31/31-300 PA-31-350 PA-31P | 7/17/81 | ** | | 2730 18I8 |
| 917 | Portable Fire Extinguisher Inspection | PA-31 PA-31-325 PA-31-350 | 7/20/81 | 459-839 459-848 | | 2620 18I11 |
| 921 | Main Landing Gear Lock Rod Attachment Fork Replacement | PA-31P | 4/21/82 | 764-127 | | 3230 18I21 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|-----------------|------------|
| 935 | ELT Antenna Inspection | PA-31 PA-31-325 PA-31-350 | 3/26/82 | ** | | 2560 18J23 |
| 958 | Flap Travel Restriction Supplementary Kit | PA-31 PA-31-300/325 PA-31-350 PA-31P | 10/25/82 | 764-920L | | 5750 18L18 |
| 959 | Flap System Modification | PA-31 PA-31-300/325 PA-31-350 PA-31P | 6/10/83 | 764-957L | | 5750 19A1 |
| 959 | Part I - Calco Flap System Installation | PA-31 PA-31-300/325 PA-31-350 | 6/10/83 | 764-938L | | 5750 19A1 |
| 959 | Part II - Flap Transmission Replacement (Dukes 20:1 To Calco 40:1) | PA-31 PA-31-300/325 PA-31-350 PA-31P | 6/10/83 | 764-957L | | 5750 19A2 |
| 987 | Main Landing Gear Mount Bolt Inspection | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 7/25/86 | 400-384 | | 3213 19C22 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 20C2 |
| 1086 | Propeller Blade De-ice Boots Maintenance | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 | 7/16/2004 | N/A | | 3112 20F3 |
| 1088 | 40336-000 Link Assembly Inspection | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 12/15/2004 | 40336-000 | | 3220 20F11 |
| 1092C | Main Gear Retraction Arms Inspection, 42042-000/-002 | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 7/25/2013 | 42042-000 42042-002 | | 3211 |
| 1093B | Electrical Contactor Replacement Kit | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P | 11/28/2017 | 88371 | | 2400 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|------------------------|----------|----------|
| 1116A | Contactator Maintenance | PA-31 PA-31-300/325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1188 | Landing Gear Hydraulic System Filter Maintenance | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350 | 3/19/2015 | N/A | | 2912 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1316 | Main Landing Gear Door Bolt Replacement | PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31R-350 | 5/10/2023 | 453-204 (43972-000) | | 3211 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31/PA-31-300/325
PA-31-350, PA-31P
PA-31P-350

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SL46

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--------------------|----------|--------------------|
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 736 | M-4D Automatic Flight Control System Modification | PA-31T1 | 12/3/74 | ** | | 2210 16L14 |
| 741 | Radome Weather Seal | PA-31T | 1/23/75 | 760-919 760-920 | | 5340 17A7 |
| 743 | Cabin Altitude Controller Relocation | PA-31T | 2/19/75 | 760-921 | | 2130 17A12 |
| 755C | Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication | PA-31T/31T1 PA-31-31T2/31T3 PA-42 | 11/4/85 | ** | | 3235 17B13 |
| 755C | Part II - Landing Gear Lock Actuator Rod Replacement | PA-31T/31T1 PA-31-31T2/31T3 PA-42 | 11/4/85 | 764-958 | | 3235 17B15 |
| 755C | Part III - Installation of Anti-Rotation Stops | PA-31T1 | 11/4/85 | ** | | 3235 17B16 |
| 764A | Wing Flap System Maintenance Procedure | PA-31T PA-31T1 | 7/17/79 | | | 2750 17C19 |
| 770 | Aileron Sprocket/Chain Inspection | PA-31T | 1/27/77 | ** | | 2710 17D18 |
| 773 | Nose Cone ("Radome") Latch System Refinement | PA-31T | 6/28/76 | 761-012 | | 5340 17E7 |
| 779 | Heater Fuel Pressure Relief Valve Inspection | PA-31T | 8/16/76 | ** | | 2140 17E16 |
| 780 | New Engine Top Mounts | PA-31T | 6/8/76 | 761-612 761-613 | | 7120 17E19 |
| 783 | Inspection of Air Conditioning System Capillary Sensor | PA-31T | 9/20/76 | ** | | 2150 17F7 |
| 789 | Inspection of Elevator Bellcrank And Elevator Control Rod | PA-31T | 10/6/77 | ** | | 2730 17F21 |
| 790 | Paralleling Relay Terminal Strip Tab | PA-31T | 9/21/76 | | | 2450 17G1 |
| 794 | Wing Tip Tank Drain Hose Replacement | PA-31T | 1/4/77 | 80007-37 | | 5720 17G7 |
| 798 | Cabin Headliner/Oxygen Cover Panel Refinement | PA-31T | 2/4/77 | | | 2520 17G13 3520 |
| 801 | Goodyear Tri-Metallic Brakes, Maintenance And Operation; Goodyear SL-1 Dated January 15, 1977 | PA-31T | 2/25/77 | | | 3240 17G21 |
| 802 | Main Landing Gear Door Hinge Attachment Screw Replacement | PA-31T | 3/9/77 | 761-128 | | 3210 17G24 |
| 804 | Heater System Maintenance And Operation | PA-31T | 2/8/77 | ** | | 2140 17H4 |
| 805 | Engine Ignition Exciter Box Relocation | PA-31T | 3/18/77 | 761-126 | | 7420 17H9 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-------------------|------------------|--------------------|----------|--------------------|
| 806 | Air Scoop Lip Deicer Rewiring/ Hour Meter Harness Revision | PA-31T | 2/22/77 | 456-763 | | 3020 3120 17H10 |
| 809 | Engine Oil Breather Tube Extension | PA-31T | 4/6/77 | 55997-03 | | 7920 17H16 |
| 816 | Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks) | PA-31T | 12/19/77 | 763-831 | | 2910 17I18 |
| 817 | Propeller Synchronizer System Refinement | PA-31T | 2/13/78 | 560-807 | | 6120 17I20 |
| 819A | Air Conditioning Compressor Drive Belt Alignment Procedure | PA-31T | 8/31/77 | 49186-02 | | 2150 17I23 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiSO ₂) ELT Batteries and/or Transmitters | PA-31T PA-31T1 | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 822 | Engine Compartment Fire Extinguisher Switch Protection | PA-31T | 7/12/77 | ** | | 2620 17J8 |
| 823 | Heater/Evaporator Return Air Duct Hose Replacement | PA-31T | 2/10/78 | 49478-02 | | 2120 17J10 |
| 829 | Emergency Exit Window Latch Modification | PA-31T | 11/14/77 | 763-809 | | 5620 17J18 |
| 830 | 24 Volt Cigar Lighter Element Replacement | PA-31T | 11/22/77 | | | 3310 17J19 |
| 831 | Heater Fuel Pressure Regulator Valve Installation | PA-31T | 1/10/78 | 761-139 | | 2140 17J20 |
| 833 | Cabin Pressurization System Rupture Disc Elimination | PA-31T | 4/10/78 | | | 2130 17J22 |
| 834 | Flap Electrical System Refinement | PA-31T | 3/3/78 | | | 2750 17J24 |
| 835B | Stability Augmentation System Refinement | PA-31T | 6/20/80 | 763-896 764-031 | | 2220 17K2 |
| 840 | Air Conditioning System Refinements | PA-31T PA-31T1 | 8/29/80 | | | 2150 17K12 |
| 840 | Part I - Condenser Fan Motor Support Bracket Replacement | PA-31T | 8/29/80 | 764-034 | | 17K12 |
| 840 | Part II - Unpressurized Air Source Annunciator Light And Freon Pressure Limiting Device Installation | PA-31T PA-31T1 | 8/29/80 | 764-035 | | 17K13 |
| 841 | Heater Spark Plug Replacement Or Modification | PA-31T PA-31T1 | 1/7/80 | 763-495 | | 2140 17K14 |
| 847 | Avionics Emergency Bus Power Switch Guard Installation | PA-31T | 8/13/79 | ** | | 2450 17L2 |
| 854 | Generator Airscoop Door Replacement | PA-31T PA-31T1 | 1/3/79 | 763-875 | | 8000 17L22 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|------------------------------|---------------------|---------------------|-------------|-------------|
| 857 | Propeller Beta Switch Replacement | PA-31T PA-31T1 | 2/7/79 | 763-839 | | 6120 18A22 |
| 866 | Windshield Wiper Arm Retaining Wire Installation | PA-31T PA-31T1 | 12/7/79 | 151-295 | | 5610 18C1 |
| 868 | Wing Flap Selector Switch Positive Detent Kit Installation | PA-31T PA-31T1 | 3/26/79 | 763-894 | | 2750 18C16 |
| 871 | Pedestal Control Assembly Inspection | PA-31T PA-31T1 | 3/7/79 | | | 7600 18D3 |
| 883 | Wing Flap Rivet Installation | PA-31T PA-31T1 | 10/20/79 | ** | | 5750 18F8 |
| 888 | Lift Transducer Case Rewire | PA-42 | 7/21/81 | 764-098 | | 3050 18F21 |
| 890 | Janitrol Heater Conversion | PA-31T PA-31T1 | 10/15/79 | 763-963 | | 2140 18F23 |
| 893A | Gyro Indicator Relay Replacement | PA-31T1 | 5/21/80 | ** | | 3420 18G5 |
| 896 | Landing Gear - Left Main, Torque Link And Safety Switch Deflector Replacement | PA-31T PA-31T1 | 5/23/80 | 764-014 | | 3210 18G11 |
| 902A | Gyro Slaving Panel Switch Modification | PA-31T PA-31T1 | 4/15/81 | 29299-R2 | | 3420 18G24 |
| 913A | Part I - Torque Transmitter Electrical Connector Restraint | PA-31T PA-31T1 | 3/16/83 | 764-105 | | 7710 18I3 |
| 913A | Part II - Torque Transmitter Relocation/Isolation | PA-31T PA-31T1 PA-42 | 3/16/83 | 764-126 764-947L | | 7710 18I3 |
| 916 | Elevator Control Stop Screw Replacement | PA-31T PA-31T1 | 7/17/81 | ** | | 2730 18I8 |
| 917 | Portable Fire Extinguisher Inspection | PA-42 | 7/20/81 | 459-839 459-848 | | 2620 18I11 |
| 921 | Main Landing Gear Lock Rod Attachment Fork Replacement | PA-31T PA-31T1 PA-31T2 | 4/21/82 | 764-127 | | 3230 18I21 |
| 922 | Autopilot Rudder Servo Motor Access | PA-42 | 8/2/82 | 420-217 | | 5320 18I22 |
| 924 | Maximum Operating Airspeed (VMO) | PA-31T1 | 1/20/82 | 764-150 764-151 | | 3410 18J2 |
| 925 | Bleed Air Line Inspection/ Generator Cooling Scoop Cam Loc Receptacle Removal | PA-42 | 7/21/81 | ** | | 7110 18J3 |
| 926 | Deice Relay Shelf Modification And Diode Addition | PA-42 | 7/21/81 | ** | | 2450 18J6 |
| 928 | Pedestal Support Channel Assembly Removal | PA-42 | 9/29/81 | 404-829 | | 7600 18J11 |
| 929 | Pitch Servo Bridle Clamp Instruction | PA-42 | 2/11/82 | | | 2210 18J13 |
| 930 | Powerplant Cowl Drain Inspection/ Modification | PA-42 | 7/21/81 | | | 7100 18J15 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------------------|---------------------|----------------------|-------------|-------------|
| 932 | Pressurization Control Wiring Rework | PA-42 | 11/19/82 | 764-403 | | 2130 18J19 |
| 935 | ELT Antenna Inspection | PA-42 | 3/26/82 | ** | | 2560 18J23 |
| 937 | Nose Gear Actuator Hose Replacement | PA-42 | 5/24/82 | ** | | 3210 18K1 |
| 941 | Nose Wheel Shimmy Dampener Replacement | PA-31T PA-31T2 | 9/21/82 | 456-010 | | 3250 18K5 |
| 942 | Flap Handle Travel Inspection | PA-42 | 4/4/82 | 77196-03 | | 2750 18K7 |
| 943 | Pilot's Right Rudder Pedal Torque Tube Retention | PA-42 | 11/4/81 | 424-059 | | 2720 18K9 |
| 945 | Cowl Inlet Lip Screw Replacement | PA-42 | 2/16/82 | 414-468 406-561 | | 5440 18K14 |
| 949 | Elevator Trim Mechanism Modification And Enclosure Installation | PA-42 | 9/24/82 | 764-411L | | 2730 18K23 |
| 950 | Battery Ventilation Tube Inspection | PA-42 | 6/8/82 | 420-202 | | 2430 18K24 |
| 952 | Engine Dual Drive Oil Supply Line Oil Pressure Snubber Relocation | PA-42 | 12/10/82 | 764-414 | | 7920 18L3 |
| 954 | Nose Landing Gear Strut Placard Inspection Replacement | PA-42 | 2/2/83 | 72236-02 | | 3220 18L9 |
| 956 | Cabin Door Cable Assembly Inspection And Modification | PA31T PA-31T1 PA-31T2 | 5/17/82 | 47716-04 57462-03 | | 5210 18L11 |
| 960 | Aft Fuselage Drain Holes Inspection | PA-42 | 12/3/82 | | | 5560 19A4 |
| 961 | Environmental Control System Wiring Modification | PA-42 | 1/5/83 | * | | 2100 19A7 |
| 962 | Pitch Trim Drum Shaft Roll Pin Security | PA-42 | 3/18/83 | MS20995-C32 | | 2731 19A10 |
| 964 | Avionics Bay Blanket Modification | PA-31T2 | 4/29/83 | 764-946 | | 3400 19A14 |
| 969 | Wing Tip Ground Strap Installation | PA-31T1 PA-31T3 | 7/11/84 | ** | | 2360 19A24 |
| 977 | Dynamic Stability Improvement Kit | PA-31T | 3/1/85 | 765-158 | | 2730 19B21 |
| 979 | Emergency Pressurization Bleed Air Valve Modification | PA-42 | 1/8/85 | ** | | 7530 19C1 |
| 983 | Engine Air Inlet Duct Assembly Reinforcement | PA-42 PA-42-720 | 3/14/86 | ** | | 7161 19C12 |
| 986 | Series Start Circuit Change Modification | PA-42-1000 | 7/22/86 | 765-194 | | 2453 19C20 |
| 993 | Engine Air Inlet Drain Holes | PA-42-1000 | 1/5/87 | N/A | | 7162 19D13 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|--------------------|------------|
| 994 | Propeller Ground Clearance | PA-42-1000 | 1/12/87 | ** | | 3223 19D15 |
| 998 | Remote Control Circuit Breaker (RCCB) Ground Wire Installation | PA-42-1000 | 7/8/87 | 765-322 | | 2451 19E4 |
| 1002 | Overhead Panel Map Light Switch Installation | PA-42-1000 | 4/4/88 | 84112-03 | | 3314 19E14 |
| 1003 | Oxygen Shutoff Valve Assembly | PA-42-720 PA-42-720R PA-421000 | 8/19/88 | ** | | 3510 19E17 |
| 1013 | Improved Elevator Trim Cover Replacement | PA-42 PA-42-720 PA-42-720R | 10/11/94 | ** | | 5510 19G1 |
| 1014 | Addition of Grease Fitting to Nose Gear Steering Arm Bracket | PA-42 PA-42-720 PA-42-720R | 10/17/94 | ** | | 3250 19G1 |
| 1015 | Replacement of EATON Brand Electrical Contactor Box | PA-42-1000 | 7/14/95 | 766-296 557-125 | | 2436 19G6 |
| 1017 | Engine Fire Extinguisher System Rewire and Distribution of Walter Kidde Service Bulletin 899857-26-365 | PA-42 PA-42-720 | 3/7/97 | 766-617 | | 2623 19G11 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1054 | Propeller Control Arm Attachment Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 | 10/10/2002 | 51623-000 | | 6120 20A3 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 20C2 |
| 1088 | 40336-000 Link Assembly Inspection | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 12/15/2004 | 40336-000 | | 3220 20F11 |
| 1092C | Main Gear Retraction Arms Inspection, 42042-000/-002 | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 | 7/25/2013 | 42042-000 42042-002 | | 3211 |
| 1116A | Contactor Maintenance | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-1000 | 3/15/2019 | N/A | | 2435 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1
 PA-31T2/31T3
 PA-42

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|----------|----------|
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1188 | Landing Gear Hydraulic System Filter Maintenance | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000 | 3/19/2015 | N/A | | 2912 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1316 | Main Landing Gear Door Bolt Replacement | PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 | 5/10/2023 | 453-204 (43972-000) | | 3211 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|------------|--------------|
| 177 | Firewalls | All Models | 8/10/51 | | | 13B13 |
| 467 | Alternator - Regulator System Modification | PA-32-260 | 1/10/66 | 756-992V | | 2430 14I5 |
| 475 | Inspection of Landing Gear Strut Exposure | PA-32-260 | 7/6/66 | | | 3210 14I17 |
| 476 | Replacement of Fuel Selector Valve | PA-32-260 | 4/26/66 | 492-104V | 67-03-07 | 2820 14I18 |
| 484 | Fuel System Operating Procedures | PA-32 | 12/20/66 | | | 2800 14J7 |
| 486A | Cylinder Head Temperature Probe Location | PA-32 | 4/16/68 | | | 7720 14J13 |
| 494 | Inspection of Cherokee Landing Gears | PA-32-260/300 | 11/7/67 | | | 3200 14J24 |
| 495 | Inspection of Control Cable-Constant Speed Propellers | PA-32-260/300 | 1/29/68 | ** | | 6120 14K2 |
| 499 | Owners Handbook Revision | PA-32-260 | 3/14/68 | | | General 14K6 |
| 527D | Inspection of Control Wheels | PA-32-260/300 | 6/21/78 | ** | 69-22-02 | 2700 15A14 |
| 535A | Rudder Trim Locking Pin | PA-32-260/300 | 9/26/69 | | | 2720 15B9 |
| 566 | Autopilot Servo Spacer Bushing Installation | PA-32-260/300 | 9/25/70 | 760-508V | | 2210 15F3 |
| 571 | Flap Handle Assembly Modification | PA-32-260/300 | 3/30/71 | 760-531V | | 2750 15F15 |
| 576 | Stabilator Balance Weight Tube Replacement | PA-32-260/300 | 4/20/71 | ** | | 5570 15G2 |
| 577 | Servo Bridle Cable Clamp Replacement | PA-32-260/300 | 6/1/71 | 757-863V | | 2210 15G8 |
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-32-300 PA-32-301 PA-32-301FT PA-32-301T PA-32-301XTC PA-32R-300 PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC PA-32RT-300/300T PA-32S-300 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 581 | Inspection of Aileron Hinge Doublers | PA-32-260/300 | 7/12/71 | 760-540V | | 5550 15G20 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 612A | Fuel Leakage - Fuel Sender Unit | PA-32-260/300 | 6/8/72 | 68101-00V | | 7330 15K1 |
| 614 | Stabilator Attachment Fittings Bolt Torque | PA-32-260/300 | 6/15/72 | | 72-14-07 | 2740 15K6 |
| 615 | Stabilator Drain Holes | PA-32-260/300 | 7/6/72 | | | 2740 15K8 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|-----------------|------------------|--------------|----------|------------|
| 617B | Piper Automatic Locator Transmitter Replacement | PA-32 | 8/30/73 | | 72-22-03 | 2560 15K18 |
| 620 | Forward Cabin Door Reinforcement | PA-32-260/300 | 2/23/73 | 760-729V | | 5210 15L8 |
| 621 | Main Landing Gear Torque Link Replacement | PA-32-260/300 | 11/9/72 | ** | | 3210 15L10 |
| 624 | Altimatec III-1 Gyro Horizon Fitting Installations | PA-32-300 | 9/1/72 | 458 840 | | 3420 15L17 |
| 636 | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement) | PA-32 | 10/24/72 | ** | | 2430 16B2 |
| 647 | Seat Back Stop Modification | PA-32-260/300 | 3/31/73 | 760-740V | | 2510 16C1 |
| 653 | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265, Dated December 15, 1972) | PA-32 | 4/9/73 | ** | | 7610 16C14 |
| 662 | Engine Mount Bolt Torque | PA-32-260/300 | 7/6/73 | AN960-616 | | 7120 16D10 |
| 665A | Rotator Type Intake Valves | PA-32-300 | 10/24/73 | ** | | 7160 16D16 |
| 671 | Inspection And Modification Rudder Bar Assembly | PA-32-260/300 | 10/5/73 | | | 2720 16E9 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D) | PA-32 | 4/19/74 | ** | | 7230 16F9 |
| 695 | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974) | PA-32 | 5/3/74 | ** | | 2210 16G13 |
| 700 | Toe Brake System Modification | PA-32-260/300 | 4/9/74 | 760-842V | | 3240 16H5 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-32 | 2/27/74 | ** | | 7710 16I11 |
| 708 | Nose Wheel Steering System Inspection | PA-32-260/300 | 6/7/74 | ** | | 3250 16I14 |
| 715 | Emergency Locator Transmitter Switch Cover Modification | PA-32-260/300 | 9/27/74 | 760-876V | | 2560 16J12 |
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-32 | 5/31/74 | ** | | 7410 16J18 |
| 732 | Steering Stop Replacement | PA-32-260/300 | 9/30/74 | 95061-129 | | 3250 16L6 |
| 734 | Bendix ADF-T-12 C/D Installation Inspection And Modification | PA-32-260/300 | 12/3/74 | 760-857V | | 3450 16L8 |
| 738A | Modification of The Overhead Fresh Air Vent System | PA-32-260/300 | 1/14/75 | ** | | 2120 16L20 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|----------|------------|
| 745 | Inspection of Wing Mainspar Attach Bolts | PA-32-260/300 | 4/24/75 | 404-890 | | 5710 17A14 |
| 747 | Inspection of Throttle Mixture Control Attachments | PA-32-260/300 | 5/28/75 | ** | | 7610 17A18 |
| 749 | Torque Link Greaser Bolt Replacement Kit | PA-32-260/300 | 10/14/75 | 760-910V | | 3210 17A21 |
| 750 | Rain Gutter Installation | PA-32-260/300 | 8/15/75 | 760-975V | | 5210 17A22 |
| 756 | Dual Glideslope Indicator Placard (King Radio Installations Only) | PA-32-260/300 | 1/6/76 | 69669-112V | | 3430 17B22 |
| 758 | Inspection of Bendix Ignition Switches; Re: Bendix Service Bulletin No. 583 | PA-32-260/300 PA-32R-300 | 5/17/76 | 761-065V | | 7410 17C2 |
| 761 | Magnetic Compass Relocation Kit | PA-32-260/300 | 11/17/75 | 760-695V | | 3440 17C14 |
| 762 | Modification of ELT Remote Switches | PA-32-260/300 PA-32R-300 | 1/26/76 | 761-009V | | 2560 17C15 |
| 763A | Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection | PA-32-260/300 | 11/14/75 | ** | 75-24-02 | 2570 17C16 |
| 768 | Aileron Balance Cable Pulley Support Bracket Modification | PA-32R-300 | 5/25/76 | 761-042V | | 2710 17D14 |
| 788 | Air Conditioning Installations | PA-32-300 PA-32R-300 | 9/3/76 | 79584-02V 79589-05V | | 2150 17F19 |
| 791 | Electrical System Refinement | PA-32R-300 | 2/24/77 | 761-087V | | 2400 17G3 |
| 793 | Flap Warning Placard | PA-32-260/300 PA-32S-300 PA-32R-300 | 1/6/77 | 35664-02 | | 2750 17G5 |
| 796 | Lower Cowl Drain Inspection | PA-32-260 | 3/30/77 | | | 7100 17G10 |
| 797 | Front Seat Modification (Aircraft With Club Seating Only) | PA-32-260/300 PA-32R-300 | 2/25/77 | 761-110V | | 2510 17G12 |
| 800 | Performance Refinement of Narco ADF - 140 Installation | PA-32-260/300 PA-32R-300 | 2/25/77 | ** | | 3450 17G19 |
| 808 | Hydraulic Pump Terminal Inspection | PA-32R-300 | 6/8/77 | ** | | 2910 17H14 |
| 810 | Landing Gear Extender, Backup, Diaphragm Replacement | PA-32R-300 | 4/15/77 | 761-138V | | 3230 17H18 |
| 813 | Vertically Adjustable Seat Refinement | PA-32-260/300 PA-32R-300 | 6/9/77 | ** | | 2510 17I8 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-32-260/300 PA-32R-300 PA-32RT-300/300T | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 836 | Inspection And Modification Narco ADF-140/141 Antenna | PA-32-260 PA-32-300 PA-32R-300 | 2/9/78 | ** | | 3450 17K4 |
| 837 | Inspection of Elbow Assembly Engine Air Filter | PA-32-300 PA-32R-300 | 5/22/78 | | | 7160 17K7 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|----------------------|----------|------------|
| 842 | Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement | PA-32-260/300 | 9/26/78 | 760-910V | | 3210 17K17 |
| 861 | Part I - Forward Facing Seat Back Modification | PA-32-260/300 PA-32R-300 PA-32RT-300/300T | 11/13/78 | 763-890V | | 2520 18B7 |
| 861 | Part II - Rear Facing (Club) Seat Back Retention | PA-32-260/300 PA-32RT-300/300T | 11/13/78 | 408 834V | | 2520 18B8 |
| 862 | Main Landing Gear And Strut Fairing Replacement | PA-32-260 PA-32-300 | 3/30/79 | 760-910V | | 3210 18B11 |
| 864 | Part I - Forward Cabin Door Stop (Striker Plate) Installation | PA-32-260/300 PA-32RT-300/300T | 12/8/78 | ** | | 5210 18B16 |
| 864 | Part II - Cabin Heat Control Refinement | PA-32-260/300 PA-32RT-300/300T | 12/8/78 | 763-870V 763-871V | | 2140 18B19 |
| 864 | Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision | PA-32-260 | 12/08/78 | 763-874 | | 3420 18B20 |
| 864 | Part IV - Induction Sump Drain Valve | PA-32R-300 PA-32RT-300 | 12/8/78 | 763-887V | | 7160 18B21 |
| 869 | Part I - Installation of Top Cowl Exhaust System Heat Shields | PA-32RT-300T | 9/10/79 | 753-910V | | 7810 18C18 |
| 869 | Part II - Modification of Fuel Boost Pump Outlet Fitting | PA-32RT-300T | 9/10/79 | ** | | 2820 18C19 |
| 869 | Part III - Tachometer Cable Rerouting | PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T | 9/10/79 | 763-916V | | 7710 18C20 |
| 882A | Part I - Rudder Skin Inspection And Modification | PA-32RT-300 PA-32RT-300T | 11/12/81 | 763-936V | 79-26-04 | 5540 18F4 |
| 882A | Part II - Rudder Skin Replacement | PA-32RT-300 PA-32RT-300T | 11/12/81 | 763-940V | 79-26-04 | 5540 18F6 |
| 884 | Fuel Quantity Sender Check | PA-32-260/300 | 9/15/80 | 68101-002V | | 2840 18F11 |
| 895A | Magneto Switch Modification | PA-32-301 | 3/19/81 | 153-010 488-396 | | 7430 18G8 |
| 900 | Air Induction Valve Assembly Support Reinforcement | PA-32R-301T | 7/30/80 | ** | | 7160 18G19 |
| 901 | Cabin Air Intake Duct Modification | PA-32-301/301T PA-32R-301/301T | 9/2/80 | 764-013V | | 2120 18G22 |
| 903A | Alternator Belt Installation (Air Conditioned Models) | Any Textron-Lycoming Powered PA-32 | 3/11/96 | 62833-82 | | 2431 18H2 |
| 908 | Instrument Panel Lighting - Century 21 And 41 Autopilot Installation | PA-32-301/301T PA-32R-301/301T | 12/20/80 | | | 3310 18H11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|------------------------|--------------------------------|------------|
| 920 | Required Placard Adhesion Check | PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 6/29/81 | | | 2500 18119 |
| 923A | Cabin Heat Cable Heatshield Installation | PA-32-301T PA-32R-301T PA-32RT-300T | 2/12/82 | 764-138V 764-137V | | 2140 18124 |
| 927 | Nose Landing Gear Refinement | PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T | 10/2/81 | 764-135V | 81-24-07 | 3220 18J10 |
| 934 | Bottom Cowl Modification | PA-32-300 PA-32-301 | 11/23/81 | 764-136V | | 7110 18J22 |
| 947 | Pressure Switch Relocation Manifold Pressure Gauge | PA-32RT-300T PA-32R-301T PA-32-301T | 2/5/82 | 764-216V | | 7710 18K19 |
| 948 | Heated Windshield Panel Sealing And Gyro Filter Protection | PA-32R-301T | 2/5/82 | ** | | 5610 18K20 |
| 997 | Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08-08 | PA-32-260 PA-32-300 | 5/14/87 | ** | 87-08-08 | 5711 19D24 |
| 1032 | Improved Fuel Quantity Senders Available | PA-32R-301 II HP PA-32R-301T II TC | 3/13/2001 | 686-202 686-203 | | 2842 19J1 |
| 1033 | Air Conditioning Hose Replacement | PA-32R-301 II HP PA-32R-301T II TC | 7/9/2001 | 566-419 454-868 | | 2155 19J4 |
| 1040A | Alternator Drive Belt Conversion Kit (for Aircraft Equipped with Optional Factory Installed Air Conditioning) | PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32R-301 PA-32R-301T PA-32RT-300 PA-32RT-300T | 10/7/2021 | 767-310 (88306-000) | | 2410 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1043 | Oil Cooler Kit | PA-32R-301T II TC | 4/25/2002 | 767-332 | | 7921 19K15 |
| 1049 | Voltage Regulator Replacement | PA-32R-301 II HP PA-32R-301T II TC | 4/30/2002 | 68804-007 68804-006 | | 2424 19L9 |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-11-01 CE-02-05 (SAIB) | 2702 20C2 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|--------------|----------|----------|
| 1074 | S-TEC Autopilot Component Seating Procedure | All | 11/3/2003 | N/A | | 2210 |
| 1084 | Cabin Heater Improvement Kit | PA-32-301XTC PA-32R-301T II TC | 1/14/2005 | 767-333 | | 2140 |
| 1089 | Aircraft Painting Requirement | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 10/21/2004 | N/A | | 1100 |
| 1093B | Electrical Contactor Replacement Kit | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/300T | 11/28/2017 | 88371 | | 2400 |
| 1095C | Classification and Disposition of Hail Damage | PA-32-260/300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/300T | 5/7/2024 | N/A | | 5100 |
| 1103 | Attitude Indicator Standby Battery Failure | PA-32-301FT PA-32-301XTC | 4/20/2007 | 88411-002 | | 3420 |
| 1105 | Automatic Baggage Door Light Switch Upgrade | PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC | 4/24/2007 | 88422-002 | | 3300 |
| 1106A | Sky-Tec Starter Cranking Instructions | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 10/28/2009 | N/A | | 8011 |
| 1108 | Manifold Pressure Transducer Failures | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 3/4/2008 | N/A | | 7713 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|---|----------|----------|
| 1116A | Contactactor Maintenance | PA-32-260/300 PA-32S-300 PA-32R-300 PA-32RT-300/300T PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC | 3/15/2019 | N/A | | 2435 |
| 1123 | Avidyne EXP5000 Software Upgrade (Mod 57) | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 9/27/2010 | N/A | | 3420 |
| 1126A | Voltage Suppressor Advisory | PA-32-301FT PA-32-301XTC PA-32R-301 II HP PA-32R-301T II TC | 3/23/2017 | N/A | | 3400 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1165 | Hydraulic Pump Identification and Servicing Requirements | PA-32R Series | 10/18/2012 | | | 2910 |
| 1218A | Crew Seat Control Cable Modification | PA-32-301 PA-32-301FT PA-32-301XTC PA-32R-301 SP PA-32R-301 II HP PA-32R-301T Turbo SP PA-32R-301T II TC | 8/8/2017 | 76356-003 554-422 487-490 | | 2510 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1268 | Hartzell 'K' Flange Propeller Hub Replacement | PA-32-300 PA-32S-300 PA-32R-300 PA-32RT-300 | 10/9/2019 | N/A | | 6114 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1311 | Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits' | PA-32-301 PA-32-301FT PA-32-301XTC PA-32R-301 II HP | 6/7/2022 | 470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40 | | 7120 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------|----------|----------|
| 1320 | Wing And Fuselage Skin Repair Limitations | PA-32-260/300 PA-32R-300 PA-32RT-300/300T PA-32-301 PA-32-301T PA-32-301FT PA-32-301XTC PA-32R-301 PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC | 12/1/2022 | N/A | | 5100 |
| 1327G | Wing Walk Modification and Inspection | PA-32-260 PA-32-300 PA-32-301/301T PA-32-301FT PA-32-301XTC PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T | 9/25/2024 | N/A | | 5720 |
| 1331A | Improved Spring Attachment Plate | PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T | 7/1/2024 | 67753-000 | | 3210 |
| 1346 | Spar Box Inspection | PA-32-260/-300 PA-32-301FT PA-32-301XTC PA-32-301/-301T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC PA-32RT-300/-300T PA-32S-300 | 11/12/2024 | | | 5711 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|-----------------|------------------|----------------------|------------|------------|
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-34-200 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 614 | Stabilator Attachment Fittings Bolt Torque | PA-34-200 | 6/15/72 | | 72-14-07 | 2740 15K6 |
| 615 | Stabilator Drain Holes | PA-34-200 | 7/6/72 | | | 2740 15K8 |
| 617B | Piper Automatic Locator Transmitter | PA-34-200 | 8/30/73 | | 73-07-02 | 2560 15K18 |
| 618 | Alternator Fan Replacement | PA-34-200 | 10/8/73 | 754-827V | 72-15-02 | 2430 15L1 |
| 620 | Forward Cabin Door Reinforcement | PA-34-200 | 2/23/73 | 760-729V | | 5210 15L8 |
| 622 | Cabin Heater/Defroster Modification | PA-34-200 | 8/24/72 | 760-692V 760-693V | | 2140 15L12 |
| 624 | Altimatic III-1 Gyro Horizon Fitting Installation | PA-34-200 | 9/1/72 | 458-840 | | 3400 15L17 |
| 625 | Heat Exchangers And Heat Silencers Modification | PA-34-200 | 11/13/72 | 69471-21V | | 2140 15L20 |
| 626 | Landing Gear Bolt Lubrication | PA-34-200 | 11/20/72 | | | 3200 15L23 |
| 647 | Seat Back Stop Modification | PA-34-200 | 3/31/73 | 760-740V | | 2510 16C1 |
| 661 | Engine Firewall Modification | PA-34-200 | 6/26/73 | 760-758V | | 5410 16D8 |
| 663 | Stabilator Drain Hole Inspection (Deicer Equipped Aircraft Only) | PA-34-200 | 5/25/73 | | | 5300 16D11 |
| 664 | Wing Skin/Rib Inspection And Modification | PA-34-200 | 4/17/74 | 760-771V | | 5710 16D13 |
| 665A | Intake Valves, Rotator Type | PA-34-200 | 10/24/73 | ** | | 7160 16D16 |
| 668A | Engine Cowl Modifications | PA-34-200 | 8/7/74 | ** | | 7110 16E4 |
| 669 | Aileron/Rudder Interconnect Cable System Modification | PA-34-200 | 4/16/74 | 760-776V | | 2710 16E6 |
| 671 | Rudder Bar Assembly Inspection And Modification | PA-34-200 | 10/5/73 | | | 2720 16E9 |
| 673 | Exhaust System Replacement | PA-34-200 | 9/28/73 | 760-764V | | 7810 16E14 |
| 677A | Propeller Spinner And Propeller Damper Installation Kits | PA-34-200 | 11/14/73 | 760-766V 760-781V | | 6110 16E22 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D) | PA-34-200 | 4/19/74 | ** | | 7230 16F9 |
| 684 | Landing Gear Lubrication | PA-34-200 | 1/9/74 | | | 3200 16F18 |
| 700 | Toe Brake System Modification | PA-34-200 | 4/9/74 | 760-842V | | 3240 16H5 |
| 704A | Inspection of Fuel Crossfeed Drain Valves | PA-34-200 | 11/25/74 | 492-202V | | 2820 16H10 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--------------------|---------------------|-----------------|-------------|---|-------|
| 706 | Propeller Damper Compression Spring (Reference Hartzell Service Bulletin No. 103 Dated 2/20/74) | PA-34-200 | 5/6/74 | 760-853V | | 6120 | 16I3 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-34-200 | 2/27/74 | ** | | 7710 | 16I11 |
| 714 | Rudder Trim Modification | PA-34-200 | 6/4/74 | 760-800V | 73-13-01 | 2720 | 16J11 |
| 715 | Emergency Locator Transmitter Switch Cover Modification | PA-34-200 | 9/27/74 | 760-876B | | 2560 | 16J12 |
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-34-200 | 5/31/74 | ** | | 7410 | 16J18 |
| 734 | Bendix ADF-T-12 C/D Installation Inspection And Modification | PA-34-200 | 12/3/74 | 760-857V | | 3450 | 16L8 |
| 737 | Manifold Pressure Gauge Line Modification | PA-34-200 | 12/2/74 | 760-765V | | 7710 | 16L19 |
| 738A | Modification of The Overhead Fresh Air Vent System | PA-34-200 | 1/14/75 | ** | | 2120 | 16L20 |
| 742 | Seneca II Refinement Modifications | PA-34-200T | 5/9/75 | ** | | 1. 7110 2. 5200 3. 2740 4. 3400 5. 7410 | 17A8 |
| 747 | Inspection of Throttle And Mixture Control Attachments | PA-34-200 | 5/28/75 | ** | | 7610 | 17A18 |
| 750 | Rain Gutter Installation | PA-34-200 | 8/15/75 | 760-975V | | 5210 | 17A22 |
| 754 | Auxiliary Fuel System Modification | PA-34-200T | 7/31/75 | 760-926V | | 2810 | 17B12 |
| 756 | Glideslope, Dual, Indicator Placard (King Radio Installation Only) | PA-34-200/200T | 1/6/76 | 69669-112V | | 3430 | 17B22 |
| 757 | Aft Wing Modification (Optional) | PA-34-200 | 10/22/75 | ** | | 5710 | 17C1 |
| 761 | Magnetic Compass Relocation Kit | PA-34-200/200T | 11/17/75 | 760-795V | | 3440 | 17C14 |
| 762 | Modification of ELT Remote Switches | PA-34-200/200T | 1/26/76 | 761-009V | | 2560 | 17C15 |
| 763A | Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection | PA-34-200/200T | 11/14/75 | ** | 75-24-02 | 2510 | 17C16 |
| 769 | Cold Weather Starting Procedures | PA-34-200T | 3/10/76 | ** | | 7200 | 17D15 |
| 792 | Optional Cold Weather Priming System Installation | PA-34-200T | 12/10/76 | 761-094V | | 7310 | 17G4 |
| 793 | Flap Warning Placard | PA-34-200/200T | 1/6/77 | 35664-02 | | 2750 | 17G5 |
| 795 | Oil Cooler Baffle Winterization Modification | PA-34-200T | 2/8/77 | ** | | 7230 | 17G9 |
| 797 | Front Seat Modification (Aircraft With Club Seating Only) | PA-34-200T | 2/25/77 | 761-110V | | 2510 | 17G12 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------------|------------------|--------------|----------|------------|
| 800 | Refinement of Narco ADF-140 Installation Performance | PA-34-200T | 2/25/77 | ** | | 3450 17G19 |
| 808 | Hydraulic Pump Terminal Inspection | PA-34-200/200T | 6/8/77 | ** | | 2910 17H14 |
| 813 | Vertically Adjustable Seat Refinement | PA-34-200/200T | 6/9/77 | ** | | 2510 17I8 |
| 818 | Outside Air Temperature Gauge Replacement | PA-34-200T | 10/19/77 | 99479-03V | | 3410 17I22 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiSO ₂) ELT Batteries and/or Transmitters | PA-34-200 PA-34-200T | 7/28/80 | ** | 79-18-05 | 2560 17J2 |
| 836 | Inspection And Modification Narco ADF-140/141 Antenna | PA-34-200T | 2/9/78 | ** | | 3450 17K4 |
| 839 | Main Landing Gear Trunnion Bushings | PA-34-200T | 9/27/78 | 67026-10 | | 3210 17K10 |
| 852 | Nose Gear Placard (P/N 582 943V) | PA-34-200/200T | 9/14/78 | 582-943V | | 3220 17L17 |
| 858 | Inspection of The Landing Gear Relay Wiring | PA-34-200T | 10/10/78 | | | 3230 18A24 |
| 861 | Part I - Forward Facing Seat Back Modification | PA-34-200 PA-34-200T | 11/13/78 | 763-890V | | 2520 18B7 |
| 861 | Part II - Rear Facing (Club) Seat Back Retention | PA-34-200T | 11/13/78 | 408-834V | | 2520 18B8 |
| 881 | Wiring Harness Protective Sleeve Installation | PA-34-200T | 11/13/79 | ** | | 2400 18F1 |
| 889 | Pneumatic Pump Inlet Filter Relocation | PA-34-200T | 11/6/79 | 763-919V | | 3710 18F22 |
| 898 | King KNS - 80 Area Navigation System Cooling | PA-34-200T PA-34-220T | 5/28/82 | 764-385V | | 2300 18G15 |
| 920 | Required Placard Adhesion Check | PA-34-200T PA-34-220T | 6/29/81 | | | 2500 18I19 |
| 946B | KNS - 81 Wiring Change | PA-34-220T | 9/1/82 | | | 3450 18K15 |
| 948 | Heated Windshield Panel Sealing And Gyro Filter Protection | PA-34-220T | 2/5/82 | ** | | 5610 18K20 |
| 963 | Radio Master Relay Retrofit | PA-34-200T | 11/9/83 | ** | | 2450 19A12 |
| 966 | Tachometer Generator Mounting Modification | PA-34-220T | 12/19/83 | 764-942V | | 7710 19A18 |
| 1020 | Relocation of Signal Ground for Cylinder Head and Oil Temperature Sensors | PA-34-220T V | 8/27/98 | ** | | 7701 19H4 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--------------|--------------------------------|----------|
| 1021 | Distribution of Teledyne Continental Motors Service Bulletin SB 98-8 "Number One and Three Cylinder Intake Tube Modification" and subsequent modification of the engine installation to facilitate compliance. | PA-34-220T V | 1/27/99 | ** | | 7313 |
| 1025 | Replacement of Existing Cylinder Head Temperature Wires with Shielded Wiring. | PA-34-220T V | 10/1/99 | ** | | 7701 |
| 1031 | Fuel Pump Cooling Inlet Installation | PA-34-220T V | 12/11/2000 | 766-678 | | 7311 |
| 1036 | Teledyne Continental Motors Service Information Letter SIL 01-2, "Precision Airmotive Corporation SIL RS-59" | PA-34-220T V | 11/5/2001 | 554-321 | | 7318 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1048A | DDMP May Provide Erroneous Information in the Percent Power Query Mode at High Altitudes | PA-34-220T V | 5/30/2003 | 680-475 | | 7700 |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-11-01 CE-02-05 (SAIB) | 2702 |
| 1074 | S-TEC Autopilot Component Seating Procedure | All | 11/3/2003 | N/A | | 2210 |
| 1078 | Improved Flap Potentiometer | PA-34-220T V | 1/19/2004 | 100661-003 | | 2751 |
| 1086 | Propeller Blade De-ice Boots Maintenance | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 7/16/2004 | N/A | | 3112 |
| 1087 | Wing Aft Spar-to-Fuselage Attachment Hardware | PA-34-220T V | 3/30/2005 | ** | | 5740 |
| 1089 | Aircraft Painting Requirement | PA-34-220T V | 10/21/2004 | N/A | | 1100 |
| 1093B | Electrical Contactor Replacement Kit | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 11/28/2017 | 88371 | | 2400 |
| 1095C | Classification and Disposition of Hail Damage | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 5/7/2024 | N/A | | 5100 |
| 1108 | Manifold Pressure Transducer Failures | PA-34-220T V | 3/4/2008 | N/A | | 7713 |
| 1116A | Contactor Maintenance | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 3/15/2019 | N/A | | 2435 |
| 1123 | Avidyne EXP5000 Software Upgrade (Mod 57) | PA-34-220T V | 9/27/2010 | N/A | | 3420 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--|------------------|---|----------|----------|
| 1126A | Voltage Suppressor Advisory | PA-34-220T V | 3/23/2017 | N/A | | 3400 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | PA-34-200 PA-34-200T | 4/27/2011 | MS20995-C32 | | 2800 |
| 1154 | Engine Starter Motor Replacement | PA-34-220T V | 3/28/2012 | ** | | 8010 |
| 1156 | Propeller Feather Stop Product Improvement | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 4/2/2012 | 78713-003 | | 6120 |
| 1162 | Cowl Flap Replacement | PA-34-220T V | 3/5/2013 | ** | | 7110 |
| 1164 | Engine Front Baffle Replacement Kit | PA-34-220T V | 11/6/2012 | 88537-001 | | 7160 |
| 1165 | Hydraulic Pump Identification and Servicing Requirements | PA-34 Series | 10/18/2012 | | | 2910 |
| 1197 | Propeller Spinner Bulkhead Improvement | PA-34-220T V | 6/21/2016 | 688-023 (E-7258-5) | | 6113 |
| 1210 | Magneto Timing Procedure | PA-34-220T IV | 12/21/2016 | 761-888 | | 7414 |
| 1218A | Crew Seat Control Cable Modification | PA-34-220T III-IV-V | 8/8/2017 | 76356-003 554-422 487-490 | | 2510 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1268 | Hartzell 'K' Flange Propeller Hub Replacement | PA-34-200 | 10/9/2019 | N/A | | 6114 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1284A | Aspen Avionics EFD1000 Update to Software Version 2.10.2 | PA-34-220T V | 5/15/2023 | N/A | | 3420 |
| 1311 | Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits' | PA-34-200 | 6/7/2022 | 470-516 / J-9613-19 475-115 / J-9613-12 475-124 / J-9613-40 | | 7120 |
| 1320 | Wing And Fuselage Skin Repair Limitations | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 12/1/2022 | N/A | | 5100 |
| 1327G | Wing Walk Modification and Inspection | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 9/25/2024 | N/A | | 5720 |
| 1331A | Improved Spring Attachment Plate | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 7/1/2024 | 67753-000 | | 3210 |
| 1337 | Flight Controls Maintenance Improvements | PA-34-220T | 1/29/2023 | | | 2700 |
| 1346 | Spar Box Inspection | PA-34-200 PA-34-200T PA-34-220T III-IV-V | 11/12/2024 | | | 5711 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|
|--------|---------|--------------------|---------------------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|------------------------|---------------------|-----------------|-------------|-------------|
| 177 | Firewalls | All Models | 8/10/51 | | | 13B13 |
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-36-300 PA-36-375 | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 633 | Inspection And Repair of Flood Exposed Airplanes | PA-36 | 10/9/72 | | | 5300 16A18 |
| 652A | Pilot And Maintenance Training Program | PA-36 | 6/14/73 | | | 500 16C11 |
| 659 | Seat Back Modification | PA-36 | 5/9/74 | 760-797V | | 2510 16D6 |
| 678 | Relocation of Throttle Control Rod End | PA-36 | 12/12/73 | | | 7610 16E24 |
| 682B | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D) | PA-36 | 4/19/74 | ** | | 7230 16F9 |
| 693 | Upper Cowl Support Modification | PA-36 | 3/29/74 | 760-811V | | 7110 16G9 |
| 707 | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-36 | 2/27/74 | ** | | 7710 16I11 |
| 718 | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974) | PA-36 | 5/31/74 | ** | | 7410 16J18 |
| 727 | Spray Pump Windmill Assembly Modification (Reference Agrinautics Service Bulletin No. SP-74-1 Dated April 30, 1974) | PA-36 | 8/8/74 | ** | | 910 16K17 |
| 729 | Elevator Control System Modification | PA-36-285 | 11/6/74 | 760-879V | | 2730 16K22 |
| 746 | Air Filtration | PA-36 | 7/10/75 | ** | | 7160 17A16 |
| 759 | Fuselage Forward Bottom Panel Reinforcement | PA-36 | 3/26/76 | 760-999 | | 5310 17C11 |
| 765 | Oil Change And Pre-Start Procedures | PA-36 | 11/26/75 | | | 7920 17D5 |
| 767 | Replacement of Parking Brake Valve | PA-36 | 1/28/76 | 98384-00 | | 3240 17D12 |
| 771 | Engine Care And Operational Tips, Tiara 6-285 | PA-36 | 5/18/76 | | | 7200 17E1 |
| 774 | Engine Cowl Modification | PA-36 | 5/18/76 | 761-062 | | 7110 17E9 |
| 776 | Fitting Installation Flap Control Bellcrank Grease | PA-36 | 10/11/76 | 761-068 | | 2750 17E11 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|---------------------|--------------------|----------|
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-36-285/300 PA-36-375 | 7/28/80 | ** | 79-18-05 | 2560 |
| 825 | Cockpit Door Emergency Release Refinement | PA-36-285 PA-36-300 | 11/30/78 | 763-811 | | 5210 |
| 838 | Manifold Pressure Gauge Line Filter Installation | PA-36-300 | 3/14/78 | 763-835 | | 7710 |
| 849 | Stabilizer Refinement | PA-36-300 | 10/31/78 | | | 5530 |
| 892 | Engine Air Induction System Modification | PA-36-285 PA-36-300 PA-36-375 | 3/21/80 | 99849-14 555-846 | | 7160 |
| 897 | Rudder Attachment Hardware Replacement | PA-36-285/300 PA-36-375 | 6/2/80 | ** | | 5540 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 |
| 1093B | Electrical Contactor Replacement Kit | PA-36-285 PA-36-300 PA-36-375 | 11/28/2017 | 88371 | | 2400 |
| 1116A | Contactor Maintenance | PA-36-285 PA-36-300 PA-36-375 | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1268 | Hartzell 'K' Flange Propeller Hub Replacement | PA-36-300 (Restricted Category Only) | 10/9/2019 | N/A | | 6114 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE | |
|--------|---|--------------------|---------------------|---------------------|-------------|---|-------|
| 177 | Firewalls | All Models | 8/10/51 | | | | 13B13 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 | 15J21 |
| 820 | Replacement of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters | PA-38-112 | 7/28/80 | ** | 79-18-05 | 2560 | 17J2 |
| 855 | Tomahawk Product Refinement Program | PA-38-112 | 10/20/78 | ** | | 1. 2520 2. 2510 3. 5300 4. 6110 5. 7810 6. 2520 7. 5340 8. 3210 9. 2740 2560 10. 5210 11. 2820 12. 5530 13. 2750 14. 3220 15. 5300 16. 2140 | 18A1 |
| 865 | Elevator Trim System Inspection/Modification | PA-38-112 | 1/22/79 | 77878-02 | | 2730 | 18B22 |
| 870 | Upper Rudder Fairing Clearance Inspection | PA-38-112 | 7/5/79 | | | 5350 | 18C23 |
| 876 | Additional Flow Strip Installation | PA-38-112 | 4/12/79 | ** | 83-14-08 | 5720 | 18D17 |
| 877 | Part I - Seat Cover Attachment Replacement | PA-38-112 | 4/30/79 | 455-001 | | 2510 | 18D19 |
| 877 | Part II - Aft Bulkhead Stiffener Channel Installation | PA-38-112 | 4/30/79 | 77554-06 | | 5310 | 18D20 |
| 877 | Part III - Placards Replacement | PA-38-112 | 4/30/79 | 763-932 | | 2500 | 18D21 |
| 877 | Part IV - Fuel Selector Handle Inspection | PA-38-112 | 4/30/79 | | | 2820 | 18D22 |
| 877 | Part V - Stabilizer Drain Holes Addition | PA-38-112 | 4/30/79 | ** | | 5300 | 18D22 |
| 877 | Part VI - Compass Compensation | PA-38-112 | 4/30/79 | ** | | 3440 | 18D23 |
| 877 | Part VII - Main Gear Alignment | PA-38-112 | 4/30/79 | ** | | 3210 | 18D24 |
| 877 | Part VIII - Elevator Stop Attachment | PA-38-112 | 4/30/79 | ** | | 5520 | 18E5 |
| 877 | Part IX - Elevator Leading Edge Straps | PA-38-112 | 4/30/79 | 77618-D2 420-200 | | 5720 | 18E5 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|--------------------|---------------------|----------------------|--------------------|-------------|
| 895A | Magneto Switch Modification | PA-38-112 | 3/19/81 | 153-010 488-396 | | 7430 |
| 909 | Magneto Switch Replacement | PA-38-112 | 6/9/81 | 688 178 | 93-05-06 | 7430 |
| 911 | Aft Spinner Bulkhead Replacement | PA-38-112 | 4/22/81 | 77710-04 77710-06 | | 6110 |
| 931 | Nose Gear Fork Assembly Improvement | PA-38-112 | 8/25/81 | 764-213 | | 3220 |
| 944 | Fuel Selector Valve Inspection And Lubrication | PA-38-112 | 4/20/82 | ** | | 2820 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 |
| 1093B | Electrical Contactor Replacement Kit | PA-38-112 | 11/28/2017 | 88371 | | 2400 |
| 1116A | Contactor Maintenance | PA-38-112 | 3/15/2019 | N/A | | 2435 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1141 | Gascolator Maintenance Procedures | PA-38-112 | 4/27/2011 | MS20995-C32 | | 2800 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SL70

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P,
PA-46-500TP, PA-46-600TP,
PA-46-701TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---------------------------|------------------|--------------|------------|------------|
| 177 | Firewalls | All Models | 8/10/51 | | | 13B13 |
| 578B | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-46-350P PA-46R-350T | 7/27/2011 | N/A | 2011-26-04 | 7310 |
| 609 | Control Surfaces Inspection And Maintenance Guidelines | All Models | 2/21/72 | | | 5500 15J21 |
| 938 | Forward Baggage Door Modification | PA-46-310P | 7/10/84 | 765-109V | | 5230 18K4 |
| 965 | Hydraulic Pump Installation Modification | PA-46-310P | 9/25/85 | 765-161 | | 2910 19A16 |
| 967 | Lower Cabin Door Modification | PA-46-310P | 6/28/84 | 765-104V | | 5210 19A20 |
| 968A | Oil Filler Door/Top Cowl Modification | PA-46-310P | 7/28/86 | ** | | 7250 19A22 |
| 970 | Main Landing Gear Door Link | PA-46-310P | 8/7/84 | ** | | 3216 19B3 |
| 971B | Engine Baffle Modification And Aftercooler Clip Installation | PA-46-310P | 2/23/87 | ** | | 7230 19B6 |
| 972 | PART I - Hydraulic Pressure Gauge Line Fitting Replacement | PA-46-310P | 8/20/84 | 762-643V | | 2930 19B9 |
| 972 | PART II - Hydraulic Pressure Gauge Line Poppet Spring Replacement | PA-46-310P | 8/20/84 | 764-874V | | 2930 19B9 |
| 973 | Lower Cabin Door Step Up - Stop Installation | PA-46-310P | 8/20/84 | 765-107V | | 5260 19B13 |
| 974 | Fiberglass Nose Cowl Replacement | PA-46-310P | 8/20/84 | ** | | 5430 19B15 |
| 975 | Lower Cabin Door Duct Seal & Chain Stand-off | PA-46-310P | 2/13/85 | 765-135V | | 2120 19B17 |
| 976 | Seat Pan Reinforcement | PA-46-310P | 8/20/84 | 765-103V | | 2506 19B19 |
| 978 | Cabin Heat Valve Modification | PA-46-310P | 1/15/86 | 765-176 | | 2140 19B23 |
| 981 | Engine Tachometer Replacement | PA-46-310P | 10/22/85 | 765-183 | | 7710 19C7 |
| 982 | Turbo Inlet Temperature Probe Wiring Modification | PA-46-310P | 2/4/86 | 588-859 | | 7728 19C9 |
| 984 | Hydraulic Pump Annunciator And Controller Installation | PA-46-310P | 7/15/86 | ** | | 2917 19C15 |
| 985 | PART I - Teledyne Continental Motors Special Service Notice No. 3-86. "TSIO-520BE Engine" | PA-46-310P | 4/18/86 | | | 7230 19C17 |
| 985 | PART II - Alternate Air Intake Assembly Modification | PA-46-310P | 4/18/86 | 765-198 | 87-04-01 | 7160 19C17 |
| 989 | Stiffener Installation - Induction Air Panel | PA-46-310P | 8/20/86 | 765-304 | | 7102 19D3 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--------------------------|------------------|----------------------|----------|------------|
| 990 | Engine And Airframe Operational Characteristics And Operating Limitations | PA-46-310P | 11/17/86 | N/A | | 1100 19D5 |
| 991 | Pilot/Copilot Oxygen System Modification | PA-46-310P | 11/18/86 | ** | | 3512 19D9 |
| 992 | Stereo System Power Supply Modification | PA-46-310P | 11/19/86 | 584-387 | | 2334 19D11 |
| 995A | Landing Gear Actuator Switch Modification - Gar Kenyon | PA-46-310P | 5/28/87 | 407-560 | | 3266 19D18 |
| 996 | Engine Mount Heat Shield Installation | PA-46-310P | 3/5/87 | 765-323 | | 7120 19D22 |
| 999 | Air Conditioner Compressor Mount - Shim Installation | PA-46-310P | 7/17/87 | 84044-10 84044-11 | | 2152 19E6 |
| 1000 | Nose Gear Door Hinge Support Modification | PA-46-310P | 10/16/87 | 765-347 | | 3226 19E9 |
| 1001 | Engine Mount Inspection/Modification | PA-46-310P | 12/9/87 | 84010-48 | | 7121 19E11 |
| 1004 | Addition of Main Gear Door Protection Pad | PA-46-310P PA-46-350P | 5/23/89 | ** | | 3216 19E20 |
| 1005 | Nose Bowl Modification | PA-46-350P | 6/8/89 | 766-215 | | 5422 19E23 |
| 1006 | Fuel Vent Line Protection | PA-46-310P | 8/25/89 | 63913-199 488-702 | | 3216 19F1 |
| 1007 | Engine Air/Oil Separator Improvement | PA-46-350P | 9/25/89 | 42414-00 2565-02 | | 7251 19F3 |
| 1008 | Operational Caution: Inoperative Turbine Inlet Temperature System | PA-46-350P | 6/22/90 | N/A | | 7200 19F5 |
| 1009 | Bendix/King Installation Bulletin No. 312, Water Damage to the Pitch and Yaw Capstans and Servos | PA-46-310P PA-46-350P | 9/19/90 | ** | | 2212 19F7 |
| 1010 | Modification of Engine Baffle | PA-46-350P | 1/19/94 | ** | | 7230 19F14 |
| 1011 | Nose Gear Trunnion Replacement | PA-46-310P | 4/27/94 | 766-211 | | 7230 19F16 |
| 1012 | Aileron Control Cable Replacement | PA-46-310P PA-46-350P | 11/30/94 | ** | | 2710 19F23 |
| 1018A | Improved Intercooler Attachment Clips | PA-46-350P | 9/13/99 | 89082-05 | | 7236 18G23 |
| 1022 | Lower Cowling Assembly Modification | PA-46-350P | 2/12/99 | 766-658 | | 5432 19H15 |
| 1023 | Improved Security of the Pressure Controls Cable | PA-46-350P | 4/12/99 | ** | | 2125 19H17 |
| 1026 | Storm Window Seal Improvement Kit | PA-46-350P | 11/3/99 | 766-659 | | 5614 19I5 |
| 1035 | Concorde Lead Acid Battery Conditioning | PA-46-500TP | 7/20/2001 | N/A | | 2432 19J12 |
| 1037 | Power Lever / Manual Override (MOR) Knob | PA-46-500TP | 7/26/2001 | N/A | | 7611 19J21 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--------------------|-----------------|------------|
| 1039A | Replacement TIT Probe Availability | PA-46-350P | 12/8/2006 | 686-216 | 2011-06-10 | 7726 19K4 |
| 1041A | In-Service Safety Event Reporting | All | 3/17/2020 | N/A | | N/A |
| 1046A | Generator Control Unit (GCU) Rewire Kit | PA-46-500TP | 9/27/2002 | 767-329 | | 2430 19L1 |
| 1051 | Gullwing Door Rub Strip Installation | PA-46-500TP | 1/21/2003 | 104644-004 | | 7110 19L15 |
| 1052 | Life Limited Parts Marking and Disposition | All | 5/21/2002 | N/A | | 510 19L19 |
| 1053 | Engine Starter Motor Replacement | PA-46-350P | 10/16/2002 | 767-337 | | 8011 20A1 |
| 1055 | Executive Table Stow Adjustments | PA-46-500TP | 6/20/2003 | N/A | | 2520 20A6 |
| 1056 | Accessory Cooling Air Inlet Drain Hose Routing Inspection | PA-46-500TP | 2/19/2003 | ** | | 7500 20A9 |
| 1057 | Upper Wing Skin Inspection and Reinforcement | PA-46-310P PA-46-350P PA-46-500TP | 1/29/2003 | 767-352 767-353 | | 5730 20A12 |
| 1058A | Horizontal Stabilizer Maintenance Manual Correction - Torque Value | PA-46-500TP | 10/16/2012 | 767-005 | | 5510 |
| 1059A | Tailcone Gusset Installation Kit | PA-46-500TP | 10/16/2015 | 767-356 | | 5300 |
| 1062 | Lower Torque Link Bolt Inspection | PA-46-500TP | 2/13/2003 | ** | | 3213 20B4 |
| 1065 | Aileron Rivet Inspection | PA-46-500TP | 7/29/2005 | 522-655 | | 2710 20B13 |
| 1067 | Steering Bellows Improvement | PA-46-500TP | 3/31/2003 | 691-527 | | 3250 20B20 |
| 1069 | Flight Control Cable Terminal Corrosion Inspection | All | 3/31/2003 | N/A | CE-02-05 (SAIB) | 2702 20C2 |
| 1072 | Possible Magnetization of ELT Antenna | PA-46-500TP | 6/4/2003 | 762-362 | | 2300 20C9 |
| 1074 | S-TEC Autopilot Component Seating Procedure | All | 11/3/2003 | N/A | | 2210 20C14 |
| 1075 | Higher Capacity Battery Availability | PA-46-500TP | 10/27/2003 | 601-910 767-375 | | 2432 20C19 |
| 1076 | Stall Warning Computer Verification | PA-46-500TP | 1/9/2004 | 600-517 599-161 | | 3418 20C22 |
| 1077 | Magic 1500 Autopilot Go-Around Switch Wire Security | PA-46-500TP | 12/3/2003 | 767-376 | | 2200 20D1 |
| 1079 | ADAHRS Fault Finding Guide (Meggitt SIL No. 26, Issue 1) | PA-46-500TP | 5/5/2004 | N/A | | 3400 20D7 |
| 1082 | Fuel Filter Replacement (Pall SB ADB474-72-01) | PA-46-500TP | 6/25/2004 | 601-808 601-809 | | 2821 20E12 |
| 1085 | ADAHRS Calibration Harness | PA-46-350P PA-46-500TP | 7/1/2004 | 101453-002 | | 3420 20E23 |
| 1086 | Propeller Blade De-ice Boots Maintenance | PA-46-310P PA-46-350P PA-46-500TP | 7/16/2004 | N/A | | 3112 20F3 |
| 1089 | Aircraft Painting Requirement | PA-46-350P PA-46-500TP | 10/21/2004 | N/A | | 1100 20F15 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------|----------|------------|
| 1090 | Performance Upgrade, Lower Operating Temperature Limitation | PA-46-500TP | 9/26/2005 | 767-380 767-381 | | 2843 20F18 |
| 1091 | Door Seal Protection (Latch Stop Kit) | PA-46-350P | 12/15/2005 | 767-387 | | 5210 20F21 |
| 1093B | Electrical Contactor Replacement Kit | PA-46-310P PA-46-350P PA-46R-350T | 11/28/2017 | 88371 | | 2400 |
| 1097 | Flap Bellcrank Inspection and Flap Rigging Check | PA-46-310P PA-46-350P PA-46-500TP | 10/17/2005 | 82905-10/-11 | | 2700 20H4 |
| 1100 | Crew Seat Modification | PA-46-350P PA-46-500TP | 6/18/2006 | 767-522 | | 2510 20H10 |
| 1102 | Oil Pressure Indication Subject to RFI/EMI | PA-46-500TP | 10/9/2006 | 88408-002 | | 7261 20H14 |
| 1104 | Flow Sensor Assy., Mass Flow Controller and ECS Crossover Tube Assy. Replacement | PA-46-500TP | 3/14/2008 | 88417-002 88417-003 | | 2140 20H20 |
| 1106A | Sky-Tec Starter Cranking Instructions | PA-46-350P PA-46R-350T | 10/28/2009 | N/A | | 8011 20I2 |
| 1107A | Modification to Eliminate False "GEN INOP" Annunciation | PA-46-500TP | 10/3/2007 | N/A | | 2420 20I6 |
| 1108 | Manifold Pressure Transducer Failures | PA-46-350P PA-46R-350T | 3/4/2008 | N/A | | 7713 20I10 |
| 1110A | Pratt & Whitney Canada SIL No. PT6A-206 latest revision, Compressor and Turbine Washes as an Effective Means of Preventative Maintenance | PA-46-500TP | 9/3/2013 | N/A | | 7100 |
| 1111 | Autopilot Pitch Servo and Programmer / Computer Upgrade | PA-46-350P PA-46R-350T | 5/29/2008 | 88438-002 88439-002 | | 2212 20I23 |
| 1113 | Crew Seat Back Modification | PA-46-500TP PA-46-350P PA-46R-350T | 2/25/2009 | 88444-002 (Kit) | | 2510 |
| 1114 | NACA Inlet Guide Vane Installation Kit | PA-46R-350T | 2/16/2009 | 88446-002 (Kit) | | 2140 |
| 1115A | WAAS Compatible Autopilot | PA-46-500TP | 2/19/2009 | N/A | | 2210 |
| 1116A | Contactor Maintenance | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 3/15/2019 | N/A | | 2435 |
| 1117 | MLB 700 Remote Control Antenna Modification | PA-46R-350T | 3/16/2009 | 561-572 | | 2330 |
| 1118 | Sky-Tec Starter Replacement | PA-46-350P PA-46R-350T | 10/28/2009 | ** | | 8011 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|------------------------------------|----------|----------|
| 1120 | Air Conditioning Servicing | PA-46-350P PA-46-500TP PA-46R-350T | 6/18/2010 | ** | | 2150 |
| 1121 | RG-41 Battery Service Life Improvement | PA-46-500TP | 4/1/2010 | 601-910 | | 2430 |
| 1122 | G1000 Split Communciations Enable | PA-46-350P PA-46R-350T | 5/20/2010 | N/A | | 2300 |
| 1123 | Avidyne EXP5000 Software Upgrade (Mod 57) | PA-46-350P PA-46-500TP PA-46R-350T | 9/27/2010 | N/A | | 3420 |
| 1126A | Voltage Suppressor Advisory | PA-46-350P PA-46-500TP PA-46R-350T | 3/23/2017 | N/A | | 3400 |
| 1127 | Emergency Exit Interior Panel Hook and Loop Fastener Replacement | PA-46-350P PA-46-500TP PA-46R-350T | 7/2/2010 | ** | | 5220 |
| 1128 | Improved Capacity Battery | PA-46-350P PA-46R-350T | 3/7/2012 | 88495-002 601-919 | | 2430 |
| 1129 | Improved Landing Gear Service Replacement Actuators Available | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 6/27/2011 | ** | | 3230 |
| 1130 | Lower Entry Door Upgrade | PA-46-350P PA-46-500TP | 8/4/2010 | 88423-002 452-215 106611-003 | | 5210 |
| 1131A | Aileron Sector Bearing Lubrication Requirements | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 2/11/2019 | MIL-PRF-7870C | | 5755 |
| 1132 | Fuel Tank Leaks | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 12/7/2010 | N/A | | 5712 |
| 1135 | Control Cable / Pulley Inspections | All | 10/19/2010 | N/A | | 5720 |
| 1136A | Fuel Pressure Switch Adjustment | PA-46-350P PA-46R-350T | 4/28/2011 | 74093-002 688-192 | | 2820 |
| 1137 | Circuit Breaker Panel Modification | PA-46-500TP | 11/3/2010 | 88482-002 88482-003 | | 3910 |
| 1138 | Safe Flight Service Letter No. 65, Lift Transducer Modification | PA-46-350P PA-46-500TP PA-46R-350T | 1/17/2011 | 599-160 652-689 | | 3410 |
| 1140 | Garmin G1000 Software Version 720.12 | PA-46-350P PA-46R-350T | 6/22/2011 | ** | | 3420 |
| 1142A | Line Contactor and Generator Control Unit Replacement | PA-46-500TP | 3/10/2014 | 602-943 PS60047-1 601-922 | | 2430 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SL75

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|--|------------------|--|----------|----------|
| 1147 | Garmin G1000 Software Version 720.14 | PA-46-500TP | 12/1/2011 | ** | | 3420 |
| 1148 | Garmin G1000 Software Version 720.14 | PA-46-350P PA-46R-350T | 5/2/2012 | ** | | 3420 |
| 1155 | Ground Idle Adjustment | PA-46-500TP | 1/30/2012 | N/A | | 7610 |
| 1157 | Exterior Lighting - Led Upgrade | PA-46-310P PA-46-350P PA-46-500TP PA-46R-350T | 4/26/2012 | ** | | 3340 |
| 1158 | Hubcap Upgrade | PA-46-500TP | 4/26/2012 | 551-621 | | 3240 |
| 1159B | Fuel Sender Upgrade | PA-46-310P PA-46-350P PA-46R-350T | 10/12/2018 | 88535 88462 | | 2840 |
| 1160 | Interior Lighting – LED Upgrade | PA-46-350P PA-46-500TP PA-46R-350T | 10/31/2017 | 479-000 479-001 479-002 488-770 103203-005 103203-006 103203-007 | | 3300 |
| 1168 | False Alternator Fail Annunciations | PA-46-350P PA-46R-350T | 2/28/2013 | N/A | | 2300 |
| 1170 | Evaporator Module Assembly Replacement Requirements | PA-46-350P PA-46-500TP PA-46R-350T | 6/27/2013 | 88542 | | 2150 |
| 1178A | Garmin G1000 Software Version 720.15 | PA-46-500TP | 4/23/2014 | ** | | 3420 |
| 1179 | Garmin G1000 Software Version 720.15 | PA-46-350P PA-46R-350T | 4/24/2014 | ** | | 3420 |
| 1183 | Elevator Plate Assembly Rivet Inspection | PA-46-310P PA-46-350P PA-46R-350T | 10/21/2014 | 83515-002, 83508-002 | | 2730 |
| 1184 | Stall Warning System Test Update | PA-46-350P PA-46R-350T | 2/11/2015 | ** | | 2730 |
| 1185A | Stall Warning System Test Update | PA-46-500TP | 3/26/2015 | ** | | 2730 |
| 1189B | Inspection of GCU Reverse Current Protection Circuit and Connector | PA-46-500TP | 8/14/2015 | 461-659 | | 2424 |
| 1194A | Garmin G1000 Software Update Version 720.17 | PA-46-350P PA-46R-350T | 9/1/2015 | N/A | | 3420 |
| 1195 | Garmin G1000 Software Update Version 720.17 | PA-46-500TP | 9/2/2015 | N/A | | 3420 |
| 1196A | Availability of GTX 33ES Transponder | PA-46-350P PA-46-500TP PA-46R-350T | 12/21/2017 | N/A | | 3452 |
| 1198 | Garmin G1000 Software Version 2164.03 | PA-46-350P M350 | 2/24/2016 | N/A | | 3420 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|--|---|------------------|--|----------|----------|
| 1199A | Garmin G1000 Software Version 2163.05 | PA-46-500TP M500 | 7/26/2016 | N/A | | 3420 |
| 1200A | Pratt & Whitney Canada Service Bulletin No. 3482 – Replacement/Modification of Turboprop Fuel Control Unit | PA-46-500TP | 4/27/2016 | N/A | | 7320 |
| 1201B | Garmin G1000 Software Update Version 2164.06 with Stall Heat Control | PA-46-350P M350 | 8/19/2016 | 88589-002 190-01889-00 190-01888-00 | | 3420 |
| 1202 | Main Landing Gear Actuator Hydraulic Hose Replacement | PA-46-350P PA-46-500TP PA-46R-350T | 2/7/2017 | 187-273 102551-004 | | 3230 |
| 1203A | Garmin G1000 Software Update Version 720.17 with Stall Heat Control | PA-46-350P PA-46R-350T | 3/21/2019 | 88589-002 88589-003 190-01108-01 190-01107-01 | | 3420 |
| 1204 | Heated Windshield Test Procedure | PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 8/17/2016 | N/A | | 3040 |
| 1205 | Garmin G1000 Software Update Version 720.17 with Stall Heat Control | PA-46-500TP | 6/27/2017 | 88590-002 VB-1993 R17 | | 3420 |
| 1206 | Garmin G1000 Software Update Version 2163.08 with Stall Heat Control | PA-46-500TP M500 | 4/14/2017 | 88590-003 | | 3420 |
| 1208A | Garmin G3000 Software Update Ver. 2039.06 with Sidetone Improvement | PA-46-600TP | 12/12/2016 | 10-01615-06 | | 3420 |
| 1211 | Audio Bus Wiring Inspection and Fuse Replacement | PA-46-350P PA-46-500TP | 5/3/2017 | 461-685 | | 2350 |
| 1212 | Garmin G3000 Software Update Version 2039.08 with Aural Alert Improvement | PA-46-600TP | 3/10/2017 | 10-01615-08 | | 3420 |
| 1217 | Garmin G3000 Software Update Version 2039.11 with FIKI Modification | PA-46-600TP | 7/13/2017 | 10-01615-11 VB-2366 R03 | | 3420 |
| 1219 | Cabin Pressure Control System (CPCS) Troubleshooting Procedure Revision | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 1/5/2018 | N/A | | 2130 |
| 1220 | Garmin G1000 Software Version 2164.08 | PA-46-350P M350 | 11/6/2017 | 190-01889-00 190-01888-00 | | 3420 |
| 1221A | Wing Access Cover Clinch Nut Repair | PA-46-500TP PA-46-600TP | 4/25/2024 | 477-899 414-779 | | 2810 |
| 1222B | Hydraulic Pump Pressure Switch Replacement | PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 3/29/2018 | 102559-002 (461-751) 102559-003 (461-768) 102559-004 (461-770) | | 2913 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|---|----------|--------------|
| 1224 | Decorative Window Sealant Improvement | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP | 10/9/2017 | 179-759 | | 5610 5620 |
| 1227 | Forward Ballast Plates Installation | PA-46-600TP | 11/2/2017 | 46N08A000-800 | | 5300 |
| 1228A | Engine Wiring Harness Improvement | PA-46-500TP M500 PA-46-600TP | 1/23/2019 | ** | | 2497 |
| 1230C | G3000 And G3000 NG Electronic Checklist – M600 | PA-46-600TP | 12/2/2024 | N/A | | 3140 |
| 1231A | Garmin G3000 Software Version 2039.12 | PA-46-600TP | 8/3/2018 | 190-01927-01 190-01928-01 | | 3420 |
| 1232C | Garmin G1000 Software Version 2163.09 | PA-46-500TP M500 | 8/21/2018 | 190-01843-01 190-01842-01 | | 3420 |
| 1233 | Wing And Flap Protective Tape Improvement | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 7/13/2020 | 380-066 | | 5753 |
| 1234 | Garmin GIA Software Update 2963.01 for Transponder Compatibility with ADS-B Out in G1000 Sw Ver. 720.17 | PA-46-350P PA-46-500TP PA-46R-350T | 1/16/2018 | ** | | 3452 |
| 1236 | Channel Modification For Nose Landing Gear Trunnion Clearance | PA-46-500TP PA-46-600TP | 10/2/2019 | N/A | | 5311 |
| 1238B | Aileron Seal Removal And Aileron Replacement | PA-46-600TP | 1/6/2022 | 46W43A001 415-533 (MS35206-243) | | 5751 |
| 1244 | Wiring Ground Modification | PA-46-600TP | 6/21/2018 | N/A | | 2397 |
| 1245 | G1000 NXi Electronic Checklist | PA-46-500TP M500 | 12/14/2022 | N/A | | 3140 |
| 1246 | G1000 NXi Electronic Checklist | PA-46-350P M350 | 1/7/2020 | N/A | | 3140 |
| 1247A | Hydraulic System Flexible Hose Inspection And Replacement | PA-46-600TP | 11/5/2019 | 566-670 (171001-4CR-0110) | | 2910 3233 |
| 1249 | Control Column Plug Modification | PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 5/20/2019 | 85228-002 | | 2701 |
| 1250B | Garmin G1000 Software Update - M350 | PA-46-350P M350 | 4/12/2019 | 88642-001 190-01889-01 190-01888-01 | | 3420 |
| 1251 | Garmin G1000 Software Version 2163.10 | PA-46-500TP | 12/18/2023 | 88651-001 | | 3420 |
| 1253 | G1000 Electronic Checklist | PA-46-350P M350 | 12/11/2019 | N/A | | 3140 |
| 1257 | Servicing The Alternative Wheel Nut Configuration | PA-46-600TP | 5/6/2019 | N/A | | 3420 |
| 1259A | Garmin G3000 Software Version 2039.15 | PA-46-600TP | 11/17/2020 | 88644-001 | | 3420 |
| 1260 | Optional Nav/Com Analog Conversion Kit | PA-46-600TP | 5/24/2019 | 88648-001 | | 2397 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

PA-46-310P, PA-46-350P
PA-46-500TP, PA-46-600TP,
PA-46-700TP, PA-46R-350T

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--|----------|----------|
| 1261 | Stall Warning Heat Control Inspection | PA-46-350P PA-46-350T PA-46-500TP | 7/19/2019 | N/A | | 3418 |
| 1264 | Garmin G3000NG Software Version 2975.05 | PA-46-600TP | 8/16/2019 | 88637-001 | | 3420 |
| 1265 | Flight Control System Checks | All | 8/6/2019 | N/A | | 2700 |
| 1266 | Piper HALO Autoland System Activation and Garmin Software Update Ver. 2975.16 | PA-46-600TP | 6/26/2020 | 88660-701 88660-702 88645-702 88680-001 | | |
| 1269A | Radar Altimeter Installation | PA-46-600TP | 3/6/2023 | 88643-701 88654-001 | | 3444 |
| 1270 | Radar Altimeter Installation | PA-46-600TP | 1/28/2021 | 88645-702 88654-001 | | 3444 |
| 1272 | Elevator Spar Inspection | PA-46-500TP PA-46-600TP | 10/25/2019 | N/A | | 5521 |
| 1274 | Hartzell Propeller Preferred Grease | All | 1/6/2020 | NYCO GN 3058 | | 6110 |
| 1275 | Optional Radar Altimeter Installation (Garmin GRA 55 Radar Altimeter) | PA-46-600TP | 1/12/2021 | 88645-701 88654-001 | | 3444 |
| 1279 | High-Side Current Monitor Calibration | PA-46-600TP | 7/8/2020 | N/A | | 3420 |
| 1280 | Rudder Pedal And Bar Assembly Inspection | All | 2/14/2020 | N/A | | 2720 |
| 1281B | Piper Halo Autoland System Activation | PA-46-600TP | 1/7/2022 | 88670-701 | | 2230 |
| 1282 | Avionics Cooling Fan Advisory | PA-46-350P PA-46-500TP PA-46R-350T | 6/22/2020 | 460-124 | | 2120 |
| 1283A | Piper HALO Autoland System Activation | PA-46-600TP | 1/7/2022 | 88662 | | 2230 |
| 1284A | Aspen Avionics EFD1000 Update to Software Version 2.10.2 | PA-46-350P PA-46-500TP PA-46-600TP | 5/15/2023 | N/A | | 3420 |
| 1285C | Proper Tire Pressure Maintenance | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 3/29/2022 | ** | | 3244 |
| 1286D | Nose Landing Gear Steering Components Inspection And Adjustment | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 10/15/2021 | N/A | | 3200 |
| 1292D | Garmin G3000NG Software Version 2975.24 | PA-46-600TP | 8/13/2024 | 88680-001 88704-701 | | 3420 |
| 1296 | Flap Fail Module Assembly Replacement | PA-46-600TP | 3/10/2022 | 602-575 | | 2756 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.

SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS AFFECTED | EFFECTIVITY DATE | PART/KIT NO. | A.D. NO. | ATA CODE |
|--------|---|---|------------------|--|----------|----------|
| 1297 | Rudder Tube Assembly Inspection | PA-46-310P PA-46-350P PA-46R-350T PA-46-500TP PA-46-600TP | 10/22/2021 | 82810-015 82810-016 | | 2720 |
| 1301B | Standalone Autothrottle Enablement | PA-46-600TP | 9/26/2024 | 88661/88663 | | 2230 |
| 1304B | Garmin G1000 NXi Software Update - M350 | PA-46-350P M350 | 3/11/2024 | 88711-701 | | 3420 |
| 1310A | M600 Unpaved Field Operations | PA-46-600TP | 11/7/2022 | 88596-001 88705-701 | | 3200 |
| 1314 | Oxygen Generator Inspection | PA-46-310P PA-46-350P PA-46-500TP PA-46-600TP | 8/22/2022 | N/A | | 3500 |
| 1315 | Elevator Trim Tab Pushrods Corrosion Control | PA-46-310P PA-46-350P Mirage / M350 PA-46-500TP Meridian / M500 PA-46-600TP PA-46R-350T | 5/2/2023 | 82998-013 82998-015 82836-007 102846-005 | | 5520 |
| 1317 | GI 275 Standby Instrument Magnetic Model Update | PA-46-350P M350 PA-46-500TP M500 PA-46-600TP | 11/11/2022 | 006-B3182-10 | | 3420 |
| 1323 | Garmin G1000 NXi Software Update Version 2785.11 | PA-46-500TP M500 | 3/20/2023 | 88719-701 | | 3420 |
| 1332C | Garmin G3000NG Software Version 2975.45 | PA-46-600TP M600 | 10/16/2024 | 88739-701 | | 3420 |
| 1336 | GDL 60 Datalink Installation - M600 | PA-46-600TP M600 | 3/27/2024 | 88737-701 88737-702 88737-703 88737-704 88737-705 88724-701 88724-702 88724-703 88724-704 88724-705 | | 3425 |
| 1337 | Flight Controls Maintenance Improvements | PA-46-350P PA-46-500TP PA-46-600TP PA-46R-350T | 1/29/2023 | | | 2700 |
| 1338 | Garmin G1000 NXi Software Update – M350 | PA-46-350P M350 | 4/1/2024 | 88749-701 | | 3420 |
| 1344 | Garmin G3000 NG Software Update - M700 | PA-46-701TP M700 Fury | 5/31/2024 | 88752-701 | | 3420 |
| 1345 | Unpaved Field Operations - M700 Fury | PA-46-701TP M700 Fury | 8/15/2024 | | | 3200 |
| 1349 | Pratt & Whitney Canada Engine Fuel Line Installation - Standard Practices | PA-46-500TP PA-46-600TP PA-46-701TP | 12/9/2024 | | | 7300 |

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service letter for material identification and/or appropriate aircraft model.